

ASS. REC. BY:

REF:

a/TPD18016115/Ze

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): Kameliah Kamie

of

SPF

Date/Time: 1/9/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM7686P

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000004093

Claim No: TP/1P/43847/2018

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/8/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SLM7686P-X.

530/9

2

Motor Car SLM 7686P

Rohaizal (LKKAUTO)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Saturday, 1 September 2018 12:39 PM
To: Rohaizal (LKKAUTO)
Cc: Bryan Ang (LKKAUTO); SPF-TP FAIT; Nor Faizal YAHYA (SPF)
Subject: RE: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 9 vehicles below:

a) Case IAFP-IB-20180823 - Mechanical Inspection of Motorcycle, FS7646U (TP/IP/43085/2018)

On 31.7.2018 at about 9.12 am, motorcycle was riding along Tampines Ave 2 towards Tampines Ave 9 near LP 34A on the centre lane of 3 lanes road where he lost control of his motorcycle and self-skidded, Deceased (motorcyclist) was unconscious and conveyed to CGH. But however, he succumbed to his injuries and in CGH and pronounced dead on the same day at 2.40 pm

Vehicle to be inspected: FS7646U – Rider (Deceased)

IO In-Charge: SIO Vilton

b) Case IAFP-IB-20180823 - Mechanical Inspection of Motor Car, SLM7686P (TP/IP/43847/2018)

On 3.8.2018 at about 4.31 am, motor car was driving along Nicoll Highway towards Guillemard Road on the 1st lane of 3 lanes road when his front right portion collided onto the rear left of stationary lorry whom had stopped for traffic related works at LP 23/1. Deceased (car driver) sustained head injuries and was pronounced dead at the scene.

Vehicle to be inspected: SLM7686P – Driver (Accused)

IO In-Charge: SIO Vilton

c) Case IAFP-IB-20180823 - Mechanical Inspection of Motorcycle JQV5714 (TP/IP/43461/2018)

On 02/08/2018 at about 2.22 am, the Deceased was riding motor cycle JQV5714 along SLE towards BKE, near to lamp post 125, when he lost control and collided onto the rear of a moving tipper truck. The rider (Deceased) suffered fatal injuries and passed away at scene. He was pronounced dead by paramedic, Melissa at 2.53 am.

Vehicle to be inspected: JQV5714 - Rider (Deceased)

IO In-Charge: SIO Farhan

d) Case IAFP-IB-20180823 - Mechanical Inspection of Motor Lorry, GBF3128R (TP/IP/45327/2018)

e) Case IAFP-IB-20180823 - Mechanical Inspection of Motorcycle, JSU8134 (TP/IP/45327/2018)

On 13 August 2018 at about 6.24 am., a Critical turned Fatal road traffic accident involved a Singapore motor lorry and a Malaysian motorcycle, which happened along Woodlands Road towards Upper Bukit Timah Road opposite Singapore Turf Club. As a result of the accident, the Malaysian Rider, the Deceased

was reported to be unconscious due to traumatic head injuries and was conveyed to Khoo Teck Puat by ambulance. The Deceased succumbed to his injuries and was pronounced dead by Doctor Vinoban at 11.05am.

Vehicle to be inspected: GBF312BR – Driver (Accused)

Vehicle to be inspected: JSU8134 – Rider (Deceased)

IO In-Charge: IO Clarence

f) Case IAFP-IB-20180823 - Mechanical Inspection of Motorcycle, FBE785T (TP/IP/47547/2018)

On 22 August 2018 (Wednesday) at about 4.37 a.m., the Deceased was riding his motorcycle alone along Pan Island Expressway towards Tuas, on lane 1 of 3 lanes road. Somewhere near the 17.5 km mark, the Deceased lost control of his motorcycle, collided onto the wall of the center divider and skidded. The Deceased was pronounced dead at scene at 4.54 a.m. by the attending paramedic, SS Terry.

Vehicle to be inspected: FBE 785 T – Rider (Deceased)

IO In-Charge: IO Clarence

g) Case IAFP-IB-20180823 - Mechanical Inspection of Motor Car, SLN9906L (TP/IP/44465/2018)

On 7 August 2018 at 8.46 pm, Motor car was travelling along Sheares Avenue when he lost control of his motor car and skidded, mounted the kerb and collided onto a tree. The driver died on the spot and SCDF had to extricate the deceased out of the motor car.

Vehicles to be inspected: SLN9906L – Driver (Deceased)

IO In-Charge: SIO Yazid

h) Case IAFP-IB-20180823 - Mechanical Inspection of Motor Taxi, SHD7126J (TP/IP/43683/2018)

On 2 August 2018 at 12.41 pm, motor taxi was involved in an accident along Jurong West Avenue 1 junction of Jurong West Street 42. The said driver was driving on the left of 3 lanes road. He claimed while changing lane, as he was applying brake, his vehicle continued to surge forward despite him stepping on the brake. His vehicle then collided onto one motor car and one motor lorry which were stationary while stopping at the junction due to red light. He claimed the brake was faulty.

Vehicles to be inspected: SHD7126J – Driver (At fault)

IO In-Charge: SIO Nor Faizal

i) Case IAFP-IB-20180823 - Mechanical Inspection of Motor Van, GBE9701B (TP/IP/38745/2018)

On 8 July 2018 at 6.45 am, motor van was travelling along Eunos Link Slip Road into PIE (Airport) on lane 2 of the 2-lanes road when he suddenly felt an impact from his frontal left portion. He claimed that he was unaware where the pedal cyclist came from. Due to the collision, the pedal cyclist sustained head injury and was conveyed to Changi General Hospital (CGH) in an unconscious state by an ambulance. However on 16 August 2018 at 1.32 am, the pedal cyclist succumbed to his injuries and he was pronounced dead by Dr Yohan in CGH.

Vehicles to be inspected: GBE9701B – Driver (Deceased)

IO In-Charge: IO Kamaliah