

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 03.09.2018

Time: 11:43:36

Page: 1/2 TS

AXA - CP(P)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305207574
REGN NO : SHC3317G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 19.05.2016
DATE/TIME IN : 03.09.2018 08:25
ACCIDENT DATE : 01.09.2018

1150

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G REAR BUMPER 1 603.60 20.00 482.88

X repair

0002 04-01-0103-0783-G REAR BUMPER SIDE BRKT RH 1 49.00 20.00 39.20

X

0003 04-01-0101-0111-G REAR BUMPER CLIPS 10 L 22.00 20.00 17.60

X

0004 04-01-0103-1150-A REAR BUMPER MAT 1 50.00 50.00

X

SUB-TOTAL : 589.68

JOB NATURE

0000 20-05 Rear Bumper Adv.Sticker

50.00 X

0001 L PANEL BEATING

280.00 100

0002 23-502 SPRAYPAINT ON AFFECTED AREA

250.00 200

0003 L R/I REVERSE SENSOR

120.00 X

SUB-TOTAL : 700.00

TS

AVA - P/P)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305207574
REGN NO : SHC3317G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 19.05.2016
DATE/TIME IN : 03.09.2018 08:25
ACCIDENT DATE : 01.09.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lamps

TOTAL : 1,289.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

1 Calini 1 CLK
3/9/18 1426 hrs.
2 Pys.
P/P
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: