

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6006U

DATE 3/9/2018 11:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x 1442</i>			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>x</i>			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover <i>x</i>			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Advertisement Logo <i>✓</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>✓</i>		\$ 100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70 Nett
				\$ 385.70
	Labour Charge			
	Panel Beating			\$ 380.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,439.06
<i>Kalvin LKK</i> <i>4/9/18 1020 L.</i> <i>2 Bx</i> <i>L/S</i> <i>After Repair photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				