

ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4022 G
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 YEAR : 2007
 CHASSIS NO : JTFHT02P600004453

SURVEYOR NAME :
 DATE OF SURVEY : 11 SEP 2018
 TIME OF SURVEY :

DATE : 1-Sep-18
 DATE OF ACCIDENT : 31-Aug-18
 THIRD PARTY REF : SJV 1792 G / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			<i>Bu</i> \$	458.40
1 pc	Rear Bumper Retainer			<i>mi</i> \$	68.40
1 pc	Tailgate Emblem			<i>mi</i> \$	89.80
				\$	616.60
	Less 25%			\$	154.15
				\$	462.45
1 set	Rear Bumper Sensor	S.Nett		<i>mi</i> \$	200.00
1 pc	70km/h Sticker	S.Nett		<i>mi</i> \$	15.00
1 set	DHL Logo Sticker	S.Nett		<i>(Bill)</i> \$	480.00
	To putty and spray painting.			<i>500</i> \$	680.00
	Labour Charges.			<i>400</i> \$	450.00
	<i>Not Authorised</i> <i>11 Sep @ ?</i> <i>Resurvey After Paint</i> <i>3 days</i>				
TG-RA/-	TOTAL			\$	2,287.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 675721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0