

ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4022 G
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 YEAR : 2007
 CHASSIS NO : JTFHT02P600004453

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 1-Sep-18
 DATE OF ACCIDENT : 31-Aug-18
 THIRD PARTY REF : SJV 1792 G / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 458.40
1 pc	Rear Bumper Retainer				\$ 68.40
1 pc	Tailgate Emblem				\$ 89.80
					\$ 616.60
	Less 25%				\$ 154.15
					\$ 462.45
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 pc	70km/h Sticker	S.Nett			\$ 15.00
1 set	DHL Logo Sticker	S.Nett			\$ 480.00
	To putty and spray painting.				\$ 680.00
	Labour Charges.				\$ 450.00
TG-RA/-	TOTAL				\$ 2,287.45

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0