

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC1183M  
 MAKE : HYUNDAI  
 MODEL : IONIQ

DATE: 3. Sep. 2018

DOA: 1. Sep. 2018

**EQ**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper Cover			\$459.40
1	Rear Bumper Centre Molding (black)			\$270.10
1	Rear Bumper Reinforcement ?			\$294.80
2	Rear Bumper Stay – LH/RH ?		\$138.10	\$276.20
10	Rear Bumper Clips		\$2.20	\$22.00
<b>SUB TOTAL</b>				<b>\$1,322.50</b>
<b>LESS 20%</b>				<b>\$264.50</b>
<b>DISCOUNTED TOTAL</b>				<b>\$1,058.00</b>
1	Reverse Sensor			\$135.70
				<b>Nett</b>
				<b>\$135.70</b>
<b>Labour Charge</b>				
1	Panel Beating			\$500.00
1	Spray Painting Charge			\$500.00
1	Remove/refix Reverse Sensor			\$100.00
1	Wiring Charge			\$50.00
1	Tuff Kote			\$50.00
<b>TOTAL LABOUR</b>				<b>\$1,200.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$2,393.70</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No application is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Kalvin LKK*  
*3/9/18*  
*20%*  
*PIP*

*Before Paint photo*

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.