

22/03/2002

ASS. REC. BY:

REF: CS3/SM018016141/Gcd307 Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

4/9/18 @ 9.49am.

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 1635E

Insured:

XA 8988H

at Workshop m/s

M1 Motoring

Tel:

6743 7030

of

411 Changi Rd

Policy No:

Claim No:

CMTD1803575/7HE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/08/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10.55am @ 4/9/18

Person Contacted:

Mr. Albert

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBK 1635E - X

XA 8988H - X.

(08/11/13) wof

ASS REC. BY:

PRS

Xal

REF: SMO

ASSIGNMENT

From:

Date:

4/1/18

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBK 1635 E

at Workshop n/s

MI Motoring

of

411 Changi Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Alberto 67437030

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBK 1635 E

Yr Regn:

-

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha F8

c.c.

-

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

100/80-17

R:

140/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MRF

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

04-09-18

Survey held at

W/S

5:30pm

Des. of Damages: Frt / Rear ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

6/9/18

Submit PRS Report

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

100

Transportation:

S + RS, SI

Photos

Others

TOTAL

100

Report Format :

Lump Sum / I.B.I. (\$)

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 4 September 2018 9:46 AM
To: Mail office; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1803575/THE - SUV(LKK)/ XA8988H/ FBK1635E/ SLU6014T ACC ON 17.08.18
Attachments: GOH JP FBK1635E.pdf

Our Reference: CMTD1803575/THE
Your Reference GTW.ACC.8144.18 wk

Without Prejudice
EMAIL ONLY

Date: 4th September 2018

Attention:
M/S GOH JP & WONG LLC

Dear Wee Ka,

ACCIDENT INVOLVING XA8988H & FBK1635E ON 17.08.2018

We refer to your email reply dated 04/09/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

Kindly provide us the address of location and contact for our motor surveyor to conduct the pre-repair survey.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Mail office [mailto:mail@gohjpwong.com]

Sent: Tuesday, September 04, 2018 9:31 AM

To: Teo, Grace

Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James

Subject: Re: CMTD1803575/THE - PRI/ XA8988H/ FBK1635E/ SLU6014T ACC ON 17.08.18

Dear Sir/Mdm

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert ("SJE") as follows:-

1. Teo Liak Hoo of L H Teo Appraisal Services
2. Jayson Liaw Leong San of Pro-Option Services
3. Seah Kwang Boon of Absolute Appraisal Services
4. Oh Han Cheong of Oh Appraisal
5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Kindly let us hear from you soonest.

Lee Wee Ka
for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, Sep 4, 2018 at 9:24 AM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1803575/THE
Your Reference GTW.ACC.8144.18 wk

Without Prejudice
EMAIL ONLY

Date: 4th September 2018

Attention:
M/S GOH JP & WONG LLC

Dear Teck Wee,

ACCIDENT INVOLVING XA8988H & FBK1635E ON 17.08.2018

We refer to your Notice of Accident dated 03/09/2018 via fax.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	

2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

Nivitha (LKK Auto)

From: Mail office <mail@gohjpwong.com>
Sent: Tuesday, 4 September 2018 9:49 AM
To: Teo, Grace
Cc: admin-d@lkkauto.com; assignments@lkkauto.com; Choo, Thelma; Ye, Yong Kang
Subject: Re: CMTD1803575/THE - SUV(LKK)/ XA8988H/ FBK1635E/ SLU6014T ACC ON 17.08.18

Dear Sir/Mdm

Our client's motorcycle FBK 1635E is now at M1 Motoring located at 411 Changi Road Singapore 419860 (Mr Albert Ang - 6743 7030).

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days.

Lee Wee Ka
for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, Sep 4, 2018 at 9:45 AM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1803575/THE

Your Reference GTW.ACC.8144.18 wk

Without Prejudice



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO18016141/Gcd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 04-09-2018



Code : SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XA 8988H	Veh. Inspected	FBK 1635E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803575/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/08/2018	Inspection Date	04/09/2018
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18016141/Gcd3e2	
50 RAFFLES PLACE #05-01/06		Date: 07-09-2018	
SINGAPORE LAND TOWER SINGAPORE 048623		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XA 8988H	Veh. Inspected	FBK 1635E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803575/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/09/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA FZ	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	100/80-17	MRF	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/60 R17	MRF	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/08/2018	Inspect Date / Time	04/09/2018 (05:30 PM)
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/SMO18016141/Gcd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18016141/Gcd3e2		
50 RAFFLES PLACE #05-01/06		Date: 07-09-2018		
SINGAPORE LAND TOWER SINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XA 8988H	Veh. Inspected	FBK 1635E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1803575/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100/80-17	MRF	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/60 R17	MRF	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.				
5. General Information				
Accident Date	17/08/2018	Inspect Date / Time	04/09/2018 (05:30 PM)	
Survey held at	M 1 MOTORING 411 CHANGI ROAD SINGAPORE 419860			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/SMO18016141/Gcd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.