

ASS. SEC. BY:

REF:

CS/msc118016146/Ksb n2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

mslt

Date/Time: 04/09/2018 3:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 5225J

Insured:

YP 9103Y

at Workshop m/s

Cheng Hoe motor

Tel:

6755 6142

of

38 Woodlands Ind Park E1 #05-04

Policy No:

A7A090742MKC

Claim No:

569191

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

04/09/2018 4:00pm

Person Contacted:

Efreda

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 5225J - X

YP 9103Y - X

06/08/18

@ 14:31 p.m. revised IA to Katherine Wong via merimer.

17/10

L1 Lyn 855001 Carfax E1210

ASS. REC. BY:

REF: *MSG /**Kenneth*

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *8376*

IDAC Accident Report: \_\_\_\_\_

Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent?: Yes or No

Est. Repairs: *07* days

Res.: Yes or No

Lum Sum: *20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: *1/11*

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *SKW 5225*Yr Regn: *06, 07*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toy Estima*c.c. *2362*Colour: *M.P. White*

A/C: Insured / Std / NI / NA

Sp. Reading: *124543*

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *ACR 50**0032698*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModl: *NI* / S/Rim / STD A/Rim orTyre Size: F: *225/55R18*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *8* mmR/Bal. *8* mmL/Bal. *8* mmL/Bal. *8* mmD.O.A. *2/9/18*D.O.I. *5/9/18*

Survey held at \_\_\_\_\_

Des. of Damages: *Front* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*6/9 File pass to Catherine**17/10/18 Confirmed HS \$5,500/- @ 7 days with Kenneth  
C \$4,537.76 Red - 45%*

RECEIVED 17 OCT 2018

Date/Time, File Pass to?

*17/10/18*☐ : Prell. Report1) *Typist*☒ : Final Report

Date/Time, File Return to?

Days Of Repair: *7*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$

*5,500/- HS**200**10**210*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18016146/Ksb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 04-09-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 9103Y	Veh. Inspected	SKW 5225J	
Policy No.	A29090742MKC	Coverage (\$)	0.00	
Claim No.	569191	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	04/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/09/2018	Inspection Date	04/09/2018	
Survey held at	CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700			
<b>5a. Remarks</b>				

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 06 Sep 2018

**Preliminary Advice**

Insured Vehicle No	: YP9103Y	Accident Date	: 02/09/2018
TP Vehicle No	: SKW5225J	Assignment Date	: 04/09/2018
Make	: TOYOTA ESTIMA	Est. Duration of Repair	: 6-7 days
Date of Inspection	: 05/09/2018		
Inspection At	: Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05 Singapore 757700		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,727.65
Revised Amount	:S\$	5,286.06
Check Items (Estimated)	:S\$	4,007.17
Total	:S\$	9,293.23

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018		04 Sep 2018 15:55 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:		B-Mech Engineering Pte Ltd, Co. Reg. No.: 199907733D [Created by insurer]							
Main Claimant:		CHUA YONG BOON JUSTIN, ID: S8215554F							
Vehicle Reg. No.:		SKW5225J	Date of Loss:	02/09/2018 17:00 - :59 [134 Months and 4 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 569191	Policy/Cover Note No.:	A29090742MKC (Comprehensive) Coverage: 01/08/2018 - 31/07/2019					
Vehicle Reg. No. (Insured):		YP9103Y	Policy No. (Claimant):						
			Excess:						
Repairer:		Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05, 757700 Woodlands - Tel: 6765 6142							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/09/2018]							
Driver/Custodian (Insured):		SUBRAMANIAN NALLAIYA @ SURENDRAN (32 / Male), NRIC: G6522077L							
Adj Asg. Remarks:		SJE AGREE LKK - Kenneth Kong. Pls contact June Phua @ 67556142. Liability 100%							
<b>ASSOCIATED MAIL RECEIVED</b>									
			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
						Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

SKW5225J

71/MS16.

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5554F
<b>Vehicle Details</b>	
Vehicle No.:	SKW5225J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA 2.4 A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	2AZF017706
Chassis No.:	ACR500032698
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$26,784.00
Original Registration Date:	29 Jun 2007
First Registration Date:	29 Jun 2007
Transfer Count:	4
Actual ARF Paid:	\$29,463.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jun 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$27,044.00
COE Rebate Amount:	\$20,658.00
<b>Total Rebate Amount:</b>	<b>\$20,658.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Sep 2018

OK

**Enquire Vehicle & Owner Information ( Vehicle No. YP9103Y As At 02 Sep 2018 / 18:10:00 )**

## Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SKW5225

## Current Owner Details

Owner ID Type: Company

Owner ID: 199907733D

Owner Name: B-MECH ENGINEERING PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:50

Registered Street Name: TUAS AVENUE 11

Registered Unit No.: # 02 - 01

Registered Building Name: TUAS LOT

Registered Postal Code: 639107

## Current Vehicle Details

Vehicle No.: YP9103Y

Make Description/Model: ISUZU / NPR85UH5A 3.0 MT

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 12:45
Date Of Accident	02/09/2018 18:10
Exact Location Of Accident	CHINESE GARDEN TEMPORARY CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW5225J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA YONG BOON, JUSTIN
NRIC No	S8215554F
Email Address	THEANGRYDYNAMO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97398079
Alternative Phone No	OTHERS-97398079

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA 2.4A
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	16/11/17 - 15/11/18
Cover Note Number	DMPCSN3088481700

### Driver

Name of Driver	CHUA YONG BOON, JUSTIN
NRIC No	S8215554F
Date Of Birth	19/05/1982
Occupation	INDOOR
Date Of Driving Pass	10/04/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97398079
Fax Number	
Contact Number	OTHERS-97398079
Email Address	THEANGRYDYNAMO@GMAIL.COM



Address	BLK 211 CHOA CHU KANG CENTRAL #08-124
Postcode	680211
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I park my car at the temporary carpark of Chinese Garden at about 5.30pm and went for my walk with family. When I came back about 6.30pm, I notice that my right side of the car is badly crashed. The right side (driver side) and the headlight is shattered into many pieces. The front bonnet is also slightly damaged. The Toyota Logo is on the floor. My family members were with me at 6.30pm. I saw a note and a namecard and the note said he saw someone hit my car and ran off. I called the person and he give me details of the foreign worker. Foreign worker send me his details and admitted he was the driver. I recorded down the conversation as he admitted to it via whatsapp.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	AH CHAI
Phone Number	82632225
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP9103Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SUBRAMANIAN NALLAIYA ALSOKNOWNAS SURENDRAN
NRIC/Passport Number	G6522077L
Contact Number	82847914
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: SKW 5225 J  
INSURER : CHINA TRIPING  
DATE & TIME: 2/9/18 6.10 P.M.

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

3/9/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## Sketch Plan #2

SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) I park my car at the temporary car park of Chinese Garden at about 5:30 pm and went for my walk with family.
- 2) When I came back about 6:30 pm, I notice that my right side of the car is badly crushed. The right side (driver side) and the headlight is shattered into ~~the~~ many pieces. The front bonnet is also slightly damaged. The Toyota logo is on the floor.
- 3) My family members were with me ~~was~~ at 6:30 pm
- 4) I saw a note and a namecard and the note said he said someone hit my car and ran off
- 5) I called the person and he give me details of the foreign worker.
- 6) Foreign worker sends me his details and admitted he was the driver.
- 7) I recorded down the conversation as he admitted to it ~~and~~ via whatsapp.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 3/9/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CLAIMANT'S DECLARATION V2

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )

NOTE

I see People crashing into  
your car, please call me for  
more details. My number

Q2632225

**Fixmate Auto Pte Ltd**

Ah Chai  
8263 2225  
9372 7000



Ah Loon  
9049 1522

8 Kaki Bukit Ave 4 #02-37 Premier @ Kaki Bukit  
Singapore 415875  
Email: [sales@fixmatesauto.com](mailto:sales@fixmatesauto.com)



IC

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8215554F



Name  
CHUA YONG BOON, JUSTIN



蔡 永 文

Race  
CHINESE

Date of birth  
19-05-1982


Sex  
M

Country of birth  
SINGAPORE






LIC (Frt)



LIC (Back)





# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SKW5225J  
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 02/09/2018

TP Veh Reg No: YP9103Y

Estimate No: ES1891019/WL

Date: 04 Sep 2018

Policy No: DMPCSN3088481700

Veh Reg No: SKW5225J

Make/Model: TOYOTA ESTIMA 2.4 A

Chassis No: ACR500032698

Engine No: 2AZF017706

Reg. Date: 29/06/2007

## Estimate Repair Cost to Vehicle No :SKW5225J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 FRONT BUMPER	551.68	1 PC	551.68	✓
2 FRONT BUMPER RH SIDE RETAINER	82.80	1 PC	82.80	✓
3 FRONT BUMPER TOP BEAM	133.49	1 PC	133.49	✓
4 FRONT BUMPER REINFORCEMENT	388.98	1 PC	388.98	✓
5 FRONT BUMPER RH INNER SPONGE	38.90	1 PC	38.90	X
6 FRONT BUMPER CENTRE SPONGE	99.10	1 PC	99.10	✓
7 FRONT BUMPER RH FOG LAMP	248.20	1 PC	248.20	✓
8 FRONT BUMPER RH FOG LAMP GARNISH	99.54	1 PC	99.54	✓
9 FRONT BUMPER CENTRE LOWER GRILLE	121.85	1 PC	121.85	X
10 FRONT BUMPER CENTRE UNDER LOWER COVER	129.81	1 PC	129.81	✓
11 FRONT BUMPER CENTRE UNDER LOWER COVER CLIPS	3.50	6 PCS	21.00	✓
12 BONNET	599.30	1 PC	599.30	✓
13 BONNET INNER LOCK	95.80	1 PC	95.80	X
14 BONNET HINGES	55.50	2 PCS	111.00	✓
15 BONNET SPONGE	226.07	1 PC	226.07	✓
16 BONNET SPONGE CLIPS	3.50	6 PCS	21.00	✓
17 BONNET INNER RUBBER	45.90	1 PC	45.90	X
18 FRONT RH FENDER	654.88	1 PC	654.88	✓
19 FRONT RH FENDER INNER SHIELD	253.83	1 PC	253.83	✓
20 FRONT RH FENDER INNER SHIELD CLIPS	3.50	6 PCS	21.00	✓
21 HEADLAMP RH	896.40	1 PC	896.40	✓
22 HEADLAMP RH CLIP	17.60	1 PC	17.60	✓
23 HEADLAMP PANEL	255.10	1 PC	255.10	✓
24 HEADLAMP LH	896.40	1 PC	896.40	✓
25 FRONT TOP PANEL	262.90	1 PC	262.90	✓
26 FRONT WIPER GARNISH RH EXTENSION	55.30	1 PC	55.30	✓
27 FRONT TOP PANEL GARNISH	281.00	1 PC	281.00	✓
28 FRONT TOP PANEL GARNISH CLIPS	3.50	4 PCS	14.00	✓
29 AIR-CON CONDENSER	1,405.30	1 PC	1,405.30	X
30 RADIATOR	1,947.93	1 PC	1,947.93	X
31 RADIATOR TOP GARNISH	74.14	1 PC	74.14	✓
			10,050.20	
Less 25%			2,512.55	7,537.65

Not Authorised

6/10/18

Repair After Paint

6-7 days

Reborn

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402  
 ATTN: Motor Claim Department  
 WS Ref: TP/MSIG/WL  
 Claim Type: Third Party  
 Accident Date: 02/09/2018  
 TP Veh Reg No: YP9103Y

Estimate No: ES1891019/WL  
 Date: 04 Sep 2018  
 Policy No: DMPCSN3088481700  
 Veh Reg No: SKW5225J  
 Make/Model: TOYOTA ESTIMA 2.4 A  
 Chassis No: ACR500032698  
 Engine No: 2AZF017706  
 Reg. Date: 29/06/2007

## Estimate Repair Cost to Vehicle No :SKW5225J

Description	U/Price	Quantity	List Price S\$	Amount S\$
<b>Labour</b>				
32 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
33 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,FRT FENDERS,BONNET & ATTACHMENT,RADIATOR & MOTOR,STRAIGHTEN,KNOCK & REPAIR FRT CHASSIS,FRT RH FENDER INNER PANEL,RENEW FRT SUPPORT PANEL & REALIGN THE SAME	1,000.00	1 LA	1,000.00	700
34 PUTTY & RESPRAY ON FRT RH FENDER INNER PANEL,BONNET,FRT SUPPORT PANEL,FRT BUMPER,REINFORCEMENT & ALL AFFECTED AREAS(PEARL WHITE)	1,000.00	1 LA	1,000.00	900
35 RUSTPROOFING	90.00	1 LA	90.00	✓
	1790		2,190.00	2,190.00
			Total	S\$ 9,727.65
			Add GST @ 7%	680.94
			Total Amount Payable	S\$ 10,408.59

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

10,037.76

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SKW 5225J

SUPP 1

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 02/09/2018

TP Veh Reg No: YP9103Y

Estimate No: ES1891019/WL

Date: 07 Sep 2018

Policy No: DMPCSN3088481700

Veh Reg No: SKW5225J

Make/Model: TOYOTA ESTIMA 2.4 A

Chassis No: ACR500032698

Engine No: 2AZF017706

Reg. Date: 29/06/2007

## Estimate Repair Cost to Vehicle No :SKW5225J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 FRONT GRILLE	413.48	1 PC	413.48	
			413.48	
		Less 25%	103.37	310.11
Total				S\$ 310.11
GST Amount				S\$ 21.71
Total Amount Payable				S\$ 331.82

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016146/KSBN2  
Date: 19/10/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29090742MKC
Claimant Vehicle No :	SKW5225J	Insured Vehicle No :	YP9103Y
Date of Loss:	02/09/2018	Nature of Claim:	TP
		Claim No:	569191

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKW5225J	Engine No:	2AZF017706
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500032698
Reg. Date:	29/06/2007 (Man. Year: 2007)	Odometer:	124543 km
Colour:	Metallic Pearl White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,847.76	5,106.00	2,741.76	34.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,790.00	400.00	18.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,037.76</b>	<b>6,896.00</b>	<b>3,141.76</b>	<b>31.30</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>(S\$)</b>	10,037.76	5,500.00	4,537.76	45.21
<b>+ GST 7.00/7.00% (S\$)</b>	702.64	385.00	317.64	45.21
<b>Nett Amount (S\$)</b>	<b>10,740.40</b>	<b>5,885.00</b>	<b>4,855.40</b>	<b>45.21</b>

## INSPECTION

Date of Assignment:	04/09/2018	
Date Inspected:	05/09/2018 Inspected At:	BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761 REPAIRER: CHENG HOE MOTOR PTE LTD

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2018)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW5225J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	551.68 FL	*551.68 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	82.80 FL	*82.80 FL
3	1		*FRONT BUMPER TOP BEAM	Bent	133.49 FL	*133.49 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	388.98 FL	*388.98 FL
5	1		*FRONT BUMPER RH INNER SPONGE	Serviceable	38.90 FL	*- FL
6	1		*FRONT BUMPER CENTRE SPONGE	Cracked	99.10 FL	*99.10 FL
7	1		*FRONT BUMPER RH FOG LAMP	Broken	248.20 FL	*248.20 FL
8	1		*FRONT BUMPER RH FOG LAMP GARNISH	Mtg Cracked	99.54 FL	*99.54 FL
9	1		*FRONT BUMPER CENTRE LOWER GRILLE	Serviceable	121.85 FL	*- FL
10	1		*FRONT BUMPER CENTRE UNDER LOWER COVER	Cracked	129.81 FL	*129.81 FL
11	6		*FRONT BUMPER CENTRE UNDER LOWER COVER CLIPS	Necessary	21.00 FL	*21.00 FL
12	1		*BONNET	Bent	599.30 FL	*599.30 FL
13	1		*BONNET INNER LOCK	Repair	95.80 FL	*- FL
14	2		*BONNET HINGES	Bent/Distorted	111.00 FL	*111.00 FL
15	1		*BONNET SPONGE	Deformed	226.07 FL	*226.07 FL
16	6		*BONNET SPONGE CLIPS	Necessary	21.00 FL	*21.00 FL
17	1		*BONNET INNER RUBBER	Serviceable	45.90 FL	*- FL
18	1		*FRONT RH FENDER	Bent	654.88 FL	*654.88 FL
19	1		*FRONT RH FENDER INNER SHIELD	Cracked	253.83 FL	*253.83 FL
20	6		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	21.00 FL	*21.00 FL
21	1		*HEADLAMP RH	Broken	896.40 FL	*896.40 FL
22	1		*HEADLAMP RH CLIP	Necessary	17.60 FL	*17.60 FL
23	1		*HEADLAMP PANEL	Buckled	255.10 FL	*255.10 FL
24	1		*HEADLAMP LH	Mtg Cracked	896.40 FL	*896.40 FL
25	1		*FRONT TOP PANEL	Buckled	262.90 FL	*262.90 FL
26	1		*FRONT WIPER GARNISH RH EXTENSION	Missing	55.30 FL	*55.30 FL
27	1		*FRONT TOP PANEL GARNISH	Cracked	281.00 FL	*281.00 FL
28	4		*FRONT TOP PANEL GARNISH CLIPS	Necessary	14.00 FL	*14.00 FL
29	1		*AIR-CON CONDENSER	Serviceable	1,405.30 FL	*- FL
30	1		*RADIATOR	Serviceable	1,947.93 FL	*- FL
31	1		*RADIATOR TOP GARNISH	Cracked	74.14 FL	*74.14 FL
32	1		*FRONT GRILLE	Mtg Cracked	413.48 FL	*413.48 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,463.68</b>	<b>6,808.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,615.92</b>	<b>1,702.00</b>
<b>Total Parts (\$\$)</b>	<b>7,847.76</b>	<b>5,106.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
2	REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,FRT FENDERS,BONNET & ATTACHMENT,RADIATOR & MOTOR,STRAIGHTEN,KNOCK & REPAIR FRT CHASSIS,FRT RH FENDER INNER PANEL,RENEW FRT SUPPORT PANEL & REALIGN THE SAME	New	1,000.00	700.00
3	PUTTY & RESPRAY ON FRT RH FENDER,INNER PANEL,BONNET,FRT SUPPORT PANEL,FRT BUMPER,REINFORCEMENT & ALL AFFECTED AREAS (PEARL WHITE)	New	1,000.00	900.00
4	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			2,190.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >