

15/5/2018

INS. CASE OWNER:

Joe

CC 4/EQ1801

6148, D 46h⁵²

LKK:

IDAC:

Surveyor:

Bijun

DOI:

5/4/2018

Date / Time:

Registered in Merimen:

pohkin

4/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

XE 15727

Name of Insured:

EV ENVIRO blu

Insured Tel No.:

HP:

D.O.A:

1/4/18

Excess Sec II :SS

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

KONG LEE KONG

Driver Tel No.:

(VL: ☒ YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Dmipra18-001741
1VCD
PIONEER KD

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

sha wengay

INSRS:
WSP:
Tel:
Liability:
RMKS:

Chunni

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
6/4/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE: 25/10/18	
	After call ltr to OE: 20/12/18	
	Documentation Check List:	Handler: Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OE:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>
PRELIMINARY ADVICE Date/Time: 21/4/2018	Sent By: LSP	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: SS 16,000.00 (13 days) Reduction: 52.64 %		Email <input checked="" type="checkbox"/> Call <input checked="" type="checkbox"/>
FINAL SETTLEMENT Date/Time: 24/1/2019	Confirm with: william	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: H1		
Repair Cost: SS 17,120.00		
Loss of Rental (LOR): SS 1768.50 (13 days) x \$98.25		
Loss of Use (LOU): SS (S x days)		
Loss of Income (LOI): SS 900.00 (S 50.00 x 18 days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/> [Tick only one]		
GIA/LTA Search: SS 2.00		
Medical: SS		
Disbursement: SS (e.g. Tow/ Independent)		
Legal Cost: SS		
Total: SS 19,790.50	Global Sum SS: 19,790.00	
FINAL PAYMENT Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input checked="" type="checkbox"/>
Payee 1: SS 19,790.00	Name 1: Chunni Motor work Pte Ltd	
Payee 2: (Strike if N.A.) SS	Name 2:	
Payee 3: (Strike if N.A.) SS	Name 3:	

COPY SENT
20/1/19

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: 4400.00

REF:

ASSIGNMENT

00E March 2020

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / RV / MV

Exh/pos / Vehicle No: _____

at Work/Shop no: _____

of: _____

Insured: _____

Policy No: _____

Claim No: _____


Can Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Conditions)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SHA 2459 Y** Yt Regn: **2012 / March**

Type: M/Car / M/Cycle / Bus / Van / Lorry ☒ Prime Mover /

Truck / Trailer or

Make: **Hyundai Sonata** cc: **1991**Color: **Blue** A/C: Insured / Std / FR / HASp. Branding: **439488** TA/allo: Insured / Std / FR / HAEng/No: **D4EAB934123**Chassis: **KMHET4IVMCA821723**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Normal / Jammed / Leaked / Burnt orBrake: ☒ Normal / Jammed / Leaked / Burnt orModi: ☒ S/Rim / STD A/Rim orTyre Size: F: **215/60 R16**R: **— 11 —**

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Westlake**

Front

Rear

R/Bal: **S** mmR/Bal: **S** mmL/Bal: **S** mmL/Bal: **S** mmD.O.A: **01/09/2018**D.O.A: **05/09/2018**Survey held at **Chunni AMK**

Don. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Front y o/s Body y o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

EQ XE 1572 Z**15/11/18**

Insured H/S 16000/- at 13 days 2 am

vehicle left 16 minutes -

4516,000.00 / Red 17,786.24 / 52.64%

Date/Time, File Path b7

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Path b7

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + PB, 24

) Photos

) Other

Report Format :

Lump Sum / L.B.E (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18016148/fb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 04-09-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 1572Z	Veh. Inspected	SHA 2459Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/09/2018	Inspection Date		
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI18016148/Dfb3

Date: 21.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA2459Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.09.2018 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	33,786.84
Revised Estimate Amount	: S\$	22,235.80
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Front Portion & O/S Body & O/S Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 13 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

To Survey by L&K

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>BT</i>			\$ 1,151.80
	Bonnet Hinge (LH/RH) <i>NH</i>		\$ 87.50	\$ 175.00
	Front Bumper Cover <i>distorted</i>			\$ 538.80
	Front Bumper Bracket (RH) <i>NH</i>			\$ 20.10
	Headlamp Support Panel Assy <i>not broken</i>			\$ 1,023.00
	Headlamp (RH) <i>not broken</i>			\$ 797.90
	Front Fender (RH) <i>Buc</i>			\$ 593.00
	Front Fender Apron Panel (RH) <i>lyn</i>			\$ 1,120.50
	Front Fender Shield (RH) <i>deformed</i>			\$ 86.00
	Front Fender Signal Lamp (RH) <i>broken</i>			\$ 45.40
	Front Door (RH) <i>Buc</i>			\$ 1,345.00
	Front Door Rubber <i>Nec</i>			\$ 110.40
	Front Door Regulator <i>not BT</i>			\$ 625.00
	Front Door Hinge Upper (RH) <i>BT</i>			\$ 51.10
	Front Door Hinge Lower (RH) <i>BT</i>			\$ 51.10
	Front Door Check (RH) <i>BT</i>			\$ 105.50
	Front Door Inner Lock (RH) <i>not NH</i>			\$ 334.40
	Front Door Key Lock Set (RH) <i>NH</i>			\$ 82.40
	Front Door Outer Handle (RH) <i>broken</i>			\$ 37.00
	Front Door Outer Moulding (RH) <i>BT</i>			\$ 61.00
	Front Door Power Motor <i>NH</i>			\$ 425.00
	Front Door Trim Board (RH) <i>not mounting crack</i>			\$ 1,147.00
	Front Door Protector (RH) <i>BT</i>			\$ 74.90
	Front Windscreen Glass <i>crack</i>			\$ 1,015.00
	Front Windscreen Moulding <i>Nec</i>			\$ 60.00
	Front Windscreen Pillar Outer (RH) <i>not distorted</i>			\$ 1,766.20
	Wiper Panel Top Garnish <i>NH</i>			\$ 87.40
	Front Wheel Rim (RH) <i>not distorted</i>			\$ 284.70
	Front Wheel Hub Cap (RH) <i>cut</i>			\$ 145.00
	Front Wheel Bearing <i>Dem</i>			\$ 258.50
	Front Shock Absorber (Assy) (RH) <i>not distorted</i>			\$ 203.70
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 72.00
	Front Shock Absorber Fork (RH) <i>not distorted</i>			\$ 203.30
	Front Suspension Upper Arm (RH) <i>not distorted</i>			\$ 240.00
	Front Drive Shaft (RH) <i>NH</i>			\$ 1,025.00
	Rack & Pinion Assy <i>NH</i>			\$ 2,093.00
	STG Tie End <i>not not distorted</i>			\$ 66.50
	Front Suspension Lower Arm (RH) <i>not distorted</i>			\$ 685.20
	Knuckle Arm (RH) <i>not distorted</i>			\$ 558.60
	Engine Under Cover <i>NH</i>			\$ 328.70
	Engine Crossmember <i>NH</i>			\$ 2,143.70
	SUB TOTAL			\$ 21,237.80
	LESS 20%			\$ 4,247.56
	DISCOUNTED TOTAL			\$ 16,990.24

SHA 2459Y

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door Comfort Logo (RH) <i>huc</i>			\$ 75.00	Nett ✓
	Front Windscreen Sealant <i>huc</i>			\$ 46.00	Nett ✓
	Front ERP Sticker <i>huc</i>			\$ 30.00	Nett ✓
	Front Tyre (RH) <i>HN</i>			\$ 207.00	Nett X
			151.00	\$ 358.00	
	Rear Fender (RH) <i>Dented</i>			\$ 1,935.90	✓
	Rear Fender Inner Lining (RH) <i>SVC</i>			\$ 74.10	X
	Rear Windscreen Moulding <i>huc</i>			\$ 60.00	✓
	Rear Door (RH) <i>Buc</i>			\$ 1,294.70	✓
	Rear Door Rubber (RH) <i>huc</i>			\$ 121.20	✓
	Rear Door Glass (RH) <i>shattered</i>			\$ 241.60	✓
	Rear Door Outer Moulding (RH) <i>ist</i>			\$ 203.30	✓
	Rear Door Outer Handle (RH) <i>new</i>			\$ 39.60	X
	Rear Door Gear/Regulator (RH) <i>new crack</i>			\$ 625.00	X ✓
	Rear Door Motor (RH) <i>HN</i>			\$ 280.40	X
	Rear Door Hinge Upper (RH) <i>SVC</i>			\$ 51.00	X
	Rear Door Hinge Lower (RH) <i>SVC</i>			\$ 51.00	X
	Rear Door Check (RH) <i>SVC</i>			\$ 72.30	X
	Rear Door Trim Board (RH) <i>new mounty crack</i>			\$ 855.30	X ✓
	Rear Door Protector (RH) <i>ist</i>			\$ 54.50	✓
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 1,711.00	✓
	Rocker Panel Outer Garnish (RH) <i>new broken</i>			\$ 463.40	X ✓
	Rear Tyre Rim (RH) <i>new distorted</i>			\$ 284.70	X ✓
	Rear Wheel Hup-Cap (RH) <i>cut</i>			\$ 145.00	✓
	Rear Wheelbearing ING & Hub <i>new</i>			\$ 384.60	✓
	Rear Trailing Arm (RH) <i>new distorted</i>			\$ 115.00	✓
	Rear Assist (RH) <i>new distorted</i>			\$ 115.00	✓
	Rear Shock Absorber (RH) <i>new distorted</i>			\$ 190.60	✓
	Rear Shock Absorber Mounting (RH) <i>huc</i>			\$ 55.30	X
	Rear Crossmember <i>new</i>			\$ 1,140.40	X
	Stabilizer Bar <i>new distorted</i>			\$ 196.00	X ✓
	Stabilizer Link <i>new distorted</i>			\$ 65.30	✓
	Rear Upper Arm (RH) <i>new distorted</i>			\$ 321.70	✓
	Rear Lower Arm (RH) <i>new distorted</i>			\$ 195.80	✓
	Rear Knuckle Arm (RH) <i>new distorted</i>			\$ 550.80	✓
			10130.40		
			8104.32		
			8104.72		
	SUB TOTAL			\$ 11,894.50	
	LESS 20%			\$ 2,378.90	
	DISCOUNTED TOTAL			\$ 9,515.60	
	Rear Windscreen Sealant <i>huc</i>			\$ 46.00	Nett ✓
	Rear Door Tel No. Sticker (RH) <i>huc</i>			\$ 10.00	Nett ✓
	Rear Tyre (RH) <i>HN</i>			\$ 207.00	Nett X
			56.00	\$ 263.00	

SHA 2459Y

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,600.00 1400/-
	Spray Painting Charge			\$ 1,800.00 1000/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 60/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 44
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 44
	Remove/Refix Dashboard			\$ 450.00 44
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 50/-
	TOTAL LABOUR			\$ 6,660.00
	ESTIMATE TOTAL			\$ 33,786.84
	05/09/2018 @ 0900m			22235.80
	Not Actual			4/s 16000/-
	2/Sum 13 days.			vehicle
	ryan			upt 16
	2KK Auto			months.
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 2459 Y

Technician:

Mileage: 439488

Time Printed 5.9.18 1:00 PM

Hyundai : Sonata : 2005-

Front : Left

Actual	BEFORE	Specified Range
0°10'		-0°30' 0°30'
3°36'		3°50' 5°50'
0°04'		-0°05' 0°05'
13°42'		
13°52'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
9°50'		-0°30' 0°30'
3°35'		3°50' 5°50'
25°25'		-0°05' 0°05'
0°08'		
9°58'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-9°41'		
0°01'		
13°34'		
25°29'		-0°09' 0°09'

Rear : Left

Actual	BEFORE	Specified Range
0°29'		-1°00' 0°00'
0°08'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
13°32'		-1°00' 0°00'
27°18'		0°00' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-13°03'		
27°26'		0°00' 0°19'
-13°35'		

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Tuesday, 4 September 2018 8:58 AM
To: assignments
Subject: FW: Accident involving veh no: SHA 2459Y & XE1572Z (EQ) on 01.09.18
Attachments: 03092018151240.pdf

9.49am @ 4/9/18
vehicle in
person @ Lynn.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Tuesday, 4 September 2018 8:58 AM
To: Chunni Motor <chunnimotor@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving veh no: SHA 2459Y & XE1572Z (EQ) on 01.09.18

Without Prejudice

Dear Sirs

Thank you for your confirmation.
We will appoint LKK to conduct PRS.

Dear LKK

please assist on the following PRS.

Best Regards,

Joel Goh
Executive | Claims

 *You've Got a Friend*

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Monday, September 3, 2018 4:45 PM
To: Joel Goh
Subject: Re: Accident involving veh no: SHA 2459Y & XE1572Z (EQ) on 01.09.18

Dear Sir,

We agree to appoint LKK Auto Consultants P/L .

Thank you

Regards,
Chunni Motor Work P/L

On Mon, Sep 3, 2018 at 4:11 PM, Joel Goh <joel.goh@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Sirs,

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon

5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
11) Infiniti Appraisal Service Tel: 96684818 / 90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Monday, September 3, 2018 3:20 PM
To: EQI PRS
Subject: Accident involving veh no: SHA 2459Y & XE 1572Z on 01.09.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06, Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162.

Thank you for your kind assistance.

Poh Kin (LKKAUTO)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Tuesday, 29 January 2019 10:38 AM
To: Poh Kin (LKKAUTO)
Subject: Re: ACCIDENT INVOLVING SHD 2459 Y & XE 1572 Z ON 01-09-2018

Your Ref : CC4/EQ118016148/Dfb3
Our Ref : SHD 2459 Y (010918)

WITHOUT PREJUDICE

Dear Poh Kim

Your email of even date refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the loss of rental & income during the period of repair) at a global sum of \$19,790.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHD 2459 Y, Chia Cher Poh's injury claim and other losses against your principals, M/s EQ Insurance Pte Ltd and /or their insured.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you.

Best Regards
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Tuesday, 29 January 2019, 9:14:52 AM SGT, Poh Kin (LKKAUTO) <pohkin@lkkauto.com> wrote:

WITHOUT PREJUDICE

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 29 January 2019 9:15 AM
To: 'Chunni motor Work'
Subject: RE: ACCIDENT INVOLVING SHD 2459 Y & XE 1572 Z ON 01-09-2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/EQI18016148/Dfb3
Your Ref: SHA 2459Y

Dear William,

We refer to the above matter.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement at global sum of **\$19,790.00**(all in) on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Chunni motor Work [mailto:chunnimw@yahoo.com.sg]
Sent: Monday, 21 January 2019 10:09 AM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: Re: ACCIDENT INVOLVING SHD 2459 Y & XE 1572 Z ON 01-09-2018

Poh Kin (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 28 January 2019 6:41 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z (OI) AND SHA 2459Y (TP) ON 01-09-2018; LKK ref : CC4/EQI18016148/Dfb3; EQ ref: DM18HO02328-JG

Dear Poh Kin

Please proceed to resolve this matter up to S\$19,790.50.


Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Friday, January 25, 2019 10:17 AM
To: Joel Goh
Cc: Admin A
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z (OI) AND SHA 2459Y (TP) ON 01-09-2018; LKK ref : CC4/EQI18016148/Dfb3; EQ ref: DM18HO02328-JG
Importance: High

Your ref : DM18HO02328-JG
Our ref : CC4/EQ18016148/Dfb3

Dear Joel,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y ON 01/09/2018

We refer to the above matter.

Liability: OID collided into TP vehicle as per TP video footage. Liability is down against our insured.

https://drive.google.com/open?id=14btFLyxRE6CJy9CxeDEI_yLna9VeRx_U

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Friday, 25 January 2019 10:17 AM
To: 'Joel Goh'
Cc: Admin A
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z (OI) AND SHA 2459Y (TP) ON 01-09-2018; LKK ref : CC4/EQ18016148/Dfb3; EQ ref: DM18HO02328-JG
Attachments: LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK resurvey photo- after repair.pdf; LKK resurvey photo.pdf; LKK survey photo.pdf; TP LOD_SHA 2459Y.pdf
Importance: High

Your ref : DM18HO02328-JG
Our ref : CC4/EQ18016148/Dfb3

Dear Joel,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y ON 01/09/2018

We refer to the above matter.

Liability: OID collided into TP vehicle as per TP video footage. Liability is down against our insured.

https://drive.google.com/open?id=14btfLyxRE6CJy9CxeDEI_yLna9VeRx_U

We did forward the video footage to PIC (Ms Zee) and they agreed to settle and aware NCD (if any) is affected.

We seek your approval to offer Third Party repairer "**Chunni Motor Work Pte Ltd**" at **\$ 19,790.50(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 33,786.84	\$ 17,120.00 (\$16,000.00 +7% gst)
2. Loss of Rental	\$ 1,768.50 (18 days x \$98.25)	\$ 1,768.50 (18 days x \$98.25)
3. Loss of Income	\$ 900.00 (18 days x \$50.00)	\$ 900.00 (18 days x \$50.00)
4. GIA search fee	\$ 2.00	\$ 2.00
Total	\$ 36,457.34	\$ 19,790.50

****13 days** recommendation for repair + 2 days PRI + 3 weekends = **18 days**.

Enclosed here with all the relevant documents for your perusal.

For your approval/instruction please.

Poh Kin (LKKAuto)

From: OPS <ops@klenviro.com>
Sent: Friday, 26 October 2018 10:43 AM
To: Poh Kin (LKKAuto)
Cc: 'Soh'
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y
ALONG PIONEER ROAD ON 01.09.2018

Dear Poh Kin,

I am afraid that we do not have a copy of the footage.

Thank You!
Best Regards,



Zee (Miss)
Operation Executive
Office: +65 68610332 / Cell: +65 86111983 / Ext: 125

KL Enviro Pte Ltd
*Blue Sky, Green Earth,
Our Aspirations*

From: Poh Kin (LKKAuto) <pohkin@lkkauto.com>
Sent: Friday, 26 October 2018 8:27 AM
To: OPS <ops@klenviro.com>
Cc: Soh <soh@klenviro.com>
Subject: RE: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y ALONG PIONEER ROAD
ON 01.09.2018
Importance: High

Our Ref: CC4/EQ18016148/Dfb3
Your Veh: XE 1572Z

Dear Ms Zee,

Thank you for furnishing accident scene photo.

Do you have the accident video footage?, appreciate if you could furnish us a copy of the accident video
footage(if you have).

Your prompt reply will be very much appreciated.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 25 October 2018 2:51 PM
To: 'ops@klenviro.com'
Cc: Admin A
Subject: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y ALONG PIONEER ROAD ON 01.09.2018

Importance: High

Our Ref: CC4/EQ18016148/Dfb3
Your Veh: XE 1572Z

Attn: Ms Zee

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. XE 1572Z AND SHA 2459Y ALONG PIONEER ROAD ON 01.09.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from M/s Chunni Motor Works Pte Ltd, acting on behalf of the owner of SHA 2459Y against your motor insurance policy.

As spoken over the phone, We appreciate if you could furnish us a copy of the accident video footage or accident scene photo for our assessment and necessary action.

Your prompt reply will be very much appreciated.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 21 September 2018 6:04 PM
To: 'chunnimw@yahoo.com.sg'
Cc: Admin A
Subject: ROAD TRAFFIC ACCIDENT INVOLVING XE 1572Z AND SHA 2495Y ON 01/09/2018

Importance: High

WITHOUT PREJUDICE

Your Ref: XE 1572Z
Our Ref: CC4/EQI18016148/fb3

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING XE 1572Z AND SHA 2495Y ON 01/09/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence yet to substantiate either party's version. Below is a copy of our insured's accident report statement for your perusal.

Circumstances of Accident

ON 01/09/2018 AT ABOUT 0815 HRS. WHILE I WAS TRAVELLING ALONG PIONEER ROAD. WHILE I CHECK THAT WAS TRAFFIC CLEAR, I THEN CHANGE TO LEFT LANE. SUDDENLY I FEEL AN IMPACT FROM MY LEFT PORTION. I THEN IMMEDIATELY STOP MY VEHICLE. I NOTICED THAT VEHICLE B CUT INTO THE LANE AND WE BOTH COLLIDED TOGETHER.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

CHUNNI MOTOR WORK
PTE LTD

pk

Our Ref : SHA 2459 Y (010918)

Your Ref : CC4/EQI18016148/Dfb3

Date : 18-12-2018

M/s LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial
#02-25
Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Dear Sir/Madam

ACCIDENT INVOLVING SHA 2459 Y & XE 1572 Z ALONG PIONEER RD TOWARDS CITY ON 01-09-18

Your email of 11-12-2018 refers.

As requested, we enclose the Video footage for you to read.

This is a Direct Settlement, kindly reciprocate to expedite this matter and revert with your offer of an amicable settlement as soon as possible.

Thank you.

Yours faithfully,
For **CHUNNI MOTOR WORK PTE LTD**


Claims Department

Email : chunnimw@yahoo.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ18016148/Dfb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 31-01-2019



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1572Z	Veh. Inspected	SHA 2459Y
Policy No.	DMCPHQ18-001741	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOEL	Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KMHET41VMCA821723	Colour	BLUE
Odometer	439488	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	WEST LAKE	5 mm
L/H Front Tyre	215/60R16	WEST LAKE	5 mm
R/H Rear Tyre	215/60R16	WEST LAKE	5 mm
L/H Rear Tyre	215/60R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION, O/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/09/2018	Inspection Date	05/09/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2459Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT	1,151.80	1,151.80
2	BONNET HINGE (LH/RH) @ \$87.50	NOT NECESSARY	175.00	-
1	FRONT BUMPER COVER	DISTORTED	538.80	538.80
1	FRONT BUMPER BRACKET (RH)	NOT NECESSARY	20.10	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,023.00	1,023.00
1	HEADLAMP (RH)	BROKEN	797.90	797.90
1	FRONT FENDER (RH)	BUCKLED	593.00	593.00
1	FRONT FENDER APRON PANEL (RH)	TO REPAIR SEE LABOUR	1,120.50	-
1	FRONT FENDER SHIELD (RH)	DEFORMED	86.00	86.00
1	FRONT FENDER SIGNAL LAMP (RH)	BROKEN	45.40	45.40
1	FRONT DOOR (RH)	BUCKLED	1,345.00	1,345.00
1	FRONT DOOR RUBBER	NECESSARY	110.40	110.40
1	FRONT DOOR REGULATOR	BENT	625.00	625.00
1	FRONT DOOR HINGE UPPER (RH)	BENT	51.10	51.10
1	FRONT DOOR HINGE LOWER (RH)	BENT	51.10	51.10
1	FRONT DOOR CHECK (RH)	BENT	105.50	105.50
1	FRONT DOOR INNER LOCK (RH)	NOT NECESSARY	334.40	-
1	FRONT DOOR KEY LOCK SET (RH)	NOT NECESSARY	82.40	-
1	FRONT DOOR OUTER HANDLE (RH)	BROKEN	37.00	37.00
1	FRONT DOOR OUTER MOULDING (RH)	BENT	61.00	61.00
1	FRONT DOOR POWER MOTOR	NOT NECESSARY	425.00	-
1	FRONT DOOR TRIM BOARD (RH)	MTG CRACKED	1,147.00	1,147.00
1	FRONT DOOR PROTECTOR (RH)	BENT	74.90	74.90
1	FRONT WINDSCREEN GLASS	CRACKED	1,015.00	1,015.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	FRONT WINDSCREEN PILLAR OUTER (RH)	DENTED	1,766.20	1,766.20
1	WIPER PANEL TOP GARNISH	NOT NECESSARY	87.40	-
1	FRONT WHEEL RIM (RH)	DISTORTED	284.70	284.70
1	FRONT WHEEL HUB CAP (RH)	CUT	145.00	145.00
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50

Report Ref No. CC4/EQ18016148/Dfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SHOCK ABSORBER (ASSY) (RH)	DISTORTED	203.70	203.70
1	FRONT SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	72.00	-
1	FRONT SHOCK ABSORBER FORK (RH)	DISTORTED	203.30	203.30
1	FRONT SUSPENSION UPPER ARM (RH)	DISTORTED	240.00	240.00
1	FRONT DRIVE SHAFT (RH)	NOT NECESSARY	1,025.00	-
1	RACK & PINION ASSY	NOT NECESSARY	2,093.00	-
1	STG TIE END	DISTORTED	66.50	66.50
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	685.20	685.20
1	KNUCKLE ARM (RH)	DISTORTED	558.60	558.60
1	ENGINE UNDER COVER	NOT NECESSARY	328.70	-
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,143.70	-
1	REAR FENDER (RH)	DENTED	1,935.90	1,935.90
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	74.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (RH)	BUCKLED	1,294.70	1,294.70
1	REAR DOOR RUBBER (RH)	NECESSARY	121.20	121.20
1	REAR DOOR GLASS (RH)	SHATTERED	241.60	241.60
1	REAR DOOR OUTER MOULDING (RH)	BENT	203.30	203.30
1	REAR DOOR OUTER HANDLE (RH)	TO REPAIR SEE LABOUR	39.60	-
1	REAR DOOR GEAR / REGULATOR (RH)	CRACKED	625.00	625.00
1	REAR DOOR MOTOR (RH)	NOT NECESSARY	280.40	-
1	REAR DOOR HINGE UPPER (RH)	SERVICEABLE	51.00	-
1	REAR DOOR HINGE LOWER (RH)	SERVICEABLE	51.00	-
1	REAR DOOR CHECK (RH)	SERVICEABLE	72.30	-
1	REAR DOOR TRIM BOARD (RH)	MTG CRACKED	855.30	855.30
1	REAR DOOR PROTECTOR (RH)	BENT	54.50	54.50
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	1,711.00	1,711.00
1	ROCKER PANEL OUTER GARNISH (RH)	BROKEN	463.40	463.40
1	REAR TYRE RIM (RH)	DISTORTED	284.70	284.70
1	REAR WHEEL HUP-CAP (RH)	CUT	145.00	145.00
1	REAR WHEELBEARING ING & HUB	DAMAGED	384.60	384.60
1	REAR TRAILING ARM (RH)	DISTORTED	115.00	115.00

Report Ref No. CC4/EQI18016148/Dfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ASSIST (RH)	DISTORTED	115.00	115.00
1	REAR SHOCK ABSORBER (RH)	DISTORTED	190.60	190.60
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	55.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,140.40	-
1	STABILIZER BAR	DISTORTED	196.00	196.00
1	STABILIZER LINK	DISTORTED	65.30	65.30
1	REAR UPPER ARM (RH)	DISTORTED	321.70	321.70
1	REAR LOWER ARM (RH)	DISTORTED	195.80	195.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	550.80	550.80
	LESS 20% DISCOUNT		-6,626.46	-4,692.20
			26,505.84	18,768.80
	SPECIAL NETT ITEMS			
1	FRONT DOOR COMFORT LOGO (RH) (SN)	NECESSARY	75.00	75.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT ERP STICKER (SN)	NECESSARY	30.00	30.00
1	FRONT TYRE (RH) (SN)	NOT NECESSARY	207.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR TEL NO. STICKER (RH) (SN)	NECESSARY	10.00	10.00
1	REAR TYRE (RH) (SN)	NOT NECESSARY	207.00	-
			621.00	207.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER APRON PANEL (RH) AND REAR DOOR OUTER HANDLE (RH).		2,600.00	1,400.00
	SPRAY PAINTING CHARGE.		1,800.00	1,000.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE / REFIX UNDERCARRIAGE (RR)		200.00	150.00
	TRANSFER OF DOOR.		240.00	120.00

Report Ref No. CC4/EQI18016148/Dfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX UNDERCARRIAGE (FRT)		200.00	150.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE / REFIX FRONT WINDSCREEN GLASS.		120.00	80.00
	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.		90.00	50.00
			6,660.00	3,260.00
GRAND TOTAL			33,786.84	22,235.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,000.00

Report Ref No. CC4/EQ18016148/Dfb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.