

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier @ Kaki Bukit

Singapore 415875

Tel : 94513429

Not Withheld
L1 by @?
Penny After Paint

-1

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Department

Date : 05.09.2018

Vehicle No. : SBJ 7777U

Make/Model : BMW 316

Chassis/Eng# :

Accident Date : 02.09.2018

Parts

01) Front fender rh	\$	2,250.00	—
02) Front fender emblme (sport)	\$	55.00	—
03) Front door rh	\$	2,550.00	—
04) Rear door rh	\$	2,650.00	X
05) Rocker panel rh	\$	1,850.00	X
06) Rear rim rh	\$	750.00	—
07) Rear knuckle arm rh	\$	1,532.00	?
08) Rear lower arm rh	\$	1,330.00	?
09) Reare wheel bearing rh	\$	1,150.00	?
10) Rear shock absorber rh	\$	1,950.00	?
	\$	16,067.00	
	\$	(1,606.70)	
	\$	14,460.30	

Less 10%

S/Nett

11) rear tyre rh	\$	550.00	?
	\$	550.00	

Labour charges

12) To check wiring	\$	200.00	301
13) To dismantle upholstery	\$	250.00	X
14) To dismantle door glass(front & rear rh)	\$	240.00	801
27) To knock out dents on effected areas and renew parts	\$	1,500.00	7001
28) To putty & respray painting	\$	2,000.00	13001
	\$	4,190.00	

for JA AUTOCARE PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following: Grand Total

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 19,200.30