

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 2874 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-LH <i>Distorted.</i>	\$ 3,850.00 ✓	3080.00
2	REAR DOOR ATTACHEMENET PARTS-LH <i>Not nec</i>	\$ 85.00 ✗	
3	REAR DOOR SIDE REINFORCEMENT-LH <i>Not nec</i>	\$ 147.00 ✗	
4	INSULATION STRIP <i>Not nec.</i>	\$ 14.00 ✗	
5	REAR DOOR HANDLE -LH <i>Int</i>	\$ 516.00 ✓	412.80
6	REAR DOOR HANDLE HOUSING-LH <i>Not nec</i>	\$ 22.00 +	
7	REAR DOOR HANDLE CAP-LH <i>Not nec</i>	\$ 21.00 +	
8	REAR DOOR MOUNTING BAR -LH <i>Not nec</i>	\$ 196.00 ✗	
9	REAR DOOR WINDOW REGULATOR-LH <i>Not nec</i>	\$ 268.00 +	
10	REAR SIDE WINDOW GUIDE RAIL-LH	\$ 83.00 +	
11	REAR DOOR COVER -LH <i>Missing</i>	\$ 390.00 ✓	311.60
12	REAR SIDE PANEL-LH <i>Repis</i>	\$ 4,624.00 +	
13	REAR SIDE WINDOW-LH	\$ 489.00 +	
14	REAR SIDE WINDOW TRIM STRIPS-LH	\$ 241.00 +	
15	REAR SUDE WINDOW COVER TRIM-LH <i>Not nec</i>	\$ 294.00 ✓	234.80
16	REAR SIDE WINDOW PRIMED TRIM STRIPS-LH <i>Not nec</i>	\$ 222.00 +	
17	PROTECTIVE FILM <i>Not nec</i>	20 \$ 44.00 ✗	
18	REAR ALUMINIUM RIM-LH <i>Not nec</i>	\$ 822.00 +	
19	RUBBER VALVE <i>Not nec</i>	4 \$ 12.00 ✗	
20	ACRYLIC SEALANT	S/N \$ 180.00 ✗	
SUB-TOTAL SPARE PARTS		\$ 12,520.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 2874 E .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CAVITY WAX	S/N \$ 140.00	+
22	STONE CHIP	S/N \$ 180.00	+
23	METAL FILLER POWDER	S/N \$ 280.00	+
24	1/4 GLASS SEALANT	S/N \$ 100.00	+
25	SUNDRIES	Net \$ 500.00	23.44.
TOTAL SPARE PARTS		:	\$ 13,720.00
TOTAL LABOUR CHARGES		:	\$ 16,032.00
GRAND TOTAL		:	\$ 29,752.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

30151.84

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 04/09/18 ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1018/2018/GW
Date 27-Sep-18
Service Advisor Jeffery Tan
Pages 1
Regn No SKD 2874 E
Model No Audi Q 7 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
Parts			
1	Stone chip film - LHS <i>new</i>	\$ 67.00 ✓	53.44
2	C-pillar trim - LHS <i>new</i>	\$ 153.00 ✓	122.00
3	Outer door seal - LHS <i>new</i>	\$ 281.00 ✓	224.40
		\$ 501.00	
TOTAL		\$ 501.00	

For Premium Automobiles Pte Ltd

Adrian Ling.
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 2874 E

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00
2	To remove and transfer lhs rear door's multi-lock system and power window devices.	S/N \$	280.00 \$ 280.00
3	To renew lhs 1/4 glass to facillitate fender renewal.	S/N \$	300.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and trays, electrical and audio equipment.	S/N \$	1,400.00
5	To remove and reinstall rear seat, back rest , hat tray, abcd pillar trims, luggage compartment trims, seat belts, dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00
SUB- TOTAL LABOUR CHARGES		: \$	<u>3,660.00</u> \$ <u>280.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 2874 E

S/N	Nature of Jobs	Estimated Charges		
		c/f	\$	280.00
6	To dismantle rear bumper , rear lid and lhs rear door . Cut out and weld lhs rear fender. Renew lhs rear door. Re-organize rear crash management components. Reinstall all parts removed.	\$ 7,200.00	\$	900.00
7	To respray lhs rear door, lhs rear door cover, lhs rear door handle, lhs rear fender, lhs sill panel, roof channel, door entrances and end panalling. To carry out stone chip treatment and joint sealer works.	\$ 4,700.00	\$	1,580.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00		
9	To carry out diagnostic check.	S/N \$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		: \$ 16,032.00	\$	2,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 2874 E

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR DOOR-LH	\$ 3,850.00	\$ 3,080.00
2	REAR DOOR ATTACHEMENET PARTS-LH	\$ 85.00	
3	REAR DOOR SIDE REINFORCEMENT-LH	\$ 147.00	
4	INSULATION STRIP	\$ 14.00	
5	REAR DOOR HANDLE -LH	\$ 516.00	\$ 412.80
6	REAR DOOR HANDLE HOUSING-LH	\$ 22.00	
7	REAR DOOR HANDLE CAP-LH	\$ 21.00	
8	REAR DOOR MOUNTING BAR -LH	\$ 196.00	
9	REAR DOOR WINDOW REGULATOR-LH	\$ 268.00	
10	REAR SIDE WINDOW GUIDE RAIL-LH	\$ 83.00	
11	REAR DOOR COVER -LH	\$ 390.00	\$ 311.60
12	REAR SIDE PANEL-LH	\$ 4,624.00	
13	REAR SIDE WINDOW-LH	\$ 489.00	
14	REAR SIDE WINDOW TRIM STRIPS-LH	\$ 241.00	
15	REAR SUDE WINDOW COVER TRIM-LH	\$ 294.00	\$ 234.80
16	REAR SIDE WINDOW PRIMED TRIM STRIPS-LH	\$ 222.00	
17	PROTECTIVE FILM	20 \$ 44.00	
18	REAR ALUMINIUM RIM-LH	\$ 822.00	
19	RUBBER VALVE	4 \$ 12.00	
20	ACRYLIC SEALANT	S/N \$ 180.00	
SUB-TOTAL SPARE PARTS		\$ 12,520.00	\$ 4,039.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 2874 E .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	4,039.20
21	CAVITY WAX	S/N	\$ 140.00	
22	STONE CHIP	S/N	\$ 180.00	
23	METAL FILLER POWDER	S/N	\$ 280.00	
24	1/4 GLASS SEALANT	S/N	\$ 100.00	
25	<i>Added parts - see attached</i>		\$ 501.00	\$ 399.84
26	SUNDRIES		\$ 500.00	\$ 23.44
	TOTAL SPARE PARTS	:	\$ 14,221.00	\$ 4,462.48
	TOTAL LABOUR CHARGES	:	\$ 16,032.00	\$ 2,952.00
	GRAND TOTAL	:	\$ 30,253.00	\$ 7,414.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1018/2018/GW
Date 27-Sep-18
Service Advisor Jeffery Tan
Pages 1
Regn No SKD 2874 E
Model No Audi Q 7 3.0 TFSI Qu

Quantity	Description	Unit Price	Amount
Parts			
1	Stone chip film - LHS	\$ 67.00	\$ 53.44
2	C-pillar trim - LHS	\$ 153.00	\$ 122.00
3	Outer door seal - LHS	\$ 281.00	\$ 224.40
		\$ 501.00	\$ 399.84
TOTAL		\$ 501.00	\$ 399.84

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKD 2874 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1018/2018/MAS

7 March 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKD 2874 E, Audi Q7 3.0 TFSI Qu

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKD 2874 E**, claimant, **Mr. Clydesdale Peter Currie**, please find the related document per attached.

1. A copy of the Original invoice no. 85013481 – S\$6,435.49
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKD 2874 E

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SKD 2874 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1018/2018/PH
01 Oct 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q7 3.0 TFSI Qu
Vehicle Chassis No. : WAUZZZ4L4CD009221
Vehicle Regn No. : **SKD 2874 E**
Vehicle Mileage : 56136 KM
Vehicle Owner : Mr. Clydesdale Peter Currie
Certificate No : 2100470289-02
Policy Excess : S\$1498.00 (Inclusive of GST)
Accident Date : 30/08/2018
Place : Causeway Point Entrance Basement Carpark
Repair Cost : \$ 6,435.49.
WIP No. : 23194
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____
Time : 1700
Date : 02/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018		04 Sep 2018 17:18 Edit Adj Rpt	S\$7,414.48 Edit Estimates	S\$7,414.48 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CLYDESDALE PETER CURRIE, ID: F5597396L, Tel: +6597835022, Email: PETERCLYDESDALE0120@GMAIL.COM		
Vehicle Reg. No.:	SKD2874E	Date of Loss:	30/08/2018 14:00 - :59 [81 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3912538050SG	Policy/Cover Note No.:	2100470289-02 (Comprehensive)
		Excess:	S\$1,400.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2018]		
Driver/Custodian:	CLYDESDALE PETER CURRIE (53 / Male), NRIC: F5597396L, Tel: +6597835022 Email: PETERCLYDESDALE0120@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (11/09/2018): Alert - Adj Mandate Approved (S\$7708.00) - SKD2874E - Claim Handler: Chan, Kian ...
- AIG_SG (10/09/2018): SKD2874E / OD / 30/08/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD2874E (3912538050SG)**
OD
Aug 30 2018 2:20PM
[CLYDESDALE PETER CURRIE]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 16:25	Adjuster Immediate Advice	1	Load HTM	
2	22/11/18 10:10	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 15:48	General View	1	Load JPG	☒
2	05/09/18 15:48	General View	1	Load JPG	☒
3	05/09/18 15:48	General View	1	Load JPG	☒
4	05/09/18 15:48	General View	1	Load JPG	☒
5	05/09/18 15:48	General View	1	Load JPG	☒
6	05/09/18 15:48	General View	1	Load JPG	☒
7	05/09/18 15:48	General View	1	Load JPG	☒
8	05/09/18 15:48	General View	1	Load JPG	☒
9	05/09/18 15:48	General View	1	Load JPG	☒
10	05/09/18 15:48	General View	1	Load JPG	☒
11	05/09/18 15:48	General View	1	Load JPG	☒
12	05/09/18 15:48	General View	1	Load JPG	☒
13	05/09/18 15:48	General View	1	Load JPG	☒
14	05/09/18 15:48	General View	1	Load JPG	☒
15	05/09/18 15:48	General View	1	Load JPG	☒
16	05/09/18 15:48	General View	1	Load JPG	☒
17	05/09/18 15:48	General View	1	Load JPG	☒
18	05/09/18 15:48	General View	1	Load JPG	☒
19	17/12/18 11:18	Reinspection Photo	1	Load JPG	☒
20	17/12/18 11:18	Reinspection Photo	1	Load JPG	☒
21	17/12/18 11:18	Reinspection Photo	1	Load JPG	☒
22	17/12/18 11:18	Reinspection Photo	1	Load JPG	☒
23	17/12/18 11:18	Reinspection Photo	1	Load JPG	☒

Documentation

1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 15:47	SKD 2874E ESTIMATE	1	Load PDF	
2	05/09/18 15:47	Certificate of Insurance	1	Load PDF	
3	05/09/18 15:47	Insured's NRIC	1	Load PDF	
4	05/09/18 15:47	Singapore Accident Statement	1	Load PDF	
5	13/03/19 13:26	SUPPLEMENTARY	1	Load PDF	
6	13/03/19 13:26	DISCHARGE VOUCHER	1	Load PDF	
7	13/03/19 13:26	WORKSHOP INVOICE	1	Load PDF	

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/08/18 12:39	Accident Statement	 Load HTM	☒

Photos/Images

3 per page ▼ ☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
2	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
3	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
4	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
5	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
6	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
7	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
8	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
9	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒
10	31/08/18 12:36	Accident Photo	 Load JPG ☒	☒

Documentation

1 per page ▼ ☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/08/18 12:33	Sketch Plan	 Load JPG ☒	☒
2	31/08/18 12:33	Sketch Plan #2	 Load JPG ☒	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016152/ACD3S2

Date: 13/03/2019

REFERENCE

Insured/Claimant: CLYDESDALE PETER CURRIE Policy No: 2100470289-02
Date of Loss: 30/08/2018 Nature of Claim: OD Claim No: 3912538050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD2874E**
Make & Model: AUDI Q7, 3.0 (A) Engine No: CJT036552
Reg. Date: 16/11/2011 (Man. Year: 2011) Chassis No: WAUZZZ4L4CD009221
Colour: Black Odometer: 55204 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/45R20 Rear Tyre Size: 275/45R20
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,119.84	4,462.48	9,657.36	68.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,032.00	2,952.00	13,080.00	81.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,151.84	7,414.48	22,737.36	75.41
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	28,751.84	6,014.48	22,737.36	79.08
+ GST 7.00/7.00% (S\$)	2,012.63	421.01	1,591.62	79.08
Nett Amount (S\$)	30,764.47	6,435.49	24,328.98	79.08

INSPECTION

Date of Assignment: 04/09/2018
Date Inspected: 04/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Distorted	3,850.00 FS	*3,080.00 FS
2	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	85.00 FS	*- FS
3	1		*REAR DOOR SIDE REINFORCEMENT - LH	Not Necessary	147.00 FS	*- FS
4	1		*INSULATION STRIP	Not Necessary	14.00 FS	*- FS
5	1		*REAR DOOR HANDLE - LH	Cut	516.00 FS	*412.80 FS
6	1		*REAR DOOR HANDLE HOUSING - LH	Not Necessary	22.00 FS	*- FS
7	1		*REAR DOOR HANDLE CAP - LH	Not Necessary	21.00 FS	*- FS
8	1		*REAR DOOR MOUNTING BAR - LH	Not Necessary	196.00 FS	*- FS
9	1		*REAR DOOR WINDOW REGULATOR - LH	Not Necessary	268.00 FS	*- FS
10	1		*REAR SIDE WINDOW GUIDE RAIL - LH	Not Necessary	83.00 FS	*- FS
11	1		*REAR DOOR COVER - LH	Missing	390.00 FS	*311.60 FS
12	1		*REAR SIDE PANEL - LH	Repair	4,624.00 FS	*- FS
13	1		*REAR SIDE WINDOW - LH	Not Necessary	489.00 FS	*- FS
14	1		*REAR SIDE WINDOW TRIM STRIPS - LH	Not Necessary	241.00 FS	*- FS
15	1		*REAR SIDE WINDOW COVER TRIM - LH	Necessary	294.00 FS	*234.80 FS
16	1		*REAR SIDE WINDOW PRIMED TRIM STRIPS - LH	Not Necessary	222.00 FS	*- FS
17	20		*PROTECTIVE FILM	Not Necessary	44.00 FS	*- FS
18	1		*REAR ALUMINIUM RIM - LH	Not Necessary	822.00 FS	*- FS
19	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
20	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
21	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
22	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
23	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
24	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*SUNDRIES	Necessary	500.00 FS	*23.44 FS
26	1		*STONE CHIP FILM - LHS	Necessary	53.44 FS	*53.44 FS
27	1		*C-PILLAR TRIM - LHS	Necessary	122.00 FS	*122.00 FS
28	1		*OUTER DOOR SEAL - LHS	Necessary	224.40 FS	*224.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	14,119.84	4,462.48
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	New	300.00	0.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	0.00
6	TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RENEW LHS REAR DOOR. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	7,200.00	900.00
7	TO RESPRAY LHS REAR DOOR, LHS REAR DOOR COVER, LHS REAR DOOR HANDLE, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	4,700.00	1,580.00
8	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			16,032.00	2,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >