

INVOICE

INS. CASE OWNER

CC 3 /AIG1801

6153, Gw639

LKK

IDAC

Surveyor:

YHR

DOI:

ASSIGNMENT

6/2/18

Date / Time:

4/9/18

Registered in Member:

4/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 2559B

Name of Insured:

WY BOON HUI SHAN

Insured Tel No.:

HP:

96/8/18

Excess Sec II :\$5

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: YONG LINEN - 38 YEARS

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

01915758754

Policy No.:

1800063754

Make / Model:

BMW

Place of Accident:

DUNELAN RD BY
SHEFFORD RD

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLW 689A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/2/18
vignan

SLW 689A - X

SMA 2559B - X

STAGE

DATE / PIC

Non-Reporting In (1st)

Non-Reporting In (2nd)

Non-Reporting In (Final)

Notification In (if non-pickup)

Call OI:

After call In to OI:

22/9/18
vignan

Documentation Check List: Handler Typist

Notification In (if non-pickup)

After call In to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

8/5/19

Confirm with:

Master

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

57

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

9898.06

Loss of Rental (LOR):

\$5

(days)

Loss of Use (LOU):

\$5

560.00

x 7 days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search:

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$10458.06

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

9898.06

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

\$5

560.00

Name 2:

Audi Singapore Pte Ltd.

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
10/6/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18016153/wb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-09-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMA 3559B	Veh. Inspected	SLW 689A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/08/2018	Inspection Date	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1027/2018/PH
Date : 4-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SMA 3559 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Audi Singapore Pte Ltd
Address :
Singapore
Telephone : HP +65 92333513
Type of Claim : Third Party Claims
Policy No. : 200819216Z
Vehicle No : **SLW 689 A**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Jan-18
Engine No : CYG 018925
Chassis No : WAUZZZ4G7HN093961
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Aug-18
Place of Accident : Dunearn Road / Shelford Road.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 689 A.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	/ /
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$ 1,400.00	X 1 NN
3	To dismantle rear bumper and rear lid. Cut out reweld end panelling. Renew rear bumper. repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,550.00	500 1250 /
4	To respray rear bumper, rear lid, rhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,900.00	550 1100 /
5	To remove and renew center and rear exhaust silencer. Align to position.	S/N \$ 480.00	/ /
6	To carry out diagnostic check	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 9,882.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER / BTN	\$ 2,519.00	2015.20
2	FIXING PARTS FOR BUMPER X 4 NN	\$ 234.00	X
3	FIXING PARTS FOR BUMPER X	\$ 25.00	X
4	SECURINMG STRIP / MC	\$ 191.00	152.80
5	STICKY PADS X NN 4	\$ 20.00	X
6	SPOILER / CRA	\$ 416.00	333.80
7	SECURING STRIP X MC NN	\$ 191.00	X
8	CLOSING ELEMENT -LH/RH / MC	2 \$ 138.00	109.44
9	CABLE TERMINAL X	13 \$ 84.00	X
10	REAR BUMPER CARRIER X MC NN	2 \$ 92.00	X
11	CONNECTING PIECE X	2 \$ 851.00	X
12	HEX COLLARED X NN	3 \$ 22.00	X
13	SEAL - LH / RH X	2 \$ 24.00	X
14	GUIDE SECTION - RH / MC	\$ 28.00	22.00
15	GUIDE SECTION - RH X MC	2 \$ 46.00	36.08
16	CONNECTING PIECE X NN	\$ 11.00	X
17	GUIDE PROFILEV-RH X BR	\$ 57.00	45.28
18	GUIDE SECTION - CENTRE X NN	\$ 91.00	X
19	HOLDING STRAP - RH X CRA	\$ 54.00	42.96
20	SENSOR SPM IPC, DM 2405.9	3 \$ 632.00	168.40
SUB - TOTAL SPARE PARTS CHARGES :		\$ 5,726.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	WIRING SET FOR BUMPER / <i>ACC</i>	\$ 603.00	482.00
22	CONTROL UNIT FOR OPENING BOOT LID <i>X</i> <i>NN</i>	372.00	<i>X</i>
23	PACKING ADHESIVE / <i>ACC</i>	\$ 15.00	11.60
24	AUDI LOGO <i>X</i>	\$ 108.00	<i>X</i>
25	A' 6 MBLEM <i>X</i>	\$ 83.00	<i>X</i>
26	TFSI ' EMBLEM <i>X</i>	\$ 83.00	<i>X</i>
27	DECORATIVE TRIM FOR LI <i>X</i>	\$ 317.00	<i>X</i>
28	LED TAIL LIGHT - RH OUTER / <i>CRA</i>	\$ 1,094.00	875.20
29	TRIM FOR TAIL LIGHT <i>X</i> / <i>ACC</i>	\$ 26.00	20.08
30	LED TAILLIGHT - RH INNER <i>X</i>	\$ 1,094.00	<i>X</i>
31	TRIM FOR TAIL LIGHT -RH <i>X</i>	\$ 26.00	<i>X</i>
32	REAR CROSS PANEL <i>X</i>	\$ 274.00	<i>X</i>
33	REINFORCEMENT FOR CROSS PANEL <i>X</i> <i>MS</i>	\$ 639.00	<i>X</i>
34	CONNECTING PLATE - RH LOWER <i>X</i>	\$ 39.00	<i>X</i>
35	CENTRE SILENCER <i>X</i>	\$ 875.00	<i>X</i>
36	DUAL CLIP <i>X</i>	\$ 52.00	<i>X</i>
37	DUAL CLIP <i>X</i>	2 \$ 105.00	<i>X</i>
38	REAR SILENCER - RH / <i>NT</i>	\$ 1,157.00	925.60
39	DUAL CLIP / <i>ACC</i>	2 \$ 405.00	83.68
40	BRACKET <i>X</i> / <i>CRA</i>	2 \$ 100.00	79.20
SUB - TOTAL SPARE PARTS CHARGES :		\$ 7,467.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	TRIM FOR EXHAUST TAIL PIPE - RH / BT	\$ 497.00	397.60
42	CAR PLATE - REAR / N	\$ 25.00	25
43	ARCYLIC SEALANT X	\$ 180.00	X
44	CAVITY WAX X	\$ 140.00	X { NN
45	STONE CHIP TREATMENT X	\$ 180.00	X
46	SUNDRIES X / MCL	\$ 500.00	40.96
TOTAL SPARE PARTS CHARGES :		\$ 1,522.00	
TOTAL LABOUR CHARGES :		\$ 9,882.00	
GRAND TOTAL :		\$ 11,404.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

4 Days.

Quo Quip - 8288 0282

before paint photos.

06/9/18.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	9216Z

Vehicle Details

Vehicle No.:	SLW689A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CYG018925
Chassis No.:	WAUZZZ4G7HN093961
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$40,630.00
Original Registration Date:	26 Jan 2018
First Registration Date:	26 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$48,882.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jan 2028
PARF Rebate Amount:	\$36,661.00

Intended COE Rebate Details

COE Expiry Date:	25 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$45,147.00
Total Rebate Amount:	\$81,808.00

The information contained herein is correct as at 06 Sep 2018

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1027/2018/PH
Date : 4-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SMA 3559 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Hi Guo Qiang

you recommended 4 days. We took
6 days exclude 1 Sunday with added
repairs. Jb - 12 Nov 18

Owner's Name : Audi Singapore Pte Ltd
Address :
Singapore
Telephone : HP +65 92333513
Type of Claim : Third Party Claims
Policy No. : 200819216Z
Vehicle No : **SLW 689 A**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Jan-18
Engine No : CYG 018925
Chassis No : WAUZZZ4G7HN093961
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Aug-18
Place of Accident : Dunearn Road / Shelford Road.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 689 A.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$	1,400.00	nil
3	To dismantle rear bumper and rear lid. Cut out reweld end panelling. Renew rear bumper. repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed. <i>(Added \$750/- for rear panelling repairs - Agreed GQ on 2/10/18)</i>	\$	4,550.00	\$ 1,250.00
4	To respray rear bumper, rear lid, rhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$	2,900.00	\$ 1,100.00
5	To remove and renew center and rear exhaust silencer. Align to position.	S/N \$	480.00	\$ 480.00
6	To carry out diagnostic check	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 9,882.00</u>	<u>\$ 3,382.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER	\$ 2,519.00	\$ 2,015.20
2	FIXING PARTS FOR BUMPER	\$ 234.00	
3	FIXING PARTS FOR BUMPER	\$ 25.00	
4	SECURINMG STRIP	\$ 191.00	\$ 152.80
5	STICKY PADS	4 \$ 20.00	
6	SPOILER	\$ 416.00	\$ 332.80
7	SECURING STRIP	\$ 191.00	
8	CLOSING ELEMENT -LH/RH	2 \$ 138.00	\$ 109.44
9	CABLE TERMINAL	13 \$ 84.00	
10	REAR BUMPER CARRIER	2 \$ 92.00	
11	CONNECTING PIECE	2 \$ 851.00	
12	HEX COLLARED	3 \$ 22.00	
13	SEAL - LH / RH	2 \$ 24.00	
14	GUIDE SECTION - RH	\$ 28.00	\$ 22.00
15	GUIDE SECTION - RH	2 \$ 46.00	\$ 36.08
16	CONNECTING PIECE	\$ 11.00	
17	GUIDE PROFILEV-RH	\$ 57.00	\$ 45.28
18	GUIDE SECTION - CENTRE	\$ 91.00	
19	HOLDING STRAP - RH	\$ 54.00	\$ 42.96
20	SENSOR	3 \$ 632.00	\$ 168.40
SUB - TOTAL SPARE PARTS CHARGE\$:		\$ 5,726.00	\$ 2,924.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A .

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 2,924.96
21	WIRING SET FOR BUMPER	\$	603.00	\$ 482.00
22	CONTROL UNIT FOR OPENING BOOT LID	\$	372.00	
23	PACKING ADHESIVE	\$	15.00	\$ 11.60
24	AUDI LOGO	\$	108.00	
25	A' 6 MBLEM	\$	83.00	
26	TFSI ' EMBLEM	\$	83.00	
27	DECORATIVE TRIM FOR LI	\$	317.00	
28	LED TAIL LIGHT - RH OUTER	\$	1,094.00	\$ 875.20
29	TRIM FOR TAIL LIGHT	\$	26.00	\$ 20.08
30	LED TAILLIGHT - RH INNER	\$	1,094.00	
31	TRIM FOR TAIL LIGHT -RH	\$	26.00	
32	REAR CROSS PANEL	\$	274.00	
33	REINFORCEMENT FOR CROSS PANEL	\$	639.00	
34	CONNECTING PLATE - RH LOWER	\$	39.00	
35	CENTRE SILENCER	\$	875.00	
36	DUAL CLIP	\$	52.00	
37	DUAL CLIP	2 \$	105.00	
38	REAR SILENCER - RH	\$	1,157.00	\$ 925.60
39	DUAL CLIP	2 \$	405.00	\$ 83.68
40	BRACKET	2 \$	100.00	\$ 79.84
SUB - TOTAL SPARE PARTS CHARGES:			\$ 7,467.00	\$ 5,402.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A .

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		<i>c/f</i>		\$ 5,402.96
41	TRIM FOR EXHAUST TAIL PIPE - RH		\$ 497.00	\$ 397.60
42	CAR PLATE - REAR	S/N	\$ 25.00	\$ 25.00
43	ARCYLIC SEALANT	S/N	\$ 180.00	
44	CAVITY WAX	S/N	\$ 140.00	
45	STONE CHIP TREATMENT	S/N	\$ 180.00	
46	SUNDRIES		\$ 500.00	\$ 42.96
	TOTAL SPARE PARTS CHARGES	:	\$ 1,522.00	\$ 5,868.52
	TOTAL LABOUR CHARGES	:	\$ 9,882.00	\$ 3,382.00
	GRAND TOTAL	:	\$ 11,404.00	\$ 9,250.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
AUDI SINGAPORE PTE. LTD.



Name
RENTS HEIKO KARL
Occupation
INFORMATION TECHNOLOGY MANAGER

FIN
G3431915X

Date of Application
28-11-2017

Date of Issue
02-01-2018

Date of Expiry
02-01-2020



L8542687

VISIT PASS
Immigration Regulations

Name
RENTS HEIKO KARL



Date of Birth	Sex	Nationality
14-08-1979	M	GERMAN
FIN	Date of Issue	Date of Expiry
G3431915X	02-01-2018	02-01-2020

MULTIPLE JOURNEY VISA ISSUED

**YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.**



FUHRERSCHEIN BUNDESREPUBLIK DEUTSCHLAND

1. **Reints**

2. **Heiko Karl**

3. **14.08.79** **Emden**

4a. **15.04.15** **Stadt Emden**

4b. **Der Oberbürgermeister**

4c. **14.04.30**

5. **1371010CX52**

7. **H. Reints**

8. **AM/A1/A/B/CVC/BE/CE/DE/LIT**

19.6.15

10CX52

	9	10	11	12
AM 05	15.05.97			
A1 05	15.05.97		15.05.14.04	
A3 05				
A 05	14.05.97		15.05.14.04	
B1 05				
B 05	15.05.97			
C1 05	15.05.97		15.05.14.04	
C 05	14.05.97	15.05.14.04		
D1 05				
D 05				
BE 05	15.05.97		15.05.14.04	
CE 05	15.05.97		15.05.14.04	
DE 05	15.05.97	15.05.14.04	15.05.14.04	15.05.14.04
L 05	15.05.97		15.05.14.04	
T 05	15.05.97		15.05.14.04	

12. 01

11 Wohnort / Residence / Domicile
EMDEN

11. Wohnort / Residence / Domicile

11. Wohnort / Residence / Domicile

12. Größe / Height / Taille
186 cm


13. Augmentarbe / Colour of eyes / Couleur des yeux

BLAUGRÜN

14. Ordens- oder Künstlername / Religious name or pseudonym /
Nom de religion ou pseudonyme

677222

► Zugangsnummer (CAN)



BUNDESREPUBLIK DEUTSCHLAND

FEDERAL REPUBLIC OF GERMANY - RÉPUBLIQUE FÉDÉRALE D'ALLEMAGNE

REISEPASS

REISEPASS
PASSPORT - PASSEPORT

Typ / Type / Type

Kode / Code / Code

Pass-Nr. / Passport No. / Passeport No.

P

D

C2CH24GN2

1 [a]Name / Surname / Nom [b]Geburtsname / Name at birth / Nom de naissance

(a) REINTS



2. **Vornamen / Given names / Prénoms**

HEIKO KARL

3. Geburtstag / Date of birth /
Date de naissance

14.08.1979

4. Geschlecht / Sex / Sexe

M

5 Staatsangehörigkeit / Nationality / Nationalité

DEUTSCH

6. Geburtsort / Place of birth / Lieu de naissance

EMDEN

7. **Ausstellungsdatum / Date of issue / Date de délivrance**

06.10.2017

8. Gültig bis / Date of expiry /
Date d'expiration

05.10.2027

10. Unterschrift der Inhaberin,
des Inhabers / Signature of bearer /
Signature de la titulaire, du titulaire

9. Behörde / Authority / Autorité

STADT EMDEN
BÜRGERBÜRO

H. R. 25

P<D<<REINTS<<HEIKO<KARL<<<<<<<<<<<<<<<<<<<

C2CH24GN24D<<7908149M2710051<<<<<<<<<<<<<<<2

BREAKDOWN OF PAYMENT

Vehicle No: SLW689A

Accident on 26/08/2018 at Dunearn Road / Shelford Road

Involving vehicle/s SMA 3559 B

1) Repair cost	\$ 9,898.06	Payable to: Premium Automobiles Pte Ltd
----------------	-------------	---

2) GIA/LTA search fee \$ Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 560.00 Payable to: Audi Singapore Pte Ltd

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18016153/wb3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/1027/2018/MAS

13 Dec 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLW 689 A, Audi A6 1.8 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLW 689 A**, claimant, **Audi Singapore Pte Ltd**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013237 – S\$9,898.06
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$560.00 (S\$80.00 x 6 working days + 1 Sunday)
6. GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 689 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

A

View Received Message

This mail is associated with :

***SLW689A (0191875287SG)
[SMA3559B]**

TP

AUDI SINGAPORE PTE LTD

Aug 26 2018 9:00PM

[NG BOON HSI, SARAH (HUANG WENSHI)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on **23/04/2019 19:48 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10460.06) - SLW689A - Claim Handler: Loh, Chee-Heng

Approved:10460.06.

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016153/wb3

28 September 2018

Ng Boon His, Sarah
76 JALAN LIM TAI SEE
SINGAPORE 268412

Dear Sir/Madam,

ACCIDENT INVOLVING SMA 3559B AND SLW 689A ON 26/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Audi Singapore Pte Ltd (the third party claimant) of 8 Kallang Avenue
#08-01 to 09 Aperia Tower 1 S339509 (address), owner of SLW 689 A (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLW 689 A that was damaged pursuant to the accident which occurred on 26/08/2018
(date) along Dunearn Road / Shelford Road (location) involving vehicle no/s
SMA 3559 B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 4 (day) of Oct (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)





Signed by "the workshop"
(with chop)



RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 9898.06 (Repair Cost), S\$ 560.00 (Loss of rental/loss), S\$ NIL (Disbursement), for vehicle no. SLW 689 A that was damaged pursuant to the accident which occurred on 26/08/2018 (date) along Dunearn Road / Shelford Road (location) involving vehicle no/s SMA 3559 B. This is pursuant to the inspection conducted on 06/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner AUDI SINGAPORE PTE LTD ("the third party claimant") of vehicle no. SLW 689A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLW 689A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 8 (day) of 5 (month) 2019 (year)

X6Q



Signed by appointed surveyor



[Signature]

Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159538
Main Telephone: 6836 2223
Main Telefax: 6471 2721
Page 1 10:46

Alexandra Service Centre
281 Alexandra Road
Singapore 159538
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 1122
Telefax: 6388 1122

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6388 2322
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013237 Date : 05/12/2018 Order : SLW0689A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW0689A (V 33286) Regn Date: 26/01/2018 Mileage: 6610 WIP No.: 22875
Model: A6 1.8 TFSI S tronic 40000 (N Chassis: WAUZZZ4G7H093961 Engine: CYG 018925 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGED	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID,CUT OUT AND REMELD END PANELLING,RENEW REAR BUMPER, REPAIR RHS REAR FENDER,REORGANISE REAR CRASH MANAGEMENT COMPONENTS,REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND RHS REAR FENDER, TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	1100.00	1.00	1,100.00
S	BODYWORK	M: TO REMOVE AND RENEW REAR EXHAUST SILENCER,	400.00	1.00	400.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2223
Fax: 6836 2223
Page 2 10:46

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6368 2223
Telefax: 6475 1023

Ubi Service Centre
50 Ubi Road 1
Singapore 408643
Telephone: 6841 1165
Telefax: 6841 1165

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2223
6828 1223

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013237 Date : 05/12/2018 Order : SLW0689A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW0689A (V 33286) Regn Date: 26/01/2018 Mileage: 6610 WIP No.: 22875
Model: A6 1.8 TFSI S tronic 40000 (N Chassis: MAUZZI4G7H0093961 Engine: CY6 018925 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ALIGN TO POSITION	192.00	1.00	192.00
		TO CARRY OUT DIAGNOSTIC CHECK			
X	A465971085AG	006458/(V) (SK) HARNES	Less 020%	1.00	602.50
X	A468253618CE	006458/(V) (GER) SILEN	Less 020%	1.00	1157.00
X	A468253826A	006458/(V) (SK) PIPEIT	Less 020%	1.00	497.00
X	A465945096E	TAIL LIGHT	Less 020%	1.00	1094.00
X	A468807521T 989	SPOILER	Less 020%	1.00	415.00
X	A465807067K GRU	COVER	Less 020%	1.00	2519.00
X	A465807890A	GUIDE	Less 020%	1.00	27.50
X	A468807363C	PLATE	Less 020%	1.00	68.40
X	A468807329	STRAP	Less 020%	1.00	53.70
X	A468807330	(SK) STRAP	Less 020%	1.00	53.70
X	A468807364C	PLATE	Less 020%	1.00	68.40
X	A465807900B 989	STRIP	Less 020%	1.00	191.00
X	A8D0853419F	PACKING	Less 020%	1.00	14.50
X	A8K0253144M	BRACKET	Less 020%	2.00	49.90
X	A1K0253141L	CLAMP	Less 020%	2.00	52.30

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
211 Alexandra Road
Singapore 119938
Main Telephone: 6346 2223
Fax: 6346 2223
Page 3 10/48

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2223
Telefax: 6475 1525

Ubi Service Centre
Singapore 119938
Singapore 119938
Telephone: 6346 2223
Telefax: 6475 1525

Customer Service
"Service Appointment"
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2223
6346 2223

INS TAX INVOICE
Company Reg. No. 199902271M
GST Reg. No. 199902271M

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013237 Date : 05/12/2018 Order : SLW0689A Term : 30	Account: A0006 (T: 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SLW0689A (V 33286) Regn Date: 26/01/2018 Mileage: 6610 WIP No.: 22875
Model: A6 1.8 TFSI S tronic 40066 (N Chassis: WAUZZZ467H0033961 Engine: CYG 018925 Dept: U
VSB No.:
You have been assisted by :- UA-Jiayee (87)

		Details		Qty	Unit Price	Amount
X	A465807454C	(SK)GUIDE	Less 020%	1.00	45.10	36.08
X	A465807394D	006468/(V) (SK)PIECE (	Less 020%	1.00	56.60	45.28
X	A46594525A	TRIM	Less 020%	1.00	25.10	20.08
X	A190919275C GRU	SENSOR	Less 020%	1.00	210.50	168.40

Parts	5,843.52	Sub-Total	9,250.52
Labour	0.00		
Sublet	3,407.00	7% GST	647.54
Menus	0.00		
Lubricant	0.00	Grand Total	9,898.06



Received by

For & on behalf of
Premium Automobiles Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)
Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Aug 2018 Edit Reg		06 Sep 2018 00:00 Edit Adj Rpt	\$9,250.52 Edit Estimates	\$9,250.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

NG BOON HSI, SARAH (HUANG WENSHI), ID: S8406311H

Main Claimant:

AUDI SINGAPORE PTE LTD, Co. Reg. No.: 200819216Z

Vehicle Reg. No.:

SLW689A

Date of Loss:

26/08/2018 21:00 - :59
[7 Months From LTA Reg Date (Man Yr)]

Claim Type:

TP / 0191875287SG

Policy/Cover Note No.:

1800063754 (Comprehensive)
Coverage: 04/06/2018 - 03/06/2019

Vehicle Reg. No. (Insured):

SMA3559B

Policy No. (Claimant):

VFX/P1886473

Excess:

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Claimant's Insurer:

AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/09/2018]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (23/04/2019): Alert - Adj Mandate Approved (\$10460.06) - SLW689A - Claim Handler: Loh, Chee-H...
- AIG_SG (13/09/2018): OI contact number & home mailing address in merimen

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW689A (0191875287SG)
[SMA3559B]
TP
AUDI SINGAPORE PTE LTD
Aug 26 2018 9:00PM
[NG BOON HSI, SARAH (HUANG WENSHI)]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Letters/Correspondences															1 per page			☒					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit					
Assessment Reports															1 per page			☒					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)															Thumbnail			Print		
1	05/09/18 10:26		Accident Statement From:OD - Reg. No: SMA3559B, Claimant: NG BOON HSI,SARAH												1			Load HTM					
Photos/Images															3 per page			☒					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)															Thumbnail			Print		
1	19/11/18 14:47		General View												1			Load JPG			☒		
2	19/11/18 14:47		General View												1			Load JPG			☒		
3	19/11/18 14:47		General View												1			Load JPG			☒		
4	19/11/18 14:47		General View												1			Load JPG			☒		
5	19/11/18 14:47		General View												1			Load JPG			☒		
6	19/11/18 14:47		General View												1			Load JPG			☒		
7	19/11/18 14:47		General View												1			Load JPG			☒		
8	19/11/18 14:47		General View												1			Load JPG			☒		
9	19/11/18 14:47		General View												1			Load JPG			☒		
10	19/11/18 14:47		General View												1			Load JPG			☒		
11	19/11/18 14:47		General View												1			Load JPG			☒		
12	19/11/18 14:47		General View												1			Load JPG			☒		
13	19/11/18 14:47		General View												1			Load JPG			☒		
14	19/11/18 14:47		General View												1			Load JPG			☒		
15	19/11/18 14:47		General View												1			Load JPG			☒		
16	19/11/18 14:47		General View												1			Load JPG			☒		
17	19/11/18 14:47		General View												1			Load JPG			☒		
18	19/11/18 14:47		General View												1			Load JPG			☒		
19	19/11/18 14:47		General View												1			Load JPG			☒		
20	19/11/18 14:47		General View												1			Load JPG			☒		
21	19/11/18 14:47		General View												1			Load JPG			☒		
22	19/11/18 14:47		General View												1			Load JPG			☒		
23	19/11/18 14:47		General View												1			Load JPG			☒		
24	19/11/18 14:47		General View												1			Load JPG			☒		
25	19/11/18 14:47		General View												1			Load JPG			☒		
26	19/11/18 14:47		General View												1			Load JPG			☒		
27	19/11/18 14:47		General View												1			Load JPG			☒		
28	19/11/18 14:47		General View												1			Load JPG			☒		
29	19/11/18 14:47		General View												1			Load JPG			☒		
30	19/11/18 14:47		General View												1			Load JPG			☒		

Letters/Correspondences			1 per page	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	19/11/18 14:47	General View		☒
32	19/11/18 14:47	General View		☒
33	19/11/18 14:47	General View		☒
34	19/11/18 14:47	General View		☒
35	19/11/18 14:47	General View		☒
36	19/11/18 14:47	General View		☒
37	19/11/18 14:47	General View		☒
38	19/11/18 14:47	General View		☒
39	19/11/18 14:47	General View		☒
40	19/11/18 14:47	General View		☒
41	19/11/18 14:47	General View		☒
42	19/11/18 14:47	General View		☒
43	19/11/18 14:47	General View		☒
44	19/11/18 14:47	General View		☒
45	19/11/18 14:47	General View		☒
46	19/11/18 14:47	General View		☒
47	19/11/18 14:47	Odometer Reading		☒
48	19/11/18 14:47	Chassis Number		☒
49	19/11/18 14:48	Dismantled Parts		☒
50	19/11/18 14:48	Dismantled Parts		☒
51	19/11/18 14:48	Dismantled Parts		☒
52	19/11/18 14:48	Dismantled Parts		☒
53	19/11/18 14:48	Dismantled Parts		☒
54	19/11/18 14:48	Dismantled Parts		☒
55	19/11/18 14:48	Dismantled Parts		☒
56	19/11/18 14:48	Dismantled Parts		☒
57	19/11/18 14:48	Dismantled Parts		☒
58	19/11/18 14:48	Dismantled Parts		☒
59	19/11/18 14:48	Dismantled Parts		☒
60	19/11/18 14:48	Dismantled Parts		☒
61	19/11/18 14:48	Dismantled Parts		☒
62	19/11/18 14:48	Dismantled Parts		☒
Documentation			1 per page	☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 17:19	TP ESTIMATE		☐
2	04/09/18 17:19	TP GIA REPORT		☐
3	07/09/18 17:11	TP ESTIMATE- MARKED		☐
4	22/04/19 14:28	LETTER TO OI		☐
5	23/04/19 12:35	Email to AIG to seek mandaet -SLW 689A		☐
6	13/05/19 08:36	WORKSHOP INVOICE		☐
7	13/05/19 08:36	AUTHORISATION TO ACT FORM		☐
8	13/05/19 08:36	Release Voucher		☐
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/09/18 08:09	TP GIA addendum #1		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SMA3559B (Insd veh)	Model:	AUDI A6 1.8 TFSI S-TRONIC
	SLW689A (TP veh)		(A)
Date of Accident:	26/08/2018		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate	: \$	26,318.79	
Final Repair Cost	: \$	9,898.06	
Loss of Use	: \$	560.00	7.00 days at \$80.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	10,458.06	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	9,898.06
2)	Audi Singapore Pte Ltd	: \$	560.00

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

13 May 2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18016153/GWB3Q2

Date: 13/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800063754

Claimant Vehicle No: SLW689A

Insured Vehicle No: SMA3559B

Date of Loss: 26/08/2018

Nature of Claim: TP

Claim No: 0191875287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW689A

Make & Model: AUDI A6, 1.8 TFSI S-tronic (A)

Engine No: CYG018925

Reg. Date: 26/01/2018 (Man. Year: 2017)

Chassis No: WAUZZZ4G7HN093961

Colour: Silver

Odometer: 6220 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,715.00	5,868.52	8,846.48	60.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,882.00	3,382.00	6,500.00	65.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,597.00	9,250.52	15,346.48	62.39
+ GST 7.00/7.00% (S\$)	1,721.79	647.54	1,074.25	62.39
Nett Amount (S\$)	26,318.79	9,898.06	16,420.73	62.39
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
Nett Liability (S\$)		10,458.06		

INSPECTION

Date of Assignment: 06/09/2018

Date Inspected: 06/09/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Torn	2,519.00 FS	*2,015.20 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	234.00 FS	*- FS
3	1		*FIXING PARTS FOR BUMPER	Not Necessary	25.00 FS	*- FS
4	1		*SECURING STRIP	Necessary	191.00 FS	*152.80 FS
5	4		*STICKY PADS	Not Necessary	20.00 FS	*- FS
6	1		*SPOILER	Cracked	416.00 FS	*332.80 FS
7	1		*SECURING STRIP	Not Necessary	191.00 FS	*- FS
8	2		*CLOSING ELEMENT -LH/RH	Necessary	138.00 FS	*109.44 FS
9	13		*CABLE TERMINAL	Not Necessary	84.00 FS	*- FS
10	2		*REAR BUMPER CARRIER	Not Necessary	92.00 FS	*- FS
11	2		*CONNECTING PIECE	Not Necessary	851.00 FS	*- FS
12	3		*HEX COLLARED	Not Necessary	22.00 FS	*- FS
13	2		*SEAL -LH/RH	Not Necessary	24.00 FS	*- FS
14	1		*GUIDE SECTION -RH	Necessary	28.00 FS	*22.00 FS
15	2		*GUIDE SECTION -RH	Necessary	46.00 FS	*36.08 FS
16	1		*CONNECTING PIECE	Not Necessary	11.00 FS	*- FS
17	1		*GUIDE PROFILEV-RH	Broken	57.00 FS	*45.28 FS
18	1		*GUIDE SECTION -CENTRE	Not Necessary	91.00 FS	*- FS
19	1		*HOLDING STRAP -RH	Cracked	54.00 FS	*42.96 FS
20	1		*SENSOR (3 PCS)	Damaged (1 PCS ONLY)	632.00 FS	*168.40 FS
21	1		*WIRING SET FOR BUMPER	Necessary	603.00 FS	*482.00 FS
22	1		*CONTROL UNIT FOR OPENING BOOT LID	Not Necessary	372.00 FS	*- FS
23	1		*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
24	1		*AUDI LOGO	Not Necessary	108.00 FS	*- FS
25	1		*A 6 EMBLEM	Not Necessary	83.00 FS	*- FS
26	1		*TESI EMBLEM	Not Necessary	83.00 FS	*- FS
27	1		*DECORATIVE TRIM FOR LI	Not Necessary	317.00 FS	*- FS
28	1		*LED TAIL LIGHT -RH OUTER	Cracked	1,094.00 FS	*875.20 FS
29	1		*TRIM FOR TAIL LIGHT	Necessary	26.00 FS	*20.08 FS
30	1		*LED TAILLIGHT -RH INNER	Not Necessary	1,094.00 FS	*- FS
31	1		*TRIM FOR TAIL LIGHT -RH	Not Necessary	26.00 FS	*- FS
32	1		*REAR CROSS PANEL	Not Necessary	274.00 FS	*- FS
33	1		*REINFORCEMENT FOR CROSS PANEL	Not Necessary	639.00 FS	*- FS
34	1		*CONNECTING PLATE -RH LOWER	Not Necessary	39.00 FS	*- FS
35	1		*CENTRE SILENCER	Not Necessary	875.00 FS	*- FS
36	1		*DUAL CLIP	Not Necessary	52.00 FS	*- FS
37	2		*DUAL CLIP	Not Necessary	105.00 FS	*- FS
38	1		*REAR SILENCER -RH	Bent	1,157.00 FS	*925.60 FS
39	2		*DUAL CLIP	Necessary	405.00 FS	*83.68 FS
40	2		*BRACKET	Cracked	100.00 FS	*79.84 FS
41	1		*TRIM FOR EXHAUST TAIL PIPE -RH	Bent	497.00 FS	*397.60 FS
42	1		*CAR PLATE -REAR	Necessary	25.00 FS	*25.00 FS
43	1		*ARCYLIC SEALANT	Not Necessary	180.00 FS	*- FS
44	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
45	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
46	1		*SUNDRIES	Necessary	500.00 FS	*42.96 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,715.00 5,868.52

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENTS	New	1,400.00	0.00
3	TO DISMANTLE REAR BUMPER AND REAR LID .CUT OUT REWELD END PANELLING .RENEW REAR BUMPER .REPAIR RHS REAR FENDER .RE-ORGANISE REARCRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,550.00	1,250.00
4	TO RESPRAY REAR BUMPER ,REAR LID ,RHS REAR FENDER AND END PANELLING .TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,900.00	1,100.00
5	TO REMOVE AND RENEW CENTER AND REAR EXHAUST SILENCER .ALIGN TO POSITION	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,882.00	3,382.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >