

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1027/2018/PH
Date : 4-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SMA 3559 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Audi Singapore Pte Ltd
Address :
Singapore
Telephone : HP +65 92333513
Type of Claim : Third Party Claims
Policy No. : 200819216Z
Vehicle No : **SLW 689 A**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Jan-18
Engine No : CYG 018925
Chassis No : WAUZZZ4G7HN093961
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Aug-18
Place of Accident : Dunearn Road / Shelford Road.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 689 A .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$ 1,400.00	
3	To dismantle rear bumper and rear lid. Cut out reweld end panelling. Renew rear bumper. repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,550.00	
4	To respray rear bumper, rear lid, rhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,900.00	
5	To remove and renew center and rear exhaust silencer. Align to position.	S/N \$ 480.00	
6	To carry out diagnostic check	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 9,882.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER	\$ 2,519.00	
2	FIXING PARTS FOR BUMPER	\$ 234.00	
3	FIXING PARTS FOR BUMPER	\$ 25.00	
4	SECURINMG STRIP	\$ 191.00	
5	STICKY PADS	4 \$ 20.00	
6	SPOILER	\$ 416.00	
7	SECURING STRIP	\$ 191.00	
8	CLOSING ELEMENT -LH/RH	2 \$ 138.00	
9	CABLE TERMINAL	13 \$ 84.00	
10	REAR BUMPER CARRIER	2 \$ 92.00	
11	CONNECTING PIECE	2 \$ 851.00	
12	HEX COLLARED	3 \$ 22.00	
13	SEAL - LH / RH	2 \$ 24.00	
14	GUIDE SECTION - RH	\$ 28.00	
15	GUIDE SECTION - RH	2 \$ 46.00	
16	CONNECTING PIECE	\$ 11.00	
17	GUIDE PROFILEV-RH	\$ 57.00	
18	GUIDE SECTION - CENTRE	\$ 91.00	
19	HOLDING STRAP - RH	\$ 54.00	
20	SENSOR	3 \$ 632.00	
SUB - TOTAL SPARE PARTS CHARGES		\$ 5,726.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	WIRING SET FOR BUMPER	\$ 603.00	
22	CONTROL UNIT FOR OPENING BOOT LID	\$ 372.00	
23	PACKING ADHESIVE	\$ 15.00	
24	AUDI LOGO	\$ 108.00	
25	A' 6 MBLEM	\$ 83.00	
26	TFSI ' EMBLEM	\$ 83.00	
27	DECORATIVE TRIM FOR LI	\$ 317.00	
28	LED TAIL LIGHT - RH OUTER	\$ 1,094.00	
29	TRIM FOR TAIL LIGHT	\$ 26.00	
30	LED TAILLIGHT - RH INNER	\$ 1,094.00	
31	TRIM FOR TAIL LIGHT -RH	\$ 26.00	
32	REAR CROSS PANEL	\$ 274.00	
33	REINFORCEMENT FOR CROSS PANEL	\$ 639.00	
34	CONNECTING PLATE - RH LOWER	\$ 39.00	
35	CENTRE SILENCER	\$ 875.00	
36	DUAL CLIP	\$ 52.00	
37	DUAL CLIP	2 \$ 105.00	
38	REAR SILENCER - RH	\$ 1,157.00	
39	DUAL CLIP	2 \$ 405.00	
40	BRACKET	2 \$ 100.00	
SUB - TOTAL SPARE PARTS CHARGES :		\$ 7,467.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No SLW 689 A .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	TRIM FOR EXHAUST TAIL PIPE - RH	\$ 497.00	
42	CAR PLATE - REAR	S/N \$ 25.00	
43	ARCYLIC SEALANT	S/N \$ 180.00	
44	CAVITY WAX	S/N \$ 140.00	
45	STONE CHIP TREATMENT	S/N \$ 180.00	
46	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS CHARGES		:	\$ 1,522.00
TOTAL LABOUR CHARGES		:	\$ 9,882.00
GRAND TOTAL		:	\$ 11,404.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant