



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV06093/Ms Tay Choon Noi
	Reg No/Reg Date	SJS2255A /
	Date In/Mileage	04/09/2018/ 0
	Chassis No	KNAFX411MJ5762348
	Engine No	G4FGHH692708
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	04/09/2018/ 12:47	DS	218 / MarsLer	64346

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				60 80.00
S MIPNT88088 DIAGNOSTIC / SCANNING				✓ 250.00
S MIPNT88088 TO REMOVE AND RE-INSTALL RAD & A/C CONDENSER TO GIVE WAY ACCESS REPAIR ON FRONT ACCIDENT AFFECTED AREAS				x. 280.00
S MIPNT88088 TO REPLACE FRONT BUMPER, LWR MOULDING, ETC -TO REPLACE TOP SUPPORT PANEL STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS				600 2400.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				x 100.00
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS				920 1260.00
M KS 86511 A7 800 COVER - FRONT BUMPER <i>Repis</i>	1.00	633.00	0.00	+ 633.00
M KS 86350 A7 810 GRILLE ASSY - RADIAT <i>cut</i>	1.00	328.00	0.00	✓ 328.00
M KS 86568 A7 800 RH AIR CURTAIN DUCT <i>new</i>	1.00	6.00	0.00	+ 6.00
P KS 0G032 50 037A CLIP - BUMPER <i>new</i>	10.00	2.00	0.00	✓ 20.00
M KS 86513 A7 000 LH SIDE BRACKET-FR B <i>new</i>	1.00	12.00	0.00	+ 12.00
M KS 86514 A7 000 RH SIDE BRACKET -FR <i>new</i>	1.00	12.00	0.00	x 12.00
M KS 86522 A7 800 MOULDING - FRONT BUM <i>cracked</i>	1.00	70.00	0.00	✓ 70.00
M KS 92202 A7 500 RH FOG LAMP ASSY <i>cut</i>	1.00	241.00	0.00	✓ 241.00
M KS 86520 A7 800 ABSORBER - FRONT BUM <i>new</i>	1.00	84.00	0.00	+ 84.00
M KS 86530 A7 600 RAIL ASSY - FRONT BU <i>new</i>	1.00	496.00	0.00	+ 496.00
M KS 64101 A7 600 CARRIER ASSY - FRONT <i>new</i>	1.00	675.00	0.00	x 675.00
P JJMZ313950 COOLANT <i>new</i>	4.00	26.00	0.00	+ 104.00
P KS 92102 A7 600 RH HEAD LAMP ASSY <i>cut</i>	1.00	1523.00	0.00	✓ 1523.00
Z NOTES ACCIDENT ON 31/08/2018 ALONG BLK 698 HOUGANG ST 61 CARPARK OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV06093/Ms Tay Choon Noi
	Reg No/Reg Date	SJS2255A /
	Date In/Mileage	04/09/2018/ 0
	Chassis No	KNAFX411MJ5762348
	Engine No	G4FGHH692708
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	04/09/2018/ 12:47	DS	218 / MarsLer	64346

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TP #SKD5302U TP INS : CHINA TAIPING				
Estimate				
<p><i>Adrian King</i> 10/09/18 03 Days.</p>				

Confirm & accepted by	Parts	4,204.00
	Labour	0.00
Authorized signatory and company stamp	Standard Menu	0.00
	Specialist Job	4,370.00
	Others (Lub, etc)	0.00
	Sundry	0.00
	Total (w/o GST)	8,574.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.