

Adrian Ling

REF: CC3 / ALG 18016159 / Albez

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____

Veh No: STQ920L Yr Regn: 2016 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi Q5 cc 1984
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 59705 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAU2228 R16A134716
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 235/60R18
 R: 235/60R18

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 145K
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 07885 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 04/09/18
 Survey held at Premium
 Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ALG.
	Part by Part \$7787.52 Used to 28801.80, 77% Out: 13.12.2017
	330 301 - CC3/ALG17023955/Albez
5/9/18	Report via merimen
6/9@14:17pm	authorise repair by victor koh, asking why diagnostic not at \$19200
6/9@2:27	email to premium advise on diagnostic, authorise repair to premium excess \$0

RECEIVED 30 JAN 2018

Date/Time, File Pass to: Prel. Report
 Final Report
 11/30/18
 Date/Time, File Return to: _____
 Report Format: MER-20
 Lump Sum / L.B.I: (\$) 7787.52

Days Of Repair: 7
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$) Interview (\$) Tech. Inv (\$) Wheel cost (\$)
 Survey Fee: 300
 Transportation: _____
 Photo: _____
 Other: _____
0
300

View Received Message

This mail is associated with :

***SJQ920L (0720696510SG)**
OD
Aug 25 2018 10:35AM
[JASON LIM CHYE PENG]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 06/09/2018 14:18 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8381.00) - SJQ920L - Claim Handler: Loo, Tong Shing

Approved:8381.00:Kindly advise why the Diagnostic check not at \$192,00? Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 6 September 2018 3:15 PM
To: Denise Tay (LKKAuto); SUR
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SLQ 920 L

Dear Denise,

For the diagnostic check fee we will amend to \$192.00

Sorry for the misstake.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 6 September, 2018 2:27 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SLQ 920 L

Dear Sir,

AIG is would like to know why the Diagnostic check not at \$192.00? Kindly advise.

As instructed by our client, please proceed to repair the insured vehicle **SLQ 920L (Excess \$0.00/-)**.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Daily Amri, Mimi Zarina

Date: 05 Sep 2018

Preliminary Advice

Vehicle No	: SJQ920L	Accident Date	: 25/08/2018
Make	: AUDI Q5	Policy No.	: 2100477353-01000
Assignment Date	: 04/09/2018	Excess	: S\$0.00
Date of Inspection	: 04/09/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,539.00
Revised Amount	:S\$	7,541.00 8381.
Check Items (Estimated)	:S\$	500.00
Total	:S\$	8,041.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	78,134.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,866.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0671F
Vehicle Details	
Vehicle No.:	SJQ920L
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QU (180 BHP)
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CNC167804
Chassis No.:	WAUZZZ8R1GA134716
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$36,901.00
Original Registration Date:	28 Jul 2016
First Registration Date:	28 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$43,662.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2026
PARF Rebate Amount:	\$32,746.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$45,388.00
Total Rebate Amount:	\$78,134.00

The information contained herein is correct as at 05 Sep 2018

OK

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 05 Sep 2018

Preliminary Advice

Vehicle No	: SJQ920L	Accident Date	: 25/08/2018
Make	: AUDI Q5	Policy No.	: 2100477353-01000
Assignment Date	: 04/09/2018	Excess	: S\$0.00
Date of Inspection	: 04/09/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,539.00
Revised Amount	:S\$	8,381.00
Check Items (Estimated)	:S\$	500.00
Total	:S\$	8,881.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	78,134.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,866.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2018 11:43
Date Of Accident	25/08/2018 10:35
Exact Location Of Accident	KPE NEAR AIRPORT RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ920L
Insured/Policyholder	
Name Of Registered Owner	JASON LIM CHYE PENG
NRIC No	S7300671F
Email Address	JASON.LIM@ERICSSON.COM
Mobile Phone No	(LOCAL) +65-91267795
Alternative Phone No	OFFICE-98290813

Vehicle Particulars

Manufacturer	AUDI
Model	Q5 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100477353-01000
Cover Note Number	

Driver

Name of Driver	JASON LIM CHYE PENG
NRIC No	S7300671F
Date Of Birth	07/01/1973
Occupation	INDOOR
Date Of Driving Pass	15/03/1995
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91267795
Fax Number	
Contact Number	OFFICE-98290813
EMail Address	JASON.LIM@ERICSSON.COM

Address	10 RIVERVALE LINK #16-19
Postcode	545044
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CADEE LIM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NPC
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20180825/2061

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL7825D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ARIF BIN ABDUL
NRIC/Passport Number	S9242082E
Contact Number	87117656
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBL7825D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

28/4/13

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature


Name: Toy Fung

NRIC/IN No:

G2248971

Sketch Plan #2

SKETCH PLAN



A = SJQ920L

Q = FBL7825D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report
NO: T/20180825/2061

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 22/8/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Day Fong
NRIC/FIN No: 62040167E

Police Report



**SINGAPORE
POLICE FORCE**



T/20180825/2061

Police Station Of Origin
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 3
Report No: T/20180825/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/08/2018 12:55	Video Report No.: G/20180825/0093	Station Diary No.: 86
--	--------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: JASON LIM CHYE PENG		Address: 10 RIVERVALE LINK #18-19 SINGAPORE 545044	
ID Type / ID No.: NRIC NO / S7300671F		Contact No.: Home/Office: Mobile: 91267795	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 45	Date of Birth: 07/01/1973	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SALES STAFF		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/08/2018 10:35	Type of Location:
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY KPE towards town just before Airport Road exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Plate No.	Type	Make	Model	Color	Condition	No of Passenger
FBL7825D	Motorcycle					0
BJ2992A	Car	AUDI	Q5 2.0 TFSI QU (180 BHP)	Green	Slightly Damaged	1

Details of Vehicle Insurance			
Insurance Company	Insurance No	Effective	Expiry Date
AIG ASIA PACIFIC INSURANCE PTE LTD	2100477353-02	28/07/2018	27/07/2019

Police Report



**SINGAPORE
POLICE FORCE**



T/20180825/2081

Police Station Of Origin:
Sengkang N. P. C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No: T/20180825/2081

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ARIF BIN ABDUL	ID No	S9242082E
Related Vehicle	FBL7825D (Motorcycle)	Contact No	87117656
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JASON LIM CHYE PENG	ID No	S7300671F
Related Vehicle	SJQ920L (Car)	Contact No	91267795
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/08/18 at about 1037hrs, I was driving my dark green Audi car bearing registration number: SJQ920L, along KPE towards town just before Airport Road exit, when I got involved in a traffic accident with a motorcycle bearing registration number: FBL7825D.

I was travelling on the first lane and the motorcycle was travelling behind. A gray BMW car bearing registration number: SFD9218M was travelling in front of me when the driver of the BMW car suddenly made an abrupt stop while changing to the second lane. As such, I engaged my jam brakes to avoid colliding with him. However, the motorcycle behind me suddenly hit onto the left rear of my vehicle and grazed to the side of my vehicle. The driver of the BMW was Kwok Chi Biu, S6960577Z, hp: 90600289. Ambulance and traffic police were at scene and the motorcycle rider was conveyed to hospital. I have in-vehicle camera of the accident. No one else is injured. That is all.

Police Report



SINGAPORE
POLICE FORCE



T/20180825/2061

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No: T/20180825/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report.

F /

Sr Staff Sgt SITI NORAINI BINTE RAMLI

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

25/08/2018 12:55

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

SN 085

Classification Of Case

Authentication Stamp

NP165

Signature

Singapore Police Force

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7300671F



Name

JASON LIM CHYE PENG

林 財 平

Race

CHINESE

Date of birth

07-01-1973

Sex

M

S7300671F

Country/Place of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Number S7300671F



JASON LIM CHYE PENG

Birth Date: 07 Jan 1973

Issue Date: 19 Jan 2018



002765522D



5842311

NRIC No. S7300671F



Date of issue

04-12-2017

Address

10 RIVERVALE LINK
#10-19
SINGAPORE S45044

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg 15 Mar 1995

NP 428A



Licence No: S7300671F

AUDI AUTO PROTECTOR

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$1000.00 (1)

WINDSCREEN EXCESS S\$100.00

(For policies with effect from 1st November 2002)

CERTIFICATE NO. 2100477353-01000

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SJQ920L

2) NAME OF INSURED

Jason Lim Chye Peng

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

28 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

27 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : 40 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63862323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethos - 30 Bukit Batok Cres (Tel: 65547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479566) 7. Lai Hual (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 18 Jul 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-259
PREMIUM LEASING (PSHS)
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938


AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0989/2018/PH
Date : 29-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr JASON Lim Chye Peng
Address : 10 Rivervale Link
: #16-19
: (S) 545044
Telephone : HP +65 91267795
Type of Claim : Own Damage Claims
Policy No. : 2100477353-01000
Vehicle No : **SJQ 920 L**
Model Code : Audi Q5 2.0 FSI Qu
Model / Year : Jul-16
Engine No : CNC 167804
Chassis No : WAUZZZ8R1GA134716
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Aug-18
Place of Accident : KPE near Airport Rd Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 920 L.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid rear lid kick sensor. Check function.	S/N \$	360.00	✓
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	X
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00 480	✓
4	To remove and reinstall rear seat, back rest, hat tray, ABCD oillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	X
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 3,760.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 920 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To dismantle and renew rear bumper and rear lid. Cut out and weld lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 5,600.00 1250 ✓	1500 ✓
6	To respray rear bumper, rear lower bumper, rear lid, lhs rear fender, lhs sill panel, drain panel, roof channel, door entrances and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,200.00 2200 ✓	✓
7	To carry out diagnostic check	S/N \$ 384.00 ✓	192 ✓
TOTAL LABOUR CHARGES		: \$ 14,944.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJO 920 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Reband</i>	S	1,430.00 ✓ 1144
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	S	143.00 +
3	REAR BUMPER TAIL LIGHT - LH <i>cracked</i>	S	263.00 ✓ 210
4	REAR BUMPER GUIDE SECTION - LH REAR <i>Reband</i>	S	46.00 + 3672
5	GROMMET <i>new</i>	2 S	20.00 +
6	REAR BUMPER SPOILER <i>Reband Repair</i>	S	749.00 +
7	REAR BUMPER CARRIER <i>new</i>	S	571.00 +
8	FIXING PARTS FOR REAR BUMPER <i>new</i>	S	143.00 +
9	HEXAGON HEAD BOLT <i>new</i>	4 S	29.00 +
10	HEX .NUT WITH WASHER <i>new</i>	4 S	7.00 +
11	HEXAGON HEAD BOLT <i>new</i>	4 S	38.00 +
12	SENSOR - OUTER PRIMED <i>new</i>	S	196.00 +
13	REAR LID <i>Repair</i>	S	3,844.00 +
14	ATTACHMENT PARTS FOR REAR LID <i>new</i>	S	106.00 +
15	GASKET FOR FLAP <i>new</i>	S	176.00 +
16	REAR LID STOP BUFFER <i>new</i>	2 S	48.00 +
17	REAR LID STOP BUFFER <i>new</i>	2 S	35.00 +
18	DECORATIVE TRIM FOR LID <i>new</i>	S	377.00 ✓ 301.60
19	FIXING PARTS FOR SPOILER <i>new</i>	S	147.00 +
20	LOCKING CLIP FOR REAR BOOT STRUT <i>new</i>	2 S	41.00 +
SUB TOTAL SPARE PARTS			S 8,409.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 920 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	PACKING ADHESIVE	\$	15.00 ✓ 11.60
22	AUDI LOGO	\$	108.00 ✓ 86.00
23	Q5 EMBLEM	\$	83.00 ✓ 66.16
24	TFSI EMBLEM	\$	83.00 ✓ 66.16
25	QUATTRO EMBLEM	\$	83.00 ✓ 66.16
26	REAR WINDSCREEN <i>not on</i>	\$	1,020.00 *
27	PRIMER <i>not on</i>	2 \$	38.00 *
28	REAR 1/4 GLASS - LH	\$	446.00 *
29	CHROME TRIM STRIPS FOR 1/4 GLASS <i>not on</i>	\$	282.00 *
30	MOLDING - ROOF CHROME	\$	543.00 *
31	SECTIONAL PART - SIDE PANEL - LH <i>Repair</i>	\$	3,913.00 *
32	LED TAIL LIGHT - LH <i>cracked</i>	\$	1,265.00 ✓ 1012
33	COVER - LED TAIL LIGHT <i>not on</i>	\$	42.00 *
34	ARCYLIC SEALANT	S/N \$	180.00 *
35	CAVITY WAX	S/N \$	140.00 *
36	STONE CHIP TREATMENT	S/N \$	180.00 *
37	METAL FILLER POWDER <i>not on</i>	S/N \$	280.00 *
38	REAR WINDSCREEN SEALANT	S/N \$	100.00 *
39	1/4 GLASS SEALANT	S/N \$	100.00 *
40	CAR PLATE - REAR <i>not on</i>	S/N \$	25.00 *
SUB TOTAL SPARE PARTS		:	\$ 8,926.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 920 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	SUNDRIES <i>MRC.</i>	\$ 500.00	<i>74.80</i>
	TOTAL SPARE PARTS	: \$ 17,835.00	
	TOTAL LABOUR CHARGES	: \$ 18,704.00	
	GRAND TOTAL	: \$ 36,539.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

32829.32

36539.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim,
Surveyed Date : 04/09/18 ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 06 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To involve polisher/spray painting
- To involve damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0989/2018/PH 14-Sep-18 Jeffery Tan 1 SJK 920 L Audi Q5 2.0 FSI Qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Vent trim - LHS <i>cracked-</i>	\$ 63.00	<i>✓</i>
		\$ 63.00	

For Premium Automobiles Pte Ltd

Adrian Ling.
A.L.S.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0989/2018/PH
Date : 29-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
We took 7 days with additional repairs
jb 3 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr JASON Lim Chye Peng
Address : 10 Rivervale Link
: #16-19
: (S) 545044
Telephone : HP +65 91267795
Type of Claim : Own Damage Claims
Policy No. : 2100477353-01000
Vehicle No : **SJQ 920 L**
Model Code : Audi Q5 2.0 FSI Qu
Model / Year : Jul-16
Engine No : CNC 167804
Chassis No : WAUZZZ8R1GA134716
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Aug-18
Place of Accident : KPE near Airport Rd Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 920 L.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid rear lid kick sensor. Check function.	S/N \$	360.00	\$ 360.00
2	To renew rear windscreen and lhs 1/4 glass to facillitate fender renewal.	S/N \$	600.00	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 480.00
4	To remove and reinstall rear seat, back rest, hat tray, ABCD oillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 3,760.00	\$ 840.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJQ 920 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
	<i>c/f</i>		\$ 840.00
5	To dismantle and renew rear bumper and rear lid.Cut out and weld lhs rear fender.Re-organise rear crash management components.Reinstall all parts removed.	\$ 5,600.00	\$ 1,500.00
6	To respray rear bumper, rear lower bumper , rear lid, lhs rear fender, lhs sill panel, drain panel, roof channel, door entrances and end panelling.To carry out stone chip treatment and joint sealer works .	\$ 5,200.00	\$ 2,200.00
7	To carry out diagnostic check	S/N \$ 384.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 14,944.00	\$ 4,732.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 920 L .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,430.00	\$ 1,144.00
2	FIXING PARTS FOR REAR BUMPER	\$ 143.00	
3	REAR BUMPER TAIL LIGHT - LH	\$ 263.00	\$ 210.00
4	REAR BUMPER GUIDE SECTION - LH REAR	\$ 46.00	\$ 36.72
5	GROMMET	2 \$ 20.00	
6	REAR BUMPER SPOILER	\$ 749.00	
7	REAR BUMPER CARRIER	\$ 571.00	
8	FIXING PARTS FOR REAR BUMPER	\$ 143.00	
9	HEXAGON HEAD BOLT	4 \$ 29.00	
10	HEX .NUT WITH WASHER	4 \$ 7.00	
11	HEXAGON HEAD BOLT	4 \$ 38.00	
12	SENSOR - OUTER PRIMED	\$ 196.00	
13	REAR LID	\$ 3,844.00	
14	ATTACHMENT PARTS FOR REAR LID	\$ 106.00	
15	GASKET FOR FLAP	\$ 176.00	
16	REAR LID STOP BUFFER	2 \$ 48.00	
17	REAR LID STOP BUFFER	2 \$ 35.00	
18	DECORATIVE TRIM FOR LID	\$ 377.00	\$ 301.60
19	FIXING PARTS FOR SPOILER	\$ 147.00	
20	LOCKING CLIP FOR REAR BOOT STRUT	2 \$ 41.00	
SUB TOTAL SPARE PARTS		\$ 8,409.00	\$ 1,692.32

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 920 L .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			1,692.32
			\$
		c/f	
21	PACKING ADHESIVE	\$	15.00 \$ 11.60
22	AUDI LOGO	\$	108.00 \$ 86.00
23	Q5 EMBLEM	\$	83.00 \$ 66.16
24	TFSI EMBLEM	\$	83.00 \$ 66.16
25	QUATTRO EMBLEM	\$	83.00 \$ 66.16
26	REAR WINDSCREEN	\$	1,020.00
27	PRIMER	2 \$	38.00
28	REAR 1/4 GLASS - LH	\$	446.00
29	CHROME TRIM STRIPS FOR 1/4 GLASS	\$	282.00
30	MOLDING - ROOF CHROME	\$	543.00
31	SECTIONAL PART - SIDE PANEL - LH	\$	3,913.00
32	LED TAIL LIGHT - LH	\$	1,265.00 \$ 1,012.00
33	COVER - LED TAIL LIGHT	\$	42.00
34	ARCYLIC SEALANT	S/N \$	180.00
35	CAVITY WAX	S/N \$	140.00
36	STONE CHIP TREATMENT	S/N \$	180.00
37	METAL FILLER POWDER	S/N \$	280.00
38	REAR WINDSCREEN SEALANT	S/N \$	100.00
39	1/4 GLASS SEALANT	S/N \$	100.00
40	CAR PLATE - REAR	S/N \$	25.00
SUB TOTAL SPARE PARTS		:	\$ 8,926.00 \$ 3,000.40

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0989/2018/PH 14-Sep-18 Jeffery Tan 1 SJO 920 L Audi Q5 2.0 FSI Qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Vent trim - LHS <i>rebound.</i>	\$ 63.00	\$ 50.32
		\$ 63.00	\$ 50.32

For Premium Automobiles Pte Ltd

Adrian Ling
ALS.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJQ 920 L .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 3,000.40
	<i>c/f</i>		
41	Added parts - see attached	\$ 63.00	\$ 50.32
42	SUNDRIES	\$ 500.00	\$ 4.80
	TOTAL SPARE PARTS	\$ 17,835.00	\$ 3,055.52
	TOTAL LABOUR CHARGES	\$ 18,704.00	\$ 4,732.00
	GRAND TOTAL	\$ 36,539.00	\$ 7,787.52

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJQ 920 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0984/2018/MAS

28 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SJQ 920 L Audi A3 Q5 2.0 TFSI Qu

With reference to the above-mentioned vehicle, no. **SJQ 920 L**, claimant, **Mr. Jason Lim Chye Peng**, please find the related document per attached.

1. A copy of the Original invoice no. 85013337 – S\$8,332.65
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJQ 920 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Mail Telephone: 6334 2223
Main Telefax: 6471 5723
Page 1 11:37

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2223
Telefax: 6475 1025

UBI Service Centre
55 Ubi Road 1
Singapore 408724
Telephone: 6781 4000
Telefax: 6741 7127

Customer Service
Service Appointment
Hour Breakdown Service
Email
6466 2323
6428 1215
customer.care@premiumcars.com.sg

INS TAX INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013337 Date : 02/01/2019 Order : SJ00920L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJ00920L (V 30510) Regn Date: 28/07/2016 Mileage: 62884 WIP No.: 22676
Model: 05 2.0 TFSI quattro (180 bhp) Chassis: WAUZZZ8R16A134716 Engine: CNC 167804 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD LHS REAR FENDER.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LOWER BUMPER, REAR LID AND LHS REAR FENDER.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00

Sub-Total	
7% GST	
Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6836 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6888 2222
Telefax: 6473 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2222
Telefax: 6344 1033

Customer Service
Service Appointment: 6584 2323
Hour Breakdown Service: 6628 1233
Email: customer.care@premiumaudis.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 11:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: B5013337 Date : 02/01/2019 Order : SJD0920L Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJD0920L (V 30S10) Regn Date: 28/07/2016 Mileage: 62884 WIP No.: 22676

Model: 05 2.0 TFSI quattro (180 bhp) Chassis: WAUZZZ8R16A134716 Engine: DMC 167804 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A8R0945095	TAILLIGHT	Less 020%	1.00	262.50	210.00
X	A8R0945093C	REVERSING	Less 020%	1.00	1265.00	1,012.00
X	A8R0807303 GRU	BUMPER	Less 020%	1.00	1430.00	1,144.00
X	A8R0853741 2Z2	INSCRIPTION '05'	Less 020%	1.00	82.70	66.16
X	A4G0853737 2Z2	INSCRIPTION 'QUATRO	Less 020%	1.00	82.70	66.16
X	A4H0853737D 2Z2	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	A4H0853742A 2Z2	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	A8D0853419F	PACKING	Less 020%	1.00	14.50	11.60
X	A8R0807453B	GUIDE	Less 020%	1.00	45.90	36.72
X	A8K0819161C	TRIM	Less 020%	1.00	62.90	50.32
X	AN 10596201	NUT	Less 020%	6.00	1.00	4.80
X	A8R0853927 2Z2	HOLDING	Less 020%	1.00	377.00	301.60

Parts	3,855.52	Sub-Total	7,787.52
Labour	0.00	7% GST	545.13
Sublet	4,732.00	Grand Total	8,332.65
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJQ 920 L

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/ 920 /2018/TF
5 Oct 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ8R1GA134716
Vehicle Regn No. : **SJQ 920 L**
Vehicle Mileage : 61381KM
Vehicle Owner : Mr. Jason Lim Chye Peng
Certificate No : 2100477353-01000
Policy Excess : \$0
Accident Date : 25 August 2018
Place : KPE – Near Airport Rd Exit
Repair Cost : \$ 8,332.65
WIP No. : 22676
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

5/10/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7300671F



Name

JASON LIM CHYE PENG

林 財 平

Race

CHINESE

Date of birth

07-01-1973

Country/Place of birth

SINGAPORE

Sex

M

57300671F



5842311

NRIC No. S7300671F



Date of issue

04-12-2017

Address

10 RIVERVALE LINK
#18-19
SINGAPORE 545044

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg	EFFECTIVE DATE
Class 3		15 Mar 1995

NP 428A



AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100477353-01000

(This Certificate is subject to GST)

OWN DAMAGE EXCESS S\$1000.00 (1)

WINDSCREEN EXCESS S\$100.00

(Windscreen Excess Effective From 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SJQ920L

Jason Lim Chye Peng

28 Jul 2017

27 Jul 2018

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : 40 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDER") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, livery, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63562323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortJeep Enorg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 68864501)

4. Fihor - 39 Bukit Batok Cres (Tel: 66547772) 5. Glass Fix - 52 Ubi Ave 3 (Tel: 62760867) - For windscreen only

6. Koh Fook Sing Motor - 81 Delia Lane 12 (Tel: 67479580) 7. Lal Hual (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64938110)

8. Move Automotive - 1003 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

* NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1967 (Malaysia).

Issued in Singapore 18 Jul 2017

AIG Asis Pacific Insurance Pte. Ltd.

604125-259
PREMIUM LEASING (PSHS)
281 ALEXANDRIA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 169038

AUTHORISED REPRESENTATIVE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Sep 2018		04 Sep 2018 17:26 Edit Adj Rpt	S\$7,787.52 Edit Estimates	S\$7,787.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	JASON LIM CHYE PENG , ID: S7300671F, Tel: +6591267795, Email: JASON.LIM@ERICSSON.COM								
Vehicle Reg. No.:	SJQ920L	Date of Loss:	25/08/2018 10:00 - :59 [24 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 0720696510SG	Policy/Cover Note No.:	2100477353-01000 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/09/2018]								
Driver/Custodian:	JASON LIM CHYE PENG (45 / Male), NRIC: S7300671F, Tel: +6591267795								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (06/09/2018): Alert - Adj Mandate Approved (S\$8381.00) - SJQ920L - Claim Handler: Loo, Tong Sh... AIG_SG (05/09/2018): SJQ920L / OD / 25/08/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ920L (0720696510SG)
 OD
 Aug 25 2018 10:35AM
 [JASON LIM CHYE PENG]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>			
Video															1 per page			<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print					
1	28/08/18 12:01	Video - Accident <small>[Linked Accident Report Documents]</small>											Load MP4	<input type="checkbox"/>				
2	28/08/18 12:01	Video - Accident <small>[Linked Accident Report Documents]</small>											Load MP4	<input type="checkbox"/>				
Assessment Reports															1 per page			<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	05/09/18 15:01	Adjuster Immediate Advice											Load HTM	<input type="checkbox"/>				
Photos/Images															3 per page			<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
2	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
3	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
4	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
5	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
6	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
7	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
8	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
9	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
10	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
11	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
12	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
13	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
14	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
15	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
16	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
17	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
18	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
19	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
20	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
21	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
22	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
23	05/09/18 15:06	General View											Load JPG	<input checked="" type="checkbox"/>				
24	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
25	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
26	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
27	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
28	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
29	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				
30	19/12/18 09:43	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>				

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
31	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	19/12/18 09:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/09/18 15:03	Certificate of Insurance	1	Load PDF	
2	05/09/18 15:03	Driver's Driving License and NIRC	1	Load PDF	
3	05/09/18 15:03	estimate	1	Load PDF	
4	05/09/18 15:03	Singapore Accident Statement	1	Load PDF	
5	03/10/18 15:19	SUPPLEMENTARY	1	Load PDF	
6	31/01/19 09:47	Workshop Invoice	1	Load PDF	
7	31/01/19 09:47	Discharge Voucher	1	Load PDF	

Linked Accident Report Documents

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/18 12:01	Video - Accident	1	Load MP4	
2	28/08/18 12:01	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/18 12:07	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/18 11:53	Police Report	1	Load JPG	<input checked="" type="checkbox"/>
2	28/08/18 11:53	Police Report	1	Load JPG	<input checked="" type="checkbox"/>
3	28/08/18 11:53	Police Report	1	Load JPG	<input checked="" type="checkbox"/>
4	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
14	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
15	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
16	28/08/18 11:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/18 11:53	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	28/08/18 11:53	Sketch Plan #2	1	Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016159/ATBE2

Date: 31/01/2019

REFERENCE

Insured/Claimant: JASON LIM CHYE PENG Policy No: 2100477353-01000
Date of Loss: 25/08/2018 Nature of Claim: OD Claim No: 0720696510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ920L**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: CNC167804
Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: WAUZZZ8R1GA134716
Colour: Green Odometer: 59705 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,885.32	3,055.52	14,829.80	82.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,944.00	4,732.00	10,212.00	68.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,829.32	7,787.52	25,041.80	76.28
+ GST 7.00/7.00% (S\$)	2,298.05	545.13	1,752.92	76.28
Nett Amount (S\$)	35,127.37	8,332.65	26,794.72	76.28

INSPECTION

Date of Assignment: 04/09/2018
Date Inspected: 04/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,430.00 FS	*1,144.00 FS
2	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	143.00 FS	*- FS
3	1		*REAR BUMPER TAIL LIGHT - LH	Cracked	263.00 FS	*210.00 FS
4	1		*REAR BUMPER GUIDE SECTION - LH REAR	Damaged	46.00 FS	*36.72 FS
5	2		*GROMMET	Not Necessary	20.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Repair	749.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	571.00 FS	*- FS
8	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	143.00 FS	*- FS
9	4		*HEXAGON HEAD BOLT	Not Necessary	29.00 FS	*- FS
10	4		*HEX NUT WITH WASHER	Not Necessary	7.00 FS	*- FS
11	4		*HEXAGON HEAD BOLT	Not Necessary	38.00 FS	*- FS
12	1		*SENSOR - OUTER PRIMED	Not Necessary	196.00 FS	*- FS
13	1		*REAR LID	Repair	3,844.00 FS	*- FS
14	1		*ATTACHMENT PARTS FOR REAR LID	Not Necessary	106.00 FS	*- FS
15	1		*GASKET FOR FLAP	Not Necessary	176.00 FS	*- FS
16	2		*REAR LID STOP BUFFER	Not Necessary	48.00 FS	*- FS
17	2		*REAR LID STOP BUFFER	Not Necessary	35.00 FS	*- FS
18	1		*DECORATIVE TRIM FOR LID	Necessary	377.00 FS	*301.60 FS
19	1		*FIXING PARTS FOR SPOILER	Not Necessary	147.00 FS	*- FS
20	2		*LOCKING CLIP FOR REAR BOOT STRUT	Not Necessary	41.00 FS	*- FS
21	1		*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
22	1		*AUDI LOGO	Necessary	108.00 FS	*86.00 FS
23	1		*Q5 EMBLEM	Necessary	83.00 FS	*66.16 FS
24	1		*TFSI EMBLEM	Necessary	83.00 FS	*66.16 FS
25	1		*QUATTRO EMBLEM	Necessary	83.00 FS	*66.16 FS
26	1		*REAR WINDSCREEN	Not Necessary	1,020.00 FS	*- FS
27	2		*PRIMER	Not Necessary	38.00 FS	*- FS
28	1		*REAR 1/4 GLASS - LH	Not Necessary	446.00 FS	*- FS
29	1		*CHROME TRIM STRIPS FOR 1/4 GLASS	Not Necessary	282.00 FS	*- FS
30	1		*SECTIONAL PART - SIDE PANEL - LH	Repair	3,913.00 FS	*- FS
31	1		*LED TAIL LIGHT - LH	Cracked	1,265.00 FS	*1,012.00 FS
32	1		*COVER - LED TAIL LIGHT	Not Necessary	42.00 FS	*- FS
33	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
34	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
35	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
36	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
38	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*CAR PLATE - REAR	Not Necessary	25.00 FS	*- FS
40	1		*SUNDRIES	Necessary	500.00 FS	*4.80 FS
41	1		*VENT TRIM - LHS	Deformed	50.32 FS	*50.32 FS
42	1		*MOLDING - ROOF CHROME	Not Necessary	543.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	17,885.32	3,055.52
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	480.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
5	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,500.00
6	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID, LHS REAR FENDER, LHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,200.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			14,944.00	4,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >