



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 05.09.2018

China Taiping Insurance (S) Pte Ltd

2 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
wp
7/9/18 @ 1120
Resurvey after repair
sur @ 11h auto. com
4 days

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2343G HONDA SHUTTLE HYBRID (2017)

To Supply

1) 1pc	Front bonnet	\$	920.80	bt
2) 1pc	Front bonnet left hinge	\$	45.00	bt
3) 1pc	Left front fender	\$	435.00	bt
4) 1pc	Front bumper	\$	1,350.00	de
5) 1set	Front bumper clip	\$	30.00	ue

Sub total parts	\$	2,780.80
Less: 20% discount	\$	(556.16)
	\$	2,224.64

L/charges

1) To remove front bonnet, left front fender & front bumper. Replace front bonnet, front bumper and the above parts. Align & adjust front bonnet.	\$	400.00	300
2) To putty, respray painting front bonnet inlet & outer, front bumper & left front fender. To polish.	\$	650.00	600

Sub total L/charges	\$	1,050.00
Estimated Grand Total	\$	3,274.64