

Survived

MTH

DOI:

ASSIGNMENT

3/9/2018

Date / Time:

3/9/18

Registered in Merimen:

4/9/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SKL 1419B

Name of Insured

TAY JIE QI

Insured Tel No.

HP:

96469165

Excess Sec II:SS

D.O.A:

28/9/2018

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

TAY JIE QI

Driver Tel No.:

91728300

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

17000 76333

Land Rover

Mymonny Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SMC 8596 A



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/9

11/18

SMC 8596 A - X: SKL 1419 B - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

6/9/18

called OAD, no response

6/9/18

called OI, Mr Tay confirm accident details  
inform TP claim. then end call

6/9/18

RECEIVED 26 NOV 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

S\$

5371.02

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

240.00

(\$ 60

x 4

days)

Loss of Income (LOI):

S\$

—

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

5619.02

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5371.02

Name 1:

Performance Motors Ltd.

Payee 2: (Strike if N.A.)

S\$

240.00

Name 2:

Yeow Boon Chin.

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT  
26/11/18



# Car in on 1/9  
- arrange. For survey  
- Pending for liability



BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 AUG 2018

## ESTIMATE

Estimate No. : b1 48258	Page No. : 1 of 5
Date Estimated : 30/08/2018	
Prepared By : Inthiran A/L Thurasamy	

<b>- ESTIMATE REPAIR FOR -</b> <b>Yeow Boon Chin (Yao Wenjun)</b> <b>30 Fernvale Link</b> <b>#06-01</b>  <b>Singapore 797530</b>	<b>- ACCOUNT - 40000</b> <b>Cash Sales - Service</b> <b>Singapore</b>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC8596A	5G87629	26/07/2018	116d	0

DESCRIPTION	VALUE
To replace rear bumper, attachments and repair tailgate.	1720 2,550.00
Painting rear bumper and tailgate.	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install rear side view cameras including program and conduct checks for proper function.	226 266.00
<del>To supply</del> rear emboss number plate.	dd 83.00
Sundries.	80.00

Total Labour 1: **5,079.00**

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER	1	385.25	385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER PRIMED (RFC)	1	947.35	947.35
REAR PDC HOLDER SET	1	23.10	23.10
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
RR PDC SENSOR BLACK SAPPHIRE (475)	2	236.85	473.70
REVERSING CAMERA	1	681.10	681.10

Total Parts : **2,642.65**

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-K



## SUPPLEMENTARY

Estimate No. : b1 48258  
Date Estimated : 30/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Yeow Boon Chin (Yao Wenjun)  
30 Fernvale Link  
#06-01

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 797530

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SMC8596A	5G87629	26/07/2018	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CAMERA SYSTEM *	32.75	1.00		32.75
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

Total Labour :	
Total Parts :	85.80
Total Labour & Parts :	85.80

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 48258  
Date Estimated : 30/08/2018  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Yeow Boon Chin (Yao Wenjun)  
30 Fernvale Link  
#06-01

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 797530

REGN NO	CHASSI S NO	REGN DATE	MODEL	MILEAGE
SMC8596A	5G87629	26/07/2018	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the tailgate and knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and tailgate	1730.00		1,730.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove and install rear side view cameras include programming and conducting checks for proper function	226.00		226.00	
To supply rear emboss number plate.	83.00		83.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CAMERA SYSTEM *	32.75	1.00		32.75
REAR BUMPER PRIMED (RFC)	947.35	1.00		947.35
REAR PDC HOLDER SET	23.10	1.00		23.10
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

### # SUPPLEMENTARY ITEMS

Total Labour :	3,969.00
Total Parts :	1,056.25
Total Labour & Parts :	5,025.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,025.25
GST @7%:	351.77
Grand Total :	5,377.02

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

260, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449771

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/836 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No.	: b1 48258	Page No. : 2 of 5
Date Estimated	: 30/08/2018	
Prepared By	: Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC8596A	5G87629	26/07/2018	116d	0

Vehicle OD : 3rd Party / Uninsured / Insured / Direct Settlement

Claim No. \_\_\_\_\_

Excess \$ \_\_\_\_\_

Surveyor's Name: Tan Jiah Sign: [Signature]

Surveyor's Tel: 97445745 Authorized: Yes / No

Est. Valid Date: \_\_\_\_\_ Date: \_\_\_\_\_

REPAIR PARTS PHOTO BY SURVEYOR: [Signature] (Yes / No) Yes

Remarks: 4 days

Estimate Valid Days Recommended: \_\_\_\_\_

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Labour 1	:	5,079.00
Parts	:	2,642.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	540.52
Grand Total	:	8,262.17

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SM C8596A	Model:	BMW
Date of Accident:	28.8.2018		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	8262.17
Final Repair Cost	: \$	5377.02
Loss of Use	: \$	240.00
Rental (if any)	: \$	
LTA / GIA Search Fee	: \$	2.00
Others	: \$	
	: \$	
Final Settlement Sum	: \$	5619.02

4 days at \$ 60 per day  
days

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Application: Yes / No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	5377.02
2)	Performance Motors Ltd	: \$	2.00
3)	Yeow Boon Chin	: \$	240.00

Signed by appointed surveyor \_\_\_\_\_

Date \_\_\_\_\_

Please attach all the supporting documents to the form.  
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report / Bill (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016164/T1wa3

07 September 2018

**Tay Yuen Chee**  
2 Jalan Sayang  
Singapore 418622

Dear Sir/Madam,

**ACCIDENT INVOLVING SKL 1419B AND SMC 8596A ON 28/08/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, Yeow Boon Chin (the third party claimant) of 30 Fernvale  
Link #06-01 SC 797530 (address), owner of SMC8596A (vehicle no.)  
hereby authorize Performance Motors Ltd ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SMC8596A that was damaged pursuant to the accident which occurred on 28-8-2018  
(date) along Marymount Road (location) involving vehicle no/s  
SKL1419B ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 3 (day) of 9 (month) 2018 (year)



Signed by "the third party claimant"  
(with chop if applicable)

  
Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd, LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 5377-02 (repair costs), S\$ 240-00 (loss of use/~~rental~~) S\$ 2-00 (search fees) for vehicle no. SMC 8596A that was damaged pursuant to the accident which occurred on 28-8-18 (date) along Marymount Road (location) involving vehicle no/s SKL1419B.

This is pursuant to the inspection conducted on 3-9-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Yeow Boon Chih ("third party claimant") of vehicle no. SMC 8596A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SMC 8596A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 day of 11 (month) 20 18 (year)

M11



Signed by AIG appointed surveyor

PERFORMANCE MOTORS LIMITED

303 Alexandra Road  
#01-01/02 Darby Performance Centre  
Singapore 159041  
TEL: 63190130 (Main)  
63190111 (Afternoon)

HP

Chopped & Signed by "the workshop"

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 15740155W GST Reg. No. M2-0823081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438188  
Tel. 63190888 (AfterSales)  
Fax. 63449773

111, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190128 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

(VIV)

## SERVICE TAX INVOICE

Repair Order No. : <b>B1 1297093</b>	Page No. : <b>1 of 2</b>
Date IN : <b>07/09/2018</b>	Invoice Number : <b>2030284 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>15/11/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

## - CUSTOMER INFORMATION -

**Mr Yeow Boon Chin (Yao Wenjun)**  
**30 Fernvale Link**  
**#06-01**

**Singapore 797530**

## - INVOICE TO - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO. / <b>SMC8596A</b>	CHASSIS NO. <b>5G87629</b>	REGN. DATE <b>26/07/2018</b>	MODEL <b>116D</b>	MILEAGE <b>2133</b>
-----------------------------	----------------------------	------------------------------	-------------------	---------------------

## - - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to make good the tailgate and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.

To respray rear bumper and tailgate.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove and install rear side view cameras including program and conduct checks for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 28.8.2018. 3RD PARTY CAR : SKL1419B.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 3.9.2018 AT 12.30 PM. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 6.9.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$60X4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

1,700.00

1,730.00

150.00

226.00

80.00

0.00

0.00

0.00

Total Labour 1: **3,886.00**

## - - - - PARTS - - - -

REAR BUMPER PRIMED (RFC)

REAR PDC HOLDER SET

(DG/SL) ADHESIVE SET K6

HOLDER CAMERA SYSTEM

Qty	Retail Price
-----	--------------

1 947.35

1 23.10

1 53.05

1 32.75

Total Parts : **1,056.25**

NETT

947.35

23.10

53.05

32.75

## - - - - LABOUR 2 - - - -

To supply rear silver emboss lettering black base number plate with bracket.

NETT

83.00

Total Labour 2: **83.00**

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197461359W GST Reg. No. M2-0020001-9



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64787770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190828 (AfterSales)  
63190533/330 (Motorrad)  
Fax. 64794601 (AfterSales)  
64794624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1297093</b>	Page No. : <b>2 of 2</b>
Date IN : <b>07/09/2018</b>	Invoice Number : <b>2030284 / WSB</b>
Cust. Svc. Advisor: <b>Inthiran A/L Thurasamy</b>	Invoice Date : <b>15/11/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>3,889.00</b>	Total Labour & Parts Charges : <b>S\$ 5,025.25</b>
Parts Charges : <b>1,056.25</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 5,025.25</b>
	GST @ 7% : <b>S\$ 351.77</b>
	Invoice Total Amount Include GST : <b>S\$ 5,377.02</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 5,377.02**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-132264  
Date of Request: 28/08/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 28/08/2018  
Enquiry By: Melanie Setiawati  
TP Vehicle No.: SKL1419B  
Accident Date: 28/08/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKL1419B	Sompo Insurance Singapore Pte. Ltd.	30/09/2017-29/09/2018	6461 6555
SKL1419B	AIG Asia Pacific Insurance Pte. Ltd.	09/11/2017-08/11/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-132264

Date of Request: 28/08/2018

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 28/08/2018  
Enquiry By Melanie Setiawati  
TP Vehicle No. SKL1419B  
Accident Date 28/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7503405I



Name

YEOW BOON CHIN  
(YAO WENJUN)

姚文鈞

Race

CHINESE

Date of birth

28-01-1975

Sex

M

Country of birth

SINGAPORE

3678747



NRIC No. S7503405I




Date of issue

22-02-2005

30 FERNVALE LINK #06-01  
SINGAPORE 797530

NRIC No: S7503405I

Date: 31/07/2017





## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018 <a href="#">Edit Reg</a>		03 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,025.25</b> <a href="#">Edit Estimates</a>	<b>S\$5,025.25</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>TAY YUEN CHEE</b> , ID: S1519504E									
Main Claimant: <b>YEOW BOON CHIN</b> , ID: S75034051									
Vehicle Reg. No.: <b>SMC8596A</b>		Date of Loss: 28/08/2018 07:00 - :59 [1 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 4201357192SG</b>		Policy/Cover Note No.: 1700076333 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKL1419B</b>		Policy No. (Claimant): C0085792							
		Excess:							
Repairer: <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com									
Claimant's Insurer: <b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: (65) 6221 8611									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 13/09/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SMC8596A (4201357192SG)**  
**[SKL1419B]**  
**TP**  
**YEOW BOON CHIN**  
**Aug 28 2018 7:00AM**  
**[TAY YUEN CHEE]**  
**Performance Motors Limited**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
<b>Assessment Reports</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/09/18 10:09	<b>Accident Statement</b> <small>From: OD - Reg. No: SKL1419B, Claimant: TAY YUEN CHEE</small>		Load HTM
<b>Photos/Images</b>			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
2	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
3	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
4	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
5	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
6	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
7	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
8	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
9	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
10	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
11	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
12	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
13	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
14	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
15	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
16	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
17	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
18	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
19	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
20	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
21	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
22	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
23	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
24	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
25	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
26	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
27	26/11/18 14:32	General View		Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/18 17:52	TP ESTIMATE + DOCS		Load PDF
2	04/09/18 17:52	TP GIA REPORT		Load PDF
3	05/09/18 09:04	TP ESTIMATE - MARKED		Load PDF
4	28/11/18 09:36	AUTHORISATION TO ACT FORM		Load PDF
5	28/11/18 09:36	WORKSHOP INVOICE		Load PDF
6	28/11/18 09:36	Release Voucher		Load PDF
7	28/11/18 09:36	IC		Load PDF
8	28/11/18 09:36	GIA SEARCH		Load PDF
9	28/11/18 09:36	LETTER TO OI		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKL1419B (Insd veh)	Model:	BMW 116D 1.5 (A)
	SMC8596A (TP veh)		
Date of Accident:	28/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	8,353.97
Final Repair Cost	:	\$	5,377.02
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,619.02

4.00 days at \$60.00 per day  
days

**Is Third Party Workshop GIA Registered?** ☒ YES ☐ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_(%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: \_\_\_\_\_100\_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 5,379.02
2)	Yeow Boon Chin	:	\$ 240.00
3)		:	\$

JOANNE LEE KHANG MIN

28 Nov  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18016164/T1WA3Q2

Date: 28/11/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700076333  
 Claimant Vehicle No: SMC8596A Insured Vehicle No: SKL1419B  
 Date of Loss: 28/08/2018 Nature of Claim: TP Claim No: 4201357192SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMC8596A  
 Make & Model: BMW 116D, 1.5 (A) Engine No: 31305233B37D15A  
 Reg. Date: 26/07/2018 (Man. Year: 2018) Chassis No: WBA1V720805G87629  
 Colour: Black Odometer: 2123 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/35 R18 Rear Tyre Size: 245/35 R18  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,891.45	1,219.25	1,672.20	57.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,916.00	3,806.00	1,110.00	22.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,807.45</b>	<b>5,025.25</b>	<b>2,782.20</b>	<b>35.64</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>546.52</b>	<b>351.77</b>	<b>194.75</b>	<b>35.63</b>
<b>Nett Amount (S\$)</b>	<b>8,353.97</b>	<b>5,377.02</b>	<b>2,976.95</b>	<b>35.64</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		<b>240.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>5,619.02</b>		

## INSPECTION

Date of Assignment: 03/09/2018  
 Date Inspected: 03/09/2018 Inspected At:

Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Dented	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
3	1		*REAR BUMPER CARRIER	Not Necessary	385.25 FS	*- FS
4	1		*REAR BUMPER CENTRE GUIDE (M)	Not Necessary	57.45 FS	*- FS
5	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	54.50 FS	*- FS
6	1		*REAR BUMPER PRIMED (RFC)	Deformed	947.35 FS	*947.35 FS
7	1		*SET REAR PDC HOLDER	Necessary	23.10 FS	*23.10 FS
8	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
9	2		*RR PDC SENSOR BLACK SAPPHIRE (475)	Not Necessary	473.70 FS	*- FS
10	1		*REVERSING CAMERA	Not Necessary	681.10 FS	*- FS
11	1		*HOLDER CAMERA SYSTEM	Necessary	32.75 FS	*32.75 FS
12	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (\$\$)					2,891.45	1,219.25

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,ATTACHMENTS AND REPAIR TAILGATE	New	2,550.00	1,700.00
2	PAINTING REAR BUMPER AND TAILGATE	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL REAR SIDE VIEW CAMERAS INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	266.00	226.00
Gross Labour Cost (S\$)			<b>4,916.00</b>	<b>3,806.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >