

Car in on 1/9
- arrange for survey
- Pending for liability



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 AUG 2018

ESTIMATE

Estimate No.	: b1 48258	Page No. : 1 of 5
Date Estimated	: 30/08/2018	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR -
Yeow Boon Chin (Yao Wenjun)
30 Fernvale Link
#06-01

Singapore 797530

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC8596A	5G87629	26/07/2018	116d	0

DESCRIPTION	VALUE
To replace rear bumper, attachments and repair tailgate.	1700 2,550.00
Painting rear bumper and tailgate.	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install rear side view cameras including program and conduct checks for proper function.	226 266.00
To supply rear emboss number plate.	del 83.00
Sundries.	? 80.00

Total Labour 1: 5,079.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER	1	385.25	? 385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	? 57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER PRIMED (RFC)	1	947.35	del 947.35
REAR PDC HOLDER SET	1	23.10	del 23.10
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	del 20.20
RR PDC SENSOR BLACK SAPPHIRE (475)	2	236.85	? 473.70
REVERSING CAMERA	1	681.10	? 681.10

Total Parts : 2,642.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48258
Date Estimated : 30/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC8596A	5G87629	26/07/2018	116d	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 3/9/18 e 1230 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Inthiran

Surveyor's Tel 9749574 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Tan Jiah

No. of Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,079.00
Parts	:	2,642.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	540.52
Grand Total	:	<u>8,262.17</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **