

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not allowed
 that
 2/5 @ 4100/c
 4 day.
 10/9/18
 The Ins. Attorney -

DATE 10/9/2018
 M/S AXA INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SFB2020Y (TOYOTA RUSH)

LIST PRICE

TO SUPPLY :

01)	1 PC	TAILGATE	Body	\$ 819.80	---
02)	1 PC	TAILGATE RUSH EMBLEM	nu	\$ 113.20	---
03)	1 PC	REAR W/S MOULDING	nu	\$ 69.20	---
04)	1 PC	REAR BUMPER	no/De	\$ 997.60	---
188 05)	13 PCs	REAR BUMPER CLIPS	nu	\$ 38.00	---
06)	1 PC	NUMBER PLATE LAMP	CR	\$ 62.90	---
07)	1 PC	LH TAILLAMP	CR	\$ 449.70	---
08)	1 PC	SPARE TYRE COVER	3rd	\$ 1,536.80	---
09)	1 PC	SPARE TYRE COVER INNER	CR	\$ 395.80	---
				\$ 4,483.00	
LESS 20% 25%				\$ (896.60)	
				\$ 3,586.40	
10)	1 PC	NUMBER PLATE	CR	\$ 40.00	✓ S.N
11)	1 PC	PARKING SENSOR	nu	\$ 280.00	✓ S.N
12)	Rear windscreen	SEALANT	nu	\$ 40.00	✓ S.N
13)	Disassemble	SENSOR LABOUR		\$ 80.00	-50
14)		W/S LABOUR To disassemble & refix rear windscreen		\$ 150.00	120
15)	1 PC	SPRAY PAINTING		\$ 880.00	800
16)		LABOUR CHARGE		\$ 900.00	600
17)		TUFF COAT		\$ 80.00	50
18)		WIRING CHECK		\$ 50.00	20
19)		TO REMOVE AND REFIX GARNISHES ,LUGGAGE TRIM ETC		\$ 100.00	60
				\$ 6,186.40	

5142.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: