

樹 發 汽 車 修 理 廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo 6th September 2018 TP Alb

EE 7700 G TOYOTA PREVIA

EE //00 G	101	OTAPREVIA	S\$
Spare Parts	1	Rear boot.	1850.00 1
	1	Rear boot logo.	96.00 nec
	1	Rear boot centre chrome garnish.	285.00 X
	1	Rear boot lock.	485.00 ?
	1	Rear boot rubber.	385.00?
	1	Rear windscreen moulding.	185.00 rec
	1	Rear support panel.	775.00 RX
	1	Rear panel inner garnish.	420.10 X
	1	Rear panel lower garnish.	285.00 ?
	2	Rear tail light lower retainers. @\$68/-	136.00 ?
	2	Rear bumper tow covers. @\$38/-	76.00 ?
	2	Left rear bumper reflectors. @\$75/-	150.00×
	1	Rear bumper	1550.00 de
	2	Rear bumper foams. @\$115/-	230.00 ?
	1	Set rear bumper clips.	60.00 Nec
	2		130.00 ?
	1	Rear bumper side retainers. @\$65/-	45.00 Snet NC
	1	Rear windscreen inner seal. Rear windscreen sealant.	60.00 Snet AL
	1		00.00
	1	Set rear reverse sensors.	280.00 Snet 200
			7483.10
		Less 25%	1774.52
			5708.58
' Labour		To brook straighten rear inner panel rear lower panel	1250.00 700
Labour		To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, rear lower member, left rear fender, rt rear fender, renew rear boot, rear support panel, rear lights, rear bumper and	1250.00 400
		assembly.	1050.00700
		To respray damaged parts.	180.00 120
		To remove, replace rear windscreen.	
		To remove rear seats, upholstery, garnishes, side covers, low covers to facilitate repairs and assembly.	240.00 Go
		To reseal joints, reinsulate, anti rust panels and assembly.	120.00 ?40
			8548.58

LKK Auto Consultants hence notify the Repairer of the following R16

- Torresurvey Derdre/Shiet Edring Derling \011161
- Toydisplay damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufum 97-195760 S/9/18 Resurg effer repair. 4-5 days sur @ Whanto won Repair limt \$4000