

REF:

Surveyor: N/A

REF:

NS/INC18016177/NS607 TAX/08/18/2119

5269 K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLP 4398A

Policy No. 509160 0855-01 050618 - 040619

Claims No. MT/1009707 - 002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 5015U Yr Regn: 3 NOV/201

Typr M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIMA C.C. 1,798

Colour BROWN A/C: Insured / Std / Nil /

Sp. Reading N/A (can't start) T/Rado: Insured / Std / Nil /

Eng/No: _____

C/No: JTDKB3FU103573566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Op / Jammed / Leaked / Burnt or

Brake: In Op / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAKED

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/8/18 D.O.I. 4/9/18

Survey held at SMART WOODLAND J

Des. of Damages: Frt / Rev / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	SHB 5015U - NS/INC15015531 / K16b2
	SLP 4398A - NA/INC18015908 / 21
22/10/18	Continued P/P \$ 3,240.23 @ 4 days with NAZ. (\$ 3,832.39 Red - 54%)
	RECEIVED 2 OCT 2018

Date/Time, File Pass to? : Preli. Report

22/10/18

1) Typist : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation: _____

Add Fee: : Site Insp (\$) S + RS \$

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format: _____

Lump Sum / I.B.I: (\$ 3,240.23 P/P)

TOTAL 160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18016177/Nsb

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 05-09-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 4398A	Veh. Inspected	SHB 5015U
Policy No.	5091600855-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/08/2018	Inspection Date	04/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No.

Vehicle No. (For Motor)

Date of Accident

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="checkbox"/>	5091600855-01		TWINCAR RENTAL	53092815M	GPC	drive CLASSIC	SLP4398A	SLP4398A	05/06/2018	04/06/2019

Continue

TP Claims against NTUC Income: Follow-Through Survey

Date : 22/10/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1009707-002	SMRT TAXIS PTE LTD	SHB 5015U	SLP 4398A	31/8/2018	19:20	\$ 7,072.62	\$ 3,240.23
2	MT/1013435-002	SMRT TAXIS PTE LTD	SHB 5745X	PC 2617C	26/9/2018	11:45	\$ 2,036.57	\$ 857.92
3	MT/1015544-002	COMFORT TRANSPORTATION PTE LTD	SHC 8693L	SMC 3338L	13/10/2018	22:30	\$ 740.00	\$ 500.00

Claim received from LKK Auto

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
<YeoPohsuan@smrt.com.sg>
Sent: Sunday, 21 October 2018 8:30 AM
To: Naz (LKKAuto)
Cc: SUR
Subject: RE: SHB5015U

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Naz (LKKAuto) [mailto:Naz@lkkauto.com]
Sent: Saturday, 20 October 2018 12:03 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Cc: SUR
Subject: Re: SHB5015U

Dear Ms Yeo,

Finalized Part by Part Repair \$3,240.23 / 4 Days.

Please take note of my remarks on the last page. Kindly change the circled item to LH FRONT DOOR.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ms Lee (Lee Sheng Auto) <ekchen_lee@leeshengauto.com.sg>
Sent: Thursday, 18 October 2018 4:54 PM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))'; Naz (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB5015U

Best regards

Ms Lee Ek Chen
Lee Sheng Auto Pte Ltd
1, Kaki Bukit Ave 6 #01-60, Autobay@KB . S(417883)
Tel : 67477397 Fax : 67457138
Email : ekchen_lee@leeshengauto.com.sg

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
[<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Thursday, 18 October, 2018 3:40 PM
To: Naz (LKKAuto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: SHB5015U

Hi Naz,

Attached herewith the repair estimate of SHB 5015U having Case No:
TAX/08/18/2119.

There is no change to the approved amount of \$3,240.23 @ 4 working days
under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Thursday, 18 October 2018 3:34 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 08:22
Date Of Accident	31/08/2018 19:20
Exact Location Of Accident	TANGS PLAZA EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5015U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	CHAN CHIOK HOONG
NRIC No	S1233676D
Date Of Birth	11/03/1957
Occupation	INDOOR
Date Of Driving Pass	05/12/1980
Driving Experience	37 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS EXITING TANG PLAZA TURNING LEFT TOWARDS SCOTTS ROAD WITH TWO PASSENGERS (EURASIAN COUPLE) ON BOARD. WHILST I WAS TURNING LEFT, THERE WAS A VEHICLE SLP4398A ON MY LEFT WHICH WAS ALSO TURNING LEFT. WHILST TURNING BOTH VEHICLES SIDE SWIPED EACH OTHER CAUSING DAMAGES TO BOTH VEHICLES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP4398A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	STEVEN TAN
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


01/09/18
Driver's Signature
(If driver is not the policyholder)
Date & Time:


1/9/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SH B 5015U Ref. No. TAX 8 / 18 / 2119

Make / Model : TOYOTA PRIUS 4 Reg. Date : 03/11/2017

Name of Driver : CHAN CHIOK HOONG

Date/Time of Accident : 31/08/2018

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097787

Special Instruction to ARC, if any :

Signed : _____ Date : _____



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : _____ Mileage : _____

Date Prepared : 03/09/2018 16:18 Repair Completed date/time: _____

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>845</u>	\$ _____
Total Spray Painting Charges :	\$ <u>1296</u>	\$ _____
Total Material Charges :	\$ <u>4,175.58</u>	\$ _____
Other Charges :	\$ <u>756</u>	\$ _____
TOTAL :	\$ _____	\$ _____ ()
No. of Repair Days :	[<u>6</u>] days	[<u>4</u>] days
Signature :	Prepared by: <u>MING</u> 03/09/2018 16:18	Adjusted by: _____

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Section D - Details of Repair Estimates

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845	600
Total Labour	\$ 845	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378	200
TO RESPRAY RIM	180	80
TO RESPRAY FRONT DOOR LH	378	200
TO RESPRAY ROCKER PANEL MOULDING	180	100
TO RESPRAY FRONT PILLAR LH	180	X n n
Total Spray Painting & Panel Beating	\$ 1296	\$

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56	X n n
TO CHECK WIRING AND SYSTEM FUNCTION	80 20	
TO APPLY RUST-PROOFING ON AFFECTED AREA	100	40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120	X n n
TO TRANSFER DOOR MECHANISM	120	50
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120	X
TO WASH AND VACUUM	60	X n n
TO REPLACE SUNDRY PARTS	100	X n n
Total Other Costs	\$ 756	\$

Section D - Details of Repair Estimates

Part 4 - Spare Parts / Material Usage



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63655582
Estimator Telephone Number 6662623
Accident Reporting Number 6662672

Date Generated : 18/10/2018

User ID : PehSuan

Section A - Accident Details

Registration Number	SHB5015U
Case Reference Number	TAX/08/18/2119
Registration Date	03/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHAN CHIOK HOONG
Type of Accident	Side Swipe
Accident Date and Time	31/08/18 7:20 PM
Accident Reported Date and Time	01/09/18 11:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097787
Special Instruction to ARC, if any	
Prepared Date and Time	14/10/18 11:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 767706
FAX Number 63005592
Estimator Telephone Number 99862823
Accident Reporting Number 80662572

Date Generated : 18/10/2018

User ID : PohSuan

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,296.00	\$580.00
Total Spare Part Cost	\$4,175.62	\$1,950.23
Total Other Cost	\$756.00	\$110.00
TOTAL COST	\$7,072.62	\$3,240.23 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1810-0359	Invoice Number	
Quotation Date	18.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$80.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$580.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 18/10/2018
 User ID : PohSuan

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$756.00	\$110.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
		7537447140	EMBLEM, SIDE PANEL (1.00	\$52.90	25.00	\$39.67	Replace	Replace
	UNDERCARRIAGE	5382847070	PROTECTOR, FR FENDER LH	1.00	\$90.40	25.00	\$67.80	Replace	Replace
		5387647110	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair
	BODY LH	6700247162	PANEL SUB-ASSY, FRONT	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace
			STICKER DECAL SMRT	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	25.00	\$0.00	Replace	Not Given
	BODY LH	6874012120	HINGE ASSY, FRONT DOOR ,	0.00	\$92.10	25.00	\$0.00	Replace	Not Given
	BODY LH	6872012151	HINGE ASSY, FRONT DOOR ,	0.00	\$82.10	25.00	\$0.00	Replace	Not Given
	BODY LH	6101447010	PILLAR, FRONT BODY, LH	0.00	\$339.40	25.00	\$0.00	Replace	Not Given
		7586047900	MOULDING ASSY, BODY	1.00	\$576.00	100.00	\$0.00	Replace	Repair
Total					\$5,505.24		\$1,950.23		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1950.24
 + 600.00
 + 690.00

 3240.24



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
30 Woodlands Industrial Park #4, Singapore 737203
Fax Number: 63655582
Estimator Telephone Number: 06555803
Accident Reporting Number: 95662872

Date Generated: 16/10/2018
User ID: PehSuan

Shirley

Section A - Accident Details	
Registration Number	SHB5015U
Case Reference Number	TAX/08/18/2119
Registration Date	03/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHAN CHIOK HOONG
Type of Accident	Side Swipe
Accident Date and Time	31/08/18 7:20 PM
Accident Reported Date and Time	01/09/18 11:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097787
Special Instruction to ARC, if any	
Prepared Date and Time	14/10/18 11:58 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 50 Woodlands Industrial Park E4 Singapore 157705
 FAX Number: 63685582
 Operator Telephone Number: 08002023
 Accident Reporting Number: 5002517

Date Generated: 18/10/2018
 User ID: PehSuan

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,296.00	\$580.00
Total Spare Part Cost	\$4,175.62	\$1,950.23
Total Other Cost	\$756.00	\$110.00
TOTAL COST	\$7,072.62	\$3,240.23 (PIP)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date		
Signature	<input type="checkbox"/>	<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1810-0359	Invoice Number	
Quotation Date	18.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$80.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$580.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park East, Singapore 737758
 Fax Number: 67665592
 Estimator Telephone Number: 8865203
 Accident Reporting Number: 8862872

Date Generated: 18/10/2018
 User ID: PanBuan

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$50.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$766.00	\$110.00

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	DEF
		7537447140	EMBLEM, SIDE PANEL (1.00	\$52.90	25.00	\$39.67	Replace	Replace	NEC
	UNDERCARRIAGE	5382847070	PROTECTOR, FR FENDER LH	1.00	\$90.40	25.00	\$67.80	Replace	Replace	DEF
		5387647110	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace	DEF
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X SVL
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	X R
	LH FRONT DOOR	8700247162	PANEL SUB-ASSY, FRONT	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace	DEF
			STICKER DECAL SMRT	1.00	\$60.00	0.00	\$60.00	Replace	Replace	NEC
		8861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	25.00	\$0.00	Replace	Not Given	X SVL
	BODY LH	6874012120	HINGE ASSY, FRONT DOOR	0.00	\$92.10	25.00	\$0.00	Replace	Not Given	X SVL
	BODY LH	6872012151	HINGE ASSY, FRONT DOOR	0.00	\$82.10	25.00	\$0.00	Replace	Not Given	X SVL
	BODY LH	8101447010	PILLAR, FRONT BODY, LH	0.00	\$339.40	25.00	\$0.00	Replace	Not Given	X SVL
		7585047900	MOULDING ASSY, BODY	1.00	\$576.00	100.00	\$0.00	Replace	Repair	X R
Total					\$5,505.24		\$1,950.23			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

CONFIRMED PART BY PART REPAIR
 \$3240.23 / 4 DAYS
 * Please amend item no. 6700247162
 to LH FRONT DOOR.

1950.23
 + 600.00
 + 690.00

 3240.23

8402.24



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	NS/INC18016177/Nsbe2	
73 BRAS BASAH ROAD		Date:	08-11-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 4398A	Veh. Inspected	SHB 5015U	
Policy No.	5091600855-01	Coverage (\$)	0.00	
Claim No.	MT/1009707-002	Excess (\$)	0.00	
Assign From		Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU103573566	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2018	Inspection Date	04/09/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5015U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER SUB-ASSY, FR, LH (DISC 25%)	DEFORMED	933.10	699.83
1	EMBLEM, SIDE PANEL (DISC 25%)	NECESSARY	52.90	39.67
1	PROTECTOR, FR FENDER LH (DISC 25%)	DEFORMED	90.40	67.80
1	LINER, FR FENDER, LH (DISC 25%)	DEFORMED	194.30	145.73
1	LH FRONT DOOR (DISC 25%)	DEFORMED	1,249.60	937.20
1	STICKER DECAL SMRT (SN)	NECESSARY	60.00	60.00
1	TYRE	SERVICEABLE	126.74	-
1	CHECK ASSY, FRONT DOOR	SERVICEABLE	153.50	-
1	HINGE ASSY, FRONT DOOR	SERVICEABLE	92.10	-
1	HINGE ASSY, FRONT DOOR	SERVICEABLE	82.10	-
1	PILLAR, FRONT BODY, LH	SERVICEABLE	339.40	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
1	MOULDING ASSY, BODY	TO REPAIR SEE LABOUR	576.00	-
			5,505.24	1,950.23
LABOUR				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL, DISC FRONT AND MOULDING ASSY, BODY.			845.00	600.00
SPRAY PAINT.			1,296.00	580.00
TOWING CHARGE.			56.00	-
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			120.00	-
TO TRANSFER DOOR MECHANISM.			120.00	50.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)			120.00	-
TO WASH AND VACUUM.			60.00	-
TO REPLACE SUNDRY PARTS.			100.00	-
			2,897.00	1,290.00

Report Ref No. NS/INC18016177/Nsbe2

GRAND TOTAL		8,402.24	3,240.23
RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,240.23

Report Ref No. NS/INC18016177/Nsbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.