

10/01/2018

INS. CASE OWNER:

CC 4/1111801

WBO

R2eb3

LKK:

IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT

5/1/18

Date / Time:

5/1/18

Registered in Merimen:

5/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLJ 7467X

Name of Insured:

TIEW WONG HENG (DECEASED)

Insured Tel No.:

HP:

4/1/18

Excess Sec II :SS

D.O.A.:

Claim No.:

MLW150078

Policy No.:

MOB117/13/200

Make / Model:

MERCEDES

Place of Accident:

BEDOK WORTH RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

TIEW KYE TIE

OI GIA REPORT

YES

NO

TP GIA REPORT:

YES

NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SGM 7467T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan
Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/1/18
Mshir

12.9.18

SGM 7467T

SLJ 7467X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Handler

Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: #125

Repair Cost:

45 \$52,100

(5 days) Reduction:

46 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 11.12.18

Confirm with: JOMMASON

Email ☐ Call ☐

Final Liability:

9 \$10

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28. Ass. Lia:

Repair Cost:

9 \$52,241.00

OID REAR ENDED P.

Loss of Rental (LOR):

4 \$5

(45 days) +100

Loss of Use (LOU):

\$5

(5 x days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only ☐

LOU only ☐

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

380

Total:

\$52,248.50

Global Sum \$5:

FINAL PAYMENT

Date/Time: 11.12.18

Confirm with: JOMMASON

Email ☐ Call ☐

Payee 1:

\$52,248.50

Name 1:

TAN LIM MING PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18016180/R1eb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 05-09-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 7467X	Veh. Inspected	SJM 7927T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/09/2018	Inspection Date	05/09/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2018)
 Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Meriman Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*rear bumper	25.00	0.00	438.40 FL ✓
2	1		*rear bumper parking sensor	0	0.00	200mm 250.00 FS 20031 ✓
3	1		*o/s rear bumper bracket	25.00	0.00	55.60 FL ✓
4	1		*o/s rear bumper side retainer	25.00	0.00	99.60 FL ✓
5	1		*o/s rear bumper side holder	25.00	0.00	98.80 FL ✓
6	8		*rear bumper clips	25.00	0.00	30.40 FL ✓
7	1		*rear bumper reflector accessory	0	0.00	150.00 FS 10 S/W ✓
8	1		*o/s rear lamp	25.00	0.00	368.80 FL ✓
9	3		*o/s rear lamp clip holder	25.00	0.00	12.90 FL ✓
10	1		*rear end panel	25.00	0.00	488.00 FL ✓
11	1		*rear end panel inner trim	25.00	0.00	195.00 PC ✓

F=Franchise part, S=SpotNet, L=List Item Disc.

Sub Total (S\$) 2,366.70
 - List Item Discount on L Items (S\$) 441.68

Total Parts (S\$) 1,925.02

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

part → \$1515.30 × 25% = \$1136.48 ✓
 part sp Net → 210.00 ✓
 Labor → 1310.00
 \$2656.48
 20% 531.29
 2125.19

L/m \$2100 × 5 days

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2018)
 Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*bootlid	25.00	0.00	repair *710.00 FL
2	1		*bootlid weatherstrip	25.00	0.00	no } X *185.00 FL
3	1		*bootlid lock	25.00	0.00	X *96.00 FL
4	1		*bootlid x badge	25.00	0.00	no / *36.60 FL
5	1		*bootlid Axio badge	25.00	0.00	no / *43.60 FL
6	1		*bootlid centre logo badge	25.00	0.00	no / *61.00 FL
F=Franchise part. L=List Item Disc.						
Sub Total (\$\$)						1,132.20
- List Item Discount on L Items (\$\$)						283.05
Total Parts (\$\$)						849.15

Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 OD/TP Case (Insurer)	10.00
Sub Total (S\$)		10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To check electrical lighting concerned.	New	30 80.00
2	To reinstall of rear bumper parking sensor.	New	60 120.00
3	To rust-proofing of the affected areas.	New	40 100.00
4	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	80 150.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	500 780.00
6	Putty and spray painting of the affected portion.	New	600 750.00
Gross Labour Cost (S\$)			1,960.00

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-9922054-2

Rasul @ LKKAuto.com

Rasul

Hp 90010068

5 days

48

05/09/18 @ 1535

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
In the estate of Tiew Leong Heng

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP004092018
Policy No:		Date of Loss:	04/09/2018
Vehicle Reg. No.:	SJM7927T	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOW CHONG GIAP	Driver (Insured):	TIEW KYE JIE
Make/Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Vehicle Reg. Date:	15/01/2009
Vehicle Colour:	WHITE		
Engine No:	1NZD191931	Chassis No:	NZE1416096851
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Description of Accident/Loss: ON 04.09.2018 AT ABOUT 0610HRS, I WAS DRIVING MY VEHICLE (A: SJM7927T) ALONG 3RD LANE OF BEDOK NORTH ROAD WITH NORMAL SPEED. SUDDENLY, I FELT AN IMPACT FROM BEHIND AND REALIZE THAT THERE IS A VEHICLE (B: SLJ7467X) CUT IN FROM MY RIGHT AND HIT ONTO REAR RIGHT PORTION OF MY VEHICLE. VEHICLE A (SJM7927T): 1 FEMALE PASSENGER ON BOARD. VEHICLE B (SLJ7467X): NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

Parts	1,925.02
Miscellaneous Items	10.00
Labour	1,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,895.02
+ GST 7.00% (S\$)	272.65
Nett Amount (S\$)	4,167.67

This claim is handled by: OW CAYMEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2018)
Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*rear bumper	25.00	0.00	De - *438.40 FL
2	1		*rear bumper parking sensor	0	0.00	200mm / 450.00 FS
3	1		*o/s rear bumper bracket	25.00	0.00	ren / *55.60 FL
4	1		*o/s rear bumper side retainer	25.00	0.00	re X *99.60 FL
5	1		*o/s rear bumper side holder	25.00	0.00	X *98.00 FL
6	8		*rear bumper clips	25.00	0.00	ren / *30.40 FL
7	1		*rear bumper reflector accessory	0	0.00	ren / *150.00 FS 10
8	1		*o/s rear lamp	25.00	0.00	ren / *368.80 FL
9	3		*o/s rear lamp clip holder	25.00	0.00	ren / *12.90 FL
10	1		*rear end panel	25.00	0.00	re / *468.00 FL
11	1		*rear end panel inner trim	25.00	0.00	X *195.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,366.70
- List Item Discount on L Items (S\$)	441.68
Total Parts (S\$)	1,925.02

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Sep 2018)

Parts: 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*bootlid	25.00	0.00	repair ✓ *710.00 FL
2	1		*bootlid weatherstrip	25.00	0.00	X *185.00 FL
3	1		*bootlid lock	25.00	0.00	X *96.00 FL
4	1		*bootlid x badge	25.00	0.00	re ✓ *36.60 FL
5	1		*bootlid Axio badge	25.00	0.00	re ✓ *43.60 FL
6	1		*bootlid centre logo badge	25.00	0.00	re ✓ *61.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

1,132.20

- List Item Discount on L Items (S\$)

283.05

Total Parts (S\$)

849.15

Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check electrical lighting concerned.	New	30 60.00
2	To reinstall of rear bumper parking sensor.	New	60 120.00
3	To rust-proofing of the affected areas.	New	40 100.00
4	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	80 150.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	500 780.00
6	Putty and spray painting of the affected portion.	New	600 750.00
Gross Labour Cost (S\$)			1,960.00

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
Hp 90010068
5 days
4/8
05/09/18 @ 1535
Resy after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1085G

Vehicle Details

Vehicle No.: SJM7927T
Vehicle to be Exported: No
Intended Deregistration Date: 04 Sep 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: 1N2D191931
Chassis No.: NZE1416096851
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$12,593.00
Original Registration Date: 15 Jan 2009
First Registration Date: 15 Jan 2009
Transfer Count: 1
Actual ARF Paid: \$12,593.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Jan 2019
PARF Rebate Amount: \$6,296.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$12,001.00
COE Rebate Amount: \$395.00
Total Rebate Amount: \$6,691.00

The information contained herein is correct as at 04 Sep 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle & Vehicle Information	
Owner ID Type:	Singapore NRIC
Owner ID:	1085G
Vehicle Details	
Vehicle No.:	SJM7927T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1N2D191931
Chassis No.:	NZE1416096851
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,593.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$12,593.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2019
PARF Rebate Amount:	\$6,296.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$12,001.00
COE Rebate Amount:	\$392.00
Total Rebate Amount:	\$6,688.00

The information contained herein is correct as at 05 Sep 2018

OK

10,000
6688

3312

3k

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	04 Sep 2018 15:01	Cim Veh Model Changed	(202186) TOYOTA COROLLA 1.5 AXIO (A).	[R] Ow Caymen
2	04 Sep 2018 15:01	Cim Created	Reg No: SJM7927T, Acct Date: 2018/09/04, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: India International Insurance Pte Ltd (HQ), Workshop: Tan Lim Motor Pte Ltd (Defu). Created from SAS:MTLM18114553	[R] Ow Caymen
3	04 Sep 2018 15:40	Cim Submitted	3895.02.	[R] Ow Caymen
4	05 Sep 2018 08:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Gabriel Wee
5	05 Sep 2018 08:42	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/09/14	[I] Gabriel Wee
6	05 Sep 2018 08:42	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Gabriel Wee
7	05 Sep 2018 09:07	Cim Supp Created	(S:739997)	[R] Ow Caymen
8	05 Sep 2018 09:16	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	05 Sep 2018 09:44	Cim Submitted	849.15.	[R] Ow Caymen
10	05 Sep 2018 09:44	Adj Co Assigned	(S:739997) LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
11	05 Sep 2018 12:00	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
12	05 Sep 2018 12:00	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
13	06 Sep 2018 14:11	Adj Adjuster Assigned	MARCUS CHUA -> MOHD RASUL	[A] Lau Shu Pei
14	12 Sep 2018 17:45	Adj Mandate Request	Cur,Req:0.00:PODS: LIABILITY: 100% REMARK: B:27 OLD REAR ENDED TP	[A] Asher Sng Rong Yi
15	14 Sep 2018 10:29	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/09/14, Mandate Remarks: WE ARE KEEN ON DIRECT SETTLEMENT	[I] C. Meenachi
16	14 Sep 2018 10:29	Adj Mandate Set	Approved:0.00:WE ARE KEEN ON DIRECT SETTLEMENT	[I] C. Meenachi
17	10 Oct 2018 17:52	Supp Combined	(S:739997)	[A] Asher Sng Rong Yi
18	23 Nov 2018 07:17	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
19	27 Nov 2018 17:08	Adj Mandate Request	Cur,Req:2728.50:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$2,247.00 + (b) LOR w/GST: \$481.50 (4.5days x \$100) Total: a+b = \$2,728.50 VEH MODEL: TOYOTA COROLLA 1496cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1907268	04/09/2018 15:01	Motor	Tan Lim Motor Pte Ltd (HQ)	Tan Lim Motor Pte Ltd (Defu)	SJM7927T		xx.xx
1983295	23/11/2018 07:17	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJM7927T	SLJ7467X	10.70

Print Received Message

This mail is associated with :

SJM7927T (MC20180038)
[SLJ7467X]

TP

LOW CHONG GIAP

Sep 4 2018 6:00AM

[In the estate of Tiew Leong Heng]

Tan Lim Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 28/11/2018 08:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2728.50) - SJM7927T - Claim Handler: C. Meenachi

Approved: 2728.50.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7011085G



LOW CHONG GIAP

刘宗业

Race
CHINESE

Date of Birth
25-03-1970 M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Identity Number S7011085G

LOW CHONG GIAP

Valid Date: 25 Mar 1970

Expiry Date: 21 Jun 2003



HP: 93868107

Email: cglow2004@yahoo.com

Occupation: Technical officer



1097793



NRIC No. S7011085G

Blood Group: O+
Date of issue: 11-07-1993

APT BLK 14 BEDOK SOUTH AVENUE 2 #18-578
SINGAPORE 480014

NRIC No. S7011085G Date: 27-09-2000 No. 5181126

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

- | Class | Description | Pass Date |
|---------|--|-------------|
| Class 2 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 25 Aug 1993 |
| Class 4 | Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms | 01 Aug 2002 |
| Class 5 | Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 2250 kilograms | 09 Sep 2002 |



NP 425A

3p.



INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1987

INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792K | GST Reg. No. M2-0078806-X
64 Cecil Street #04/ #05/ #06-02 10B Building Singapore 049711
Office: (65) 63476100 Email: insure@iil.com.sg
Fax: (65) 62244174 Website: www.iil.com.sg

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1980 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1999 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory insurance.

The Certificate must be returned if the insurance is suspended during its currency.

Agency Code: **91299SE**

Comprehensive

Insured/Named Drivers Excess: **\$600/- Sect 1**

Unnamed Drivers Excess: **\$1100/- Sect. 1 & additional \$2500/- Sect. 1 for age
< 21 years or >65 years &/or S'pore D.L. < 2 years**

Windscreen Excess: **\$100/-**

CERTIFICATE NO.

M494966

1. **Index Mark and Registration
Number of Vehicle**

SJM 7927 T

2. **Name of Policy Holder**

Low Chong Giap

3. **Effective date of the Commencement of
Insurance for the purposes of the Act**

15th January 2018

4. **Date of Expiry of Insurance**

14th January 2019

5. **Person or Classes of Persons entitled to drive***

(a) **The Policyholder**

The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.

(b) **Any other person who is driving on the Policyholder's order or with his/her permission.**

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. **Limitations as to use***

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: **15/12.2017**

for India International Insurance Pte. Ltd.
(APPROVED INSURERS)

**MX 1 (PRIVATE CAR)
INDIVIDUAL OWNERSHIP**

Authorized Signatory

IMPORTANT NOTICE

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner they will endorse the policy accordingly and will issue a new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE INSURANCE COMPANY. FAILURE TO DO SO WILL RESULT IN UNDERWRITERS DECLINING LIABILITY.

Agent/Broker Name: **Tan Kok Seng**

Hire Purchase Company: **NA**



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP004092018
Your Ref SLJ7467X (MC20180038)

Date 25-10-18

WITHOUT PREJUDICE

Claims Department - Executive in charge Meenachi
India International Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SJM79277 / SLJ7467X on 04-09-18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / copies of photographs
☒ Original Tax-invoice number TP1018 / 012 ☒ Original rental invoice number 17181305
☒ SAS / AS & IS / police report ☐ police result
☒ Certificate Of Insurance ☐ Vehicle search result
☒ Authorization to act ☒ Driver's IC & PL

* Survey under insurance instruction / Independent ~~Surveyor~~ / No survey.

LKK

a)	Cost of repair (inclusive GST)	\$ <u>2,247.00</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>-</u>
d)	Loss of hire / use / rental / earnings / rental fees	\$ <u>529.65</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	<u> </u>	\$ <u> </u>
	Total	\$ <u>2,776.65</u> =====

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

AUTHORIZATION TO ACT

TO : TAN LIM MOTOR PTE LTD

FROM : OWNER OF VEHICLE NUMBER SJM79277

ACCIDENT INVOLVING SLJ7467X

ALONG/AT Bedok North Road ON 04.09.18

I/We hereby authorize you to act on my/our behalf in pursuance of my/our claim for losses arising out of the above accident.

This letter serves as the 'AUTHORITY TO ACT'

I/We also hereby authorize all agreed settlement payment be made in favour to TAN LIM MOTOR PTE LTD.

Name Low Chong Giap

NRIC S7011085G

Address Block 14 Bedok South Avenue 2 # 18-578 S460014

Contact 9386 9107

Date 25/10/18

Signature



Owner's / Hirer's signature / RTP
(Company's stamp if applicable)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MC20180038

Claimant Ref: TP004092018 *15JM 7927T*

We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,247.00 (repair cost), S\$ 481.50 (loss of use/rental), S\$ — (search fee), vehicle no. SJM 7927T that was damaged pursuant to the accident which occurred on 04/09/2018 (date) at BEDOK NORTH ROAD (location) involving vehicle no. SLJ 7467X (insured vehicle). This is pursuant to the inspection conducted on 05/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LOW CHONG GIAP ("the third party claimant") of vehicle no. SJM 7927T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJM 7927T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,728.50 to TAN LIM MOTOR PTE LTD

Dated this 11th day of December 2018

CLAIMANT:

Signature:

[Signature]
Signed by "the workshop" (with chop)

Name:

Johnson Chua

NRIC:

S691779D

Address:

40 51 DEPU LANE W
S 539216

Nationality:

S'POREAN

Occupation:

CLAIMS MANAGER

WITNESS:

Signature:



MRB

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality:

Occupation:



TAX-INVOICE
NUMBER: TP1018/012

(Please quote our reference number TP004092018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

India International Insurance Pte Ltd

Date: 16/10/2018

Vehicle No: SJM7927T
Model: TOYOTA COROLLA AXIO

Description	Amount
To lump sum repair as recommended by surveyor.	\$2,100.00

Sub Total	\$2,100.00
Add 7% GST	\$147.00
Total	\$2,247.00

Tan Lim Motor Pte Ltd

Bill To: LOW CHONG GIAP (C/O TAN LIM MOTOR PTE LTD)
BLK 14 BEDOK SOUTH AVENUE 2
#18-578
SINGAPORE 460014

Tax Invoice : 17181305
Date : 08 SEP 2018
Agreement No. : ST7104

Vehicle No	Description	Total Amount
SJX1842K	Toyota Vios E Auto Rental Charges From 04-09-2018 to 08-09-2018 4.5 days @ \$110.00 per day	SGD 495.00

PAID
17 SEP 2018
BY: VOB 187673

Sub-Total 495.00
Add: GST (7.00%) 34.65
Amount Payable (SGD) 529.65

SINGAPORE DOLLAR: FIVE HUNDRED TWENTY-NINE AND CENTS SIXTY-FIVE ONLY.

Cheque should be crossed "A/C Payee Only" and made payable to GLOBAL ADVANCE LEASING.
Please write your invoice number on the reverse side of the cheque.
Payment should be made within 7 days from invoice.
Interest at 24% per annum on overdue account.
For bill enquiry, please call 6100 0425 / 9018 0988

**GLOBAL ADVANCE LEASING**

Biz Reg: B52935825E
 GST Reg No: 200409785W
 C/o 51 Defu Lane 10 S/S39218
 Tel: 61000GAL

Agreement: 7104

Vehicle No <u>SX 1842K</u>		Make & Model <u>Alfa Romeo</u>		Date <u>04.09.2018</u>	
Hirer		Class 2 / 2A / 2B / 3 / 4 / 5		Check Out / Check In	
Name <u>Low Chong Giep</u>				Date Out <u>04.09.2018</u>	
Address <u>14 Bedok East Avenue 2</u>				Time Out <u>1325hrs</u> KM Out <u>12112</u>	
Contact Person <u>93868107</u>		Tel <u>93868107</u>		PETROL <u>E 1/4 1/2 3/4 F</u>	
				Date In <u>08.09.2018</u>	
1st Driver		Class 2 / 2A / 2B / 3 / 4 / 5		Time In <u>1500hrs</u> KM In <u>127446</u>	
Name <u>AS ABOVE</u>				PETROL <u>E 1/4 1/2 3/4 F</u>	
Address					
(H/P) <u>(O)</u> <u>(H)</u>				Mode of Payment	
Passport/NRIC No <u>S7011085G</u>		Nationality <u>Singapore</u>		Cash / Cheque / Company Billing / Credit Card / Others	
Driving Licence No <u>Sigpre</u>		Driving Exp <u>25 yrs</u>		Cheque / Card Details:	
Country of Issue <u>Singapore</u>		Expiry Date <u>Unlimited</u>		Expiry Date:	
Additional Driver		Class 2 / 2A / 2B / 3 / 4 / 5		Rental Charges	
Name				<u>45</u> Day/s @ \$ <u>110.00</u> /day \$ <u>495.00</u>	
Address				<u>Week/s</u> @ \$ /week \$	
(H/P) <u>(O)</u> <u>(H)</u>				<u>Month/s</u> @ \$ /month \$	
Passport/NRIC No		Nationality		SUBTOTAL \$	
Driving Licence No		Driving Exp <u>Yrs</u>		COW @ \$ \$	
Country of Issue		Expiry Date		PAI @ \$ \$	
Non Waiverable Excess				Petrol Top Up \$	
The Hirer acknowledges a \$ <u>1500</u> collision damage excess per accident applies.				Delivery / Collection fee \$	
X <u>(Singapore Use)</u>				Misc \$ <u>34.65</u>	
Collision Damage Waiver (CDW)				Misc \$	
The Hirer may limit his liability for any damage arising from collision to \$ _____ by purchasing CDW and paying the specified sum.				Less	
X				Pre-Payment / Deposit (\$ _____)	
Personal Accident Insurance (PAI)				Misc (\$ _____)	
PAI may be purchased at a premium specified herein. The Hirer acknowledges that the insurance is written by an independent insurance company and acknowledges that he has received, read and understood the policy conditions relating to the same.				Total Due \$ <u>529.65</u>	
X				Charges Subject to Final Audit	
Special Instructions				Refundable Deposit	
				Deposit \$ _____	
				Date of Refund _____	
				Refund Acknowledgement <u>X</u>	
				For Official Use	
				Invoice No <u>17181305</u> Date <u>08.09.2018</u>	
				Receipt No _____ Date _____	

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorised by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations redirected.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X (Hirer's signature)

X (Additional Driver's signature)

X (Global Advance Leasing)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018 Sendback Est	04 Sep 2018 15:40 \$3,895.02	05 Sep 2018 08:42 Edit Adj Rpt	\$2,100.00 Edit Estimates	\$2,100.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	05 Sep 2018 09:07	05 Sep 2018 09:44 \$849.15	05 Sep 2018 09:44			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: In the estate of Tiew Leong Heng , ID: M066137/17/200									
Main Claimant: LOW CHONG GIAP , ID: S7011085G									
Vehicle Reg. No.: SJM7927T		Date of Loss: 04/09/2018 06:00 - :59 [115 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MC20180038		Policy/Cover Note No.: M066137 (Third Party Only)							
Vehicle Reg. No. (Insured): SLJ7467X		Policy No. (Claimant): M494966							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, S39216 Defu Lane - Tel: 6858 5151									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/09/2018]									
Driver/Custodian (Insured): Tiew kye Jie (), NRIC: S9170108A									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (28/11/2018): Alert - Adj Mandate Approved (\$2728.50) - SJM7927T - Claim Handler: C. Meenachi - III_SG (14/09/2018): Alert - Adj Mandate Approved (\$0.00) - SJM7927T - Claim Handler: C. Meenachi									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJM7927T (MC20180038)
[SLJ7467X]
TP
LOW CHONG GIAP
Sep 4 2018 6:00AM
[In the estate of Tiew Leong Heng]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	04/09/18 15:40	Repairer Estimates	Load HTM	☐
2	05/09/18 09:44	Repairer Estimates Suppl. #1	Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 17:09	Odometer Reading	Load JPG	☒
2	27/11/18 17:10	Chassis Number	Load JPG	☒
3	27/11/18 17:10	General View	Load JPG	☒
4	27/11/18 17:10	General View	Load JPG	☒
5	27/11/18 17:10	General View	Load JPG	☒
6	27/11/18 17:10	General View	Load JPG	☒
7	27/11/18 17:10	General View	Load JPG	☒
8	27/11/18 17:10	General View	Load JPG	☒
9	27/11/18 17:10	General View	Load JPG	☒
10	27/11/18 17:10	General View	Load JPG	☒
11	27/11/18 17:10	General View	Load JPG	☒
12	27/11/18 17:10	General View	Load JPG	☒
13	27/11/18 17:10	General View	Load JPG	☒
14	27/11/18 17:10	General View	Load JPG	☒
15	27/11/18 17:10	General View	Load JPG	☒
16	27/11/18 17:10	General View	Load JPG	☒
17	27/11/18 17:10	General View	Load JPG	☒
18	27/11/18 17:10	General View	Load JPG	☒
19	27/11/18 17:10	General View	Load JPG	☒
20	27/11/18 17:10	General View	Load JPG	☒
21	27/11/18 17:10	General View	Load JPG	☒
22	27/11/18 17:10	General View	Load JPG	☒
23	27/11/18 17:10	General View	Load JPG	☒
24	27/11/18 17:10	General View	Load JPG	☒
25	27/11/18 17:10	General View	Load JPG	☒
26	27/11/18 17:10	General View	Load JPG	☒
27	27/11/18 17:10	General View	Load JPG	☒
28	27/11/18 17:10	General View	Load JPG	☒
29	27/11/18 17:10	General View	Load JPG	☒
30	27/11/18 17:10	General View	Load JPG	☒
31	27/11/18 17:10	General View	Load JPG	☒
32	27/11/18 17:10	Reinspection Photo	Load JPG	☒
33	27/11/18 17:10	Reinspection Photo	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print	
34	27/11/18 17:10	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print	
1	05/09/18 08:38	Singapore Accident Statement	 Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	06/09/18 18:09	TP ESTIMATE- MARKED	 Load PDF		
2	23/11/18 07:21	WORKSHOP INVOICE	 Load PDF		
3	23/11/18 07:21	RENTAL RECEIPT	 Load PDF		
4	23/11/18 07:21	LOD	 Load PDF		
5	26/12/18 08:13	AUTHORISATION TO ACT FORM	 Load PDF		
6	26/12/18 08:13	DISCHARGE VOUCHER	 Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print	
1	04/09/18 14:45	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print	
1	04/09/18 14:44	Accident Photo	 Load JPG	☒	
2	04/09/18 14:44	Accident Photo	 Load JPG	☒	
3	04/09/18 14:44	Accident Photo	 Load JPG	☒	
4	04/09/18 14:44	Accident Photo	 Load JPG	☒	
5	04/09/18 14:44	Accident Photo	 Load JPG	☒	
6	04/09/18 14:44	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print	
1	04/09/18 13:30	Sketch Plan	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18016180/R1EB3Q2

Date: 26/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M066137

Claimant Vehicle No: SJM7927T

Insured Vehicle No: SLJ7467X

Date of Loss: 04/09/2018

Nature of Claim: TP

Claim No: MC20180038

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM7927T

Make & Model: TOYOTA COROLLA, 1.5 AXIO (A)

Engine No: 1NZD191931

Reg. Date: 15/01/2009 (Man. Year: 2008)

Chassis No: NZE1416096851

Colour: White

Odometer: 256420 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,774.17	1,346.47	1,427.70	51.46
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,960.00	1,310.00	650.00	33.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,744.17	2,666.47	2,077.70	43.79
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	4,744.17	2,100.00	2,644.17	55.74
+ GST 7.00/7.00% (S\$)	332.09	147.00	185.09	55.73
Nett Amount (S\$)	5,076.26	2,247.00	2,829.26	55.74
+ Car Rental (4.5 x S\$100.00/day + 7.00% GST) (S\$)		481.50		
Nett Liability (S\$)		2,728.50		

INSPECTION

Date of Assignment: 05/09/2018

Present Location:

Tan Lim Motor Pte Ltd (Defu)

Date Inspected: 05/09/2018

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

51 Defu Lane 10

Singapore 539216

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2018)
Parts:	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM7927T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*rear bumper	Deformed	438.40 FL	*438.40 FL
2	1		*rear bumper parking sensor	Not Working	450.00 FS	*200.00 FS
3	1		*o/s rear bumper bracket	Necessary	55.60 FL	*55.60 FL
4	1		*o/s rear bumper side retainer	Not Necessary	99.60 FL	*- FL
5	1		*o/s rear bumper side holder	Not Necessary	98.00 FL	*- FL
6	8		*rear bumper clips	Necessary	30.40 FL	*30.40 FL
7	1		*rear bumper reflector accessory	Necessary	150.00 FS	*10.00 FS
8	1		*o/s rear lamp	Cracked	368.80 FL	*368.80 FL
9	3		*o/s rear lamp clip holder	Necessary	12.90 FL	*12.90 FL
10	1		*rear end panel	Bent	468.00 FL	*468.00 FL
11	1		*rear end panel inner trim	Not Necessary	195.00 FL	*- FL
Supplementary #1						
12	1		*bootlid	Repair	710.00 FL	*- FL
13	1		*bootlid weatherstrip	Not Necessary	185.00 FL	*- FL
14	1		*bootlid lock	Not Necessary	96.00 FL	*- FL
15	1		*bootlid x badge	Necessary	36.60 FL	*36.60 FL
16	1		*bootlid Axio badge	Necessary	43.60 FL	*43.60 FL
17	1		*bootlid centre logo badge	Necessary	61.00 FL	*61.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,498.90	1,725.30
- List Item Discount on L Items 25.00/25.00% (S\$)	724.73	378.83
Total Parts (S\$)	2,774.17	1,346.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To check electrical lighting concerned.	New	60.00	30.00
2	To reinstall of rear bumper parking sensor.	New	120.00	60.00
3	To rust-proofing of the affected areas.	New	100.00	40.00
4	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	150.00	80.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	780.00	500.00
6	Putty and spray painting of the affected portion.	New	750.00	600.00
Gross Labour Cost (S\$)			1,960.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >