



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

**TP INSURER:** India International Insurance Pte Ltd (HQ)  
In the estate of Tiew Leong Heng

Singapore

**Claimant Insurer:** India International Insurance Pte Ltd

#### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP004092018
Policy No:		Date of Loss:	04/09/2018
Vehicle Reg. No.:	<b>SJM7927T</b>	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOW CHONG GIAP	Driver (Insured):	TIEW KYE JIE
Make/Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Vehicle Reg. Date:	15/01/2009
Vehicle Colour:	WHITE		
Engine No:	1NZD191931	Chassis No:	NZE1416096851
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		

#### Description of Accident/Loss

ON 04.09.2018 AT ABOUT 0610HRS, I WAS DRIVING MY VEHICLE (A: SJM7927T) ALONG 3RD LANE OF BEDOK NORTH ROAD WITH NORMAL SPEED. SUDDENLY, I FELT AN IMPACT FROM BEHIND AND REALIZE THAT THERE IS A VEHICLE (B: SLJ7467X) CUT IN FROM MY RIGHT AND HIT ONTO REAR RIGHT PORTION OF MY VEHICLE. VEHICLE A (SJM7927T): 1 FEMALE PASSENGER ON BOARD. VEHICLE B (SLJ7467X): NO PASSENGER ON BOARD.

**Present Location:** TAN LIM MOTOR PTE LTD (DEFU)

#### COST OF CLAIMS

	Amount
Parts	1,925.02
Miscellaneous Items	10.00
Labour	1,960.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,895.02</b>
<b>+ GST 7.00% (S\$)</b>	<b>272.65</b>
<b>Nett Amount (S\$)</b>	<b>4,167.67</b>

This claim is handled by: OW CAYMEN

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Sep 2018)

**Parts:** 143 TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*rear bumper	25.00	0.00	De *438.40 FL
2	1		*rear bumper parking sensor	0	0.00	200mm *450.00 FS
3	1		*o/s rear bumper bracket	25.00	0.00	re *55.60 FL
4	1		*o/s rear bumper side retainer	25.00	0.00	re X *99.60 FL
5	1		*o/s rear bumper side holder	25.00	0.00	X *98.00 FL
6	8		*rear bumper clips	25.00	0.00	re *30.40 FL
7	1		*rear bumper reflector accessory	0	0.00	re *150.00 FS
8	1		*o/s rear lamp	25.00	0.00	CR *368.80 FL
9	3		*o/s rear lamp clip holder	25.00	0.00	re *12.90 FL
10	1		*rear end panel	25.00	0.00	re *468.00 FL
11	1		*rear end panel inner trim	25.00	0.00	X *195.00 FL
Sub Total (S\$)						2,366.70
- List Item Discount on L Items (S\$)						441.68
Total Parts (S\$)						1,925.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 05 Sep 2018)

**Parts:** 143      TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*bootlid	25.00	0.00	<i>repair</i> *710.00 FL
2	1		*bootlid weatherstrip	25.00	0.00	<i>X</i> *185.00 FL
3	1		*bootlid lock	25.00	0.00	<i>X</i> *96.00 FL
4	1		*bootlid x badge	25.00	0.00	<i>ne /</i> *36.60 FL
5	1		*bootlid Axio badge	25.00	0.00	<i>ne /</i> *43.60 FL
6	1		*bootlid centre logo badge	25.00	0.00	<i>ne /</i> *61.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,132.20
- List Item Discount on L Items (S\$)	283.05
Total Parts (S\$)	849.15

Tan Lim Motor Pte Ltd/SJM7927T/05/09/2018 09:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To check electrical lighting concerned.	New	30 60.00
2	To reinstall of rear bumper parking sensor.	New	60 120.00
3	To rust-proofing of the affected areas.	New	40 100.00
4	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	80 150.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	500 780.00
6	Putty and spray painting of the affected portion.	New	600 750.00
Gross Labour Cost (S\$)			1,960.00

Tan Lim Motor Pte Ltd/SJM7927T/04/09/2018 15:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216  
 Tel : 6858 5151 (24 hours) Fax : 6858 0877  
 email@tlmotor.com.sg www.tlmotor.com.sg  
 Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
 Hp 90010068  
 5 days  
 4/8  
 05/09/18 @ 1535  
 Resy after repair