

ASS. REC. BY:

REF:

TH /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Trans Cab

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S11D 923X

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1.895

Colour:

n. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

30546

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL 15 AUG 283389

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

31/8/18

D.O.I.

4/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/19

File pass to Catherine

27/19

303434 Car frame Tasmara (2x110-50 +80)

(Rear 1505.02/83X1)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18016183/Kpb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 05-09-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3945T	Veh. Inspected	SHD 923X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/08/2018	Inspection Date	04/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 923X

AAD1808-271

Not Authorised
Resurvey By paint 83034.34

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 923X

VF1ABL15AUC283389

RENAULT

LATITUDE

31/8/2018

PART

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPR BRACKET SIDE RH REAR
- 5 1 BUMPR RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 1 MOULDING EXHAUST
- 1 EXHAUST REAR
- 14 1 OUTER PANEL REAR (End Panel)TRIM

LIST

\$	<i>Br</i>	1,108.46	—
\$	<i>nd/aw</i>	768.84	—
\$	<i>Sn</i>	113.47	X
\$	<i>Sn</i>	135.97	X
\$	<i>Sn</i>	44.99	X
\$	<i>Sn</i>	43.61	X
\$	<i>Sn</i>	135.97	X
\$	<i>Sn</i>	44.99	X
\$	<i>Sn</i>	43.61	X
\$	<i>R</i>	777.52	—
\$	<i>R</i>	225.95	} X
\$	<i>R</i>	225.95	
\$	<i>R</i>	1,471.77	
\$	<i>R</i>	16.59	
\$	<i>R</i>	166.95	}
\$	<i>Sn</i>	5,324.64	
\$		10,649.29	
10% \$		1,064.93	
\$		9,584.36	

Specical Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP
- 4 1SET BUMPER BRACKET SIDE CLIP RH RR
- 5 1SET BUMPR RETAINER RH CLIP RR
- 6 1SET BUMPR BRACKET SIDE CLIP LH RR
- 7 1SET BUMPR RETAINER CLIP LH RR
- 8 1SET BUMPER LOWER REAR RIVET
- 9 1SET BUMPER LOWER REAR CLIP

\$	<i>Sn</i>	700.00	X
\$	<i>Sn</i>	66.00	—
\$	<i>nbc</i>	33.00	—
\$	<i>nn</i>	10.00	X
\$	<i>nn</i>	20.00	X
\$	<i>nn</i>	10.00	X
\$	<i>nn</i>	20.00	X
\$	<i>nn</i>	22.00	X
\$	<i>nn</i>	66.00	✓

Trans-cab Auto Services Pte Ltd**AAD1808-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD923X10 1 EXHAUST MOUNTING REAR \$ *108.00 X***TOTAL \$ 1,055.00****TOTAL PARTS \$ 10,639.36****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2200*Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same\$ 3,000.00 *2000*

To Rust-Proofing Of The Affected Areas.

\$ *170.00 X*

To reinstall rear bumper parking sensor.

\$ 170.00 *600*To transfer of bootlid fittings, attachments and
perform water seepage test.\$ *170.00 X*

To repair and realign rear exhaust pipe.

\$ *170.00 X*To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.\$ *170.00 X*To transfer of rear end panel fittings, attachment and
perform water seepage test.\$ *170.00 X*To transfer of rear windscreen fittings and conduct
water seepage test.\$ *170.00 X*To check steering geometry and computer wheel
alignment\$ *220.00 X***TOTAL \$ 7,410.00****Over All Total \$ 18,049.36****(LUMP SUM)****Repair Days****10 DAYS***2 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	05 Sep 2018 12:31	Clm Veh Model Changed	(204383) RENAULT LATITUDE 2.0 L (A).	[A] Lau Shu Pei	
2	05 Sep 2018 12:31	Clm Created	Reg No: SHD923X, Acct Date: 2018/08/31, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Lau Shu Pei	
3	05 Sep 2018 12:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei	
4	05 Sep 2018 12:31	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2018/09/14	[A] Lau Shu Pei	
5	05 Sep 2018 12:31	Adj Mandate Set	Approved: 0.00. Reinsp: Adj decides.	[A] Lau Shu Pei	
6	05 Sep 2018 12:32	Label Added	(30653): Direct Settlement.	[A] Lau Shu Pei	
7	05 Sep 2018 12:32	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei	
8	11 Sep 2018 09:03	Clm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei	
9	11 Sep 2018 09:03	Clm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei	
10	12 Sep 2018 14:46	Adj Mandate Request	Cur.Req: 0.00: PODS Liability: 100% Remarks: Insured driver rear-ended third party.	[A] CHEW HSIAO TONG	
Date From Date To Audit Type None Go					

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	05 Sep 2018 12:31	Clim Veh Model Changed	(204383) RENAULT LATITUDE 2.0 L (A).	[A] Lau Shu Pei
2	05 Sep 2018 12:31	Clim Created	Reg No: SHD923X. Acct Date: 2018/08/31. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Lau Shu Pei
3	05 Sep 2018 12:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	05 Sep 2018 12:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/14	[A] Lau Shu Pei
5	05 Sep 2018 12:31	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	05 Sep 2018 12:32	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	05 Sep 2018 12:32	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	11 Sep 2018 09:03	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	11 Sep 2018 09:03	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	12 Sep 2018 14:46	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party.	[A] CHEW HSIAO TONG
11	13 Sep 2018 14:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/14	[I] Priya
12	13 Sep 2018 14:52	Adj Mandate Set	Approved:0.00.	[I] Priya

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Sep 2018 12:31	CIm Veh Model Changed	(204383) RENAULT LATITUDE 2.0 L (A).	[A] Lau Shu Pei
2	05 Sep 2018 12:31	CIm Created	Reg No: SHD923X, Acct Date: 2018/08/31, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Transcab Auto Services Pte Ltd (Ang Mo Kio)	[A] Lau Shu Pei
3	05 Sep 2018 12:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	05 Sep 2018 12:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/14	[A] Lau Shu Pei
5	05 Sep 2018 12:31	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	05 Sep 2018 12:32	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	05 Sep 2018 12:32	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	11 Sep 2018 09:03	CIm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	11 Sep 2018 09:03	CIm Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	12 Sep 2018 14:46	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver rear-ended third party.	[A] CHEW HSIAO TONG
11	13 Sep 2018 14:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/14	[I] Priya
12	13 Sep 2018 14:52	Adj Mandate Set	Approved:0.00.	[I] Priya
13	19 Oct 2018 19:55	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
14	19 Oct 2018 19:55	CIm Dtl Modified	Claimant's ID: -> -.	[A] NUR SHAQILAH BTE ABDOL WAHAB
15	19 Oct 2018 19:55	CIm Dtl Modified	JPJ Reg. Date: -> 2017/12/29.	[A] NUR SHAQILAH BTE ABDOL WAHAB
16	19 Oct 2018 19:55	CIm Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
17	28 Oct 2018 10:07	Adj Mandate Request	Cur.Req:3547.16:PODS Liability: 100% Quantum: (a)CORw/GST: \$3,246.74 + (b)LO R(2days x \$110.21): \$220.42 + (c)LOI(2days x \$40.00): \$80.00 = Total: \$3,547.16 Vehicle Model: Renault Latitude (1995cc). For your approval please.	[A] CHEW HSIAO TONG
Date From Date To Audit Type None Go				

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1951139	19/10/2018 19:55	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHD923X	SHC3945T	10.70

Print Received Message

This mail is associated with :

***SHD923X (MCT18080913)**
[SHC3945T]

TP

TRANS-CAB SERVICES PTE LTD
Aug 31 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/10/2018 11:11 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3547.16) - SHD923X - Claim Handler: Priya

Approved:3547.16.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 3 November 2018 11:59 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei' (zhewei.kek@transcab.com.sg); claims@transcab.com.sg
Subject: Your ref: AAD1808 - 271 (SHD 923X) *Our ref: CC3/III18016183/Kpb3 [ACCIDENT INVOLVING SHC 3945T(III) & SHD 923X ON 31/08/2018]
Attachments: DV_SHD 923X.pdf

Your ref: **AAD1808 - 271 (SHD 923X)**
Our ref: CC3/III18016183/Kpb3

Without Prejudice

Hi Sirs/Madam,

ACCIDENT INVOLVING SHC 3945T(III) & SHD 923X ON 31/08/2018

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,246.74
2. Loss of Rental (2days x \$110.21)	\$ 220.42
3. Loss of Income (2days x \$40.00)	\$ 80.00
TOTAL	<u>\$ 3,547.16</u>

Please duly sign the **DV** enclosed and return the original copy to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018 Edit Reg		04 Sep 2018 00:00 Edit Adj Rpt	S\$3,034.34 Edit Estimates	S\$3,034.34 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD923X	Date of Loss:	31/08/2018 08:00 - :59 [8 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18080913	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC3945T	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (29/10/2018): Alert - Adj Mandate Approved (S\$3547.16) - SHD923X - Claim Handler: Priya
- III_SG (13/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SHD923X - Claim Handler: Priya

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD923X (MCT18080913)**
[SHC3945T]

TP

TRANS-CAB SERVICES PTE LTD
Aug 31 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/09/18 14:46	General View	 Load JPG	☒
2	12/09/18 14:46	General View	 Load JPG	☒
3	12/09/18 14:46	General View	 Load JPG	☒
4	12/09/18 14:46	General View	 Load JPG	☒
5	12/09/18 14:46	General View	 Load JPG	☒
6	12/09/18 14:46	General View	 Load JPG	☒
7	12/09/18 14:46	General View	 Load JPG	☒
8	12/09/18 14:46	General View	 Load JPG	☒
9	12/09/18 14:46	Odometer Reading	 Load JPG	☒
10	12/09/18 14:46	Chassis Number	 Load JPG	☒
11	29/09/18 09:47	Reinspection Photo	 Load JPG	☒
12	29/09/18 09:47	Reinspection Photo	 Load JPG	☒
13	29/09/18 09:47	Reinspection Photo	 Load JPG	☒

Documentation

1 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/09/18 18:25	TP ESTIMATE- MARKED	 Load PDF	
2	05/09/18 18:25	TP GIA REPORT	 Load PDF	
3	22/10/18 17:08	LOD	 Load PDF	
4	22/10/18 17:08	WORKSHOP INVOICE	 Load PDF	
5	28/10/18 10:04	RENTAL & LOG BOOK	 Load PDF	
6	27/11/18 11:43	AUTHORISATION TO ACT	 Load PDF	
7	27/11/18 11:43	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 09:09	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18016183/KPB3S2
Date: 27/11/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHD923X	Insured Vehicle No :	SHC3945T
Date of Loss:	31/08/2018	Nature of Claim:	TP
		Claim No:	MCT18080913

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD923X		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)		
Reg. Date:	29/12/2017 (Man. Year: 2015)	Engine No:	M9R8839C003342
Colour:	Metallic White/Red	Chassis No:	VF1ABL15AUC283389
Engine Capacity:	1995 cc	Odometer:	50546 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,639.35	2,554.34	8,085.01	75.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	480.00	6,930.00	93.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,049.35	3,034.34	15,015.01	83.19
+ GST 7.00/7.00% (S\$)	1,263.45	212.40	1,051.05	83.19
Nett Amount (S\$)	19,312.80	3,246.74	16,066.06	83.19
+ Loss of Use (2.0 x S\$40.00/day) (S\$)		80.00		
+ Car Rental (2.0 x S\$110.21/day) (S\$)		220.42		
Nett Liability (S\$)		3,547.16		

INSPECTION

Date of Assignment:	04/09/2018	
Date Inspected:	04/09/2018	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2018)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD923X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER SIDE RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR REAR	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*MOULDING EXHAUST	Repair	16.59 FL	*- FL
15	1		*EXHAUST REAR	Repair	166.95 FL	*- FL
16	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	5,324.64 FL	*- FL
17	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
18	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
19	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
20	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
21	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
22	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
23	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
24	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
25	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
26	1		*EXHAUST MOUNTING REAR	Serviceable	108.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,704.28	2,819.82
- List Item Discount on L Items 10.00/10.00% (S\$)	1,064.93	265.48
Total Parts (S\$)	10,639.35	2,554.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	220.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
8	O TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
Gross Labour Cost (\$\$)			7,410.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >