

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 923X**AAD1808-271**

Cor not in

Not Authorised

Resumy B4 paint **83034.34**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 923X

VF1ABL15AUC283389

RENAULT

LATITUDE

31/8/2018

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 —
2	1 BUMPER LOWER REAR	\$	<i>nd/w</i> 768.84 —
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52 —
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77
	1 MOULDING EXHAUST	\$	<i>R</i> 16.59
	1 EXHAUST REAR	\$	<i>R</i> 166.95
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 5,324.64
		\$	10,649.29
10%		\$	1,064.93
		\$	9,584.36

Specical Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>Sn</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nd/c</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET BUMEP R RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET BUMEP R BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET BUMEP R RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 —

Trans-cab Auto Services Pte Ltd

AAD1808-271

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD923X10 1 EXHAUST MOUNTING REAR \$ *108.00 X***TOTAL \$ 1,055.00****TOTAL PARTS \$ 10,639.36****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2201*Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 3,000.00 *2001*To Rust-Proofing Of The Affected Areas. \$ *170.00 X*To reinstall rear bumper parking sensor. \$ 170.00 *601*To transfer of bootlid fittings, attachments and
perform water seepage test. \$ *170.00 X*To repair and realign rear exhaust pipe. \$ *170.00 X*To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe. \$ *170.00 X*To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ *170.00 X*To transfer of rear windscreen fittings and conduct
water seepage test. \$ *170.00 X*To check steering geometry and computer wheel
alignment \$ *220.00 X***TOTAL \$ 7,410.00****Over All Total \$ 18,049.36****LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(LUMP SUM)**Repair Days****10 DAYS***2 days*