

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5117D**AAD1809-009***Not Authaird
L1 By 8995/-*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5117D

VF1ABL15AUC276546

RENAULT

LATITUDE

1.9.2018

AIG

PART		LIST	
1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66
1	DOOR HINGE UPPER RH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>N</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>N</i> 505.19
1	DOOR REGUALTOR MOTOR FRT RH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sn</i> 120.97
1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>Sn</i> 1,135.10
1	DOOR REGUALTOR MOTOR REAR RH	\$	<i>Sn</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43
1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82

X

Trans-cab Auto Services Pte Ltd

AAD1809-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5117D

1	DOOR MOULDING CLIP L70Y	\$	nn	5.92
1	DOOR MOULDING SCREW L70Y	\$	nn	6.91
1	DOOR CASING REAR RH	\$	sn	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	sn	30.39
1	DOOR CASING CLIP	\$	nn	12.63
1	DOOR CASING LIGHT L70Y	\$	sn	48.74
1	DOOR FINISHER INNER REAR RH	\$	sn	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n	20.33
1	DOOR GRAB HANDLE REAR RH	\$	sn	210.96
1	DOOR BLIND REAR RH	\$	sn	741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	sn	410.66
1	DOOR SEAL REAR RH	\$	sn	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	sn	115.64
1	FENDER PANEL REAR RH	\$	n	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	sn	671.45
1	WHEELARCH REAR RH	\$	sn	543.47
1	DOOR MIRROR ASSY RH	\$	sn	1,483.40
1	ROCKER PANEL INNER GARNISH RH	\$	sn	466.51
1	ROCKER PANEL INNER RH	\$	n	1,024.79
1	ROCKER PANEL CENTER RH	\$	n	990.25
1	BUMPER COVER REAR	\$	sn	1,108.46

	\$	28,198.60
10%	\$	2,819.86
	\$	25,378.74

Specical Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	REAR DOOR STICKER '6555-3333'	\$	nn	80.00	60sn
1	DOOR CHECK BOLT	\$	nn	22.69	X
1	DOOR GUIDE SCREW	\$	nn	10.85	X
1	DOOR HINGE BOLT	\$	nn	10.85	X

Trans-cab Auto Services Pte Ltd**AAD1809-009**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5117D

1	DOOR HINGE NUT RH	\$	<i>nn</i> 14.60 <i>X</i>
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69 <i>X</i>
1	DOOR CHECK NUT	\$	<i>nn</i> 3.75 <i>X</i>
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12 <i>X</i>
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06 <i>X</i>

TOTAL	\$	261.63
--------------	-----------	---------------

TOTAL PARTS	\$	25,640.37
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>2001</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>6601</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>151</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1809-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5117D

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X**TOTAL** \$ 9,010.00**Over All Total** \$ 34,650.37**LUMP SUM (REPAIR DAY)**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before or after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: