

(4/4/2018)

INS. CASE OWNER:

Stacy

CC

3/AXA1801

6/8/18

K. 18/18

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

4/1/18

Date / Time:

P

4/1/18

Registered in Meriton:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFZ 7070T

Name of Insured:

UM Kim Seng

Insured Tel No.:

HP: 96374211

Excess Sec II :SS

D.O.A: 1/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SMD00121/ 6761

Policy No.:

GAMU121

Make / Model:

Audi

Place of Accident:

761 4.6km WLE 3 optm

SPARE UP

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SUC 5694P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans

cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/9/18

broken

SUC 5694P - 44/AXA1801/44/3/18
SFZ 7070T - 7

* amount claim

7/10/18

no body - pick-up

10/9/18

no body - pick-up

10/10/18

Call agent, spoke to (Mr. Lin) (contacted) accident statement (linked to parked vehicle) informed TP claim and HLD issue (3 copies to settle and under HLD - 18 be updated and letter to (Mr. Lin) (linked) update - Approve - 15K all in pass file to finalize

3/9/19

-FIG -> Shua Sui tan (15K all in car piece

6/9/19

File pass to LSP to close.

STAGE	DATE / PIC
Non-Reporting (1st):	
Non-Reporting (2nd):	
Non-Reporting (Final):	
Notification (if non-pickup)	
Call OI	
After call (if to OI)	7/10/18 sub 1219
Documentation Check List:	Handler Typist
Notification (if non-pickup)	
After call (if to OI)	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Man/Re/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE		Date/Time: 11/1/18	Sent By: GPK
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: 3/9/19	Confirm with: Justine
Final Liability:	%	(Agreed) Assessed	BCIA S/N No.: 22
Repair Cost:	SS	1552.00	
Loss of Rental (LOR):	SS	1511.90	15 days x 101.46
Loss of Use (LOU):	SS	15	x 15 days
Loss of Income (LOI):	SS	750.00	50 x 15 days
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>
LOR + LOU	<input type="checkbox"/>	LOR + LOI	<input type="checkbox"/>
[Tick only one]			
GIA/LTA Search	SS	2-45	
Medical:	SS	-	
Disbursement:	SS	-	(e.g. Tow/ Independent)
Legal Cost	SS	-	
Total:	SS	16831.35	Global Sum SS: 15000.00
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	1500.00	Name 1: Trans-cab Auto Services Pte Ltd
Payee 2: (Strike if N.A.)	SS	-	Name 2:
Payee 3: (Strike if N.A.)	SS	-	Name 3:

ASS. REC. BY:

REF:

AAA/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

19 File pass to Catherine

US # 13600 CRed & 55162.93 847.

Veh No:

SHC 5689R

Yr Regn:

11, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude cc

1995

Colour:

M. white / M

A/C:

Insured / Std / NI / NA

Sp. Reading

324261

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC 280295

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Giti

215/60R16

R:

Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc & C/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - \$

Fuels

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC3/ASM18016191/Kjb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 05-09-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFZ 7070T	Veh. Inspected	SHD 721L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/09/2018	Inspection Date	04/09/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R*Not Authored*
U/Ling

Vehicle No.:

SHC 5699R

Chassis No.:

VF1ABL15AUC280295

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

1.9.2018

Third Party Insurer :

AXA

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>As</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82 ✗
1	DOOR HINGE UPPER LH	\$	<i>H</i> 274.50 ✗
1	DOOR HINGE LOWER LH	\$	<i>H</i> 300.55 ✗
1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06 ✗
1	DOOR LOCK REAR LH	\$	<i>Tu</i> 908.75 ✓
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49 ✓
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52 ✗
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89 ✗
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22 ✗
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60 ✗
1	DOOR REGULATOR REAR LH	\$	<i>SL</i> 1,135.10 ✓
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Tu</i> 893.75 ✓
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i> 12.43 ✗
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31 ✗
1	DOOR FINISHER REAR LH	\$	<i>SL</i> 423.10 ✗
1	DOOR MOULDING REAR LH	\$	<i>SL</i> 176.82 ✓
1	DOOR MOULDING CLIP L70Y	\$	<i>SL</i> 5.92 ✗
1	DOOR MOULDING SCREW L70Y	\$	<i>SL</i> 6.91 ✗
1	DOOR CASING REAR LH	\$	<i>SL</i> 1,509.06 ✗
1	DOOR WATER SHIELD REAR LH	\$	<i>SL</i> 30.39 ✗
1	DOOR CASING CLIP	\$	<i>SL</i> 12.63 ✗
1	DOOR CASING LIGHT L70Y	\$	<i>SL</i> 48.74 ✗
1	DOOR FINISHER INNER REAR LH	\$	<i>SL</i> 323.44 } ✗
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>SL</i> 46.97 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>SL</i> 20.33 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>SL</i> 20.33 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>SL</i> 20.33 }
1	DOOR GRAB HANDLE REAR LH	\$	<i>SL</i> 210.96 }

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR BLIND REAR LH	\$	SL 741.80 X
1	DOOR WHEATHESTRIIP REAR LH	\$	Pull 67 410.66 ✓
1	DOOR SEAL REAR LH	\$	SL 162.02 X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	SL 229.31 X
1	DOOR WAIST SEAL OUTER REAR LH	\$	SL 334.69 X
1	DOOR WAIST SEAL INNER REAR LH	\$	SL 115.64 X
1	FENDER PANEL REAR LH	\$	B 3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR	\$	SL 671.45 X
1	WHEELARCH REAR LH	\$	SL 543.47 X
1	ROCKER PANEL INNER GARNISH LH	\$	SL 466.51 X
1	ROCKER PANEL INNER LH	\$	SL 1,024.79 X
1	ROCKER PANEL CENTER LH	\$	B 990.25 ✓
1	BUMPER COVER REAR	\$	B 1,108.46 ✓
1	BUMPER LOWER REAR	\$	SL 768.84
1	BUMPER BRACKET CTR REAR	\$	SL 113.47
1	BUMEP R BRACKET SIDE RH REAR	\$	SL 135.97
1	BUMEP R RETAINER RH REAR	\$	SL 44.99
1	BUMPER REFLECTOR RH	\$	SL 43.61
1	BUMEP R BRACKET SIDE LH REAR	\$	SL 135.97
1	BUMEP R RETAINER LH REAR	\$	SL 44.99
1	BUMPER REFLECTOR LH	\$	SL 43.61
1	BUMPER BEAM REAR	\$	N 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	N 225.95
1	BUMPER BEAM BRACKET RH REAR	\$	N 225.95
1	WHEEL HOUSING PANEL REAR LH	\$	N 4,682.09
1	CHASSIS PANEL REAR LH L70Y	\$	N 3,766.43
		\$	31,036.15
		10% \$	3,103.62
		\$	27,932.54

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	N 80.00 6555
1	DOOR CHECK BOLT	\$	N 22.69 X
1	DOOR GUIDE SCREW	\$	N 10.85 X
1	DOOR HINGE BOLT	\$	N 10.85 X
1	DOOR HINGE NUT RH	\$	N 14.60 X
1	DOOR CHECK BOLT	\$	N 22.69 X

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR CHECK NUT	\$	nn 3.75	X
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	X
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	X
1SET	PARKING AID	\$	Sh 700.00	X
1SET	REAR BUMPER CLIP	\$	nn 66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	nn 33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	} X
1SET	BUMEPR RETAINER RH CLIP RR	\$	nn 20.00	
1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn 10.00	
1SET	BUMEPR RETAINER CLIP LH RR	\$	nn 20.00	
1SET	BUMPER LOWER REAR RIVET	\$	nn 22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00	

TOTAL	\$	1,128.63
--------------	-----------	-----------------

TOTAL PARTS	\$	29,061.17
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	1400d
Putty and spray painting of the affected portion.	\$	5,000.00	132d
To rust-proofing of the affected areas.	\$	170.00	12d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	12d
To check steering geometry and computer wheel alignment	\$	220.00	6d
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	MV 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

To transfer of tire, rim and on wheel balancing.	\$	170.00 7
To Check Electrical Lighting Concerned.	\$	170.00 29
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 69
Towing Fees.	\$	120.00 50
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X

TOTAL \$ 14,890.00**Over All Total \$ 43,951.17****LUMP SUM (REPAIR DAY)****20 DAYS**
12 days

68762.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5699R

VF1ABL15AUC280295

RENAULT

LATITUDE

1.9.2018

AXA**SUPPLEMENTARY ESTIMATE****PART****LIST**

1	DOOR PANEL REAR RH	\$	2,844.66
1	DOOR GUIDE REAR RH	\$	176.82
1	DOOR HINGE UPPER RH	\$	274.50
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK REAR RH	\$	203.06
1	DOOR LOCK REAR RH	\$	908.75
1	DOOR HANDLE OUTER REAR RH	\$	126.49
1	DOOR HANDLE CAP REAR RH	\$	35.52
1	DOOR HANDLE SEAL REAR RH	\$	7.89
1	DOOR HANDLE COVER REAR RH	\$	13.22
1	DOOR HANDLE MODULE REAR RH	\$	133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75
1	DOOR REGULATOR NUT REAR RH	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR RH	\$	423.10
1	DOOR MOULDING REAR RH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR RH	\$	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR RH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR RH	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
1	DOOR SEAL REAR RH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64
1	FENDER PANEL REAR RH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL CENTER RH	\$	990.25
1	WHEEL HOUSING PANEL REAR RH	\$	4,682.09
1	CHASSIS PANEL REAR RH L70Y	\$	3,766.43
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP LH	\$	1,184.43

\$ 27,366.81

10% **\$ 2,736.68**

\$ 24,630.13

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	80.00
1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT RH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06

TOTAL \$ 181.63

TOTAL PARTS \$ 24,811.76



< S8M00UKH > IA with mandate uploaded

Type

 Question

Message

Liability: Insured collided into the parked vehicle (causing chain collision). Liability is down against our insured. We did clarify with insured the nature of the accident and agreed to settle and aware NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. Propose settlement amount is between \$14,482.49 to \$16,210.49. All the relevant documents had been uploaded in SMART CLAIM. For your kind attention and instruction. Thank you- Pohkin 11/09/2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/09/2018

Survey Details:

Date of loss	1-Sep-18
Date of appointment	5-Sep-18
Date of survey	4-Sep-18
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 5699R
Make and Model	RENAULT LATITUDE -2.0 L A
Date of registration	28/11/2014
Excess	
Market Value	\$0
Part Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 68,762.93
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 10,923.33
Check items (estimate)	\$ 2,068.08
Labour	\$ 3,150.00
Total	\$ 16,141.41
Lump Sum(if applicable)	\$ -

Number of days for repair	12
---------------------------	----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 488933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)	100%	100%
	with check item	no check item
Proposed repair cost(w/gst)	\$13,803.00 (\$12,900.00 + 7% GST)	\$12,075.00 (\$11,250.00 + 7% GST)
Loss of use	\$ -	\$ -
Loss of rental (estimate)	\$1,650.00(\$110.00 x 15days)	\$1,650.00(\$110.00 x 15days)
Loss of income (estimate)	\$750.00(\$50.00 x 15days)	\$750.00(\$50.00 x 15days)
LTA search fees	\$7.49	\$ 7.49
Others	\$ -	\$ -
Proposed Total	\$ 16,210.49	\$ 14,482.49

<< Re:< S8M00UKH > IA with mandate uploaded

Type

 Question

Message

pls proceed DS at max global sum \$15,000 all-in

[Reply](#)

Hsiao Tong (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Friday, 30 August 2019 5:09 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'
Cc: Admin A; claims@transcab.com.sg
Subject: RE: TCS REF: AAD1809-005--Accident involving SFZ7070T (AXA) & SHC5699R on 01.09.18 //LKK REF: CC3/ASM18016189/Kpb3

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 10 August 2019 4:07 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'jasminetan@transcab.com.sg'
<jasminetan@transcab.com.sg>; claims@transcab.com.sg
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: TCS REF: AAD1809-005--Accident involving SFZ7070T (AXA) & SHC5699R on 01.09.18 //LKK REF: CC3/ASM18016189/Kpb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$15,000.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>

Sent: Friday, 10 May 2019 9:08 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: FW: TCS REF: AAD1809-005--Accident involving SFZ7070T (AXA) & SHC5699R on 01.09.18

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC3/ASM18016189/Kfb3	Poh Kin

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Friday, 10 May 2019 8:31 AM

To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

Subject: TCS REF: AAD1809-005--Accident involving SFZ7070T (AXA) & SHC5699R on 01.09.18

WITHOUT PREJUDICE

Dear Sir/Mdm

We are making a claim against your client SFZ 7070T.

Enclosed is our LOD for your perusal and action.

Original hard copy will pass to Kenneth bring back your office.

Hope to receive your offer soon.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Vehicle Registration

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5699R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002174
Chassis No.:	VF1ABL15AUC280295
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	28 Nov 2014
First Registration Date:	28 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	27 Nov 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,337.00
COE Rebate Amount:	\$27,165.00
Total Rebate Amount:	\$36,538.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Sep 2018

OK

LEE

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1809-005

Your Ref : SFZ7070T, SHD721L, SHD148S

Date : 16.April 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

**ACCIDENT INVOLVING SHC5699R AND SFZ7070T, SHD721L, SHD148S ON 01/09/18
05:05 PM ALONG BLK 768 YISHUN AVENUE 3 CAR PARK**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	14,552.00
2.	Loss of Rental for <u>30</u> days @ \$ <u>101.46</u> per day	\$	2,029.20
3.	Loss of Income for <u>30</u> days @ \$ <u>50</u> per day	\$	1,000.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	17,588.69

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

10th September 2018

LIM KIM SENG

Block 832 Yishun Street 81,
#10-440,
Singapore 760832.

Dear Sir,

OUR REF : CC3/ASM18016189/Kfb3

YOUR REF : SFZ 7070T

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. SFZ 7070T, SHC 5699R AND OTHERS
ALONG BLK 769 YISHUN AVENUE 3 OPEN SPACE CARPARK ON 01.09.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party Property Damage claim against your policy.

We have received a claim from M/s Trans-Cab Auto Services Pte Ltd, acting on behalf of the owner of SHC 5699R against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had collided into Third Party vehicle SHC 5699R. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at pohkin@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHC5699R and SFZ7070T, SHD721L, SHD148S along BLK 768 YISHUN AVENUE 3 CAR PARK on 01/09/18 05:05 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 16 (day) of April 2019

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan
General Manager



A901809-005

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SFZ 7070T	(Insd veh)	Model: RENAULT LATITUDE 2.0L
	SHC 5699R	(TP veh)	
Date of Accident/ Time:	01/09/2018		

Repair Estimate	: \$	75,854.54	
Final Repair Cost	: \$		
Loss of Use	: \$		days at 5 per day
Rental (if any)	: \$		days at 5 per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
Final Settlement Sum (Global Sum)	: \$	15,000.00	

Payee Name : TRANS-CAB AUTO SERVICES PTE LTD

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: 22
	BOLA Liability: 100 (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

<p>Signature of workshop representative / Workshop stamp</p> <p>Name of Representative: NG HAI VIN</p> <p>Date: 05 SEP 2019</p> <p>KSC</p>	<p>Signature of Witness / Workshop stamp (if applicable)</p> <p>Name of Witness: Irene Tay</p> <p>Date: 05 SEP 2019</p>
--	---

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date:

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY,#27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1812-452 DATE : 31. December 2018 REFERENCE NO : AAD1809-005 TERMS : DUE DATE : 31. December 2018 PAGE : 1
---	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHC5699R;DOA 01.09.18(LUMP SUM-18)	1	14,552.00	14,552.00

Total SGD Excl. GST :	13,600.00
7% GST :	952.00
Total SGD Incl. GST :	14,552.00

****** FOURTEEN THOUSAND FIVE HUNDRED FIFTY TWO SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

16 April, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 01/09/18 05:05 PM at BLK 768 YISHUN AVENUE 3 CAR PARK

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHC5699R. The taxi was hired to TIANG BOON TECK a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$101.46 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan
General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

01-09-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.	
Accident No.	AAD1809-005		Accident Date 01-09-2018
1/9/2018 17:05	20/9/2018 15:00	SHC5699R	

Yours Faithfully,

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

[> Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SEZ1070T	01 Sep 2018 / 17:05:00	AXA INSURANCE PTE LTD
SLZ3447X	31 Aug 2018 / 18:45:00	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
PC8070P	02 Sep 2018 / 12:15:00	NTUC INCOME INS CO-OP LTD

[Print](#)[OK](#)[Save as PDF](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM18016189/Kpb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-10-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFZ 7070T	Veh. Inspected	SHC 5699R
Policy No.	GA216131	Coverage (\$)	0.00
Claim No.	S8M00UKH	Excess (\$)	0.00
Assign From		Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280295	Colour	METALLIC WHITE/RED
Odometer	324261	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR & O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/09/2018	Inspection Date	04/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5699R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR LH (CONSISTENT)	BENT	✓ 2,844.66	2,844.66
1	DOOR GUIDE REAR LH (CONSISTENT)	SERVICEABLE	✓ 176.82	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 274.50	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 300.55	-
1	DOOR CHECK REAR LH (CONSISTENT)	SERVICEABLE	✓ 203.06	-
1	DOOR LOCK REAR LH (CONSISTENT)	JAMMED	✓ 908.75	908.75
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	DISTORTED	✓ 126.49	126.49
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	✓ 35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	✓ 7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	✓ 13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	✓ 133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	BENT	✓ 1,135.10	1,135.10
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	JAMMED	✓ 893.75	893.75
1	DOOR REGULATOR NUT REAR LH (CONSISTENT)	SERVICEABLE	✓ 12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	✓ 6.31	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	✓ 423.10	-
1	DOOR MOULDING REAR LH (CONSISTENT)	BUCKLED	✓ 176.82	176.82
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	✓ 5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	✓ 6.91	-
1	DOOR CASING REAR LH (CONSISTENT)	SERVICEABLE	✓ 1,509.06	-
1	DOOR WATER SHIELD REAR LH (CONSISTENT)	SERVICEABLE	✓ 30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	✓ 12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	NOT NECESSARY	✓ 48.74	-
1	DOOR FINISHER INNER REAR LH (CONSISTENT)	SERVICEABLE	✓ 323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 20.33	-

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	< 20.33	-
1	DOOR GRAB HANDLE REAR LH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	DENTED / CUT	410.66	410.66
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUBBER SEAL REAR LH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH (CONSISTENT)	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	ROCKER PANEL INNER GARNISH LH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH (CONSISTENT)	SERVICEABLE	1,024.79	-
1	ROCKER PANEL CENTER LH (CONSISTENT)	BENT	990.25	990.25
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	WHEEL HOUSING PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	3,766.43	-

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR PANEL REAR RH (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	908.75	-
1	DOOR HANDLE OUTER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT) (ADDITIONAL)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT) (ADDITIONAL)	SERVICEABLE	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT) (ADDITIONAL)	SERVICEABLE	6.91	-
1	DOOR CASING REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	1,509.08	-
1	DOOR WATER SHIELD REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT) (ADDITIONAL)	SERVICEABLE	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT) (ADDITIONAL)	SERVICEABLE	48.74	-

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	20.33	-
1	DOOR GRAB HANDLE REAR LH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	162.02	-
1	DOOR GLASS RUBBER SEAL REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH (CONSISTENT) (ADDITIONAL)	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	543.47	-
1	ROCKER PANEL INNER GARNISH RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	1,024.79	-
1	ROCKER PANEL CENTER RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	990.25	-
1	WHEEL HOUSING PANEL REAR RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	4,682.09	-
1	CHASSIS PANEL REAR RH L70Y (CONSISTENT) (ADDITIONAL)	SERVICEABLE	3,766.43	-
1	HEADLAMP RH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	1,184.43	-
1	HEADLAMP LH (CONSISTENT) (ADDITIONAL)	SERVICEABLE	1,184.43	-

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-6,077.18	-1,519.32
			54,694.65	13,673.88
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER '6555 3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	10.06	-
1	SET PARKING AID (SN) (CONSISTENT)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	REAR DOOR STICKER '6555 3333' (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	6.12	-

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT) (ADDITIONAL)	SERVICEABLE	10.06	-
			1,310.22	219.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HINGE LOWER LH,DOOR FINISHER BRACKET INNER REAR LH,BUMPER BEAM REAR,BUMPER BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,WHEEL HOUSING PANEL REAR LH,CHASSIS PANEL REAR LH L70Y,DOOR PANEL REAR RH,DOOR HINGE UPPER RH AND DOOR HINGE LOWER RH.		6,000.00	1,400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,000.00	1,320.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.		120.00	50.00

Report Ref No. CC3/ASM18016189/Kpb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AIR OF HYDRAULIC PNEUMATIC JACK,	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			14,890.00	3,150.00
GRAND TOTAL			70,894.87	17,042.88

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,600.00
--	--	--	--	-----------

Report Ref No. CC3/ASM18016189/Kpb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBM000UKH
Reference	CCUASM1BD161B9/Kp43q2
Loss Date	1 September 2018
Report Date	5 Sep 2018 4:14:11 PM
Request Date	2 October 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SHCS899R

Make

TPVD RENAULT

Model

LATITUDE 2.0 I (A)

Service Address

...

Primary Contact/Insured

LIM KIM SENG
BLK 832 YISHUN ST B1, #10-440, 760832, Singapore

JETTAINSURANCE@GMAIL.COM

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type: Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019

NAME RENTAL RECEIPT.pdf	Forms / Claim Documents	SUB-TYPE Others	AAK AUTO CONSULTANTS PTE LTD (TP)	DATE 11 October 2019
RENTAL MILEAGE.pdf	Forms / Claim Documents	Others	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
LTA SEARCH.pdf	Forms / Claim Documents	Others	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
LKK Inspection.pdf	Forms / Claim Documents	Others	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
LKK Adjustment.pdf	Forms / Claim Documents	Others	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	AAK AUTO CONSULTANTS PTE LTD (TP)	11 October 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	AAK AUTO CONSULTANTS PTE LTD (TP)	11 September 2018
Immediate Advice (with mandate) dated 11.09.pdf	Reports & Statement	Estimate / Quotation	AAK AUTO CONSULTANTS PTE LTD (TP)	11 September 2018
TP Supplementary Estimate- Marked.pdf	Reports & Statement	Estimate / Quotation	AAK AUTO CONSULTANTS PTE LTD (TP)	11 September 2018
Letter to O/L.pdf	Letters and Correspondence	Policy Holders / Insured	AAK AUTO CONSULTANTS PTE LTD (TP)	11 September 2018
TP Estimate- Marked.pdf	Reports & Statement	Estimate / Quotation	AAK AUTO CONSULTANTS PTE LTD (TP)	11 September 2018