

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R**AAD1809-005***Not Authored*
11 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5699R

VF1ABL15AUC280295

RENAULT

LATITUDE

1.9.2018

AXA

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>Br</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	176.82 ?
1	DOOR HINGE UPPER LH	\$	<i>rr</i> 274.50 X
1	DOOR HINGE LOWER LH	\$	<i>rr</i> 300.55 X
1	DOOR CHECK REAR LH	\$	<i>rr</i> 203.06 X
1	DOOR LOCK REAR LH	\$	<i>Tm</i> 908.75 ✓
1	DOOR HANDLE OUTER REAR LH	\$	<i>rr</i> 126.49 ✓
1	DOOR HANDLE CAP REAR LH	\$	<i>rr</i> 35.52 X
1	DOOR HANDLE SEAL REAR LH	\$	<i>rr</i> 7.89 X
1	DOOR HANDLE COVER REAR LH	\$	<i>rr</i> 13.22 X
1	DOOR HANDLE MODULE REAR LH	\$	<i>rr</i> 133.60 X
1	DOOR REGULATOR REAR LH	\$	<i>Br</i> 1,135.10 ✓
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Tm</i> 893.75 ✓
1	DOOR REGULATOR NUT REAR LH	\$	<i>rr</i> 12.43 X
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>rr</i> 6.31 X
1	DOOR FINISHER REAR LH	\$	423.10 ?
1	DOOR MOULDING REAR LH	\$	<i>rr</i> 176.82 ✓
1	DOOR MOULDING CLIP L70Y	\$	<i>rr</i> 5.92 X
1	DOOR MOULDING SCREW L70Y	\$	<i>rr</i> 6.91 X
1	DOOR CASING REAR LH	\$	1,509.06 ?
1	DOOR WATER SHIELD REAR LH	\$	<i>rr</i> 30.39 X
1	DOOR CASING CLIP	\$	<i>rr</i> 12.63 X
1	DOOR CASING LIGHT L70Y	\$	<i>rr</i> 48.74 X
1	DOOR FINISHER INNER REAR LH	\$	<i>rr</i> 323.44 } X
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>rr</i> 46.97 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>rr</i> 20.33 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>rr</i> 20.33 }
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>rr</i> 20.33 }
1	DOOR GRAB HANDLE REAR LH	\$	<i>rr</i> 210.96 }

Trans-cab Auto Services Pte Ltd**AAD1809-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR BLIND REAR LH	\$	SL 741.80 X
1	DOOR WHEATHESTRIIP REAR LH	\$	Net 61 410.66 ✓
1	DOOR SEAL REAR LH	\$	SL 162.02 X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	SL 229.31 X
1	DOOR WAIST SEAL OUTER REAR LH	\$	SL 334.69 X
1	DOOR WAIST SEAL INNER REAR LH	\$	SL 115.64 X
1	FENDER PANEL REAR LH	\$	B 3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR	\$	SL 671.45 X
1	WHEELARCH REAR LH	\$	SL 543.47 X
1	ROCKER PANEL INNER GARNISH LH	\$	SL 466.51 X
1	ROCKER PANEL INNER LH	\$	SL 1,024.79 X
1	ROCKER PANEL CENTER LH	\$	B 990.25 ✓
1	BUMPER COVER REAR	\$	Bu 1,108.46 ✓
1	BUMPER LOWER REAR	\$	SL 768.84
1	BUMPER BRACKET CTR REAR	\$	SL 113.47
1	BUMEPR BRACKET SIDE RH REAR	\$	SL 135.97
1	BUMEPR RETAINER RH REAR	\$	SL 44.99
1	BUMPER REFLECTOR RH	\$	SL 43.61
1	BUMEPR BRACKET SIDE LH REAR	\$	SL 135.97
1	BUMEPR RETAINER LH REAR	\$	SL 44.99
1	BUMPER REFLECTOR LH	\$	SL 43.61
1	BUMPER BEAM REAR	\$	N 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	N 225.95
1	BUMPER BEAM BRACKET RH REAR	\$	N 225.95
1	WHEEL HOUSING PANEL REAR LH	\$	N 4,682.09
1	CHASSIS PANEL REAR LH L70Y	\$	N 3,766.43
		\$	31,036.15
		10% \$	3,103.62
		\$	27,932.54

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	N 80.00 605m
1	DOOR CHECK BOLT	\$	nn 22.69 X
1	DOOR GUIDE SCREW	\$	nn 10.85 X
1	DOOR HINGE BOLT	\$	nn 10.85 X
1	DOOR HINGE NUT RH	\$	nn 14.60 X
1	DOOR CHECK BOLT	\$	nn 22.69 X

Trans-cab Auto Services Pte Ltd

AAD1809-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR CHECK NUT	\$	nn 3.75	X
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	X
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	X
1SET	PARKING AID	\$	sh 700.00	X
1SET	REAR BUMPER CLIP	\$	nn 66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	nn 33.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	} X
1SET	BUMEP R RETAINER RH CLIP RR	\$	nn 20.00	
1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	nn 10.00	
1SET	BUMEP R RETAINER CLIP LH RR	\$	nn 20.00	
1SET	BUMPER LOWER REAR RIVET	\$	nn 22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00	

TOTAL	\$	1,128.63
--------------	-----------	-----------------

TOTAL PARTS	\$	29,061.17
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	14001
Putty and spray painting of the affected portion.	\$	5,000.00	132d
To rust-proofing of the affected areas.	\$	170.00	12d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	12d
To check steering geometry and computer wheel alignment	\$	220.00	6d
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

To transfer of tire, rim and on wheel balancing.	\$	170.00	7
To Check Electrical Lighting Concerned.	\$	170.00	29
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>Repair</i> 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	69
Towing Fees.	\$	120.00	50
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X

TOTAL \$ 14,890.00**Over All Total \$ 43,951.17****LUMP SUM (REPAIR DAY)****20 DAYS**
12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd**AAD1809-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5699R

VF1ABL15AUC280295

RENAULT

LATITUDE

1.9.2018

AXA**SUPPLEMENTARY ESTIMATE**

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66
1	DOOR GUIDE REAR RH	\$	176.82
1	DOOR HINGE UPPER RH	\$	274.50
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK REAR RH	\$	203.06
1	DOOR LOCK REAR RH	\$	908.75
1	DOOR HANDLE OUTER REAR RH	\$	126.49
1	DOOR HANDLE CAP REAR RH	\$	35.52
1	DOOR HANDLE SEAL REAR RH	\$	7.89
1	DOOR HANDLE COVER REAR RH	\$	13.22
1	DOOR HANDLE MODULE REAR RH	\$	133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75
1	DOOR REGULATOR NUT REAR RH	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR RH	\$	423.10
1	DOOR MOULDING REAR RH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR RH	\$	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR RH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33

Trans-cab Auto Services Pte Ltd**AAD1809-005**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5699R

1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR RH	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
1	DOOR SEAL REAR RH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64
1	FENDER PANEL REAR RH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL CENTER RH	\$	990.25
1	WHEEL HOUSING PANEL REAR RH	\$	4,682.09
1	CHASSIS PANEL REAR RH L70Y	\$	3,766.43
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP LH	\$	1,184.43

\$ 27,366.8110% **\$ 2,736.68****\$ 24,630.13****Specical Nett**

1	REAR DOOR STICKER '6555 3333'	\$	80.00
1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT RH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06

TOTAL \$ 181.63**TOTAL PARTS \$ 24,811.76**