

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L**AAD1809-004**

Not Notarized
Penalty B4 pain

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 721L
VF1ABL15AUC283314
RENAULT
LATITUDE
1.9.2018
AXA

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66 —
1	FENDER PANEL REAR LH	\$	<i>B</i> 3,299.13 —
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45 X
1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47 X
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sn</i> 466.51 X
1	ROCKER PANEL INNER LH	\$	<i>n</i> 1,024.79 X
1	ROCKER PANEL CENTER LH	\$	<i>n</i> 990.25 X
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
1	BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99
1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99
1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95
1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43
		\$	14,694.03
10%		\$	1,469.40
		\$	13,224.63

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	<i>n</i> 80.00 <i>basn</i>
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69 X
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85 X

Trans-cab Auto Services Pte Ltd**AAD1809-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

1	DOOR HINGE BOLT	\$	nn	10.85	}	X
1	DOOR HINGE NUT RH	\$	nn	14.60		
1	DOOR CHECK BOLT	\$	sn	22.69		
1	DOOR CHECK NUT	\$	sn	3.75		
1	DOOR LOCK SCREW L70Y	\$	sn	6.12		
1	DOOR CATCH SCREW L70Y	\$	sn	10.06		
1SET	PARKING AID	\$	sn	700.00	}	
1SET	REAR BUMPER CLIP	\$	nn	66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	}	X
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00		
1SET	BUMEP R RETAINER RH CLIP RR	\$	nn	20.00		
1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	nn	10.00		
1SET	BUMEP R RETAINER CLIP LH RR	\$	nn	20.00		
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00		

TOTAL \$ 1,128.63**TOTAL PARTS \$ 14,353.26****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	12001
Putty and spray painting of the affected portion.	\$	3,000.00	8801
To rust-proofing of the affected areas.	\$	170.00	901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 601
Towing Fees.	\$	120.00 501
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X

TOTAL \$ 9,130.00**Over All Total \$ 23,483.26**

Part - By - Part

(REPAIR DAY)**10 DAYS**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd**AAD1809-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 721L

VF1ABL15AUC283314

RENAULT

LATITUDE

1.9.2018

AXA**SUPPLEMENTARY ESTIMATE**

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66 X
1	FENDER PANEL REAR RH	\$	3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL CENTER RH	\$	990.25
1	HEADLAMP RH	\$	1,184.43
		\$	11,024.70
10%		\$	1,102.47
		\$	9,922.23

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	80.00
1	DOOR CHECK BOLT	\$	22.69
1	DOOR GUIDE SCREW	\$	10.85
1	DOOR HINGE BOLT	\$	10.85
1	DOOR HINGE NUT RH	\$	14.60
1	DOOR CHECK BOLT	\$	22.69
1	DOOR CHECK NUT	\$	3.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06

TOTAL \$ 181.63**TOTAL PARTS \$ 10,103.86**