

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier @ Kaki Bukit

Singapore 415875

Tel : 94513429

-1

Not Allowed
N/A
6/9/18
TOTAL 1055.

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

Date : 04.09.2018
Vehicle No. : SJK 3660Z
Make/Model : Toyota Allion
Chassis/Eng# :
Accident Date : 04.09.2018

Parts

- 01) Boot lid
- 02) Boot lid rubber
- 03) Boot lid lock
- 04) Tail lamp assy @\$380.5 x 2
- 05) Rear bumper
- 06) Rear bumper bracket @\$55 x2
- 07) Rear bumper retainer @\$65 x 2
- 08) Rear bumper lower reflector @35 x 2
- 09) Rear bumper reinforcement
- 10) rear bumper clips
- 11) Rear Panel

	\$	12	950.00	X
	\$	in	250.80	X
	\$	rub	380.50	✓
MLS	\$	cm	761.00	12C
	\$	Dis	550.80	✓
	\$	br	110.00	✓
	\$	br	130.00	✓
	\$	in	70.00	X
	\$	ns	450.80	X
	\$	per	60.00	✓
	\$	3410	880.50	✓
	\$		4,594.40	✓
Less 25%	\$		(1,148.60)	26923
	\$		3,445.80	

S/Nett

- 12) Reverse sensor

\$ shed 250.00

Labour charges

- 24) To check wiring
- 27) To knock out dents on effected areas and renew parts
- 28) To putty & respray painting

\$ 200.00 30
\$ 1,200.00 600
\$ 1,200.00 1000
\$ 2,600.00

Grand Total \$ 6,295.80

for JA AUTOCARE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2815