

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SJT2177L  
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739  
 ATTN: Motor Claim Department

WS Ref: TP/AXA/WL  
 Claim Type: Third Party  
 Accident Date: 04/09/2018  
 TP Veh Reg No: SJR5433M

*Not Authored*

*L1 Reg 87*

*Resurvey After Paint 6 days*

Estimate No: ES1891013/WL  
 Date: 04 Sep 2018  
 Policy No: MU012505  
 Veh Reg No: SJT2177L  
 Make/Model: TOYOTA COROLLA ALTIS 1.6 AUTO  
 Chassis No: MR053ZEE106155739  
 Engine No: 3ZZ4933599  
 Reg. Date: 29/09/2009

## Estimate Repair Cost to Vehicle No :SJT2177L

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
<b>List Price</b>				
1 REAR BUMPER	584.00	1 PC	CMA 584.00	✓
2 REAR BUMPER REINFORCEMENT	301.80	1 PC	CRA 301.80	✓
3 REAR BUMPER LH REFLECTOR	37.70	1 PC	CMA 37.70	✓
4 REAR BUMPER SIDE RETAINERS	55.60	2 PCS	DIT 111.20	✓
5 REAR BUMPER CLIPS	3.50	6 PCS	NA 21.00	✓
6 REAR BOOT	819.60	1 PC	RA 819.60	✓
7 REAR BOOT LOGO	52.15	1 PC	NA 52.15	✓
8 REAR BOOT EMBLEM (1.6)	52.10	1 PC	NA 52.10	✓
9 REAR BOOT EMBLEM (COROLLA)	44.17	1 PC	NA 44.17	✓
10 REAR BOOT EMBLEM (ALTIS)	44.80	1 PC	NA 44.80	✓
11 REAR BOOT EMBLEM (LX)	37.10	1 PC	NA 37.10	✓
12 REAR BOOT INNER LOCK	116.80	1 PC	NA 116.80	✓
13 REAR BOOT INNER RUBBER	184.70	1 PC	CA 184.70	✓
14 REAR BOOT HINGES	62.80	2 PCS	R 125.60	X
15 TAILLAMPS	414.70	2 PCS	CMA 829.40	✓
16 REAR CENTRE PANEL	580.60	1 PC	RA 580.60	✓
17 REAR CENTRE PANEL INNER GARNISH	202.70	1 PC	DIT 202.70	✓
			4,145.42	
		Less 25%	1,036.36	3,109.07
<b>Special Net</b>				
18 REVERSE SENSOR	200.00	1 SET	Shen 200.00	✓
			200.00	200.00
<b>Labour</b>				
19 PANEL BEATING	800.00	1 LA	800.00	700
20 PUTTY & RESPRAY PAINT	800.00	1 LA	800.00	720
21 RUSTPROOFING	60.00	1 LA	60.00	✓
22 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			1,710.00	1,710.00
		Total	S\$ 5,019.07	
		Add GST @ 7%	351.33	
		Total Amount Payable	S\$ 5,370.40	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE