

INS CASE OWNER:

CC 3, Asm 180

16/9/18, F 16/3 1/2

LKK:
IDAC:

67750

Surveyor:

Kenneth

DOI:

ASSIGNMENT

4/9/2018

Date / Time:

4/9/2018

Registration Number:

Pre-assign / CCU / FTE

PB6 6648 G

S8m 0040H



Insured Vehicle No.:

Name of Insured:

WIDMANN, KIM B. JAMIL

Insured Tel No.:

HP:

9286422

Excess Sec II :S\$

D.O.A.:

3/9/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 888P



INSRS:

WSP:

Tel:

Liability:

RMKS:

TRANS. G6



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHD 888P - CS/PA/2018/611 (Gohm) : DOA 2/10/18
 - CS/PA/2018/611 (Gohm) : DOA 19/10/18
 - CS/PA/2018/611 (Gohm) : DOA 3/10/18
 PB6 6648 G - X

STAGE DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI

After call Itr to OI

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA :

Medical Bill

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Red OI PR FROM APP. TP WAS FINISHED FOR INCOMING DRIVING

APP INSTRUCTED TO REJECT TP CLAIM.

Email WSP TO REJECT CLAIM.

Reject Case

By (staff):

Approved by:

Date: 19.02.19

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

G 21/2/19

250

ASS. REC. BY:

REF:

AKA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

710

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 888P

Yr Regn:

07, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude c.c. 1.9PS

Colour:

M. White / M

A/C: Insured / Std / NI / NA

Sp. Reading

463231

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL 15 AUC. 281594

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/9/18

D.O.I.

4/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/9

File pass to Catherine

89401

(RED: 20,718.10 96%)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fixing

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 888P**AAD1809-017***Not Authorised*
L1 Syg 89401

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 888P

VF1ABL15AUC281594

RENAULT

LATITUDE

3.9.2018

AXA

PART		LIST	
1	DOOR PANEL REAR RH <i>CH</i>	\$	<i>M</i> 2,844.66
1	DOOR GUIDE REAR RH <i>CH</i>	\$	<i>SH</i> 176.82
1	DOOR HINGE UPPER RH <i>CH</i>	\$	<i>M</i> 274.50
1	DOOR HINGE LOWER RH <i>CH</i>	\$	<i>M</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>SH</i> 203.06
1	DOOR LOCK REAR RH <i>CH</i>	\$	<i>M</i> 908.75
1	DOOR HANDLE OUTER REAR RH <i>CH</i>	\$	<i>M</i> 126.49
1	DOOR HANDLE CAP REAR RH <i>CH</i>	\$	<i>SH</i> 35.52
1	DOOR HANDLE SEAL REAR RH <i>CH</i>	\$	<i>SH</i> 7.89
1	DOOR HANDLE COVER REAR RH <i>CH</i>	\$	<i>SH</i> 13.22
1	DOOR HANDLE MODULE REAR RH <i>CH</i>	\$	<i>SH</i> 133.60
1	DOOR REGULATOR REAR RH <i>CH</i>	\$	<i>M</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH <i>CH</i>	\$	<i>SH</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>SH</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SH</i> 6.31
1	DOOR FINISHER REAR RH <i>CH</i>	\$	<i>SH</i> 423.10
1	DOOR MOULDING REAR RH <i>CH</i>	\$	<i>SH</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>SH</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>SH</i> 6.91
1	DOOR CASING REAR RH	\$	<i>SH</i> 1,509.06
1	DOOR WATER SHIELD REAR RH <i>CH</i>	\$	<i>SH</i> 30.39
1	DOOR CASING CLIP	\$	<i>SH</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>SH</i> 48.74
1	DOOR FINISHER INNER REAR RH <i>CH</i>	\$	<i>SH</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH <i>CH</i>	\$	<i>M</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>M</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>M</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>M</i> 20.33
1	DOOR GRAB HANDLE REAR RH <i>CH</i>	\$	<i>SH</i> 210.96

Trans-cab Auto Services Pte Ltd

AAD1809-017

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 888P

1	DOOR BLIND REAR RH <i>L/H</i>	\$	<i>Sm</i> 741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	<i>5</i> 410.66
1	DOOR SEAL REAR RH	\$	<i>5</i> 162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>5</i> 229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>4</i> 334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>5</i> 115.64
1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	<i>h</i> 671.45
1	WHEELARCH REAR RH	\$	<i>5</i> 543.47
1	ROCKER PANEL INNER GARNISH RH	\$	<i>5</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>5</i> 1,024.79
1	ROCKER PANEL CENTER RH	\$	<i>Sm</i> 990.25
		\$	18,918.30
10%		\$	1,891.83
		\$	17,026.47

Specical Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 80.00 <i>6050</i>
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69 <i>X</i>
1	DOOR GUIDE SCREW	\$	<i>5</i> 10.85 <i>X</i>
1	DOOR HINGE BOLT	\$	<i>5</i> 10.85 <i>X</i>
1	DOOR HINGE NUT RH	\$	<i>5</i> 14.60 <i>X</i>
1	DOOR CHECK BOLT	\$	<i>5</i> 22.69 <i>X</i>
1	DOOR CHECK NUT	\$	<i>5</i> 3.75 <i>X</i>
1	DOOR LOCK SCREW L70Y	\$	<i>5</i> 6.12 <i>X</i>
1	DOOR CATCH SCREW L70Y	\$	<i>5</i> 10.06 <i>X</i>

TOTAL \$ **181.63**TOTAL PARTS \$ **17,208.10****LABOUR**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts, adjust
and realign the same

\$

2001
3,000.00 *6001*

Trans-cab Auto Services Pte Ltd

AAD1809-017

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 888P

Putty and spray painting of the affected portion.	\$	3,000.00 ⁶⁶⁰¹
To rust-proofing of the affected areas.	\$	~ 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 ²⁰¹
To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X

TOTAL \$ 9,010.00**Over All Total \$ 26,218.10**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**10 DAYS****2 day**

9/3/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

3878K

Vehicle Details

Vehicle No.:

SHD888P

Vehicle to be Exported:

Yes

Intended Deregistration Date:

03 Sep 2018

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour:

Red

Manufacturing Year:

2015

Engine No.:

M9R8839C002798

Chassis No.:

VF1ABL15AUC281594

Maximum Power Output:

127.0 kW (170 bhp)

Open Market Value:

\$19,998.00

Original Registration Date:

10 Jul 2015

First Registration Date:

10 Jul 2015

Transfer Count:

0

Actual ARF Paid:

\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

09 Jul 2023

PARF Rebate Amount:

\$14,998.00

Intended COE Rebate Details

COE Expiry Date:

09 Jul 2023

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$53,004.00

COE Rebate Amount:

\$32,130.00

Total Rebate Amount:**\$47,128.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Sep 2018

OK

Vivian Lau (LKKAUTO)

From: LOH Cynthia <cynthia.loh@axa.com.sg>
Sent: Wednesday, 28 November, 2018 9:21 AM
To: Vivian Lau (LKKAUTO)
Subject: FW: S8M00UCH / P1983778 FBG6648G Exp : 1.10.18 - Received Police Investigation Letter
Attachments: IMG-20181127-WA0000.jpg.jpg
Importance: High

Dear Vivian,

We refer to the trailing email and the attached PIR.

Please proceed to reject TP.

Thanks & Regards,



Cynthia Loh
Specialist, Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Email: cynthia.loh@axa.com.sg
Customer Care No. 1800 8804741
www.axa.com.sg



 **Please consider the environment before printing this email**

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: CHEN Xinyou
Sent: Tuesday, November 27, 2018 4:51 PM
To: LOH Cynthia <cynthia.loh@axa.com.sg>
Subject: FW: P1983778 FBG6648G Exp : 1.10.18 - Received Police Investigation Letter
Importance: High

Hi Cynthia

Please find below email and attachment from Joanne for your necessary action - S8M00UCH

Thank you.

Best Regards



Chen Xinyou

Senior Executive, Claims (Litigation) Department
AXA Insurance Pte Ltd

8 Shenton Way, #24-01 AXA Tower, Singapore 068811

Email: chen.xinyou@axa.com.sg

Customer Care hotline 1800-880 4888

www.axa.com.sg



Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: joannechong@anda.com.sg [mailto:joannechong@anda.com.sg]

Sent: 27/11/2018 4:44 PM

To: KHOR Saw Theng <sawtheng.khor@axa.com.sg>; CHEN Xinyou <chen.xinyou@axa.com.sg>

Subject: P1983778 FBG6648G Exp : 1.10.18 - Received Police Investigation Letter

Importance: High

Dear both,

Insured : LUQMANULHAKIM BIN JAMIL

DOA : 3.9.2018

Pls find attached Police Investigation Result fya.

Hope to hear from you soon as Insured refused to pay the additional renewal premium imposed due to the claims reserve.

Thanks & Regards,

Joanne Chong | Anda Insurance Agencies Pte Ltd

1 King George's Avenue #06-00 Rehau Building Singapore 208557 | Co Reg No: 197903504K

Main: +65 6554 2288 | Fax: +65 6453 4466

Joannechong@anda.com.sg | www.anda.com.sg

Please do feel free to contact us should you have any other business or personal insurance needs or enquiries. We arrange all types of general insurance such as Foreign Worker's Insurance (Security Bond, Medical and Work Injury Compensation), Foreign Domestic Helper's Insurance, Motor Vehicles & Motorcycles, Travel, Home, Group & Individual Medical, Personal Accident, Contracts, Marine and all other Commercial/Business Insurance. We shall be pleased to assist.

We have moved! Our new address is as stated above. All our contact information remains unchanged.

Visit us at <http://www.anda.com.sg>

IMPORTANT NOTICE

The content of this e-mail (including any attachments) as received may not be the same as sent. If you consider that the content is material to the formation or performance of a contract or you are otherwise relying upon its accuracy, you should consider requesting a copy be sent by facsimile or normal mail. The information in this e-mail is confidential and may be legally privileged. If you are not the intended recipient, please notify the sender immediately and then delete this e-mail entirely - you must not retain, copy, distribute or use this e-mail for any purpose or disclose any of its content to others. Opinions, conclusions and other information in this e-mail that do not relate to the official business of any Anda Insurance Group company shall be understood as neither given nor endorsed by it.

Please note we intercept and monitor incoming / outgoing e-mail and therefore you should neither expect nor intend any e-mail to be private in nature. We have checked this e-mail for viruses and other harmful components and believe but not guarantee it virus-free prior to leaving our computer system. However, you should satisfy yourself that it is free from harmful components, as we do not accept responsibility for any loss or damage it may cause to your computer systems.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/49889/2018
Date : 18 October, 2018

LUQMANULHAKIM BIN JAMIL
APT BLK 491G TAMPINES STREET 45
#08-268
SINGAPORE 526491

Dear Sir/Madam

**ACCIDENT INVOLVING FBG6648G/SHD888P ON 03.09.2018 AT 1159 HRS, ALONG PIE (TUAS),
CHANGI SOUTH AVENUE 3, LP: 9**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SHD888P has committed an offence of Inconsiderate driving (accident) under Section 65(b) Of The Road Traffic Act Chapter 276. Action has been initiated against the driver for the said offence.

3. If you have any queries, please contact the Investigation Officer, Jerry Yeo at telephone number 6547 6213.

Yours faithfully

RENEE LOH
FOR HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE



Re:PROCEED DS

Type

🔔 Question

Message

Refer to our email dd 28/11. Please reject TP

Reply

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 19 February 2019 3:25 PM
To: 'Jasmine Tan'; 'Ng Wai Yin'
Cc: 'claims'
Subject: Your Ref: AAD1809-017, ACCIDENT INVOLVING SHD 888P AND FBG 6648G ON 03/09/2018
Attachments: OI PIR.pdf; OI SKETCH PLAN.pdf

Your Ref: AAD1809-017
Our Ref: CC3/ASM18016196/Kea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SHD 888P AND FBG 6648G ON 03/09/2018

We attached here with a copy of our insured's accident statement and our insured police investigation result for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client filter into our insured lane and collided into our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM18016196/Kea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 22-02-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBG 6648G	Veh. Inspected	SHD 888P
Policy No.	VMO/P1983778	Coverage (\$)	0.00
Claim No.	S8M00UCH	Excess (\$)	0.00
Assign From		Assign Date	04/09/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281594	Colour	METALLIC WHITE / RED
Odometer	463231	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/09/2018	Inspection Date	04/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 888P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	126.49	-
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH (CONSISTENT)	NOT NECESSARY	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-

Report Ref No. CC3/ASM18016196/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOO WAIST SEAL INNER REAR RH (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	ROCKER PANEL INNER GARNISH RH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH (CONSISTENT)	SERVICEABLE	1,024.79	-
1	ROCKER PANEL CENTER RH (CONSISTENT)	SERVICEABLE	990.25	-
	LESS 10% DISCOUNT		-1,891.83	-
			17,026.47	-
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	10.06	-
			181.61	60.00

Report Ref No. CC3/ASM18016196/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,DOOR HANDLE OUTER REAR LH,DOOR REGULATOR REAR LH,DOOR FINISHER BRACKER INNER REAR LH,FDOOR FINISHER BRACKET INNER REAR RH,DOOR FINISHER BRACKET INNER REAR RH,DOOR FINISHER BRACKET INNER REAR RH AND FENDE PANEL REAR.		3,000.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			9,010.00	880.00
	GRAND TOTAL		26,218.08	940.00
	RECOMMENDED COST OF REPAIRS			940.00

Report Ref No. CC3/ASM18016196/Kea3q2



Report Ref No. CC3/ASM18016196/Kea3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

