

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

AAD1809-016*Not Authored
C/Rep B***SHB 7661R**

KL1LA69RJB092574

CHEVROLET

EPICA 2.0

31.8.2018

CHINA TAIPING**PART****LIST**

1	1	Front Fender RH	\$	<i>R</i>	837.60 X
2	1	Front Fender Liner RH	\$	<i>SL</i>	47.00 X
3	1	Front Fender Inner Wheel House Panel RH	\$	<i>R</i>	1,437.00 X
4	1	Front Fender LH	\$	<i>R</i>	837.60 X
5	1	Front Fender Liner LH	\$	<i>SL</i>	47.00 X
6	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i>	1,437.00 X
7	1	Front Bumper	\$	<i>Bumper</i>	1,202.00 ✓
8	1	Front Bumper Lower Absorber	\$	<i>SL</i>	180.00 X
9	1	Front Bumper Reinforcement	\$	<i>R</i>	356.00 ✓
10	1	Front Bumper Retainer RH	\$	<i>SL</i>	102.00 X
11	1	Front Bumper Retainer LH	\$	<i>SL</i>	102.00 X
12	1	Front Bumper Lower Grille	\$	<i>SL</i>	78.00 ✓
13	1	Front Bumper Lower Stiffener	\$	<i>R</i>	134.37 X
14	1	Front Bumper Bracket LH	\$	<i>R</i>	10.00 X
15	1	Front Bumper Bracket RH	\$	<i>R</i>	10.00 X
16	1	Bumper Fog Lamp Cover RH	\$	<i>SL</i>	32.40 X
17	1	Bumper Fog Lamp Cover LH	\$	<i>SL</i>	32.40 X
18	1	Bonnet	\$	<i>Bu</i>	1,250.00 ✓
19	1	Bonnet hinge RH	\$	<i>R</i>	36.00 X
20	1	Bonnet hinge LH	\$	<i>R</i>	36.00 X
21	1	Bonnet Moulding	\$	<i>SL</i>	161.97 ✓
22	1	Bonnet Lock	\$	<i>R</i>	60.00 ✓
23	1	Bonnet cable	\$	<i>SL</i>	125.00 ✓
24	1	Front Support Panel Assy	\$	<i>Bu</i>	1,222.32 ✓
25	1	Headlamp RH	\$	<i>SL</i>	816.00 ✓
26	1	Headlamp LH	\$	<i>SL</i>	816.00 ✓
27	1	Windscreen Washer Tank - Filler Neck	\$	<i>SL</i>	4.80 X
28	1	Windscreen Washer Tank	\$	<i>SL</i>	62.00 X
29	1	Windscreen Washer Tank Motor	\$	<i>SL</i>	51.00 X

Trans-cab Auto Services Pte Ltd**AAD1809-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

30	1	Washer Tank Hose	\$	SL	21.00	X
31	1	Radiator Assembly	\$	R	618.00	✓
32	1	Radiator upper hose	\$	SL	30.00	X
33	1	Radiator lower hose	\$	SL	120.00	X
34	1	Radiator Grille (Grille A-Rad)	\$	CM	367.00	—
35	1	Radiator Grille Top Cover	\$	Dir	45.02	—
36	1	Fan Blade(A/C)	\$	CM	536.00	✓
37	1	Fan Blade(Radiator)	\$	SL	634.00	X
38	1	Aircon Condenser	\$	R	600.00	✓
39	1	Aircon hose - condenser to compressor	\$	SL	450.00	}
40	1	Aircon hose - compressor to evaporator	\$	SL	624.00	
41	1	Aircon hose - condenser to evaporator	\$	SL	580.00	
42	1	Aircon hose - condenser to compressor	\$	SL	450.00	
43	1	Aircon hose - compressor to evaporator	\$	SL	624.00	
44	1	Aircon hose - condenser to evaporator	\$	SL	580.00	
45	1	Aircon compressor - pump	\$	SL	1,847.95	
46	1	Aircon compressor bracket	\$	R	245.30	
47	1	Aircon condensor bottom bushing	\$	SL	119.00	
48	1	Air Cleaner Assembly (Cleaner A-Air)	\$	SL	112.00	
49	1	Air Filter (element A-Air Cleaner)	\$	SL	39.00	
50	1	Air-cleaner intake duct	\$	SL	89.25	
51	1	Air-cleaner intake duct hose (top)	\$	SL	75.85	
52	1	Air intake resonator top (square)	\$	SL	14.52	
53	1	Air intake resonator (beside fender)	\$	SL	20.01	
54	1	Air intake resonator hose (bottom)	\$	SL	60.90	
55	1	Air intake resonator tank top bracket	\$	R	45.00	
56	1	Resonator A-A/CL	\$	SL	137.00	
57	1	Alternator assembly	\$	SL	1,040.00	}
58	1	Battery (Battery A)	\$	SL	405.00	
59	1	Battery tray	\$	SL	65.00	
60	1	Battery fastener bracket	\$	R	23.50	
61	1	Battery fastener bolt	\$	SL	46.00	
62	1	Front Fuse Box (support panel top)	\$	SL	215.00	
63	1	Front Fuse Top Cover	\$	SL	25.00	
64	1	Fuse Box	\$	SL	716.00	
65	1	Fuse box top (cover)	\$	SL	250.00	
66	1	Fuse Box Lower	\$	SL	60.00	
67	1	Fuse box centre cover	\$	SL	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

68	1	Engine main harness wire	\$	1,500.00
69	1	Gear box assy	\$	20,800.00
70	1	Cross member	\$	1,030.71
71	1	Gear box cross member bracket	\$	450.00
72	1	Gear Box Mounting RH	\$	142.50
73	1	Engine block	\$	28,895.40
74	1	Engine mounting side	\$	175.00
75	1	Engine lower splashshield cover	\$	240.00
76	1	Front Centre Cross Member	\$	763.50
77	1	Front Centre Member (Member A-Frt Susp, Ctr)	\$	265.63
78	1	Engine suspension cross member	\$	344.07
79	1	Engine oil sump	\$	500.00
80	1	Engine oil sump strainer	\$	125.60
81	1	Engine overhaul gasket	\$	98.70
82	1	Engine oil sump sealant	\$	45.00
83	1	Engine Splash Cover RH (Cover A-Engine)	\$	168.00
84	1	Engine Splash Cover LH (Cover A-Engine)	\$	168.00
85	1	ECU assy	\$	4,575.65
86	1	ABS pump	\$	5,547.45
87	1	ABS pump pipe	\$	325.33
88	1	Steering Rack & Pinion Assy (Gear A-Strg)	\$	905.51
89	1	Steering Rack End (Spring A-Clock)	\$	88.56
90	1	Steering Tie-Rod End (End -Tie Rod)	\$	67.00
91	1	Steering wheel Assy (Wheel A-Strg)	\$	258.41
92	1	Power steering pump	\$	1,755.31
93	1	Power steering reservoir tank	\$	120.00
94	1	Power steering inlet / outlet pipe	\$	65.00
95	1	Power steering pump pulley	\$	66.00
96	1	Power steering hose - pressure	\$	256.00
97	1	Power steering hose - non pressure	\$	312.11
98	1	Dash Board lower fuse box assy	\$	545.60
99	1	Wiper/Signal switch	\$	108.20
100	1	Glove box	\$	61.00
101	1	Console Box top cover	\$	250.00
102	1	Console Box front	\$	213.00
103	1	Front Shock Absorber Assy RH	\$	216.17
104	1	Front Shock Absorber Top Mounting RH	\$	48.32
105	1	Front Shock Absorber Assy LH	\$	216.17

Trans-cab Auto Services Pte Ltd**AAD1809-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

106	1	Front Shock Absorber Top Mounting LH	\$	Sn	48.32	
107	1	Front Lower Arm RH	\$	S	283.00	
108	1	Front Lower Arm LH	\$	S	283.00	
109	1	Front Knuckle Arm RH	\$	S	230.00	
110	1	Front Knuckle Arm LH	\$	S	230.00	
111	1	Front Hub Unit	\$	S	376.00	
112	1	Front Disc Brake RH	\$		157.55	
113	1	Front Disc Brake LH	\$	S	157.55	
114	1	Front Strut Bar Bracket LH	\$	S	235.01	
115	1	Front Stabilizer Bar	\$		234.00	
116	1	Front Stabilizer Bar Link RH	\$	S	51.79	
117	1	Front Stabilizer Bar Link LH	\$		51.79	
118	1	Front Stabilizer Bar Bracket RH	\$		105.75	
119	1	Front Stabilizer Bar Bracket LH	\$		105.75	
120	1	Front Stabilizer Bar Bush RH	\$		66.00	
121	1	Front Stabilizer Bar Bush LH	\$		66.00	
122	1	Front Beam A - Impact RH	\$		214.00	
123	1	Front Beam A - Impact LH	\$		214.00	
124	1	Drive Shaft RH	\$		900.00	
125	1	Drive Shaft LH	\$		900.00	
126	1	Interm Axle Shaft (Centre)	\$		241.14	
127	1	Front Seat Belt RH	\$		402.50	
128	1	Front safety belt cover garnish	\$	Sn	125.00	
129	1	Rear Bumper	\$	Bz	1,202.00	✓
130	1	Rear Bumper Beam	\$	Bz	239.94	—
131	1	Rear Bumper Centre Absorber	\$	CNT	260.00	—
132	1	Rear Bumper Side Retainer RH	\$	Sn	68.76	X
133	1	Rear Bumper Side Retainer LH	\$	DIT	68.76	✓
134	1	Rear Bumper Reflectors RH	\$	CM	119.74	—
135	1	Rear Bumper Reflectors LH	\$	Bz	119.74	—
136	1	Rear Bumper Tow Hook Cover	\$	Sn	93.00	X
137	1	Rear End Panel Outer	\$	Bz	623.76	✓
138	1	Rear End Panel Inner Trim	\$	DIT	263.84	✓
139	1	Rear Luggage Floor Panel	\$	Bz/Au	973.00	✓
140	1	Rear Luggage Floor Panel Insulator	\$	Mc	63.50	✓
141	1	Rear Luggage Floor Panel Trim Board	\$	Sn	378.00	X
142	1	Bootlid	\$	Bz	973.00	✓
143	1	Bootlid inner trim board	\$	Sn	400.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

144	1	Bootlid Weatherstrip	\$	344.28	✓
145	1	Bootlid Lock - Top	\$	466.56	✓
146	1	Bootlid 'CHEVROLET' Badge	\$	120.62	✓
147	1	Bootlid Logo	\$	138.84	✓
148	1	Bootlid 'EPICA LT' Badge	\$	119.84	✓
149	1	Bootlid Reflector Centre	\$	217.97	X
150	1	Bootlid Reflector RH	\$	128.40	✓
151	1	Bootlid Reflector LH	\$	128.40	✓
152	1	Rear Tail Lamp RH	\$	479.30	✓
153	1	Rear Tail Lamp LH	\$	479.30	✓
154	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00	X
155	1	Rear Fender RH	\$	1,145.00	X
156	1	Rear Fender Inner Trim RH	\$	418.44	X
157	1	Rear Fender LH	\$	1,145.00	X
158	1	Rear Fender Inner Trim LH	\$	418.44	X

TOTAL	\$	113,932.24
10%	\$	11,393.22
	\$	102,539.02

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	24.00	✓
2	2	Front Windscreen Sealant	\$	100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	10.00	✓
5	1 Set	Front licence plate with holder	\$	192.00	258n
6	1 Set	Radiator Grille clip	\$	35.00	✓
7	1 Set	Front Fender Liner clip RH	\$	30.00	X
8	1 Set	Louver Cowl Top clip	\$	30.00	X
9	2	Bonnet stopper	\$	15.00	X
10	1Set	Bootlid inner trim board Clip	\$	40.00	X
11	1Set	Rear Bumper Parking Sensor	\$	300.00	✓
12	1Set	Rear Bumper Fastener Clip	\$	44.00	✓
13	1Set	Rear Fender Inner Trim Clip LH	\$	30.00	X
14	1Set	Rear Bumper End Dust Cover Clip	\$	30.00	X
15	1	Rear Exhaust Mounting	\$	300.00	X
16	2	Rear Windscreen Sealant	\$	80.00	X
17	1	Rear Windscreen Inner Sponge Seal	\$	100.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-016

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

18	1	Spare Tyre	\$	Sn 180.00 ✓
19	1	Spare Wheel Rim	\$	Sn 126.74 ✓

TOTAL \$ 1,766.74**TOTAL PARTS \$ 104,305.76****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00 401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00 20001
Towing Fees.	\$	120.00 501
Putty and spray painting of the affected portion.	\$	6,000.00 16001
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 440.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 2501
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 1001
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To replace, refix and top up coolant for radiator	\$	170.00 501

Trans-cab Auto Services Pte Ltd**AAD1809-016**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7661R

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	100/ 380.00
To rust-proofing of the affected areas.	\$	170.00 150/
To transfer of end panel fittings and conduct water seepage test.	\$	~ 170.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 170.00 X
To remove and renew engine and gear box mounting.	\$	~ 380.00 X
To dismantle and refit engine cross-member and engine mounting.	\$	~ 380.00 X
To lift-up engine with gear box and refit.	\$	~ 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
To check ABS brake efficiency, final checking and testing.	\$	~ 380.00 X
To remove and refit ABS pump relay to enable repair.	\$	~ 380.00 X
To remove and refit air bag system and reset.	\$	~ 480.00 X

TOTAL \$ 19,700.00**Over All Total \$ 124,005.76****Repair Days****25 DAYS****19 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: