

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

4-Sep-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1170 J

1 pc	Rear n/s door	\$ 2,017.48
2 pcs	Rear n/s door hinges @ \$39.00 X	\$ 78.00
		\$ 2,095.48
	Less 20%	\$ 419.10
		\$ 1,676.38

### S/NETT

1 set	N/s door sticker	\$ 100.00
1 pc	Rear n/s fender sticker	\$ 60.00
	Sundry	\$ <del>50.00</del> 20
	To dismantle and refit the inner components of the rear n/s door into new shell door	\$ <del>150.00</del> 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, n/s rocker panel etc	\$ <del>600.00</del> 300
	To putty and spray painting on rear n/s door, rear n/s fender, n/s rocker panel	\$ <del>600.00</del> 500
	To apply rustproofing on the repaired and replaced panels.	\$ <del>150.00</del> 50
		\$ 3,386.38

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ka lun 10/10/18  
5/9/18 1000 hrs  
3 Dgs.  
P.H.P  
Before P.H.P photo