



MK Vehicle Engineering Pte Ltd
 48 Toh Guan Road East, #04-124/125 Enterprise Hub, Singapore 608586
 Tel: 6763 6363 | Fax: 6763 0919
 Email: repair@mkvehicle.com.sg
 Co. Reg. No./ GST No.: 201623663G

QUOTATION

To: EQ INSURANCE CO.LTD

Our Ref : Q18090006
 Date : 10 Sep 2018

Dear Sir / Madam,

RE: Quotation for SJB2973A HONDA STREAM

Remarks :THIRD PARTY CLAIM.

No	Description	Qty	UOM	U/P (\$\$)	Amt (\$\$)
1	REAR BUMPER ASSY	1.00	PC	520.00	520.00
2	REAR DOOR BOARD GARNISH CLIP	8.00	PCS	5.00	40.00
3	REAR EXHAUST SILENECER BOX	1.00	PC	620.00	620.00
4	LABOUR TO KNOCK UP AND STRAIGHTEN REAR END PANEL, TAIL LAMP PANE, REAR DOOR, DISMANTLE & REFIX BUMPER & DOOR BOARD CLIPS.	1.00	TIME	450.00	450.00
5	DISMANTLE TO REMOVE AND REFIX REAR EXHAUST SILENCER BOX	1.00	TIME	120.00	120.00
6	RESPRAY PAINTING REAR DOOR, BUMPER, END PANEL & TAIL LAMP PANEL	1.00	TIME	600.00	600.00

ESTIAMATED THREE WORKING DAYS TO REPAIR.0

Subtotal: 2,350.00
7.00% GST: 164.50
Total Amount: 2,514.50

Rasul
 Hp 90010068
 4 days
 4/5
 10/09/18 @ 1120
 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Thank you.

Your faithfully

David TENG
 Service Adviser
 HP: 9146 9393
 Company Admin
 David Teng

Confirmed acceptance of the above

Authorised Signatory & Company Stamp