

ASS. REC. BY:

REF: CS/SMO/801622/Ard3n2 Special Instruction:

Survivor:

MEMPHIS

Adrian

ASSIGNMENT (Office)

From (Person):

Thelma chuo

of

SMO

Date/Time:

5/9/18 @ 12:52pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 5844H

Insured:

YP 2855G

at Workshop m/s

Heng Kee Workshop

Tel:

8156 2761

of

Blk 1033 Eunos Ave SA #01-31

Policy No:

D18MTPCVE001897

Claim No:

CMTD1803835

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/09/2018

CA / REV / REP. / REV 24 HRS

1up>

H.O.D. Endorsement:

Date/Time:

3:21pm @ 5/9/18

Person Contacted:

Ah hua

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

GBH 5844H - NA/1A/1G/18016147/h4

DUA: 4/9/18

YP 2855G - NA/1A/1G/18016147/h4

Don: 4/9/18

Revert 1A thru memmen

Adrian confirmed \$15 \$3500 @ 4 days (Red: \$2734.70, 44%).)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18016212/Ard3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 05-09-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 2855G	Veh. Inspected	GBH 5844H
Policy No.	D18MTPCVE001897	Coverage (\$)	0.00
Claim No.	CMTD1803835	Excess (\$)	0.00
Assign From	MERIMEN (THELMA CHOO)	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/09/2018	Inspection Date	05/09/2018
Survey held at	HENG KEE WORKSHOP 1033 EUNOS AVENUE 5A #01-31 EUNOS INDUSTRIAL ESTATE SINGAPORE 409703		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 11 Oct 2018

Preliminary Advice

Insured Vehicle No	: YP2855G	Accident Date	: 04/09/2018
TP Vehicle No	: GBH5844H	Assignment Date	: 05/09/2018
Make	:	Est. Duration of Repair	: 4.00
Date of Inspection	: 05/09/2018		
Inspection At	: HENG KEE WORKSHOP (HQ) BLK 1033 EUNOS AVENUE 5A #01-31 SINGAPORE 409703		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,234.70
Revised Amount	:S\$	4,367.97
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,367.97
Lump Sum Repair	:S\$	3,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle survey on "without prejudice" basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2018		05 Sep 2018 12:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	UNIVERSAL STEEL INDUSTRIES PTE LTD, Co. Reg. No.: 200602866K		
Main Claimant:	UNKNOWN3835		
Vehicle Reg. No.:	GBH5844H	Date of Loss:	04/09/2018 11:00 - :59
Claim Type:	TP / CMTD1803835	Policy/Cover Note No.:	D18MTPCVE001897 (Comprehensive)
Vehicle Reg. No. (Insured):	YP2855G	Policy No. (Claimant):	
		Excess:	
Repairer:	Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31, 409703 Eunos - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/09/2018]		
Driver/Custodian (Insured):	WANG CHAOLONG (), NRIC: G3033026P, Tel: +6584993293		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- SOMPO_SG (05/09/2018): TP SURVEY

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3306C
Vehicle Details	
Vehicle No.:	GBH5844H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 5DR 2.5 5AT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	YD25029102B
Chassis No.:	JN1MC2E26Z0030388
Maximum Power Output:	-
Open Market Value:	\$26,114.00
Original Registration Date:	17 Jul 2018
First Registration Date:	17 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$1,306.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$31,243.00
Total Rebate Amount:	\$31,243.00

The information contained herein is correct as at 11 Oct 2018

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	GBH5844H
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	NISSAN
Vehicle Model :	NV350 PANEL VAN 5DR 2.5 5AT
Chassis No. :	JN1MC2E26Z0030388
Propellant :	Diesel
Engine No. :	YD25029102B
Engine Capacity :	2488 cc
Maximum Power Output :	-
Maximum Laden Weight :	3300 kg
Unladen Weight :	1780 kg
Year Of Manufacture :	2018
Original Registration Date :	17 Jul 2018
Lifespan Expiry Date :	16 Jul 2038
COE Category :	C - Goods Vehicle & Bus
Quota Premium :	\$32,001.00
COE Expiry Date :	16 Jul 2028
Road Tax Expiry Date :	16 Jan 2019
Inspection Due Date :	16 Jul 2019
Intended Transfer Date :	11 Oct 2018
CO2 Emission :	222.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	0.034000 (g/km)
HC Emission :	0.007347 (g/km)
NOx Emission :	0.039000 (g/km)
PM Emission :	0.500000 (mg/km)

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

TP Sampo
Smile

FAX: 68425778

HENG KEE WORKSHOP

BLK 1033 EUNOS AVE 5A #01-31 SINGAPORE 409703
HP: 8156 2761

JNIMC2E26ZU030388

06-09-2

GBH 5844 H

Dented

REAR DOOR ASSEMBLY \$1,742.00 N ✓ New
REAR DOOR CENTRE "NISSAN" LOGO \$59.70 N ✓ New
REAR DOOR NUMBER PLATE TOP CHROME STRIP \$511.40 N X HP New
REAR DOOR "NV 250" WORDING LOGO } \$161.30 N ✓ New
REAR DOOR "URVAN" WORDING LOGO }
REAR WINDSCREEN GLASS ASSEMBLY \$900.00 N ✓ shattered
RIGHT REAR COMBINATION LIGHT ASSEMBLY \$209.80 N ✓ cracked
REAR BUMPER ASSEMBLY \$600.50 N ✓ Dented
REAR BUMPER CLIP \$75.00 30 New
REAR BUMPER REVERSE SENSOR \$280.00 N X HP New
REAR WINDSCREEN SEALANT \$65.00 S/N ✓ New
LABOUR CHARGE \$650.00 200
LABOUR CHARGE FOR REPLACING REAR WINDSCREEN \$180.00 120
SPRAY PAINTING \$680.00 400
LABOUR CHARGE FOR REPLACING REVERSE SENSOR \$120.00 50
6234.70

hist 3703.30

less 10%: 3332.97

S.N: 65

Labour 970

total: 4367.97

L/s: 3.5K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damage clearly during resurvey
- Parts price are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18016212/ARD3N2

Date: 22/10/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001897
Claimant Vehicle No :	GBH5844H	Insured Vehicle No :	YP2855G
Date of Loss:	04/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1803835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH5844H	Engine No:	YD25029102B
Make & Model:	NISSAN NV350, 2.5 D Panel Van (M)	Chassis No:	JN1MC2E26Z0030388
Reg. Date:	17/07/2018 (Man. Year: 2018)	Odometer:	6280 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,604.70	3,397.97	1,206.73	26.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	970.00	660.00	40.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,234.70	4,367.97	1,866.73	29.94
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	6,234.70	3,500.00	2,734.70	43.86

INSPECTION

Date of Assignment:	05/09/2018	
Date Inspected:	05/09/2018	Inspected At: Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31 Singapore 409703
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5844H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR ASSEMBLY	Dented	1,742.00 F	*1,742.00 FN
2	1	*REAR DOOR CENTRE NISSAN LOGO	Necessary	59.70 F	*59.70 FN
3	1	*REAR DOOR NUMBER PLATE TOP CHROME STRIP	Not Necessary	511.40 F	*- FN
4	1	*REAR DOOR NV350 WORDING LOGO }	Necessary	161.30 F	*161.30 FN
5	1	*REAR DOOR URVAN WORDING LOGO }	Necessary	0.00 F	*- FN
6	1	*REAR WINDSCREEN GLASS ASSEMBLY	Shattered	900.00 F	*900.00 FN
7	1	*RIGHT REAR COMBINATION LIGHT ASSEMBLY	Cracked	209.80 F	*209.80 FN
8	1	*REAR BUMPER ASSEMBLY	Deformed	600.50 F	*600.50 FN
9	1	*REAR BUMPER CLIP	Necessary	75.00 F	*30.00 FN
10	1	*REAR BUMPER REVERSES ENSOR	Not Necessary	280.00 F	*- FN
11	1	*REAR WINDSCREEN SEALANT	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	4,604.70	3,768.30
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	370.33
Total Parts (S\$)	4,604.70	3,397.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	650.00	400.00
2	LABOUR CHARGE FOR REPLACING REAR WINDSCREEN	New	180.00	120.00
3	SPRAY PAINTING	New	680.00	400.00
4	LABOUR CHARGE FOR REPLACING REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (S\$)			1,630.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >