



# 凱摩哆服務

## KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.  
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com  
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。  
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 04/09/2018

Attn: The Motor Claims Department

Your Insured veh no : SLG 9510 G

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

# 07-16 Chartis Building

Singapore 079120

Dear Sir / Madam

LKK Auto Consultants hence notify  
the Repairer of the following:

To resurvey before/after spray painting

WITHOUT PREJUDICE

• To display damaged parts during resurvey

• Best price to be offered to the claimant

• Third party survey on a "Without Prejudice" basis

• No illegal communication(s) is allowed

• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

(By Email Only)

Acknowledged by Repairer

Signature:

Date:

(NISC) F242080690

X: 20/09

Estimate Cost repair Bill To Nissan Cabstar NO GBC 597 E & SLG 9510 G on 28/08/2018.

To Supply:-

|     |                                                                  |                           |
|-----|------------------------------------------------------------------|---------------------------|
| 1pc | Front tyre rim <i>NEW</i>                                        | \$ 228.80 x.              |
|     |                                                                  | 30% \$ 68.64              |
|     |                                                                  | \$ 160.16                 |
| 1pc | Front upper arm w ball joint LH                                  | \$ 480.00 nett *          |
| 1pc | Front lower arm w ball joint LH                                  | \$ 489.00 nett *          |
| 1pc | Front shock absorber LH                                          | \$ 180.40 nett *          |
| 1pc | Front tie rod LH                                                 | \$ 134.80 nett *          |
| 1pc | Front fender LH                                                  | \$ 287.00 nett *          |
| 1pc | Front wheel bearing LH                                           | \$ 66.00 nett *           |
| 1pc | Rear side door LH <i>Repair</i>                                  | \$ 2,600.60 nett *        |
| 1pc | Rear fender LH <i>Beut</i>                                       | \$ 115.80 nett ✓          |
| 1pc | Rear side rubber LH <i>Missing</i>                               | \$ 14.00 nett ✓           |
| 1pc | Air cleaner assy <i>could</i>                                    | \$ 1,005.60 nett ✓ 412.60 |
| 1pc | Fuse box <i>could</i>                                            | \$ 228.00 nett ✓          |
| 1pc | Battery bracket <i>Beut</i>                                      | \$ 251.20 nett *          |
| 1pc | Air cleaner bracket <i>Beut</i>                                  | \$ 118.00 nett ✓          |
|     |                                                                  | \$ 5,970.40               |
|     |                                                                  | 10% \$ 597.04             |
|     |                                                                  | \$ 5,373.36               |
| 1pc | Battery <i>Damaged</i>                                           | \$ 250.00 s/nett 200 (sw) |
|     | To dismantl & replace damage parts, panel beat where necessary.  | \$ 950.00 400             |
|     | To putty, apply primer & body paint work on the affecte portion. | \$ 950.00 500 930         |
|     | To check wiring functions.                                       | \$ 80.00 30               |
|     | To computer wheel alignment.                                     | \$ 120.00 *               |
|     | To remove under carriage.                                        | \$ 320.00 *               |
|     |                                                                  | \$ 8,203.52               |

total: 1929.56  
A/S: 1-51K  
10/09/18  
4 Days