

22/03/2012

ASS. REC. BY:

REF:

C3 / AWA18016217 / T1Vbez

Special Instruction:

Surveyor

Tau Jich

ASSIGNMENT (Office)

From (Person):

Kin Wong

of

AWA

Date/Time:

05092018 355pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 8009U

Insured:

PC 4853Z

at Workshop m/s

Ding Auto

Tel:

9239 4128

of

249 Jin Bann Lay.

Policy No:

BVBPSB D005921800

Claim No:

NSV1800500 / KW

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31082018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Wp

06092018

H.O.D. Endorsement:

Date/Time:

05092018 410pm

Person Contacted:

Jing Feng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 8009U - X

PC 4853Z - X

10/9/18

LS \$2400 Confirmed by email (Recd 4536.10, 6590)

Tanpoh

RCE

AWA

Sub-NAL 51

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m's \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SL480094 Yr Regn: 2016 Oct  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mitsubishi Attrage C.C. 1193  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 43/60 T/Radio: Insured / Std / NI / NA  
 Eng/No: MMBSTA13AHM.602788  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/55R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kardone  
 Front: 6 mm Rear: 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 4/9/1521140  
 Survey held at Ping Auto  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 10 SEP 2018

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report  
 Date/Time, File Return to?

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Survey Fee  
 Transportation

10/9- typist

Add Fee: ☐ Site Insp (\$)  
☐ Interpret (\$)  
☐ Tech Insp (\$)  
☐ Mapland (\$)

Report Format: TP  
 Lump Sum / LB (\$): 2400/2

200  
 200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18016217/T1vb

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 05-09-2018



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 4853Z	Veh. Inspected	SLG 8009U
Policy No.	BVBPSB0005921800	Coverage (\$)	0.00
Claim No.	NSV1800500/KW	Excess (\$)	0.00
Assign From	KIN WONG	Assign Date	05/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	31/08/2018	Inspection Date	06/09/2018
Survey held at	249 JLN BOON LAY		
Repairer	DING AUTO PTE LTD		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 6 September 2018 4:40 PM  
**To:** 'Duan Hongbo'; Admin A; Admin-D (LKKAUTO)  
**Cc:** Kenneth Ding; You jingfeng; Dd hashim; Ding Auto Admin; Accounts Ding Auto; Carlor Chan  
**Subject:** RE: ACCIDENT INVOLVING SLG8009U & PC4853Z ON 31/08/2018-CHECK LIABILITY

Dear Hong Bo,

Please refer to Kin Wong for liability.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Duan Hongbo <duan.hongbo@dingauto.sg>  
**Sent:** Thursday, 6 September 2018 4:10 PM  
**To:** Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Cc:** Kenneth Ding <kenneth.ding@dingauto.sg>; You jingfeng <JINGFENG@dingauto.sg>; Dd hashim <dd.hashim@dingauto.sg>; Ding Auto Admin <admin@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; Carlor Chan <carlor.chan@dingauto.sg>  
**Subject:** ACCIDENT INVOLVING SLG8009U & PC4853Z ON 31/08/2018-CHECK LIABILITY

Dear Officer,

Please advise the liability of this case as soon as possible for us to proceed the repair.

Vehicle done survey since 06 Sep 2018 by Mr Taufikh.

Here I attached together with the GIA and Estimate for your reference.

Many thanks.

BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO

TEL Office : 92394128

FAX :62652690

\*ALL MAIL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW\*  
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 5756

**Catherine Chong (LKK Auto)**

---

**From:** Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey  
<Motorsurvey@awac.com>  
**Sent:** Wednesday, 5 September, 2018 3:58 PM  
**To:** 'assignments'  
**Cc:** 'SUR'; 'Duan Hongbo'  
**Subject:** TP Survey assignment for SLG 8009U - DOA: 31/08/2018 Our ref: NSV1800500/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Mohamad Taufikh / Mr Mohammed Rasul** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SLG 8009 U
Insured Vehicle	:	PC 4853 Z
Policy Number	:	BVBPSB0005921800
Name of Workshop	:	Ding Auto Pte Ltd
Contact Number	:	9239 4128
Person to Contact	:	Duan Hong Bo
Estimated Cost of repairs	:	\$ NA

Regards,  
Claims Division

Copy to Ding Auto Pte Ltd via Email

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/09/2018 12:44
Date Of Accident	31/08/2018 19:35
Exact Location Of Accident	ALONG DELTA ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG8009U
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	
Driver	
Name of Driver	KHO LOK HUI
NRIC No	S1150191E
Date Of Birth	04/01/1957
Occupation	OUTDOOR
Date Of Driving Pass	14/09/1982
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4853Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

John  
Bakit  
Marak

SKETCH PLAN

Lower Delta  
Road

PC 48532

SLG80094

Another  
car  
(not involved  
in accident)

To  
CTE/  
AYE

Traffic  
light  
(Red)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident involving Mitsubishi Attrage vehicle number SLG80094  
On August 31, 2018, at around 7.35pm, I  
was driving along Lower Delta Road in the  
direction of Telok Blangah Road  
Just before the ramp turning onto  
AYE / CTE I stopped behind another vehicle  
at the traffic lights (which were red)  
on the leftmost lane.  
Suddenly I felt an impact from behind  
I immediately got out of my vehicle  
and found that another vehicle with licensed  
number PC 48532 had knocked into  
the back of my vehicle.  
Upon ~~exam~~ further ~~examine~~ examination  
I found damages to the back of my  
car especially around the bumper  
The other vehicle was driven by  
Mr. John Seah Teck Hwee (V/L No S7011869F)  
PC 48532 is a white Toyota Hiace

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

1/9/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



TO :

FAX NO:

**ESTIMATE REPORT** 1ST Quotation

04/09/2018 14:34

JOB-NO: 85008591

**OWNER'S PARTICULARS**

NAME: LION CITY RENTALS PTE LTD

CONTACT:

Page 1 of 2

ADDRESS: 60 ANSON ROAD  
MAPLETREE ANSON  
LEVEL 11 SINGAPORE  
079914

NOEMAIL@GMAIL.COM

**VEHICLE DETAILS**

LICENSE NO: SLG8009U

TRANS: AUTO

CHASSIS: MMBSTA13AHH002788

MAKE / MODEL: MITSUBISHI Others

ENGINE: 3A92UDL1297

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<b>LABOUR</b>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	800.00	0.00	800.00		Y	500
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
4 TO SPRAY REAR BOOTLID	1.00	250.00	0.00	250.00		Y	200
5 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00		Y	30
6 RUST PROOFING	1.00	120.00	0.00	120.00		Y	30
7 TO REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,SPARE TYRE BOARD,CUSHION AND ETC	1.00	130.00	0.00	130.00		Y	40
8 REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	130.00	0.00	130.00		Y	30
9 R & R BOOTLID COMPONENTS	1.00	120.00	0.00	120.00		Y	60
TOTAL:		2,170.00	0.00	2,170.00			

**MATERIALS**

1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	de
2 REAR BUMPER SIDE RETAINER LHS	1.00	26.00	2.60	23.40	L	Y	ne
3 REAR BUMPER SIDE RETAINER RHS	1.00	26.00	2.60	23.40	L	Y	ne
4 REAR BUMPER REFLECTOR LHS	1.00	20.00	2.00	18.00	L	Y	X NXX
5 REAR BUMPER REFLECTOR RHS	1.00	20.00	2.00	18.00	L	Y	X NXX
6 BOOTLID	1.00	828.00	82.80	745.20	L	Y	bt
7 BOOTLID "ATTRACTION" EMBLEM	1.00	38.00	3.80	34.20	L	Y	ne
8 BOOTLID "MIT" LOGO EMBLEM	1.00	41.00	4.10	36.90	L	Y	ne
9 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	X NNA
10 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	Ry SVCK
11 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	Ry SVCK
12 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	Ry SVCK
13 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	Ry RX
14 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	? X SVCK
15 REAR FENDER MUDFLAP LHS	1.00	39.00	3.90	35.10	L	Y	X SVCK
16 REAR FENDER MUDFLAP RHS	1.00	39.00	3.90	35.10	L	Y	X SVCK
17 REAR END PANEL AIR DUCT	1.00	27.00	2.70	24.30	L	Y	X SVCK
18 REAR END PANEL AIR DUCT COVER TRIM	1.00	36.00	3.60	32.40	L	Y	X SVCK
19 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	X RX

# CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	? XNNX
21 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	X NNX
22 REAR END PANEL TOP GARNISH	1.00	65.00	6.50	58.50	L	Y	X SUCX
23 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	na
24 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200 nm ✓
25 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X NNX
26 REAR END PANEL SEALANT	1.00	30.00	0.00	30.00	S	Y	X NNX
27 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X NNX
TOTAL:		5,249.00	482.90	4,766.10			

TOTAL PARTS & LABOUR : 7,419.00 482.90 6,936.10

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 4-5 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 6/1/18

SURVEYED BY: Tayfri

CONTACT NO: 9349549 FAX NO: \_\_\_\_\_

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO :

FAX NO:

**ESTIMATE REPORT** 1ST Quotation

04/09/2018 14:34

JOB-NO: 85008591

**OWNER'S PARTICULARS**

NAME: LION CITY RENTALS PTE LTD

CONTACT:

Page 1 of 2

ADDRESS: 60 ANSON ROAD  
MAPLETREE ANSON  
LEVEL 11 SINGAPORE  
079914

NOEMAIL@GMAIL.COM

**VEHICLE DETAILS**

LICENSE NO: SLG8009U

TRANS: AUTO

CHASSIS: MMBSTA13AHH002788

MAKE / MODEL: MITSUBISHI Others

ENGINE: 3A92UDL1297

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

**CLAIM DETAILS**

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<b>LABOUR</b>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	800.00	0.00	800.00		Y	500
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	200
4 TO SPRAY REAR BOOTLID	1.00	250.00	0.00	250.00		Y	200
5 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00		Y	30
6 RUST PROOFING	1.00	120.00	0.00	120.00		Y	30
7 TO REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,SPARE TYRE BOARD,CUSHION AND ETC	1.00	130.00	0.00	130.00		Y	40
8 REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	130.00	0.00	130.00		Y	30
9 R & R BOOTLID COMPONENTS	1.00	120.00	0.00	120.00		Y	60
TOTAL:		2,170.00	0.00	2,170.00			

**MATERIALS**

1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	de
2 REAR BUMPER SIDE RETAINER LHS	1.00	26.00	2.60	23.40	L	Y	re
3 REAR BUMPER SIDE RETAINER RHS	1.00	26.00	2.60	23.40	L	Y	re
4 REAR BUMPER REFLECTOR LHS	1.00	20.00	2.00	18.00	L	Y	X
5 REAR BUMPER REFLECTOR RHS	1.00	20.00	2.00	18.00	L	Y	X
6 BOOTLID	1.00	828.00	82.80	745.20	L	Y	bt
7 BOOTLID "ATTRAGE" EMBLEM	1.00	38.00	3.80	34.20	L	Y	re
8 BOOTLID "MIT" LOGO EMBLEM	1.00	41.00	4.10	36.90	L	Y	re
9 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	X
10 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	Ry
11 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	Ry
12 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	Ry
13 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	Ry
14 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	?
15 REAR FENDER MUDFLAP LHS	1.00	39.00	3.90	35.10	L	Y	X
16 REAR FENDER MUDFLAP RHS	1.00	39.00	3.90	35.10	L	Y	X
17 REAR END PANEL AIR DUCT	1.00	27.00	2.70	24.30	L	Y	X
18 REAR END PANEL AIR DUCT COVER TRIM	1.00	36.00	3.60	32.40	L	Y	X
19 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	X

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	?
21 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	X
22 REAR END PANEL TOP GARNISH	1.00	65.00	6.50	58.50	L	Y	X
23 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	X
24 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	X
25 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
26 REAR END PANEL SEALANT	1.00	30.00	0.00	30.00	S	Y	X
27 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X
TOTAL:		5,249.00	482.90	4,766.10			

TOTAL PARTS & LABOUR :

7,419.00

482.90

6,936.10

EXCESS/LOADING:\$\$ 0.00

No. Of Day:

4-5 days

RE-SURVEY: BEFORE/AFTER PAINTING  
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY:

6/1/18

SURVEYED BY:

Tayhi

CONTACT NO:

9249549

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 10 September 2018 3:26 PM  
**To:** Duan Hongbo; SUR; Taufikh (LKKAUTO)  
**Cc:** CS A Team; Kenneth Ding; You jingfeng; Dd hashim; Accounts Ding Auto; Ding Auto Admin; Carlor Chan  
**Subject:** RE: 85008591/SLG8009U- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Hong Bo,

Noted with thanks.

**Kindly send Final invoice and all supporting documents to ALLIED WORLD**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Duan Hongbo <duan.hongbo@dingauto.sg>  
**Sent:** Monday, 10 September 2018 3:20 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** CS A Team <cs-a@lkkauto.com>; Kenneth Ding <kenneth.ding@dingauto.sg>; You jingfeng <JINGFENG@dingauto.sg>; Dd hashim <dd.hashim@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; Ding Auto Admin <admin@dingauto.sg>; Carlor Chan <carlor.chan@dingauto.sg>  
**Subject:** Re: 85008591/SLG8009U- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Veron,

We confirm the finalize amount.

Many thanks.

BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO  
TEL Office : 92394128  
FAX :62652690

\*ALL MAILL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW\*  
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 5756

On Mon, Sep 10, 2018 at 3:13 PM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Hong Bo,

WITHOUT PREJUDICE

Offer Lump Sum \$2400 @ 4 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Duan Hongbo <[duan.hongbo@dingauto.sg](mailto:duan.hongbo@dingauto.sg)>

**Sent:** Saturday, 8 September 2018 12:40 PM

**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Taufikh (LKKAuto) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>

**Cc:** CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Kenneth Ding <[kenneth.ding@dingauto.sg](mailto:kenneth.ding@dingauto.sg)>; You jingfeng <[JINGFENG@dingauto.sg](mailto:JINGFENG@dingauto.sg)>; Dd hashim <[dd.hashim@dingauto.sg](mailto:dd.hashim@dingauto.sg)>; Accounts Ding Auto <[accounts@dingauto.sg](mailto:accounts@dingauto.sg)>; Ding Auto Admin <[admin@dingauto.sg](mailto:admin@dingauto.sg)>; Carlor Chan <[carlor.chan@dingauto.sg](mailto:carlor.chan@dingauto.sg)>

**Subject:** 85008591/SLG8009U- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Taufikh,

Please see attach file for the finalize according to our conversion to finalize for SLG8009U

Total Repair - 04 Days

L/S

Labour - \$1290.00

Special Netts - \$-235.00

Parts after 25% Discount - \$1500.30

Total ( Labour + S.N + Part) :\$3025.30



L/S Repair after 20% discount :\$2420.24

Thanks You And Please Help To Close The File

BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO

TEL Office : 92394128

FAX :62652690

\*ALL MAILL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW\*  
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 5756



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD			Ref : CS/AWA18016217/T1vbe2	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Date : 18-10-2018	
			Code : AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PC 4853Z	Veh. Inspected	SLG 8009U	
Policy No.	BVBPSB0005921800	Coverage (\$)	0.00	
Claim No.	NSV1800500/KW	Excess (\$)	0.00	
Assign From	KIN WONG	Assign Date	05/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI ATTRAGE	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH002788	Colour	BLACK	
Odometer	43160	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	ROADSTONE	6 mm	
L/H Front Tyre	185/55 R16	ROADSTONE	6 mm	
R/H Rear Tyre	185/55 R16	ROADSTONE	6 mm	
L/H Rear Tyre	185/55 R16	ROADSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	31/08/2018	Inspection Date	06/09/2018	
Survey held at	249 JLN BOON LAY			
Repairer	DING AUTO PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 8009U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	708.00	708.00
1	REAR BUMPER SIDE RETAINER LHS	NECESSARY	26.00	26.00
1	REAR BUMPER SIDE RETAINER RHS	NECESSARY	26.00	26.00
1	REAR BUMPER REFLECTOR LHS	NOT NECESSARY	20.00	-
1	REAR BUMPER REFLECTOR RHS	NOT NECESSARY	20.00	-
1	BOOTLID	BENT	828.00	828.00
1	BOOTLID "ATTRAGE" EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID "MIT" LOGO EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID OUTER CHROME GARNISH	NOT NECESSARY	318.00	-
1	BOOTLID HINGE LHS	SERVICEABLE	192.00	-
1	BOOTLID HINGE RHS	SERVICEABLE	192.00	-
1	BOOTLID LOCK	SERVICEABLE	206.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	402.00	-
1	REAR END PANEL WEATHERSTRIP	SERVICEABLE	148.00	-
1	REAR FENDER MUDFLAP LHS	SERVICEABLE	39.00	-
1	REAR FENDER MUDFLAP RHS	SERVICEABLE	39.00	-
1	REAR END PANEL AIR DUCT	SERVICEABLE	27.00	-
1	REAR END PANEL AIR DUCT COVER TRIM	SERVICEABLE	36.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	906.00	-
1	TAIL LAMP LHS	NOT NECESSARY	276.00	-
1	TAIL LAMP RHS	NOT NECESSARY	276.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	65.00	-
	LESS 10% DISCOUNT		-482.90	-166.70
			<b>4,346.10</b>	<b>1,500.30</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	260.00	200.00
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	35.00	-
			<b>420.00</b>	<b>235.00</b>

Report Ref No. CS/AWA18016217/T1vbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SPARE TYRE PANEL.		800.00	500.00
	TO SPRAY REAR BUMPER.		250.00	200.00
	TO SPRAY REAR END PANEL.		250.00	200.00
	TO SPRAY REAR BOOTLID.		250.00	200.00
	TO ADJUST TAIL LAMP & CHECK WIRING.		120.00	30.00
	RUST PROOFING.		120.00	30.00
	TO REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER TRIM LHS & RHS, SPARE TYRE BOARD, CUSHION AND ETC.		130.00	40.00
	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY.		130.00	30.00
	R & R BOOTLID COMPONENTS.		120.00	60.00
			2,170.00	1,290.00
	<b>GRAND TOTAL</b>		<b>6,936.10</b>	<b>3,025.30</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,400.00</b>

Report Ref No. CS/AWA18016217/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.