

ASS. REC. BY:

REF: CS/FCI 18016218/Nqd3 12

Special Instruction:

SL

Surveyor:

Naz

ASSIGNMENT (Office)

ans

From (Person):

Lurene juw

of

FCI

Date/Time:

4/9/18 @ 6:15 pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 6836A

Insured:

SHA 00962

at Workshop m/s

World Auto

Tel:

6362 1776

of

No. 1. Krunji Jeop

Policy No:

Claim No:

D18006571MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

03/09/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:27 am @ 5/9/18

Person Contacted:

Ainee

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 6836A - X
	SHA 00962 - CS/FCI 16024397/Kqh3s2. DUA: 17/12/16
11/9 @ 8:50 am	revert via email preli advise.
04/17/18 @ 4:43 pm	confirmed with Sopura final fig \$2818.50, 4 days.
	clerk 65760, 671.)

(05/1/13) wed

ASS. REC. BY:

NAZ

REF: FCI

ASSIGNMENT

From:

Date:

5/9/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 6836A

at Workshop m/s

World Auto

of

No. 1 Krungi loop

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN 6836A

Yr Regn: 15 MAY 2017

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIMS

c.c.

1,798

Colour:

SILVER

A/C:

☒ Insured / ☐ Std / NI / NA

Sp. Reading

104,702

T/Radio:

☒ Insured / ☐ Std / NI / NA

Eng/No:

JTDK83FU503558181

C/No:

Gen. Cond: Good ☒ Fair / ☐ Poor / BurntSteering: ☒ Inorder / ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder / ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim ☒ STD A/Rim or

Tyre Size:

F:

195/65 RV

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROVELO

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

3/9/18

D.O.I.

5/9/18

Survey held at

WORLD AUTO

Des. of Damages: Frt / ☒ Rear / ☐ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 5 DEC 2018

FCI PIP

Date/Time, File Pass to?

☐

Preli. Report

1) 04/12/18

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$)

2818.50

160

50

14

224



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18016218/Nqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 96Z	Veh. Inspected	SLN 6836A
Policy No.		Coverage (\$)	0.00
Claim No.	D18006571MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/09/2018	Inspection Date	05/09/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006571MFSH

Date: 11/9/2018

Our Ref: CS/FCI18016218/Nqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 6836A

Please be informed that we had conducted the inspection of the abovementioned vehicle
5/9/2018 at the premises of M/s World auto and have the following to report: -

Workshop Estimate Amount	: S\$ 8,578.50
Revised Estimate Amount	: S\$ 2,688.50
"Check" Items Amount	: S\$ 1,180.00
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Naz

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-09-2018	Our Ref No. D18006571MFSH
Accident Date	03-09-2018	Claim Type. Third Party
Insured Vehicle	SHA0096Z	Third Party Vehicle. SLN6836A
Survey Location	NO.1, KRANJI LOOP ,SINGAPORE 739535	
Contact Person.	AINEE	
Contact No.	63621776/ 63621776	Fax No. 63631250
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 4 December 2018 4:43 PM
To: tggtan@worldauto.com.sg
Cc: SUR
Subject: RE: SLN6836A Our ref: TP/2221/18

Dear Sophia,

WITHOUT PREJUDICE

Confirm final fig \$2,818.50 and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Friday, 30 November 2018 5:18 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: SLN6836A Our ref: TP/2221/18

Hi Shiau Chan

Attach please find our estimate markings.

We are unable to agree to your proposal of item 5 at \$700 and item 11 at \$94.80.

Therefore, we finalise COR @\$2818.50 and 4 repair days.

Kindly revert.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 27 November 2018 5:54 PM
To: tggtan@worldauto.com.sg
Subject: RE: SLN6836A Our ref: TP/2221/18

Dear Sophia,

WITHOUT PREJUDICE

As spoken with you.

Offer final fig \$2,649.60 before GST and 4 repair days.

Shiau Chan (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Friday, 30 November 2018 5:18 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: SLN6836A Our ref: TP/2221/18
Attachments: SLN6836A - ESTIMATE MARKINGS.pdf

Hi Shiau Chan

Attach please find our estimate markings.

We are unable to agree to your proposal of item 5 at \$700 and item 11 at \$94.80.

Therefore, we finalise COR @\$2818.50 and 4 repair days.

Kindly revert.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 27 November 2018 5:54 PM
To: tggtan@worldauto.com.sg
Subject: RE: SLN6836A Our ref: TP/2221/18

Dear Sophia,

WITHOUT PREJUDICE

As spoken with you.

Offer final fig \$2,649.60 before GST and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Monday, 19 November 2018 11:28 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FW: SLN6836A Our ref: TP/2221/18

Hi Shiau Chan

Can revert urgently.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 11 September 2018 8:50 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006571MFSH/1
Attachments: PRELI ADVISED SSLN 6836A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLN 6836A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 5 September 2018 11:02 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006571MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 4 September 2018 6:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006571MFSH/1

Dear Sir/Mdm,


We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Sketch Plan #3



Land Transport Authority

Serial No. A 13117

Name: Wong Wee Chong

NRIC: S7104057 G

TEMPORARY PRIVATE HIRE CAR DRIVER'S VOCATIONAL LICENCE

1. You have passed the vocational licence competency test and have been granted a Private Hire Car Driver's Vocational Licence (PDVL).

PDVL Commencement Date: 12 JUN 2018

2. You must display this Temporary PDVL in your car at all times while driving a chauffeured private hire car.

3. LTA will subsequently inform you to collect your Vocational Licence Card that will replace this Temporary PDVL. You must collect your Vocational Licence Card within 6 months of the PDVL Commencement Date and display it in your car thereafter. Otherwise, your PDVL may be revoked.

Kwan Mei Fong
Assistant Registrar of Vehicles
Land Transport Authority of Singapore

This Temporary PDVL is handed to you by Samuel (centre officer name), Officer
(centre officer designation), of STA (centre name).

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED
 80 ROBINSON RD #09-02/03
 068898

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000327

Date : 04/09/2018
 Vehicle Num. : SLN 6836A (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 03/09/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | |
|-----|---|-----------------------------------|
| 1. | 1 | REAR BOOT LID |
| 2. | 1 | REAR BOOTLID OUTER GARNISH |
| 3. | 1 | REAR BOOT HYBRID EMBLEM (PRIUS) |
| 4. | 1 | REAR BOOT PRIUS EMBLEM |
| 5. | 1 | REAR BUMPER |
| 6. | 1 | REAR BUMPER TAIL LAMP LH |
| 7. | 1 | REAR LOWER BUMPER |
| 8. | 1 | REAR BUMPER TOW COVER |
| 9. | 1 | REAR WINDSCREEN GLASS MOULDING |
| 10. | 1 | REAR WINDSCREEN LOWER MOULDING |
| 11. | 1 | REAR BUMPER RETAINER LH |
| 12. | 1 | REAR BUMPER REINFORCEMENT |
| 13. | 1 | REAR BUMPER EXTENSION FILLER - LH |

List TotalS\$:

25.00% Discount S\$:

1,400.00 X R
 570.00 X R ? NNX
 89.00 / MC
 89.00 / MC
 900.00 / CRA
 750.00 X SVC
 570.00 / CRA
 100.00 X SVC
 250.00 X N
 180.00 X N
 120.00 ? NECV
 350.00 ? NNX NO PIC
 230.00 / CRA
 5,598.00
 1,399.50
 4,198.50

SPECIAL NETT ITEMS :

- | | | |
|----|-----|----------------------------------|
| 1. | 1 | REAR BOOTLID OUTER GARNISH CLIPS |
| 2. | 1 | REVERSE SENSOR |
| 3. | 2PC | REAR WINDSCREEN SEALANT |
| 4. | 1 | REAR BUMPER CLIP |

Special Nett Total S\$:

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

40.00 ? NNX
 280.00 X SVC
 160.00 320.00 ? NNX
 40.00 ? NECV
 680.00
 180.00 X N

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000327

Date : 04/09/2018

Vehicle Num. : SLN 6836A (LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 03/09/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)	360.00	360.00 $\times 11$
		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	180.00	180.00 $\times 50$
		TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	1,500.00	1,500.00 $\times 600$
		TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	1,300.00	1,300.00 $\times 600$
		TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	180.00	180.00 $\times 30$
		Labour Total S\$:		3,700.00

E. & O.E.

Total S\$: 8,578.50

=====

for WORLD AUTO PTE LTD

TGC Inc

19/11/18

NAZ LKK

19/18 1315

PIP

4 DAYS

BEFORE PAINT PHOTO

12/9/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016218/Nqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 96Z	Veh. Inspected	SLN 6836A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006571MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503558181	Colour	SILVER	
Odometer	104702	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ROVELO	6 mm	
L/H Front Tyre	195/65 R15	ROVELO	6 mm	
R/H Rear Tyre	195/65 R15	ROVELO	5 mm	
L/H Rear Tyre	195/65 R15	ROVELO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/09/2018	Inspection Date	05/09/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6836A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,400.00	-
1	REAR BOOTLID OUTER GARNISH	NOT NECESSARY	570.00	-
1	REAR BOOT HYBRID EMBLEM (PRIUS)	NECESSARY	89.00	89.00
1	REAR BOOT PRIUS EMBLEM	NECESSARY	89.00	89.00
1	REAR BUMPER	CRACKED	900.00	900.00
1	TAIL LAMP LH	SERVICEABLE	750.00	-
1	REAR LOWER BUMPER	CRACKED	570.00	570.00
1	REAR BUMPER TOW COVER	SERVICEABLE	100.00	-
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	250.00	-
1	REAR WINDSCREEN LOWER MOULDING	NOT NECESSARY	180.00	-
1	REAR BUMPER RETAINER LH	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	350.00	-
1	REAR BUMPER EXTENSION FILLER-LH	CRACKED	230.00	230.00
	LESS 25% DISCOUNT		-1,399.50	-499.50
			4,198.50	1,498.50
SPECIAL NETT ITEMS				
1	REAR BOOTLID OUTER GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
2	REAR WINDSCREEN SEALANT @\$160.00 (SN)	NOT NECESSARY	320.00	-
1	REAR BUMPER CLIP (SN)	NECESSARY	40.00	40.00
			680.00	40.00
LABOUR				
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.	NOT NECESSARY	180.00	-
	REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS).	NOT NECESSARY	360.00	-
	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE REAR DAMAGE PARTS,CUT AND WELD REAR SUPPORT PANEL,KNOCK,STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS.		1,300.00	600.00
	TO CHECK WIRES,CONNECTORS,REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS.		180.00	30.00
			3,700.00	1,280.00
GRAND TOTAL			8,578.50	2,818.50
RECOMMENDED COST OF REPAIRS				2,818.50

Report Ref No. CS/FCI18016218/Nqd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.