

ASS. REC. BY:

REF: CS / FC218016221 / U76n2

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Miss Serene Lee of FCI Date/Time: 05092018 4pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLK 1891m Insured: SHD 6619Kat Workshop m/s Specialists Motor Tel: 6742 2112of Bik 3018A Ubi Rd 1 #01-24Policy No: _____ Claim No: D18006546mFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 31-08-2018
(Client's Record)CA / REV / REP. / REV 24 HRS '03' 10-09-2018 @ after 10am H.O.D. Endorsement: _____Date/Time: 05092018 4:15pm Person Contacted: Hui Lin Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SLK 1891m - x</u>
	<u>SHD 6619K - x</u>

REF: fcl

ASSIGNMENT

From:

Date: 10/9/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No

SLK 1891 M

at Workshop m/s

Specialist Motor

of 31K 3018 A ubi Rd 1 #01-24

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10 AM

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

806.

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

1.75.1

%

3 Val.: Yes or No

CA / REV / REP. 1-24 HRS

(DS)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 1891 M

Yr Regn:

1 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Siesta

Colour:

Blue

Sp. Reading

23701

Eng/No:

C/No:

NSP1707033605

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

3.18/18

D.O.I.

10/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 49490

11/9/18

conf. and f. r. / h. & 2145.95 with handling
cred: 3759.15 (63%)

RECEIVED 27 SEP 2018

Date/Time: File Pass to?

1) 21/9/18

Date/Time: File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

2145.95

140

50

50

39

279

MOTOR SURVEY ASSIGNMENT

Date	03-09-2018	Our Ref No. D18006546MFSH
Accident Date	31-08-2018	Claim Type. Third Party
Insured Vehicle	SHD6619K	Third Party Vehicle. SLK1891M
Survey Location	BLK 3018A UBI ROAD 1 #01-24-26	
Contact Person.	HUI LIN	
Contact No.	67472112/ 67472112	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SPECIALISTS MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8023H

Vehicle Details

Vehicle No.: SLK1891M

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: SIENTA 1.5G CVT

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: 2NR8619339

Chassis No.: NSP1707033605

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$20,531.00

Original Registration Date: 09 Jan 2017

First Registration Date: 09 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$10,744.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Jan 2027

PARF Rebate Amount: \$8,058.00

Intended COE Rebate Details

COE Expiry Date: 08 Jan 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$49,751.00

COE Rebate Amount: \$41,432.00

Total Rebate Amount: \$49,490.00**Message**

The information contained herein is correct as at 10 Sep 2018

OK



hp \$59 \$930

Shopee UNBELIEVABLE DEALS UP TO 65% OFF

SHOP NOW

intel CORE i5 8th Gen

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2000 Downpayment Monthly
From \$488 Onwards. Lowest
3.18%P.A@Gv Cars Financing
GV Credit Pte Ltd StarAd



KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category Sort by Date Posted 20 results/page

17 vehicles

Toyota Sienta

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Sienta		Any	Any	2017	Any	Any	Any	Available
	Toyota Sienta Hybrid 1.5A G		\$97,800	N.A	09-Aug-2017	1,496 cc	-	MPV	Available
Fuel Type: Petrol-Electric \$5K Down Payment, Monthly \$1221, Front And Rear Recorder, 3 Free Engine Oil Change At Every 10000Km, Solar Film, Reverse Camera, Rear Parking Sensors, Floor Mat, 5 Years Warranty Or 100000Km Which Ever...									
Posted: 10-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta 1.5A G		\$82,800	\$9,080 /yr	12-Jan-2017	1,496 cc	28,200 km	MPV	Available
Elegant White, 7 Seaters MPV, One Owner Only, Trade In Welcome, Low Maintenance Cost, Very Well Maintained, Flexible In-house Loan Packages Available.									
Posted: 09-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta 1.5A G		\$85,800	\$8,940 /yr	14-Jul-2017	1,496 cc	12,000 km	MPV	Available
In House Loan And Trade In Available. Comes With Free IRoad V7 Front And Rear Camera. Hardly Driven With Only 12,000km Done. Very Well Spec'ed With 2 x Auto Sliding Doors And Toyota Safety Sense. Lots...									
Quality Motor Trading Enterprise									
Posted: 09-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta 1.5A G		\$82,800	\$9,110 /yr	12-Jan-2017	1,496 cc	-	MPV	Available
Elegant Black, 7 Seater MPV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 08-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
Car Buying Car Selling Car Ownership									
Car Aftermarket On The Move Lifestyle									
Buy Tyres Online! Latest Special Offers from Tyrepatch									
	Toyota Sienta Hybrid 1.5A G		\$93,800	\$9,820 /yr	27-Dec-2017	1,496 cc	9,000 km	MPV	Available
Fuel Type: Petrol-Electric Brand New Condition, Come With LED Lights, Warranty 3 Years, Loan Up To 90%, Call For Viewing Now!									
Posted: 08-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta Hybrid 1.5A G		\$88,000	\$9,350 /yr	30-Oct-2017	1,496 cc	300 km	MPV	Available
Fuel Type: Petrol-Electric Elegant MPV, 7 Seaters Unit, Condition Like Brand New, Drive Away With Minimum Down Payment, Flexible In House Loan Package Available.									
Prime Motor & Leasing									
Posted: 04-Sep-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota									
	Toyota Sienta 1.5A X		\$82,666	\$8,940 /yr	07-Jun-2017	1,496 cc	12,000 km	MPV	Available

[Compare](#)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLK1891M/1809128

04th September 2018

The Manager
Motor Claim Dept.
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

: Date: 31st August 2018

Date of Accident

Location

Third Party Vehicle No

Repair Cost For Vehicle No

: Mount Elizabeth (Paragon Medical drop-off point)

: SHC 6619 K (Your insured)

: SLK 1891 M Toyota Sienta

Not Adhered
to the phlo before party
3 days.
10/9/18

P/P \$2145.95

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear windscreen glass	1	1,295.10	\$ 1,295.10 X
2	Trunk lid cover	1	1,076.00	\$ 1,076.00 X
3	Trunk lid cover protector	1	221.70	\$ 221.70 ✓
4	Rear bumper fascia	1	478.70	\$ 478.70 ✓
5	Rear bumper clips	1 set	38.00	\$ 38.00 ✓
6	Rear bumper retainer	1	112.70	\$ 112.70 ✓
7	Rear bumper centre garnish	1	280.70	\$ 280.70 ✓
8	Rear bumper side garnish	1	142.80	\$ 142.80 ✓
9	Rear bumper reflector L&R	2	64.70	\$ 129.40 X
10	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00 X
				\$ 3,835.10

1252

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding trunk lid cover, lock, lock mechanism, wiper motor assy, remove & install all damage parts, straighten & re-align body	\$ 750.00 520
Tuff-kote on damage parts	11 \$ 40.00 X
Spray painting on damage parts	\$ 1,000.00 600
Remove & refix rear bumper sensor	\$ 80.00 50
Check all wiring lighting after repairs	\$ 80.00 20
Remove & refix rear windscreen glass	11 \$ 120.00 X
Labour Charge	\$ 2,070.00 1190
Total Amount	\$ 5,905.10

GST will be reflected in the final bills.

Notes :- Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

P-1274-60
257
955-95



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016221/Ulbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6619K	Veh. Inspected	SLK 1891M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006546MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NSP1707033605	Colour	BLUE	
Odometer	23701	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	TOYO	7 mm	
L/H Front Tyre	185/60 R15	TOYO	7 mm	
R/H Rear Tyre	185/60 R15	TOYO	7 mm	
L/H Rear Tyre	185/60 R15	TOYO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2018	Inspection Date	10/09/2018	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1891M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN GLASS	NOT NECESSARY	1,295.10	-
1	TRUNK LID COVER	TO REPAIR SEE LABOUR	1,076.00	-
1	TRUNK LID COVER PROTECTOR	NECESSARY	221.70	221.70
1	REAR BUMPER FASCIA	DENTED / DEFORMED	478.70	478.70
1	SET REAR BUMPER CLIPS	NECESSARY	38.00	38.00
1	REAR BUMPER RETAINER	NECESSARY	112.70	112.70
1	REAR BUMPER CENTRE GARNISH	GRAZED	280.70	280.70
1	REAR BUMPER SIDE GARNISH N/S	GRAZED	142.80	142.80
2	REAR BUMPER REFLECTOR L&R @\$64.70	NOT NECESSARY	129.40	-
	LESS 25% DISCOUNT		-	-318.65
			3,775.10	955.95
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			60.00	-
LABOUR				
	CUT OUT,RENEW,KNOCKING & WELDING TRUNK LID COVER,LOCK,LOCK MECHANISM,WIPER MOTOR ASSY,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY.		750.00	520.00
	TUFF-KOTE ON DAMAGE PARTS.	NOT NECESSARY	40.00	-
	SPRAY PAINTING ON DAMAGE PARTS.		1,000.00	600.00
	REMOVE & REFIX REAR BUMPER SENSOR.		80.00	50.00
	CHECK ALL WIRING LIGHTING AFTER REPAIRS.		80.00	20.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			2,070.00	1,190.00
GRAND TOTAL			5,905.10	2,145.95



RECOMMENDED COST OF REPAIRS			2,145.95
-----------------------------	--	--	----------

Report Ref No. CS/FCI18016221/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.