

2303/2002

ASS. REC. BY:

REF: CS/FCI18016228/Rtd3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person): Eileen Lee

of FCI

Date/Time: 5/9/18 @ 9.59am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV6541U

Insured: SH6778H

at Workshop m/s

Wearnes Automotive

Tel: 62647137 / 91294556

of

45 Leng Kee Rd

Policy No:

Claim No:

D18006520MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:05am 8/9/18

Person Contacted:

Michelle

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKV6541U-X

SH6778H-NS/INC18007661/Klvbn2

D.O.A: 24/4/18

13/9/18-4:02pm Revert pref; advise via email.

Part by Part \$16,134.94 -15days (Red: 3303.16, 16%)

Free

REF: FCI

28235

ASSIGNMENT

From:
Estimated Cost:

Date: 10/9/18

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 65414
at Workshop m/s: Wearnes
of: 249 Alexandra

Insured:
Policy No:
Claims No:
Sum Insured:
(Client's Record)
Make of Veh:

Excess:
after 10am
Michelle - 9129 4556

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKV 65414 Yr Regn: 2015 / 86P
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Renault Megan 1111.5 c.c 1461
Colour: GRAY A/C: Insured / Std / NI / NA
Sp. Reading: 51399 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: VF1BZS60ES2699171
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / 5/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or CONTINENTAL

Front: R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 30/08/18
Survey held at: WEARNES
Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rosul. PLS see my remarks

RECEIVED 23 NOV 2018

Date/Time, File Pass to?

22/11/18 Typlet.

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 16134.94

Days Of Repair: 15

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:
Transportation

\$ + R5, \$

Photos 03

Others 22/11/18

TOTAL

9x15: 135

170 + 135
50
50
70
475



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006520MFSH

Date: 13/9/2018

Our Ref: CS/FCI18016228/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 6541U


Please be informed that we had conducted the inspection of the abovementioned vehicle
10/09/2018 at the premises of M/s Wearnes Automotive and have the following to report:

Workshop Estimate Amount
Revised Estimate Amount
"Check" Items Amount
Market Value
LTA Reimbursement Value
Nett Value

: S\$ 17,508.10
: S\$ 13,345.80
: S\$ 1,717.80
: S\$ _____
: S\$ _____
: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-08-2018	Our Ref No. D18006520MFSH
Accident Date	30-08-2018	Claim Type. Third Party
Insured Vehicle	SH6778H	Third Party Vehicle. SKV6541U
Survey Location	45 LENG KEE ROAD	
Contact Person.	MICHELLE ONG	
Contact No.	91294556/ 91294556	Fax No. 62647137
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 13 September 2018 4:02 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006520MFSH/1
Attachments: PRELI ADVISED SKV 6541U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKV 6541U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 5 September 2018 5:06 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006520MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 5 September 2018 9:59 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006520MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 22 November 2018 9:37 AM
To: Michelle Ong Siew Bee; Richmond Ho; Rasul (LKKAuto); SUR
Subject: RE: Final Bill For SKV6541U

Dear Michelle,

Confirm final figure \$16184.94 at 15days

Please submit invoice direct to first capital

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Sent: Wednesday, 21 November 2018 2:46 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Richmond Ho <richmond.ho@wearnes.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Final Bill For SKV6541U
Importance: High

Dear Denise,

Please find revised Final Bill as attached.

Kindly revert with Finalized Confirmation asap.

Thanks.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

SERVICE ESTIMATE

83048 - C00001 SL: SERVICE SALES - PC

Mr Chua Yong Khian

Apt Blk 458 Yishun Ave 11
#07-752

Singapore 760458

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 01/09/2018

WIP No. : 24671

Veh.In/Out:

*Tel.No. : Mobile: 96647751

Reg.No. : SKV6541U

Reg.date : 28/09/2015

Mileage : 0

Chassis No: VF1BZS00E52699171

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Chua Yong Khian

Dp.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	B
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR BRACKET, REAR SENSOR, REAR BEAM, REAR BOOT LID, REAR END PANEL	0	4500.00	0		4,500.00 S	3600 ✓
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, REAR END PANEL, ETC	0	2800.00	0		2,800.00 S	2000 ✓
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S	✓
802	TO REPLACE REAR WINDSCREEN	0	450.00	0		450.00 S	✓
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1350.00	0		1,350.00 S	800 ✓
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S	✓
R06	TO INSTALL REAR NUMBER PLATE	0	60.00	0		60.00 S	74 ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S	✓

SERVICE ESTIMATE

83048 - C00001 SL: SERVICE SALES - PC

Mr Chua Yong Khian

Apt Blk 458 Yishun Ave 11
#07-752

Singapore 760458

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 01/09/2018

WIP No. : 24671

Veh.In/Out:

*Tel.No. : Mobile: 96647751

Reg.No. : SKV6541U

Reg.date. : 28/09/2015

Mileage : 0

Chassis No: VF1BZS00E52699171

Closed by : Michelle Ong Siaw Be

Svc Consultant :

Remarks : Mr Chua Yong Khian

Op.No Description Mech Qty Price Disc% Pkg Amount G

BUMPER REAR TOP (M3)	1.0 EA	576.60	584.37	576.60	S DE-
BUMPER REAR LOWER (M)	1.0 EA	317.10	306.18	317.10	S DE-
FIXING BRACKET	1.0 EA	142.10	118.44	142.10	S ? new
FIXING BRACKET	1.0 EA	142.10	124.17	142.10	S ? new
FIXING BRACKET	1.0 EA	114.40	108.38	114.40	S DE-
TOW COVER REAR	1.0 EA	64.60	68.22	64.60	S DE-
BUMPER REAR MLDG (M2)	1.0 EA	419.30	328.32	419.30	S new - ? DE-
REAR BUMPER PANEL	1.0 EA	420.50	383.71	420.50	S ? DE-
INNER PANEL REAR	1.0 EA	548.90	498.24	548.90	S ? new
TAILLAMP LH BZ10	1.0 EA	200.20	X	200.20	S ? new
TAILLAMP RH BZ10	1.0 EA	200.20	X	200.20	S ? new
REFLECTOR LAMP LH L3	1.0 EA	89.20	81.90	89.20	S CRA-
REFLECTOR LAMP RH L3	1.0 EA	89.20	X	89.20	S X new
BOOT REAR	1.0 EA	1282.70	1155.68	1282.70	S ? new
WINDSCREEN REAR	1.0 EA	612.70	560.34	612.70	S new - photo?
PRIMER	1.0 EA	176.60	159.84	176.60	S new
WINDSCREEN SEALANT	2.0 EA	112.10	201.78	224.20	S new

SERVICE ESTIMATE

83048 - C00001 SL: SERVICE SALES - PC
 Mr Chua Yong Khian
 Apt Blk 458 Yishun Ave 11
 #07-752

Singapore 760458

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 01/09/2018

WIP No. : 24671

Veh.In/Out:

*Tel.No. : Mobile: 96647751

Reg.No. : SKV6541U

Reg.date. : 28/09/2015

Mileage : 0

Chassis No: VF1BZS00E52699171

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Chua Yong Khian

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

LOGO REAR M3
 REAR LOGO 'MEGANE' M
 LOGO
 GT LINE BRMM
 BODY PANEL SEALANT X
 ADHESIVE SEALER FL2

1.0 EA	105.30	105.30	X	105.30	S	X	M
1.0 EA	120.50	108.81		120.50	S	ne	-
1.0 EA	81.00	80.01		81.00	S	ne	-
1.0 EA	77.80	76.86		77.80	S	ne	-
1.0 EA	937.50	847.96		937.50	S	ne	-
1.0 EA	425.40	404.19		425.40	S	ne	-

Pls check
 why so
 expensive

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Same
 Hp 90010068
 15 days
 10/09/18 @ 1620

13/9/18

19582.76

Labour Total	10,140.00
Parts Total	7,368.10
Package Total	0.00

Gross Total.	17,508.10
Net.....	17,508.10
GST @ 7.0%	1,225.57
Total.....	18,733.65
Paid.....	0.00
Please Pay..	18,733.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

19438.10

19410.7
 19539.58

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

Inv.No. : B&P 0 Page 1
 Inv.date : 21/11/2018
 WIP No. : 24671
 Veh.In/Out: 10/09/2018 02/11/2018
 *Tel.No. :
 Reg.No. : SKV6541U
 Reg.date : 28/09/2015
 Mileage : 51,399
 Chassis No: VF1BZS00E52699171

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Chua Yong Khian

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR BRACKET, REAR SENSOR, REAR BEAM, REAR BOOT LID, REAR END PANEL	0	3600.00	0		3,600.00	S /
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, REAR END PANEL, ETC	0	2000.00	0		2,000.00	S /
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	S /
802	TO REPLACE REAR WINDSCREEN	0	450.00	0		450.00	S /
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	800.00	0		800.00	S /
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S /
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00	S /
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S /

SERVICE ESTIMATE

0 - F00003
FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No: M28920628X

Inv.No. : 8&P 0 Page 2

Inv.date. : 21/11/2018

WIP No. : 24671

Veh.In/Out: 10/09/2018 02/11/2018

*Tel.No. :

Reg.No. : SKV6541U

Reg.date. : 28/09/2015

Mileage : 51,399

Chassis No: VF1B2S00E52699171

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Chua Yong Khian

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER REAR TOP (M3) ①	1.0 EA	649.30	10		584.37	S
	BUMPER REAR LOWER (M2) ②	1.0 EA	340.20	10		306.18	S
	FIXING BRACKET ③	1.0 EA	131.60	10		118.44	S
	TOW COVER REAR ④	1.0 EA	75.80	10		68.22	S
	BUMPER REAR MLDG (M2) ⑤	1.0 EA	364.80	10		328.32	S
	INNER PANEL REAR ⑥	1.0 EA	553.60	10		498.24	S
	REFLECTOR LAMP LH L ⑦	1.0 EA	91.00	10		81.90	S
	BOOT REAR ⑧	1.0 EA	1284.00	10		1,155.60	S ✓
	WINDSCREEN REAR ⑨	1.0 EA	622.60	10		560.34	S
	PRIMER ⑩	1.0 EA	176.60	10		158.94	S
	WINDSCREEN SEALANT ⑪	2.0 EA	112.10	10		201.78	S
	REAR LOGO 'MEGANE' H ⑫	1.0 EA	120.90	10		108.81	S
	LOGO ⑬	1.0 EA	88.90	10		80.01	S
	GT LINE BMMH ⑭	1.0 EA	85.40	10		76.86	S
	BODY PANEL SEALANT X ⑮	1.0 EA	942.20	10		847.98	S
	ADHESIVE SEALER FL2 ⑯	1.0 EA	549.10	10		494.19	S
	TRIM CLIP M2 C3 (A) Nec ⑰	20.0 EA	4.30	10		77.40	S A

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 21/11/2018

WIP No. : 24671

Veh.In/Out: 10/09/2018 02/11/2018

*Tel.No. :

Reg.No. : SKV6541U

Reg.date. : 28/09/2015

Mileage : 51,399

Chassis No: VF1BZS00E52699171

Closed by : Michelle Ong Siew Be

Svc Consultant : ACC

Remarks : Mr Chua Yong Khian

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FIXING BRACKET ② (K)	1.0 EA	143.20	10		128.68	S
	RIVET SILVER, REAR B <i>supp nec</i>	20.0 EA	0.60	10		10.80	S A
	FIXING BRACKET ④	1.0 EA	141.30	10		127.17	S
	BUFFER HOLDER C3 <i>supp nec</i>	2.0 EA	14.80	10		26.64	S A
	REAR BUMPER PANEL ③	1.0 EA	431.90	10		388.71	S
	BUMPER PANEL SEAL RE <i>nec</i>	2.0 EA	29.70	10		53.46	S A
	APRON PANEL <i>BT</i>	1.0 EA	440.10	10		396.09	S A
	BUMPER REAR LOWER MO <i>supp</i>	1.0 EA	559.20	10		503.28	S A
	CARPET-STORAGE TRAY <i>nec</i>	1.0 EA	35.80	10		32.22	S A
	SPARE TYRE PANEL DZ1 <i>cra</i>	1.0 EA	977.90	10		880.11	S A

Gross Total. 16,184.94

Labour Total 7,890.00
 Parts Total 8,294.94
 Package Total 0.00

Net..... 16,184.94
 GST @ 7.0% 1,132.95
 Total..... 17,317.89
 Paid..... 0.00
 Please Pay.. 17,317.89

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016228/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6778H	Veh. Inspected	SKV 6541U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006520MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT MEGANE III 1.5	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1BZS00E52699171	Colour	GREY	
Odometer	51399	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/08/2018	Inspection Date	10/09/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 6541U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR TOP (M3)(SN)	DEFORMED	584.37	584.37
1	BUMPER REAR LOWER (M)(SN)	DEFORMED	317.10	306.18
1	FIXING BRACKET (SN)	NECESSARY	142.10	118.44
1	FIXING BRACKET (SN)	NECESSARY	142.10	127.17
1	FIXING BRACKET (SN)	DEFORMED	128.88	128.88
1	TOW COVER REAR (SN)	DEFORMED	68.22	68.22
1	BUMPER REAR MLDG (M2)(SN)	NECESSARY	419.30	328.32
1	REAR BUMPER PANEL (SN)	DEFORMED	420.50	388.71
1	INNER PANEL REAR (SN)	BENT	548.90	498.24
1	TAILLAMP LH BZ10 (SN)	SERVICEABLE	200.20	-
1	TAILLAMP RH BZ10 (SN)	SERVICEABLE	200.20	-
1	REFLECTOR LAMP LH L3 (SN)	CRACKED	89.20	81.90
1	REFLECTOR LAMP RH L3 (SN)	SERVICEABLE	89.20	-
1	BOOT REAR (SN)	BENT	1,282.70	1,155.60
1	WINDSCREEN REAR (SN)	NECESSARY	612.70	560.34
1	PRIMER (SN)	NECESSARY	176.60	158.94
2	WINDSCREEN SEALANT (SN)	NECESSARY	224.20	201.78
1	LOGO REAR M3 (SN)	NOT NECESSARY	105.30	-
1	REAR LOGO "MEGANE" M (SN)	NECESSARY	120.50	108.81
1	LOGO (SN)	NECESSARY	81.00	80.01
1	GT LINE BHMM (SN)	NECESSARY	77.80	76.86
1	BODY PANEL SEALANT X (SN)	NECESSARY	937.50	847.98
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	494.19	494.19
20	RIVET SILVER REAR 8 (SN)(ADDITIONAL)	NECESSARY	10.80	10.80
2	BUFFER HOLDER C3 (SN)(ADDITIONAL)	NECESSARY	26.64	26.64
2	BUMPER PANEL SEAL RE (SN)(ADDITIONAL)	NECESSARY	53.46	53.46
1	APRON PANEL (SN)(ADDITIONAL)	BENT	396.09	396.09
1	BUMPER REAR LOWER MO (SN)(ADDITIONAL)	DEFORMED	503.28	503.28
1	CARPET-STORAGE TRAY (SN)(ADDITIONAL)	NECESSARY	32.22	32.22
1	SPARE TYRE PANEL DZ1 (SN)(ADDITIONAL)	CRACKED	880.11	880.11
1	REAR NUMBER PLATE INCLUDE HOLDER (SN)	BENT	60.00	60.00

Report Ref No. CS/FC18016228/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20	TRIM CLIP M2 C3 (SN)(ADDITIONAL)	NECESSARY	77.40	77.40
			9,502.76	8,354.94
	LABOUR			
	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR BRACKET, REAR SENSOR, REAR BEAM, REAR BOOT LID, REAR END PANEL.		4,500.00	3,600.00
	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, REAR END PANEL, ETC.		2,800.00	2,000.00
	TO TRANSFER REAR BOOT LID PART.		250.00	250.00
	TO REPLACE REAR WINDSCREEN.		450.00	450.00
	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS.		1,350.00	800.00
	TO INSTALL REAR WINDSCREEN FIL.		280.00	280.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		450.00	450.00
			10,080.00	7,830.00
	GRAND TOTAL		19,582.76	16,184.94
RECOMMENDED COST OF REPAIRS				16,184.94

Report Ref No. CS/FCI18016228/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.