

ASS. REC. BY:

REF: CS/FCI 18016230/719d3 n2

Special Instructions:

Survivor

CWS

From (Person):

Tawfik
Eileen Lee

ASSIGNMENT (Office)

FCI

Date/Time: 5/9/18 @ 10:05am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKM 1776P

Insured:

SHB 4058C

at Workshop m/s:

Volkswagen

Tel:

G3057176

of:

247 Alexander Rd

Policy No.:

Claim No.:

D180UGS36MFSH

Sum Insured:

Excess:

Make of Veh.:

(Client's Record)

D.O.A.

31/08/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

10:29am @ 5/9/18

Person Contacted:

Chermaine

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKM 1776P - X

SHB 4058C-CC3 / TMI 18067174 / Rlvbe 2 DOA: 13/4/18

25/9/18 @ 2:07pm Vended to Eileen Lee by email.

29/9/18 @ 10:44am confirmed with Chermaine final fig @ 3709.86, 3 days.

(Red @ 4249.35, 54%)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

430 PM

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SICM / 776P Yr Regn: 2014 Jan.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Vs / Langer Jet C.C. 1390Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 84596 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: www 222 / 69E Mob 7440Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205 / 55 R16R: 2 -BS / DUN / EXNOVA / GY / FS / LIZA MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 20/9/18 @ 630Survey held at V/V AlexmohDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) 05/10 4:15 PM

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 160Transportation: 50) S + RS SI 50) Photos: 26

) Others: _____

TOTAL

286Report Format: TRLump Sum / I.B.I: (\$ 3709.86)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016230/T1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Date : 05-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4058C	Veh. Inspected	SKM 1776P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006536MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/08/2018	Inspection Date	20/09/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date 03-09-2018 **Our Ref No.** D18006536MFSH

Accident Date 31-08-2018 **Claim Type.** Third Party

Insured Vehicle SHB4058C **Third Party Vehicle.** SKM1776P

Survey Location 247 ALEXANDRA ROAD

Contact Person. CHARMAINE KONG

Contact No. 63057176/ 63057299 **Fax No.** 64743643

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop VOLKSWAGEN CENTRE **Attention.** NIL
SINGAPORE

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge EILEEN LEE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 September 2018 10:41 AM
To: Ong, Germaine (VWG Singapore); Taufikh (LKKAUTO)
Cc: Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Goh, Edmund (VWG Singapore); Admin A; SUR
Subject: RE: FINALISATION SKM1776P *** LKK REF: CS/FCI18016230/T1qd3

Dear Germaine,

WITHOUT PREJUDICE

Confirm final fig \$3,709.86 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 26 September 2018 7:02 PM
To: Ong, Germaine (VWG Singapore) <Germaine.ong@vw.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINALISATION SKM1776P *** LKK REF: CS/FCI18016230/T1qd3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/FCI18016230/T1qd3	Shiau Chan

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 25 September 2018 2:07 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006536MFSH/1
Attachments: CSFCI18016230T1qd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SKM 1776P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 5 September 2018 10:31 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006536MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 5 September 2018 10:05 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006536MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006536MFSH

Date: 25 September 2018

Our Ref: CS/FCI18016230/T1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKM 1776P .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/09/2018 at the premises of M/s VOLKSWAGEN, and have the following to report:-

Workshop Estimate Amount	: S\$ 8,009.21 .
Revised Estimate Amount	: S\$ 3,709.86 .
"Check" Items Amount	: S\$ 1,019.35 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

VW DRIVEEASY

RENEWAL CERTIFICATE

Policy Number	Period of Insurance	Place of Issue
A 80422828 AVW	28/01/2018 to 27/01/2019	SINGAPORE
Name and Address of Insured	Date of Issue	Account Number
Chua Choo Huat 431 Tampines Street 41 #10-527 Singapore 520431	05/01/2018	156346
Premium	GST	Total Due
SGD774.96	SGD54.25	SGD829.21

RISK NUMBER 1

VW DRIVEEASY

OCCUPATION

Indoor Occupation

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO.	SKM1776P	SUM INSURED	MARKET VALUE
MAKE/MODEL	Volkswagen Jetta 1.4 TSI	INCL. COE/PARF	YES
ENGINE NUMBER	CAXD84250	OFF-PEAK CAR	NO
CHASSIS NUMBER	WVWZZZ16ZEM007440	NO CLAIM DISCOUNT	50.00% (or F/D)
YEAR OF MFG	2013	GOOD DRIVER'S	
CAPACITY	1390 C.C.	DISCOUNT	SGD40.79
SEATING CAPACITY	5 (INCL. DRIVER)	NCD PROTECTOR	COVERED
WINDSCREEN	UNLIMITED	EXCESS	SGD500
		ANNUAL PREMIUM	SGD774.96


ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Chua Choo Huat
Lee Wai Foon

Any other person provided he is driving on the Insured's order or with the Insured's permission.

Sketch Plan #4



PDI TUAS

PDI TUAS

CHUA CHOO HUAT
431 TAMPINES STREET 41
#10-527
Singapore, 520431
Singapore

Tanpin 97495749
WP

20/9/18 @ 1650

Repair before paint

sure@lmcars.com

03 days

25/9/18

Phone No.

Fax No.

E-Mail

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV024642
Quote No. SER/QUO/1801461
QuoteDate 31/08/18
Salesperson Delsie Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA A6 1.4 TSI DSG 90KW TL	59,681	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKM1776P	WVWZZZ16ZEM007440	28/01/14	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX D84250	1622G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		400.00 X
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				6,080.00
P 5C6807305	BUMPER REINFORCEMENT	1	Pieces		383.25 X
P 5C6807393	BUMPER BRACKET LH	1	Pieces		55.32 X
	Successor 5C6807393B				
P 5C6807393A	BUMPER GUIDE LH	1	Pieces		70.11 X
P 5C6807394	BUMPER BRACKET RHS	1	Pieces		40.56 X
	Successor 5C6807394B				
P 5C6807394A	BUMPER GUIDE RH	1	Pieces		70.11 X
P 5C6807421 GRU	REAR BUMPER COVER	1	Pieces		832.95
P 5C6807433	SPOILER	1	Pieces		411.75
P 5C6807863	STRIP	1	Pieces		65.16
	Sum Item				1,929.21

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

CHUA CHOO HUAT
431 TAMPINES STREET 41
#10-527
Singapore, 520431
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV024642
Quote No. SER/QUO/1801461
QuoteDate 31/08/18
Salesperson Delsie Ong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description
Volkswagen Passeng	JETTA A6 1.4 TSI DSG 90KW TL
License No.	VIN
SKM1776P	WVWZZZ16ZEM007440
Engine Code	Labor Type
	M4

Mileage	Service Advisor
59,681	Kong Charmaine
Initial Registration	Sales Advisor
28/01/14	Delsie Ong
Engine No.	Model Code
CAX D84250	1622G5

Sum Labor	6,080.00
Sum Item	1,929.21

Total SGD	8,009.21
7% GST	560.65
Total SGD Incl. GST	8,569.85

Explanations

P = Proportionately Charged

Payment Terms No Credit

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 18IP2436

CUSTOMER NO.: CV024642

CUSTOMER NAME: CHUA CHOO HUAT

TELEPHONE NO.:

ADDRESS: 431 TAMPINES STREET 41 #10-527

Singapore

VEH No.: SKM1776P

Order Date: 20/09/18

Reg Date: 28/01/14

KM: 84,842

VIN NO.: WVVZZZ16ZEM007440

ENGINE NO:

SA: Kong Charmaine

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480	480
2	B&P MECH	CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280	280
3	B&P ALEX LABOUR	LABOUR	1	UNIT	840	840
4	B&P ALEX PAINT	SPRAY PAINT	1	UNIT	800	800
5	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
6	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
Item						
7	5C6807421 GRU	REAR BUMPER COVER	1	PCS	832.95	832.95
8	5C6807433	SPOILER	1	PCS	411.75	411.75
9	5C6807863	STRIP	1	PCS	65.16	65.16

Remarks : DIRECT SETTLEMENT

DOA: 31/08/2018

TP VEHICLE NO: SHB4058C

SURVEY BY: TAUFIKH LKK

TOTAL	3,709.86
GST AMOUNT	259.69
TOTAL AMOUNT	3,969.55

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016230/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4058C	Veh. Inspected	SKM 1776P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006536MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WWWZZZ16ZEM007440	Colour	BLUE	
Odometer	84596	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2018	Inspection Date	20/09/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 1776P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	383.25	-
1	BUMPER BRACKET LH (SN)	NOT NECESSARY	55.32	-
1	BUMPER GUIDE LH (SN)	NOT NECESSARY	70.11	-
1	BUMPER BRACKET RHS (SN)	NOT NECESSARY	40.56	-
1	BUMPER GUIDE RH (SN)	NOT NECESSARY	70.11	-
1	REAR BUMPER COVER (SN)	DEFORMED	832.95	832.95
1	SPOILER (SN)	CUT	411.75	411.75
1	STRIP (SN)	NECESSARY	65.16	65.16
			1,929.21	1,309.86
	<u>LABOUR</u>			
	LABOUR.		2,520.00	840.00
	SPRAY PAINT.		2,400.00	800.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	CHECK WIRE HARNESS, ECU, S.		280.00	280.00
	SUPPLY & INSTALL REVERSE SE.	NOT NECESSARY	400.00	-
			6,080.00	2,400.00
	GRAND TOTAL		8,009.21	3,709.86
	RECOMMENDED COST OF REPAIRS			3,709.86

Report Ref No. CS/FCI18016230/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.