

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 07 Sep 2018

Preliminary Advice

Insured Vehicle No	: SCE3009U	Accident Date	: 03/09/2018
TP Vehicle No	: SLM6069C	Assignment Date	: 05/09/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 9.00
Date of Inspection	: 06/09/2018		
Inspection At	: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	18,802.10
Revised Amount	:S\$	10,552.57
Check Items (Estimated)	:S\$	297.53
Total	:S\$	10,850.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. Some of the parts pending for parts prices.