



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLC6360M  
Date of Accident : 04 September 2018

Mr Ang Teck Loong

Date : 05 September 2018

Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8LA  
Chassis No : LXS120026597

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	right rear lamp CM	\$ 433.70
02	3 ps	right rear lamp clip holders @ \$85.00 17	\$ 255.00
03	1 pc	right rear fender 3.55.00	\$ 775.70
04	1 pc	right rear fender inner liner 70.1	\$ 142.50
05	4 ps	right rear fender inner liner clips @ \$4.50 11	\$ 18.00
06	1 pc	right rear fender 1/4 glass weatherstrip 11	\$ 89.00
07	1 pc	right rear fender air vent 3.20	\$ 71.00
08	1 pc	right rear fender inner trim 566.10	\$ 844.40
09	4 ps	right rear fender inner trim clips @ \$4.50 11	\$ 18.00
10	1 pc	right rear fender inner extension panel 304.50	\$ 308.10
11	1 pc	battery tray 17	\$ 80.00
12	1 pc	battery brackets 11	\$ 35.00
13	1 pc	rear bumper D-5	\$ 552.30
14	1 pc	right rear bumper side retainer CM	\$ 111.50
15	1 pc	right rear bumper side holder 3.51	\$ 45.00
16	10 ps	rear bumper clips @ \$4.50 11	\$ 45.00
17	1 pc	right rear bumper end splashshield cover 70.1	\$ 115.80
18	1 pc	rear luggage floor panel 11	\$ 998.00
19	1 pc	right rear luggage floor panel side trim 11	\$ 102.10
20	2 ps	rear bumper screw spacer @ \$4.30 11	\$ 8.60
21	2 pc	rear bumperspacer screw @ \$4.50 11	\$ 9.00
22	1 pc	rear end panel 3.55.00	\$ 602.10
23	1 pc	rear end panel inner trim 11	\$ 121.10
24	1 pc	rear exhaust box 11	\$ 1,113.80
25	1 pc	rear exhaust box heat shield 11	\$ 122.20
26	2 ps	rear exhaust box mounts @ \$41.10 11	\$ 82.20
27	1 pc	right rear shock absorber 11	\$ 116.80
28	1 pc	right rear wheel bearing with hub 11	\$ 610.20
29	1 pc	front bumper 70.1 655.10	\$ 1,569.00
30	1 pc	front bumper reinforcement 3.51	\$ 691.00
31	1 pc	front bumper tow cover 70.1	\$ 45.00
32	1 pc	front bumper absorber foam 70.1	\$ 125.00
33	1 pc	front bumper lower beam 11	\$ 110.00
34	2 ps	front bumper lower beam brackets @ \$75.00 11	\$ 150.00
35	1 pc	front bumper lower beam garnish 11	\$ 85.00
36	2 ps	front bumper side retainer @ \$95.00 3.51	\$ 190.00
37	1 pc	right front bumper indicator lamp 11	\$ 511.80
38	1 pc	right front bumper lower centre air grille 11	\$ 168.00
39	1 pc	front bumper emblem badge 11	\$ 78.00

AI/Asia Insured's Veh No : SLC6360M  
Date of Accident : 04 September 2018

Mr Ang Teck Loong

Plaintiffs hence notify the following:  
after spray painting  
subject to confirmation  
is on a "Without Prejudice" basis  
No alteration/changes allowed  
Surface finish must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel: 68585151 (24 Hours) Fax: 68580877  
GST Regn. No. : M2-8922054-2

Date : 05 September 2018

**Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8LA**  
Chassis No : LXS120026597

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	3 ps	front bumper emblem badge clips @ \$45.00	\$ 135.00
41	1 pc	right front bumper air guide	\$ 125.60
42	1 pc	front bumper lower splashshield cover	\$ 178.30
43	1 pc	front bumper upper centre air grille	\$ 148.60
44	1 pc	front bumper upper weatherstrip	\$ 128.60
45	6 ps	front bumper upper weatherstrip clips @ \$4.50	\$ 27.00
46	1 pc	right headlamp	\$ 3,380.30
		Less 25 %	\$ 15,642.30
			\$ 3,910.58
			\$ 11,731.73
<u>SPECIAL NETT ITEMS</u>			
47	1 pc	right rear fender 1/4 glass sealant	\$ 100.00
48	1 pc	battery	\$ 250.00
49	1 set	rear bumper parking sensor	\$ 450.00
50	1 pc	right rear wheel rim	\$ 380.00
51	1 pc	right rear wheel tyre	\$ 280.00
			\$ 1,460.00
<u>LABOUR &amp; MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 150.00
03		To remove and refit rear fender 1/4 window glass.	\$ 100.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To check steering geometry and computer wheel alignment.	\$ 120.00
06		To drop rear exhaust box and renew the same.	\$ 150.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
08		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 400.00
09		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 550.00
10		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,950.00
11		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 5,040.00
			\$ 18,231.73
		Total	\$ 18,231.73

645891

40  
x  
200  
200  
x

20  
50  
60  
100  
60  
x  
80  
x  
1200  
1000  
3010



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP007092018

Date : 24-09-2018

Your Ref : CC6/ALH18016247/4563

WITHOUT PREJUDICE

Claims Department - Motor Claims LKK  
c/o ALH ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SH2163H & SLC6360M ON 04-09-2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / \_\_\_\_\_ copies of photographs \_\_\_\_\_

☒ Original Tax-invoice number TP09181013

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☐ Vehicle search result

☒ Authorisation To Act

☐ \_\_\_\_\_

\*Survey under insurance instruction - LKK

a)	Cost of repair (inclusive GST)	\$	6,687.50
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [A150 x 10 days]	\$	1,500.00
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)		\$	
Total		\$	8,194.99

\* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg





**TAX-INVOICE**  
**NUMBER: TP0918/013**

(Please quote our reference number SM007092018 for payment)

**陳林摩哆私人有限公司**  
**TAN LIM MOTOR PTE LTD**

Ang Teck Loong

Date: 14/09/2018

Vehicle No: SH 2163H  
Model: TOYOTA PRIUS HYBIRD

Description	Amount
To lump sum repair as recommended by surveyor.	\$6,250.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$6,257.00
Add 7% GST	\$437.99
<b>Total</b>	<b>\$6,694.99</b>

  
\_\_\_\_\_  
Tan Lim Motor Pte Ltd



AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ang Teck Loung ("the third party claimant")  
of Block 406 Sin Ming Avenue #07-237 Singapore 570406 (address),  
owner of SH 21631H (vehicle no.) hereby authorize  
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SH 21631H that was  
damaged pursuant to the accident which occurred on 04/09/2018 (date) along  
Junction of Ang Mo Kio Avenue 1 and Ang Mo Kio Avenue 8 (location)  
involving vehicle no/s SLC 6360M ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 05 day of Sep (month) 20 18 (year)

Signed by "the third party claimant"



Signed by "the workshop"

**Enquire Vehicle & Owner Information ( Vehicle No. SLC6360M As At 04 Sep 2018 / 23:20:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: SRSTP.SH2163H.TLM

**Current Owner Details**

Owner ID Type: Company  
Owner ID: 199403356Z  
Owner Name: MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 26  
Registered Street Name: TAI SENG STREET  
Registered Unit No.: # 01 - 03A  
Registered Building Name: J'FORTE  
Registered Postal Code: 534057  
**Current Vehicle Details**

Vehicle No.: SLC6360M ✓  
Make Description/Model: HONDA / VEZEL 1.5X A  
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.