

ASS. REC. BY:

REF: CS/CTI18016269/R1rd3/9

Special Instruction:

Surveyor  
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Chang Boonsen

of

CTI

Date/Time:

6/9/18 @ 11:16am

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 4034Z

Insured:

GBD604M

at Workshop m/s

comfort Delgro

Tel:

6383 8115

of

205 Braddell Rd

Policy No:

DMCVSN 3036981800

Claim No:

SNM18D04324C02

Sum insured:

Excess:

Make of Vehl:

(Client's Record)

D.O.A. 01/09/2018

CA / REV / REP. / REV 24 HRS

Imp?

H.O.D. Endorsement:

Date/Time:

11:51am @ 6/9/18

Person Contacted:

willram

Vehicle  IN  OUT

Date/Time	Action/Instruction ( - ) Estimate
	SLB 4034Z-CC312CR17007227/11da3s2      Don: 5/4/17
	GBD604M-X.

Signature: *[Handwritten Signature]*

REF:

4557K

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD /  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SLB 40342  
 at Workshop mis: COMFORT DELERO  
 of BRADSELL  
 Insured: CTI  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLB 40342 Yr Regn: 2016 / APR  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: HONDA SHUTTLE HB157.c.c 1496  
 Colour: BLACK A/C: Insured / Std / NI / NA  
 Sp. Reading: 193848 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GP 71015257  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  in order / Jammed / Leaked / Burnt or  
 Brake:  in order / Jammed / Leaked / Burnt or  
 Mod: Nil /  Rim / STD A/Rim or  
 Tyre Size: F: 185/60R15  
 R: 185/60R15

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /  PHR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A. 01/09/18 D.O.I. 06/09/18  
 Survey held at: COMFORT

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/10	Continued final by 24,254.32 and 5 days with William. (Red. HFF. 12,36%)

RECEIVED 15 OCT 2018

Date/Time. File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time. File Return to?

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee:	
Transportation:	
Photos:	
Others:	
TOTAL:	

Report Format: TP  
 Lump Sum /  (B): 15 4,254.32



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CT118016269/R1rd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 06-09-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 604M	Veh. Inspected	SLB 4034Z
Policy No.	DMCVSN3036981800	Coverage (\$)	0.00
Claim No.	SNM18D04324C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/09/2018	Inspection Date	06/09/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018		06 Sep 2018 11:16 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLB4034Z	Date of Loss:	01/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04324C02	Policy/Cover Note No.:	DMCVSN3036981800
Vehicle Reg. No. (Insured):	GBD604M	Policy No. (Claimant):	
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]		
Adj Asg. Remarks:	EST \$6731.44, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLB4034Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	LEB4228577
Chassis No.:	GP71015257
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,110.00
Original Registration Date:	06 Apr 2016
First Registration Date:	06 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$7,954.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Apr 2026
PARF Rebate Amount:	\$5,965.00
Intended COE Rebate Details	
COE Expiry Date:	05 Apr 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$46,667.00
COE Rebate Amount:	\$34,753.00
<b>Total Rebate Amount:</b>	<b>\$40,718.00</b>

The information contained herein is correct as at 15 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/09/2018 10:39
Date Of Accident	01/09/2018 13:25
Exact Location Of Accident	JUNC SUNGEI KADUT AVE AND SUNGEI KADUT ST 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4034Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	INSURANCE@LIONCITYRENTALS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID 1.5X AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SLB4034Z
Cover Note Number	

### Driver

Name of Driver	MOHAMED AKBER BIN A K S OTHUMAN GHANY
NRIC No	S1416611D
Date Of Birth	05/11/1960
Occupation	INDOOR
Date Of Driving Pass	25/01/1980
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90051993
Fax Number	
Contact Number	
Email Address	AKBER.KYARA@GMAIL.COM

Address	BLK 399 YISHUN AVE 6 #11-1180
Postcode	760399
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MR GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD604M
Vehicle Make/Model/Colour	NISSAN / CABSTAR
Details Of Properties	RUKUMAN THIRUMALAI
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	G7907512X
Contact Number	83465443
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FRN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON SATURDAY 01<sup>ST</sup> SEPT 2016 AT ABOUT 1325H WHILE COMEYING FROM VERDUN ROAD TO SUNGEI KADUT ST. 4 STOPPED AT TRAFFIC JUNCTION SUNGEI KADUT AVENUE TO MAKE A RIGHT TURN INTO SUNGEI KADUT STREET 1. STOPPED AT JUNCTION AND VEHICLE TRAFFIC LIGHT SHOWING RED. WHEN TURNS GREEN FRONT<sup>ME</sup> MOVES FORWARD AND I THEN JUST MOVED FORWARD, A NISSAN CABSTAR GDB 604M SLAMMED MY REAR (BACK OF MY VEHICLE). DAMAGED TO MY REAR (BACK) AND TO THE NISSAN CABSTAR DAMAGED IT'S FRONT. THAT'S ALL



DECLARATION

(We declare the foregoing particulars are true in every respect.)

  
Policyholder's Signature

Date & Time:

  
Driver's Signature

(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 3

REPUBLIC OF SINGAPORE DRIVING LICENSE

License Number: S1416611D



MOHAMED AKBER BIN A K S  
OTHUMAN GHANY

Birth Date: 05 Nov 1960  
Issue Date: 02 Jan 2003

000075829G

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1416611D



Name:  
MOHAMED AKBER BIN A K S  
OTHUMAN GHANY

Race:  
INDIAN

Date of birth: 05-11-1960  
Country of birth: SINGAPORE

Sex: M

4788773

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Class	ISSUE DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	25 Jan 1998

4284

License No: S1416611D

4788773



ISSUE NO: S1416611D



Date of issue:  
12-08-2011

Address:  
APT BLK 399 YISHUN AVENUE 6  
#11-1180  
SINGAPORE 780399



HOTLINE TEL: (65) 6415-3000  
FAX: (65) 6415-3723

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1988

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)

M.Z.00

		(The below excess is subject to GST)	
COMPREHENSIVE COMMERCIAL MOTOR		ALL CLAIMS EXCESS	S\$2000.00
CERTIFICATE NO.	SLB4034Z	WINDSCREEN EXCESS	S\$100.00
		SUM INSURED	Market Value
		INSURING WITH COE/PARF	Yes
1 ) VEHICLE REGISTRATION NO.		SLB4034Z	
2 ) NAME OF INSURED		LCRF Pte Ltd	
3 ) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		25 February 2018	
4 ) DATE OF EXPIRY OF INSURANCE		24 February 2019	
5 ) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*	Any person who is driving on the Insured's order or with their permission.		
	If You or Your Authorised Driver is below the age of 21 years old and/or has less than 1 year driving experience, the excess is S\$3,500(All Claims).		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.			
6 ) LIMITATION AS TO USE*	1) Use for social, domestic, pleasure purposes and business purposes of Insured 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.  The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.		
	LOSS OF USE	Not Included	
	HIRE PURCHASE COMPANY	Refer to Policy Terms and Conditions	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.			

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 13 Feb 2018

AIG Asia Pacific Insurance Pte. Ltd.

030080-000  
Aon Singapore Pte Ltd  
2 Shenton Way  
#25-01 SGX Centre 1  
SINGAPORE 068804

AUTHORISED REPRESENTATIVE

ESSAHN

ORIGINAL



Comfort Driven Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TP Vehicle No. : SLB4034Z  
 Make & Model : HONDA SHUTTLE HYBRID 1.5 CVT  
 Year of Manufacture : 2016  
 Chassis No. : GP71015257  
 Ins Company : AIG VS CHINA TAIPING Engine No. : LEB4228577  
 Excess : - Policy No. : -  
 Date of Accident : 01.09.2018 Time of Accident : 13:25  
 Suggested Days of Repair : \_\_\_\_\_ In-house Vehicle Assessor

**Repair Estimate**

Case Owner : \_\_\_\_\_  
 Signature : \_\_\_\_\_  
 Contact No  
**Frnt Counter Operation**  
 63837103 - Patrick Tia  
 63837730 - Brenda Ng  
 63837466 - Rohani  
[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)  
**Workshop Operation**  
 63837656 - Ngo Toh Wee  
 63837362 -  
 63838115 - William Wang  
 63838115 - Andrew Goh  
[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)

<b>Parts (a) Cost / List Price Items</b>	<b>\$ 4,239.30</b>
Plus/Less 20%	\$ 847.86
<b>Total of Cost / List</b>	<b>\$ 3,391.44</b>
(b) Nett Price Items	\$ -
Less	_____
<b>Total of Nett Item</b>	<b>_____</b>
(c) Special Nett Items	\$ 270.00
<b>Total Parts Cost (Appendix A)</b>	<b>\$ 3,661.44</b>
<b>Labour (Appendix B)</b>	<b>\$ 3,070.00</b>
<b>Total Repair Cost</b>	<b>\$ 6,731.44</b>

The above total will be subjected to 7% G.S.T.

Name of Surveyor	: <u>RASUL</u>
Company	: <u>LKK AUTO CONSULTANT</u>
Survey conducted on	: <u>06/09/18 @ 1556</u> at _____
<b>Remarks By Surveyor</b>	
(a) The repair of this vehicle is authorized / is not authorized until further notice.	
(b) Recommended Days of Repair	: <u>5</u> day(s) <i>part by part</i>
(c) Resurvey	: <u>Required</u> Not Required <i>10/9/18</i>
(d) Excess	: \$ _____
(e) Signature of surveyor	: <u>[Signature]</u> Date: <u>06/09/18</u>

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLB4034Z Case Owner : 0

Make & Model : HONDA SHUTTLE HYBRID Year Manufacture : 2016

Chassis No : GP71015257 Engine No : LEB4228577

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 1,150.60			PE ✓
2	Rear bumper retainer LH	1		\$ 26.50			X ✓/see
3	Rear bumper retainer RH	1		\$ 26.50			X ✓
4	Rear bumper clips	6		\$ 23.40			see ✓
5	Reverse sensor set	1				\$ 200.00	X ✓/see
6	Tailgate	1		\$ 1,193.00			PE ✓
7	Tailgate badge logo	1		\$ 38.60			see ✓
8	Tailgate emblem - SHUTTLE	1		\$ 55.00			see ✓
9	Tailgate emblem - HYBRID	1		\$ 80.10			see ✓
10	Tailgate upper lock	1		\$ 157.50			PE ✓
11	Tailgate weatherstrip	1		\$ 168.50			see ✓
12	Rear windscreen moulding	1		\$ 151.20			see ✓
13	Rear windscreen sealant	1				\$ 40.00	see ✓
14	Rear windscreen inner seal	1				\$ 30.00	see ✓
15	Rear end panel	1		\$ 601.50			Repair ✓
16	Rear end panel LH	1		\$ 205.60			X ✓
17	Rear end panel RH	1		\$ 205.60			X ✓/see
18	Rear end panel inner garnish	1		\$ 155.70			X ✓
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Labour

Vehicle No. : SLB4034Z Case Owner : 0  
 Make & Model : DA SHUTTLE HYBRID 1.5 CVT Year of Manufacture : 2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	<del>\$120.00</del>	
2	To transfer tailgate parts and fittings to new tailgate.	<del>\$180.00</del>	80
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	<del>\$280.00</del>	<del>80</del> 100
4	Labour charges to repair and panel beat the RH rear fender, rear chassis members, rear floor panel, cutting/welding and replacing damaged parts. (per day \$240.00)	<del>\$840.00</del>	600
5	To replace reverse sensor set.	\$120.00	<del>60</del> 60
6	To check wiring functions.	\$80.00	<del>20</del> 20 ✓
7	To putty, apply primer & spray-paint the rear bumper, tailgate, RH rear fender, rear end panel, rear chassis members, rear floor panel and affected areas. (per panel \$250.00)	\$1,250.00	750
8	To apply rust-proofing on repaired/replaced panels.	<del>\$200.00</del>	40
<p><b>LYC Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurface <u>color</u> after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be approved and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer                      Signature:                      Date:</p>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

## Celine Fong (LKKAuto)

---

**From:** Celine Fong (LKKAuto)  
**Sent:** Tuesday, 16 October 2018 2:36 PM  
**To:** 'CDGE Braddell Private Cars Crash Repair Operation'; assignments; Rasul (LKKAuto)  
**Cc:** Patrick Chung Chan Kim; Denis Teo Chin Chye; Kristy Tay Siew Hwa  
**Subject:** RE: SLB4034Z DOA01092018 TO FINALIZE

Dear William,

Confirm final figure \$4,254.32 and 5 days.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CDGE Braddell Private Cars Crash Repair Operation <[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)>  
**Sent:** Friday, 12 October 2018 2:36 PM  
**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** Patrick Chung Chan Kim <[patrickchung@cdge.com.sg](mailto:patrickchung@cdge.com.sg)>; Denis Teo Chin Chye <[denisteo@sparkcarcare.com](mailto:denisteo@sparkcarcare.com)>;  
Kristy Tay Siew Hwa <[kristytay@sparkcarcare.com](mailto:kristytay@sparkcarcare.com)>  
**Subject:** SLB4034Z DOA01092018 TO FINALIZE

Dear Sir,

Kindly refer to attachment and finalize the COR.

5 working days to repair.

Please reply as soon as possible.

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

**Spark Car Care**  
**ComfortDelgro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : CHINA TAIPING      Vehicle Number : SLB4034Z  
 Attn to : LKK - RASUL      Type Of Claim : TP

<b>A. Spare parts</b>	\$ 3,017.90	<b>F. Total Parts</b>	\$ 2,484.32
<b>B. Supplementary</b>	\$ -	<b>G. Total Labour</b>	\$ 1,770.00
<b>C. Nett Price</b>	\$ -	<b>H. Total Repair</b>	\$ 4,254.32
<b>D. Supp Nett Price</b>	\$ -	<b>I. Excess</b>	_____
<b>E. S/Nett</b>	\$ 70.00	<b>PIP Total</b>	<u>4,254.32</u>

Total Spare Parts Price		\$ 3,017.90
Cost plus / List Down	20%	603.58
Total		2,414.32

Total Nett Price		\$ -
Nett Price Less		\$ -
Total		-

Lump Sum Less \_\_\_\_\_ \$ -

Lump Sum Rounding \_\_\_\_\_

**Total Finalized**      \$ 4,254.32

*N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.*

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day : _____
Date Survey : _____	LOU/ Day : _____
Date Out : _____	Total LOU : _____
Sat/Sun/Ph. : _____	Rental/Day : _____
Authorized Repair Day : _____	Total Rental : _____

Submitted By / Date : WILLIAM WANG 12.10.2018	Confirmed By / Date : _____
---	--------------------------------

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837486 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLB4034Z Case Owner : 0

Make & Model : HONDA SHUTTLE HYBRID Year Manufacture : 2016

Chassis No : GP71015257 Engine No : LEB4228577

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 1,150.60			
2	Rear bumper retainer LH	1					
3	Rear bumper retainer RH	1					
4	Rear bumper clips	6		\$ 23.40			
5	Reverse sensor set	1					
6	Tailgate	1		\$ 1,193.00			
7	Tailgate badge logo	1		\$ 38.60			
8	Tailgate emblem - SHUTTLE	1		\$ 55.00			
9	Tailgate emblem - HYBRID	1		\$ 80.10			
10	Tailgate upper lock	1		\$ 157.50			
11	Tailgate weatherstrip	1		\$ 168.50			
12	Rear windscreen moulding	1		\$ 151.20			
13	Rear windscreen sealant	1				\$ 40.00	
14	Rear windscreen inner seal	1				\$ 30.00	
15	Rear end panel	1					
16	Rear end panel LH	1					
17	Rear end panel RH	1					
18	Rear end panel inner garnish	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018		06 Sep 2018 11:16 <a href="#">Edit Adj Rpt</a>	<b>S\$4,254.32</b> <a href="#">Edit Estimates</a>	<b>S\$4,254.32</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	-, ID: -								
Main Claimant:	<b>LCRF PTE LTD</b>								
Vehicle Reg. No.:	<b>SLB4034Z</b>	Date of Loss:	01/09/2018 00:00 - :59 <b>[28 Months and 26 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM18D04324C02</b>	Policy/Cover Note No.:	DMCVSN3036981800						
Vehicle Reg. No. (Insured):	<b>GBD604M</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Braddell)</b> 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 17/09/2018]</b>								
Adj Asg. Remarks:	EST \$6731.44, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLB4034Z (SNM18D04324C02)  
 [GBD604M]  
 TP  
 LCRF PTE LTD  
 Sep 1 2018 12:00AM  
 [-]  
 ComfortDelGro Engineering Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a> <span style="float: right;">▼</span>			
<b>Photos/Images</b>		3 per page <span style="float: right;">▼</span> <input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/10/18 13:43	General View	1	Load PDF	
2	16/10/18 13:45	Before Paint Photographs	1	Load PDF	
<b>Documentation</b>				1 per page <span style="float: right;">▼</span> <input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/09/18 11:15	EMAIL FM CDGE	1	Load PDF	
2	06/09/18 11:16	REPAIR EST	1	Load PDF	
3	06/09/18 11:16	TP GIA	1	Load PDF	
4	06/09/18 12:58	Singapore Accident Statement	1	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016269/R1RD3Q2

Date: 23/10/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3036981800
Claimant Vehicle No :	SLB4034Z	Insured Vehicle No :	GBD604M
Date of Loss:	01/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04324C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB4034Z</b>	Engine No:	LEB4228577
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71015257
Reg. Date:	06/04/2016 (Man. Year: 2015)	Odometer:	193848 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,661.44	2,484.32	1,177.12	32.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,770.00	1,300.00	42.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,731.44</b>	<b>4,254.32</b>	<b>2,477.12</b>	<b>36.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>471.20</b>	<b>297.80</b>	<b>173.40</b>	<b>36.80</b>
<b>Nett Amount (S\$)</b>	<b>7,202.64</b>	<b>4,552.12</b>	<b>2,650.52</b>	<b>36.80</b>

## INSPECTION

Date of Assignment:	06/09/2018	
Date Inspected:	06/09/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 23 Oct 2018)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLB4034Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.60 FL	*1,150.60 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	26.50 FL	*- FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	26.50 FL	*- FL
4	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
5	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
6	1		*TAILGATE	Bent	1,193.00 FL	*1,193.00 FL
7	1		*TAILGATE BADGE LOGO	Necessary	38.60 FL	*38.60 FL
8	1		*TAILGATE EMBLEM -SHUTTLE	Necessary	55.00 FL	*55.00 FL
9	1		*TAILGATE EMBLEM -HYBRID	Necessary	80.10 FL	*80.10 FL
10	1		*TAILGATE UPPER LOCK	Bent	157.50 FL	*157.50 FL
11	1		*TAILGATE WEATHERSTRIP	Necessary	168.50 FL	*168.50 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	151.20 FL	*151.20 FL
13	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
14	1		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
15	1		*REAR END PANEL	Repair	601.50 FL	*- FL
16	1		*REAR END PANEL LH	Serviceable	205.60 FL	*- FL
17	1		*REAR END PANEL RH	Serviceable	205.60 FL	*- FL
18	1		*REAR END PANEL INNER GARNISH	Serviceable	155.70 FL	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,509.30</b>	<b>3,087.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>847.86</b>	<b>603.58</b>
<b>Total Parts (\$\$)</b>	<b>3,661.44</b>	<b>2,484.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO TRANSFER TAILGATE PARTS AND FITTINGS TO NEW TAILGATE	New	180.00	80.00
3	TO REMOVE/REFIT BOOT COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS	New	280.00	100.00
4	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE RH REAR FENDER ,REAR CHASSIS MEMBERS ,REAR FLOOR PANEL ,CUTTUNG/WELDING AND REPLACING DAMAGED PARTS	New	840.00	600.00
5	TO REPLACE REVERSE SENSOR SET	New	120.00	60.00
6	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
7	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT THE REAR BUMPER ,TAILGATE,RH REAR FENDER ,REAR END PANEL ,REAR CHASSIS MEMBERS ,REAR FLOOR PANEL AND AFFECTED AREAS	New	1,250.00	750.00
8	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	200.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>3,070.00</b>	<b>1,770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >