

ASS. REC. BY:

REF:

CS/MSG18016272/ NS d302

Special Instruction:

Surveyor

Menimen

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSIG

Date/Time:

6/9/18 @ 9.23am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV? CS

To Inspect Vehicle No:

FBH 8275K

Insured:

YN 5635R

at Workshop m/s

Bike Production

Tel:

6392 2555

of

GIO Serangoon Rd

Policy No:

A27927444 MLC

Claim No:

569220

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/08/2018

CA / REV / REP. / REV 24 HRS

lup?

14/09/2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

10.23am @ 6/9/18

Person Contacted:

Wendy

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 8275K-X

YN 5635R-X

17/09/18

@ 14:54 p.m. revised ZA to Chhia Nyuk Pui via menimen.

04/10/18

Confirmed HS \$ 1,900/- @ 3 days with Naz

(\$ 4,346.60 Red - 70%)

Surveys

NA2

REF:

MS 16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBG 8275K Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CBF 150 C.C. _____

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 51,313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LALKC11B4C3300149

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90 R18

R: 3.60 - 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SHINKO

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 31/08/18 D.O.I. 14/9/18

Survey held at BIKE PRODUCTION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR, N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MS 16

RECEIVED 11 OCT 2018

Date/Time, File Pass to?

11/10/18

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: _____

_____ S + RS. _____ SI

Photos

Others

10

Report Format :

Lump Sum / I.B.I: (\$ 1,900/- 4/5)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

TOTAL

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Sep 2018		06 Sep 2018 09:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SL METALS PTE LTD, Co. Reg. No.: 198306087E		
Main Claimant:	SULAIMANKANI MOHAMED ABUSALITH, ID: G6583210R		
Vehicle Reg. No.:	GBF8275K	Date of Loss:	31/08/2018 17:00 - :59 [68 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569220	Policy/Cover Note No.:	A27927444MKC (Comprehensive) Coverage: 09/07/2018 - 08/07/2019
Vehicle Reg. No. (Insured):	YN5635R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/09/2018]		
Driver/Custodian (Insured):	TAN TIEW HENG (), NRIC: S1240342I, Tel: +6593907207		
Adj Asg. Remarks:	on WP. SURVEY AGREE ON SJE - REQ TO ASSIGN LKK LIABILITY:100% CONTACT:MR KWAN 6392 2555		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 11 October 2018 11:53 AM
To: 'Sbk E'
Subject: RE: FINALIZATION: RE: AFTER REPAIR PHOTOS - FBG8275K

Dear Mr Kwan,

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]

Sent: Sunday, 7 October 2018 4:04 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: FINALIZATION: RE: AFTER REPAIR PHOTOS - FBG8275K

Dear Shirley,

Please help submit report. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Thu, 10/4/18, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Subject: RE: FINALIZATION: RE: AFTER REPAIR PHOTOS - FBG8275K

To: "'Sbk E'" <sbk5643e@yahoo.com>

Cc: sur@lkkauto.com

Date: Thursday, October 4, 2018, 4:56 PM

Dear Mr Kwan,

Please confirm final fig of \$1,900.00 (lump sum) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

Shirley Hiew (LKK Auto)

From: Sbk E <sbk5643e@yahoo.com>
Sent: Sunday, 7 October 2018 4:04 PM
To: Shirley Hiew (LKK Auto)
Subject: RE: FINALIZATION: RE: AFTER REPAIR PHOTOS - FBG8275K

Dear Shirley,

Please help submit report. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Thu, 10/4/18, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Subject: RE: FINALIZATION: RE: AFTER REPAIR PHOTOS - FBG8275K
To: "'Sbk E'" <sbk5643e@yahoo.com>
Cc: sur@lkkauto.com
Date: Thursday, October 4, 2018, 4:56 PM

Dear Mr Kwan,

Please confirm final fig of \$1,900.00 (lump sum) @ 3 days of repairs before GST.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK
Auto Consultants Pte Ltd
Phone: 6256-3561 |
email: Sur@lkkauto.com
| fax: 6256-4315
Blk 51, Paya Ubi Industrial
Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]

Sent: Tuesday, 2 October 2018 3:10 PM
To: sur@lkkauto.com
Subject: FINALIZATION: RE: AFTER REPAIR PHOTOS
- FBG8275K

Dear Sur,

Please confirm the lump sum
repair amount and number of repair days. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

--- On Sun, 9/16/18, Sbk E
<sbk5643e@yahoo.com>
wrote:

> From: Sbk E
<sbk5643e@yahoo.com>
> Subject: RE: AFTER REPAIR PHOTOS -
FBG8275K
> To: "Naz (LKKAUTO)"
<Naz@lkkauto.com>
> Date: Sunday, September 16, 2018, 8:57 AM Dear Naz, > > After repair photos for your info.
> Thanks.
>
> Regards,
>
> Kwan S. H.
> Director
> Bike
Production Pte Ltd

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 17 Sep 2018

Preliminary Advice

Insured Vehicle No	: YN5635R	Accident Date	: 31/08/2018
TP Vehicle No	: GBF8275K <i>FBG 8275K</i>	Assignment Date	: 06/09/2018
Make	: HONDA CBF150	Est. Duration of Repair	: 3 days
Date of Inspection	: 14/09/2018		
Inspection At	: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,246.60
Revised Amount	:S\$	1,913.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,913.52

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Address BLK 30 KELANTAN ROAD #03-87
 Postcode 200030
 Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured? OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 Have been approached by unknown person(s) soliciting/offering accident claims assistance? NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name: BUKIT PANJANG
 Police Station Address: ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
 Police Station Contact: TEL NO. 1800-8929999 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1


Name DRAISAMY POOMALAI
 Phone Number 84291258
 Email Address:

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN5635R
 Vehicle Make/Model/Colour LORRY
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver TAN TIEW HENG
 NRIC/Passport Number
 Contact Number
 Address

Sketch Plan Pg. 1

10. SKETCH PLAN



11. OTHER CIRCUMSTANCES OF THE ACCIDENT

I am, SUGAMAN KANI MOHAMMED ABUSALIM
 Address: 5/15-2106 VEHICLE NO- EBG 8215 K
 I went PRAGA MO KIO PUN PARK 2 BIKES
 SHOP NO- #01-1077 For my company purpose
 on Friday 3:00pm Park my vehicle Entrance
 OF the Shop 3:15pm one lorry in 56.5 R
 REVERSED on the entrance of this shop and
 hit my bike. there was a very big fire and my
 colleague saw the incident and take pictures.
 Change the Responder's

12. DECLARATION

I declare the foregoing particulars are true in every respect.


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


Reporting Claim & Person's Signature
 Name:
 Date & Time:


 3/1/8

SKETCH PLAN

DISCLAIMER

1. Please ensure completing the details of the accident to speed up the claim's process.
 2. This form is to be completed by the Policyholder and/or the At-faulted Driver.
 3. Information provided in this form is truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may void the insurance cover and/or invalidate policy liability.
 4. The signature and completion of this SF Form by insurance policyholder is not an admission of policy liability on the part of the insured or the insurer.
 5. Vehicle Accident Report may be referred to the Police for investigation.
 6. There are 100 copies handed to the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) and 100 copies of this report will for a fee be made available for amplification by interested parties.
 7. For the document which report on the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available for use.
 8. Consistent with the Privacy of Data Protection Act (PDPA)
- I, the undersigned, do hereby agree and consent that
- (a) I, in writing, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided to me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to a third party who have insured vehicle(s) involved in this accident (if insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurer's lawyer/law firms, the Registrar of Motor Vehicle of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any other services relating to the claims;
 - (ii) settling the claims and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries to me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which may involve disclosure of certain personal data about me to bring about delivery of the same as well as on-line email download of documents/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes").
 - (b) Insurer(s) who have insured vehicle(s) involved in this accident and my Insurer's lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes;
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party's representative(s) or agents, including lawyer(s)/law firms, who may be based outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claim history for the purpose of future underwriting, underwriting and managing my present and all future claims;
 - (e) the information collected under (a) above may be shared and disclosed:
 - (i) to third parties and/or any third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Signature of Policyholder
 Date: 2/2/18

Driver's Signature
 of involved in the policyholder's
 Date: 2/2/18


 Reporting Centre Form (Self-Signature)
 Name:
 Signature:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 31 August 2018

ASSESSMENT FOR REPAIR: HONDA CBF150 - FBG8275K

Chassis No.: LA KC1184C3300149

Engine No.: KC 11E2107993

Qty	Description	Estimate
1 pc	Front mudguard	\$140.00 ✓ CRA
1 pc	Front wheel axle	\$45.00 X SVL
1 pc	Left fork assembly	\$80.00 X SVL
1 pc	Windshield	\$65.00 ✓ SCR
1 pc	Head fairing	\$105.00 ✓ CRA
1 pc	Headlamp assy	\$195.00 ✓ CRA
1 pc	Headlamp bracket	\$145.00 X SVL
1 pc	Left fairing assembly	\$185.00 ✓ SCR
1 pc	Left balancer	\$45.00 X SVL
1 pc	Steering stem bracket assembly	\$212.00 X nn
1 pc	Steering stem underbracket	\$211.00 X nn
1 pc	Handle bar	\$95.00 X nn
1 pc	Left view mirror	\$48.00 ✓ SCR
1 pc	Left handle balancer	\$35.00 X nn
1 pc	Clutch lever	\$35.00 ✓ SCR
1 pc	Side stand	\$70.00 ✓ SCR
1 pc	Left front signal	\$78.00 ✓ SCR
1 pc	Fuel tank assy	\$480.00 X nn
1 pc	Left engine cover	\$360.00 X nn
1 pc	Gasket	\$35.00 X nn
1 pc	Rear gear pedal assy	\$125.00 ✓ SCR
1 pc	Left front footrest holder assembly	\$135.00 X SVL
1 pc	Left front footrest	\$55.00 ✓ SCR
1 pc	Left rear footrest	\$55.00 ✓ SCR
1 pc	Left side cover	\$165.00 ✓ SCR
1 pc	Mainstand	\$130.00 ✓ SCR

Less discount 10%

Special nett items

1 pc	Front sport rim	\$80.00 X nn
1 pc	Box rack	\$150.00 X nn
1 pc	Front number plate	\$20.00 ✓ nlc
1 pc	ERP ID	\$156.00 ✓ SCR
1 pc	Top case	\$250.00 ✓ SCR
1)	Towing charges	\$80.00 ✓ nlc
2)	Dismantle, replace, realign and adjust above damaged parts	\$200.00 200
3)	Anti rust application	\$60.00 30
5)	To knock, straighten chassis & body balancing	\$280.00 100
1)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$130.00 X nn

\$3,734.00

\$373.40

\$3,360.60

1451

X0.9

1305.9

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Sep 2018		06 Sep 2018 09:23 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SL METALS PTE LTD , Co. Reg. No.: 198306087E									
Main Claimant: SULAIMANKANI MOHAMED ABUSALITH , ID: G6583210R									
Vehicle Reg. No.: FBG8275K		Date of Loss:	31/08/2018 17:00 - :59						
Claim Type: TP / 569220		Policy/Cover Note No.:	A27927444MKC (Comprehensive) Coverage: 09/07/2018 - 08/07/2019						
Vehicle Reg. No. (Insured): YN5635R		Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 06/10/2018]									
Driver/Custodian (Insured): TAN TIEW HENG (), NRIC: S12403421, Tel: +6593907207									
Adj Asg. Remarks: on WP. SURVEY AGREE ON SJE - REQ TO ASSIGN LKK LIABILITY:100% CONTACT:MR KWAN 6392 2555									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG8275K (569220)**
[YN5635R]
TP
SULAIMANKANI MOHAMED ABUSALITH
Aug 31 2018 5:00PM
[SL METALS PTE LTD]
Bike Production Pie Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	05/09/18 09:49	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: YN5635R, Claimant: SL METALS PTE LTD	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 14:54	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	20/09/18 12:01	General View	 Load JPG	☒
2	20/09/18 12:01	General View	 Load JPG	☒
3	20/09/18 12:01	General View	 Load JPG	☒
4	20/09/18 12:01	General View	 Load JPG	☒
5	20/09/18 12:01	General View	 Load JPG	☒
6	20/09/18 12:01	General View	 Load JPG	☒
7	20/09/18 12:01	General View	 Load JPG	☒
8	20/09/18 12:01	General View	 Load JPG	☒
9	20/09/18 12:01	General View	 Load JPG	☒
10	20/09/18 12:01	General View	 Load JPG	☒
11	20/09/18 12:01	General View	 Load JPG	☒
12	20/09/18 12:01	General View	 Load JPG	☒
13	20/09/18 12:01	General View	 Load JPG	☒
14	20/09/18 12:01	General View	 Load JPG	☒
15	20/09/18 12:01	General View	 Load JPG	☒
16	20/09/18 12:01	General View	 Load JPG	☒
17	20/09/18 12:01	General View	 Load JPG	☒
18	20/09/18 12:01	General View	 Load JPG	☒
19	20/09/18 12:01	General View	 Load JPG	☒
20	20/09/18 12:01	General View	 Load JPG	☒
21	20/09/18 12:01	General View	 Load JPG	☒
22	20/09/18 12:01	General View	 Load JPG	☒
23	04/10/18 13:00	Reinspection Photo	 Load JPG	☒
24	04/10/18 13:00	Reinspection Photo	 Load JPG	☒
25	04/10/18 13:00	Reinspection Photo	 Load JPG	☒
26	04/10/18 13:00	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	05/09/18 09:49	MSIG Insurance (Singapore) Pte. Ltd. (HQ) FBG8275K TP E-FILE REPORT From: SC - Reg. No: YN5635R, Claimant: SL METALS PTE LTD	 Load PDF	
2	05/09/18 09:50	PRI - APAC LAW CORPORATION	 Load PDF	
3	05/09/18 16:20	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016272/NSD3E2

Date: 15/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A27927444MKC

Claimant Vehicle No : FBG8275K

Insured Vehicle No : YN5635R

Date of Loss: 31/08/2018

Nature of Claim: TP

Claim No: 569220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBG8275K

Make & Model: HONDA CBF150, 149cc (M)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: LALKC11B4C3300149

Colour: Black

Odometer: 51313 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90 R18

Rear Tyre Size: 3.60-18

Front Left Side: Shinko 6 mm

Rear Left Side: Shinko 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,416.60	1,731.90	2,684.70	60.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	660.00	1,170.00	63.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,246.60	2,391.90	3,854.70	61.71
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	6,246.60	1,900.00	4,346.60	69.58
+ GST 7.00/7.00% (S\$)	437.26	133.00	304.26	69.58
Nett Amount (S\$)	6,683.86	2,033.00	4,650.86	69.58

INSPECTION

Date of Assignment: 06/09/2018

Date Inspected: 14/09/2018 Inspected At:

Bike Production Pie Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 11 Oct 2018)
Parts:	N/A	HONDA CBF150 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FBG8275K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cracked	140.00 FL	*140.00 FL
2	1		*FRONT WHEEL AXLE	Serviceable	45.00 FL	*- FL
3	1		*LEFT FORK ASSEMBLY	Serviceable	480.00 FL	*- FL
4	1		*WINDSHIELD	Scratched	65.00 FL	*65.00 FL
5	1		*HEAD FAIRING	Cracked	105.00 FL	*105.00 FL
6	1		*HEADLAMP ASSY	Cracked	195.00 FL	*195.00 FL
7	1		*HEADLAMP BRACKET	Serviceable	145.00 FL	*- FL
8	1		*LEFT FAIRING ASSEMBLY	Scratched	185.00 FL	*185.00 FL
9	1		*LEFT BALANCER	Serviceable	45.00 FL	*- FL
10	1		*STEERING STEM BRACKET ASSEMBLY	Not Necessary	214.00 FL	*- FL
11	1		*STEERING STEM UNDERBRACKET	Not Necessary	214.00 FL	*- FL
12	1		*HANDLE BAR	Not Necessary	95.00 FL	*- FL
13	1		*LEFT VIEW MIRROR	Scratched	48.00 FL	*48.00 FL
14	1		*LEFT HANDLE BALANCER	Not Necessary	35.00 FL	*- FL
15	1		*CLUTCH LEVER	Scratched	35.00 FL	*35.00 FL
16	1		*SIDE STAND	Scratched	70.00 FL	*70.00 FL
17	1		*LEFT FRONT SIGNAL	Scratched	78.00 FL	*78.00 FL
18	1		*FUEL TANK ASSY	Not Necessary	480.00 FL	*- FL
19	1		*LEFT ENGINE COVER	Not Necessary	360.00 FL	*- FL
20	1		*GASKET	Not Necessary	35.00 FL	*- FL
21	1		*REAR GEAR PEDAL ASSY	Scratched	125.00 FL	*125.00 FL
22	1		*LEFT FRONT FOOTREST HOLDER ASSEMBLY	Serviceable	135.00 FL	*- FL
23	1		*LEFT FRONT FOOTREST	Scratched	55.00 FL	*55.00 FL
24	1		*LEFT REAR FOOTREST	Scratched	55.00 FL	*55.00 FL
25	1		*LEFT SIDE COVER	Scratched	165.00 FL	*165.00 FL
26	1		*MAINSTAND	Scratched	130.00 FL	*130.00 FL
27	1		*FRONT SPORT RIM	Not Necessary	480.00 FS	*- FS
28	1		*BOX RACK	Not Necessary	150.00 FS	*- FS
29	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*20.00 FS
30	1		*ERP IU	Scratched	156.00 FS	*156.00 FS
31	1		*TOP CASE	Scratched	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,790.00	1,877.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	373.40	145.10
Total Parts (\$\$)	4,416.60	1,731.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	80.00	80.00
2	DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	500.00	200.00
3	ANTI RUST APPLICATION	New	60.00	30.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	100.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
6	TO REMOVE / REFIT AND REPLACE FRONT SPORT RIM	New	180.00	0.00
7	SPRAY PAINTING	New	450.00	250.00
Gross Labour Cost (S\$)			1,830.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >