

# Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374 382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST: 201001158E RCB NO 201001158I

SLN 82975

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES1891023/YISHUN

Date: 05 Sep 2018

Policy No: 8-V0017758-MVA

Veh Reg No: SLN82975

Make/Model: HONDA VEZEL 1.5X  
CVT

Chassis No: RU11211552

Engine No: L15B4411552

Reg. Date: 18/05/2017

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 04/09/2018

TP Veh Reg No: GBA1406C

*Not Withheld*  
*Repair B4 panel*

*3-5 days*

## Estimate Repair Cost to Vehicle No :SLN82975

| Description                                     | U/Price  | Quantity | List Price | Amount   |
|-------------------------------------------------|----------|----------|------------|----------|
|                                                 |          |          | SS         | SS       |
| <b>List Price</b>                               |          |          |            |          |
| 1 REAR BUMPER                                   | 538.40   | 1 PC     | 538.40     | ✓        |
| 2 REAR BUMPER CLIPS                             | 3.90     | 6 PCS    | 23.40      | ✓        |
| 3 REAR TAILGATE                                 | 1,100.90 | 1 PC     | 1,100.90   | ✓        |
| 4 TAILGATE INNER LOCK                           | 189.10   | 1 PC     | 189.10     | ✓        |
| 5 TAILGATE INNER RUBBER                         | 96.80    | 1 PC     | 96.80      | XX       |
| 6 TAILGATE EMBLEM (VEZEL)                       | 58.50    | 1 PC     | 58.50      | ✓        |
| 7 TAILGATE REFLECTORS                           | 240.30   | 2 PCS    | 480.60     | 1X       |
| 8 TAILGATE OUTER GARNISH                        | 189.50   | 1 PC     | 189.50     | 1X       |
| 9 REAR CENTRE PANEL                             | 415.60   | 1 PC     | 415.60     | 220.90   |
| 10 REAR WINDSCREEN GLASS MOULDING               | 128.40   | 1 PC     | 128.40     | ✓        |
|                                                 |          |          | 3,221.20   |          |
|                                                 |          | Less 20% | 644.24     | 2,576.96 |
| <b>Special Net</b>                              |          |          |            |          |
| 11 REVERSE SENSOR                               | 200.00   | 1 SET    | 200.00     | ✓        |
| 12 REAR WINDSCREEN GLASS GUM                    | 40.00    | 1 ROLL   | 40.00      | ✓        |
|                                                 |          |          | 240.00     | 240.00   |
| <b>Labour</b>                                   |          |          |            |          |
| 13 REMOVE AND REFIX REAR WINDSCREEN GLASS       | 120.00   | 1 LA     | 120.00     | ✓        |
| 14 PANEL BEATING                                | 700.00   | 1 LA     | 700.00     | 550      |
| 15 PUTTY & RESPRAY PAINT                        | 700.00   | 1 LA     | 700.00     | 500      |
| 16 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM | 50.00    | 1 LA     | 50.00      | ✓        |
| 17 RUSTPROOFING                                 | 60.00    | 1 LA     | 60.00      | 230      |
|                                                 |          |          | 1,630.00   | 1,630.00 |

Total SS 4,446.96

Add GST @ 7% 311.29

Total Amount Payable SS 4,758.25

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: