

德興摩哆私人有限公司

Blk 3006 Ubi Road 1 #01-356 Singapore 408700 Tel: (65) 67468582 (4 Lines) Fax: (65) 67439525

> Email: dxmotor@singnet.com.sg Website: www.dxmotor.com Co. Reg. No.: 198303312R



() Third-Party

(X) Own Damage

() List Price

To resurvey before/after spray painting

 To display damaged part(s) during resurvey) Cost Price subject to confirmation

Third party survey is on a "Without Prejudice" basis

 No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and : 02/06/2018 is subject to final approval from Insurance Company

Make/ Model: BAJAJ PULSAR 200NSFI

: FBM5848X

Chassis No

Date of Acc

: MD2A36F22GCF47149_{epairer}

Signature:

Year

Bike No

: 2016

Requested by : TIONG

Date:

S/ NO	Parts Description	Quantity	Unit Price	Total	Remarks
1	R/H HANDLE BAR !	1	\$165.00	\$165.00	· tomanto
2	R/H HANDLE BAR BALANCE	1	\$18.00	\$18.00	
3	BRAKE LEVER /W	1	\$38.00	\$38.00	
4	RH/ MIRROR wt	1	\$68.00	\$68.00	
5	LOWER FRONT FORK BRACKET	1	\$320.00	\$320.00	
6	FRONT FENDER / W	1	\$185.00	\$185.00	
7	BRAKE PEDAL / 6/5	1	\$115.00	\$115.00	
8	RH/ REAR FOOTREST BRACKET	BT 1	\$98.00	\$98.00	
9	RH/ REAR FOOTREST /	1	\$53.00	\$53.00	
10	RH/ CENTER COVER / CAT	1	\$125.00	\$125.00	
11	REAR RIM FENDER	1	\$155.00	\$155.00	
12	STEERING CONE ?	1	\$120.00	\$120.00	
13	RH ENGINE GUARD / Cot.	1	\$80.00	\$80.00	
14	REAR BOX BRACKET ?	1	\$135.00	\$135.00	
	REAR BOX KAPPA 46	1	\$180.00	\$180.00	
16	REAR NUMBER PLATE / Cot	1	\$20.00	\$20.00	
	ALIGN FORK	1	\$120.00	\$120.00	
	LABOUR	1	\$480.00	\$480.00	150
). 4				

After repair photos.
Gue Cipy - 82860282

Sub Total

\$2,475.00

ADD 7%GST

\$173.25

Grand Total

\$2,648.25

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE B ADDITIONAL PARTS REQUIRED OR DAMAGED DURING OUR COURSE OF REPAIRS, WE W INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE.

APPROVING OFFICER'S SIGNATURE & COMPANY'S STAMP