

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Company Reg No: 200704370C GST Reg No :: 200704370C

Your ref : SLV2619U

Date: 11.09.2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLV2619U(HYUNDAI ELANTRA)

DATE OF ACCIDENT : 03.09.2018

TO SUPPLY :

LIST ITEMS

01)	1 PC	REAR BUMPER	DD/Deqcu)	\$	459.00	=
02)	1 PC	REAR BUMPER LOWER GARNISH(BLACK)	(47)	\$	250.10	=
				\$	709.10	
			20%	LESS 10%	\$	(70.91)
				\$	638.19	

Labour Cost

03)	SPRAY PAINT	\$	320.00	200
04)	LABOUR CHARGE	\$	320.00	200
05)	TRANSFER PARKING SENSOR	\$	80.00	50
	TOTAL LABOUR COST	\$	720.00	

TOTAL \$ 1,358.19

Not Added
LME
12/9/18
to the phone after repair
2017.
4/5 \$800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: