

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person)

Yee Pei Li

of

EQI

Date/Time: 5/9/18 @ 5:18pm

Estimated Cost

Bill to

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJQ 1785D

Insured:

GBA 1242H

at Workshop m/s

Kai Motor

Tel:

96559667 / 6747 4006

of

B1K 3007, Ubi Rd 1 # 01-440

Policy No.

Claim No:

GBA 1242H / SL1P1

Sum Insured

Excess:

Make of Veh:

D.O.A. 01/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:30am @ 6/9/18

Person Contacted:

Ms. Kym

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJQ 1785D-X

GBA 1242H-X

11/09/18

@ 17:03 p.m. revised PA to Pei Li via email.

00811/13 wef

ASS. REC. BY:

REF: EGI

ASSIGNMENT

(-2019)

From: Date: 06/09/18

Estimated Cost:

ON ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJQ 1785D

at Workshop m/s Kai Motor

of BIK 3007, Ubi Rd 1 # 01-440

Insured: Hug

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 11500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SJQ 1785D

Yr Regn:

28 Apr 2009

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante c.c 1591

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

KMHD441BR94749141

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 195/60R15

R: 11

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

D.O.I.

06-09-18

Survey held at

W/S

1230pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

06/9 Finalised \$ 4800 with Hug

13/09/18 Confirmed L/S \$ 4,800/- @ 7 days with XGA
(\$ 4,986.52 Red - 51%)

[Signature]

13/9/2018

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

13/09/18

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

250

Report Format :

Lump Sum / I.B.I: (\$ 4,800/- L/S)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18016296/Gsd3		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 06-09-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 1242H	Veh. Inspected	SJQ 1785D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBA1242H/SLI/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	06/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/09/2018	Inspection Date	06/09/2018	
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBA1242H/SLI/pl

Date: 11 September 2018

Our Ref: CS/EG118016296/Gsd3

The Motor Claims Department
Ergo Insurance Pte Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJQ 1785D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/09/2018 at the premises of M/s Kai Motor Trading and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 9,626.20</u>
Revised Estimate Amount	: <u>S\$ 7,246.72</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 7 Days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

ERGO

Date: 05.09.2018
Our Reference: GBA 1242H/SL/pl
Your Reference: SJQ 1785D

Sent via Fax

6743 7591

or

Email

kalmotor@gmail.com

To: KAI MOTOR TRADING

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJQ 1785D
Insured's Vehicle: GBA 1242H
Date Of Accident: 01.09.2018

We acknowledge receipt of your request for PRS on: 04.09.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us to date.

☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp

Note: Our Inspection is on a without admission to liability basis.



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 11 September 2018 5:03 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: GBA1242H / TP : SJQ1785D/LKK / DOA : 01/09/2018
Attachments: SJQ 1785D - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SJQ1785D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 6 September 2018 9:31 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: 'SUR' <sur@lkkauto.com>
Subject: RE: GBA1242H / TP : SJQ1785D/LKK / DOA : 01/09/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 5 September 2018 5:18 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBA1242H / TP : SJQ1785D/LKK / DOA : 01/09/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **KAI MOTOR TRADING**.

ADDRESS : BLK 3007 UBI ROAD 1

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 5 September 2018 5:18 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBA1242H / TP : SJQ1785D/LKK / DOA : 01/09/2018
Attachments: GBA1242H - SAS.pdf; SJQ1785D - SAS.pdf; SJQ1785D - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **KAI MOTOR TRADING**,

ADDRESS : BLK 3007 UBI ROAD 1
#01-440
SINGAPORE 408701

PERSON TO CONTACT : MS KYM @ 6747 4006

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured's and third party's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax.: +65 6829 9247

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group); one of the world's leading risk carriers.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0609D
Vehicle Details	
Vehicle No.:	SJQ1785D
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9U646634
Chassis No.:	KMH DU41BR9U749141
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,706.00
Original Registration Date:	28 Apr 2009
First Registration Date:	28 Apr 2009
Transfer Count:	2
Actual ARF Paid:	\$11,706.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2019
PARF Rebate Amount:	\$5,853.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$454.00
Total Rebate Amount:	\$6,307.00

The information contained herein is correct as at 06 Sep 2018

OK



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 04/09/2018

Attn: Motor Claim Dep
Your Insured veh no :- GBA 1242 H
ERGO Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Tel : 6829 9199

Fax : 6829 9247

Email: steve.lim@ergo.com.sg

Website: www.ergo.com.sg

L KK

Adrian 96893735

Dear Sir / Madam

Estimate Cost repair Bill To Hyundai HD Avante 1.6A NO SJQ 1785 D & GBA 1242 H 01/09/2018

To Supply :-

1pc	Rear boot cover	BT	\$ 985.00	✓
1pc	Rear boot cover "Avante" plate	✓	\$ 63.00	✓
1pc	Rear boot cover logo	✓	\$ 41.00	✓
1pc	Rear boot cover "S" plate	✓	\$ 29.00	✓
1pc	Rear boot cover garnish	RE	\$ 141.00	✓
2pcs	Rear boot cover hinge	BT \$ 132.80	\$ 265.60	✓
1pc	Rear boot cover insuintor	RE	\$ 169.00	✓
10pcs	Rear boot cover insuintor clips	\$ 5.00	\$ 50.00	✓
1pc	Rear boot cover lamp RH	CRS	\$ 155.00	✓
1pc	Rear boot cover rubber	Tri	\$ 89.00	✓
1pc	Rear boot cover lock	BT	\$ 109.00	✓
1pc	Rear fender RH	Buc	\$ 1,806.70	✓
1pc	Rear lamp RH	CRS	\$ 282.60	✓
1pc	Rear panel	Buc	\$ 580.20	✓
1pc	Rear panel inner garinsh	RE	\$ 101.00	✓
1pc	Rear fender inner garnish	RE	\$ 168.00	✓
1pc	Rear spary tyre panel	X repair	\$ 898.00	X
1pc	Rear bumper	RE	\$ 497.00	✓
2pcs	Rear bumper bracket	X NN \$ 79.00	\$ 158.00	X
2pcs	Rear bumper side retainer	RES 31.00	\$ 62.00	✓
1pc	Rear bumper reinforcement	CRS	\$ 270.00	✓
1pc	Rear bumper sponge	CRS	\$ 139.30	✓
			\$ 7,059.40	
less			20%	
			\$ 1,411.88	
			\$ 5,647.52	

10pcs Rear bumper clips / Mc

\$ 50.00 ✓

6053.4
20% 4842.72



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 04/09/2018

Attn: Motor Claim Dep
Your Insured veh no :- GBA 1242 H
ERGO Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Tel : 6829 9199

Fax : 6829 9247

Email: steve.lim@ergo.com.sg

Website: www.ergo.com.sg

LKK/F- Plants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dear Sir / Madam

Page.2

Estimate Cost repair Bill To Hyundai HD Avante 1.6A NO SJQ 1785 D & GBA 1242 H on 01/09/2018

To Supply :-

\$5,647.20

1set	Reverse sensor	/ QMA	\$ 350.00	S/nett	200
1pc	Rear number plate w housing	/ SCR	\$ 75.00	S/nett	40
1pc	Rear windscreen seal	/ KC	\$ 49.00	S/nett	/
1pc	Rear camara	X NN	\$ 540.00	S/nett	X
1pc	Rear windscreen sealet	/ KC	\$ 55.00	S/nett	/

To dismantl & replace damage parts, panel beat where necessary.

\$1,250.00 800

To putty, apply primer & spray paint on the affecte portion.

\$1,300.00 1000

To check wiring functions.

\$ 80.00 30

labour charge to remove & refix windscreen.

\$ 120.00 100

To remove reverse sensor.

\$ 80.00 40

To remove & refit rear camara.

\$ 80.00 40
\$9,626.20

9,786.52

Towing charge - 7 Days.

\$120.00 50

Wmp Sum Repair.

After repair photos.

Gua Qiang - 82880282

LKK 06/9/18

7246.72

20% 4800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18016296/Gsd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 21-09-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 1242H	Veh. Inspected	SJQ 1785D	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBA1242H/SLI/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U749141	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195/60 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/60 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2018	Inspection Date	06/09/2018	
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 1785D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT COVER	BENT	985.00	985.00
1	REAR BOOT COVER "AVANTE" PLATE	NECESSARY	63.00	63.00
1	REAR BOOT COVER LOGO	NECESSARY	41.00	41.00
1	REAR BOOT COVER "S" PLATE	NECESSARY	29.00	29.00
1	REAR BOOT COVER GARNISH	DEFORMED	141.00	141.00
2	REAR BOOT COVER HINGE @\$132.80	BENT	265.60	265.60
1	REAR BOOT COVER INSUINTOR	DEFORMED	169.00	169.00
10	REAR BOOT COVER INSUINTOR CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BOOT COVER LAMP RH	CRACKED	155.00	155.00
1	REAR BOOT COVER RUBBER	TWISTED	89.00	89.00
1	REAR BOOT COVER LOCK	BENT	109.00	109.00
1	REAR FENDER RH	BUCKLED	1,806.70	1,806.70
1	REAR LAMP RH	CRACKED	282.60	282.60
1	REAR PANEL	BUCKLED	580.20	580.20
1	REAR PANEL INNER GARNISH	DEFORMED	101.00	101.00
1	REAR FENDER INNER GARNISH	DEFORMED	168.00	168.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	898.00	-
1	REAR BUMPER	DEFORMED	497.00	497.00
2	REAR BUMPER BRACKET @\$79.00	NOT NECESSARY	158.00	-
2	REAR BUMPER SIDE RETAINER @\$31.00	DEFORMED	62.00	62.00
1	REAR BUMPER REINFORCEMENT	CRACKED	270.00	270.00
1	REAR BUMPER SPONGE	CRACKED	139.30	139.30
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-1,421.88	-1,210.68
			5,687.52	4,842.72
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR NUMBER PLATE W HOUSING (SN)	SCRATCHED	75.00	40.00
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	49.00	49.00
1	REAR CAMERA (SN)	NOT NECESSARY	540.00	-

Report Ref No. CS/EGI18016296/Gsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	55.00
			1,069.00	344.00
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,250.00	800.00
	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.		1,300.00	1,000.00
	TO CHECK WIRING FUNCTIONS.		80.00	30.00
	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN.		120.00	100.00
	TO REMOVE REVERSE SENSOR.		80.00	40.00
	TO REMOVE & REFIT REAR CAMERA.		80.00	40.00
	TOWING CHARGE.		120.00	50.00
			3,030.00	2,060.00
	GRAND TOTAL		9,786.52	7,246.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/EGI18016296/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.